

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SH 7091Z

MAKE : HYUNDAI

MODEL : i40

CHINA

Date: 16.04.18

Date: 17.04.2018

Qty	Parts Description / Labour	Type	Unit Price	Amount
	Front Bumper			\$ 1,052.20
	Front Bumper Clips \$2.20 X 10pcs			\$ 22.00
	Front Bumper Sponge			\$ 142.20
	Front Bumper Reinforcement			\$ 526.10
	Radiator Grille			\$ 1,480.00
	Headlamp Support Panel			\$ 1,067.50
	A/C Condenser			\$ 1,137.35
	SUB TOTAL			\$ 5,427.35
	LESS 20%			1,085.47
	DISCOUNTED TOTAL			\$ 4,341.88
				\$ 0.00
	Labour Charge			
	Panel Beating			\$ 300.00
	Spray Painting Charge			\$ 200.00
	Wiring Charge			\$ 50.00
	Remove/refix A/C and Refill gas			\$ 150.00
	Towing Fee			\$ 60.00
	TOTAL LABOUR			\$ 700.00
	ESTIMATE TOTAL			\$ 5,041.88

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- To provide final repair quantum will be confirmed by the insurance company.
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOB REQUISITION FOR BREAKDOWN / TOWING SERVICE

Job Requisition			
1. Date: <u>16/4/18</u> Time Received: <u>16:15pm</u>		3. Vehicle Type: <input type="checkbox"/> Private <input checked="" type="checkbox"/> Taxi (CTPL/CCPL) <input type="checkbox"/> Fleet <input type="checkbox"/> STK (Boon Lay)	
2. <input type="checkbox"/> New <input type="checkbox"/> SPARK Kakis Name of Customer : <u>OMAR B ABDUL SAFAR</u> Contact No. : <u>96419672</u> Vehicle No. : <u>SH 70912</u> Make / Model / Colour : <u>140</u> Email :		4. Type of Towing: <input checked="" type="checkbox"/> Normal Tow <input type="checkbox"/> King Dolly <input type="checkbox"/> Flat Bed <input type="checkbox"/> Crane-up	
7. Location: <u>53 CHANCERY LANE</u>		6. Parts Replaced/Remarks:	
9. Preferred Workshop: <input type="checkbox"/> Braddell <input checked="" type="checkbox"/> Loyang <input type="checkbox"/> Pandan <input type="checkbox"/> Sin Ming <input type="checkbox"/> Sungei Kadut <input type="checkbox"/> Ubi <input type="checkbox"/> Senoko <input type="checkbox"/> Komoco (UBI / Leng Kee) <input type="checkbox"/> Cycle & Carriage (PD) <input type="checkbox"/> Others:		8. Vehicle Tow - In Workshop: <input type="checkbox"/> Smoky Exhaust <input type="checkbox"/> Wheel Jammed <input type="checkbox"/> Overheating <input type="checkbox"/> Steering Faulty <input type="checkbox"/> Brake Faulty <input type="checkbox"/> Alternator Faulty <input type="checkbox"/> Starting Problem <input type="checkbox"/> Loss Power <input checked="" type="checkbox"/> Accident <input type="checkbox"/> Engine Stalled <input type="checkbox"/> Return Taxi	
10. Odometer Reading : _____ Fuel Level : <input type="checkbox"/> F <input type="checkbox"/> 1/4 <input type="checkbox"/> 1/2 <input type="checkbox"/> 3/4 <input type="checkbox"/> E		11. Radio / CD Player <input checked="" type="checkbox"/> OK <input type="checkbox"/> Faulty <input type="checkbox"/> Not tested	
Job Attended			
12. Tow Truck / Recovery Van : <input type="checkbox"/> VRS <input type="checkbox"/> QA <input checked="" type="checkbox"/> GAO <input type="checkbox"/> TZ <input type="checkbox"/> YISHUN <input type="checkbox"/> OTHERS Name of Driver : <u>SMAN</u> Vehicle No. : <u>YMA91483</u> Time Dispatch : <u>16:15pm</u> Time of Arrival : <u>16:25pm</u> Time Completed : <u>17:40pm</u>		 # : Cracked X : Dented / : Scratched O : Missing Signature of Customer: <u>[Signature]</u>	

Cash Invoice Details (if applicable)

13. Cash Invoice No. : _____

Customer Acknowledgement

a. I have been advised to remove all valuable items in my vehicle, including Global Positioning System (GPS), audio compact disk, thumbdrive, carpark coupons, cash cards, spectacles, pen, etc.

b. I understand that any items left behind are at my own risk and SPARK Car Care™ will not be held liable for such losses.

c. Surcharge: Towing fee will be levied if the customer decides neither to tow nor proceed with the repairs in SPARK Car Care™.

16/4/18 Date 16:25pm Time [Signature] Signature of Customer

14. WORKSHOP

Name of Attending Staff/Guard

Date & Time of Arrival

Signature of Attending Staff/Guard