

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SH 7751C

DATE 16/4/2018 16:53

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Door (RH) ✓			\$ 1,351.10	
	Rear Wheel Hup-Cap (RH) ✓			\$ 150.70	
	<i>Rear Bumper X Rep</i> SUB TOTAL			\$ 1,501.80	
	<i>Front Door (RH) X Rep</i> LESS 20%			\$ 300.36	
	DISCOUNTED TOTAL			\$ 1,201.44	
	<i>Roz/Kear Panel Handish (RH) ✓</i>				
	Rear Bumper Rubber Mat X			\$ 50.00	Nett
	Rear Door Comfortdelgro & Apps Sticker (RH) ✓			\$ 80.00	Nett
	Front Door Coloured Comfort Logo (RH) ✓			\$ 75.00	Nett
				\$ 205.00	
	Labour Charge				
	Panel Beating-Repair Fender			\$ 1,000.00	600
	Spray Painting Charge			\$ 1,250.00	1000
	Wiring Charge			\$ 50.00	X
	Tuff Kote			\$ 50.00	20
	Remove/Refix Reverse Sensor			\$ 120.00	X
	Transfer of Door			\$ 120.00	50
	TOTAL LABOUR			\$ 2,590.00	
	ESTIMATE TOTAL			\$ 3,996.44	
	<i>16/4/18</i>				
	<i>17/4/18 1040hrs</i>				
	<i>3 Days</i>				
	<i>P/P Before Paint & Photo</i>				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.