

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 03 May 2018)	
Parts:	N/A	TOYOTA DYNA 150 D 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBF6865B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT GRILLE RUBBER <i>Missing</i>	0.00	0.00	*25.00 F ✓
2	1		*DOOR RUBBER - RH <i>at</i>	0.00	0.00	*45.00 F ✓
3	1		*VACUUM PUMP <i>Bent</i>	0.00	0.00	*130.00 F ✓
Sub Total (S\$)						200.00
+ Margin on L,N Items 15.00% (S\$)						30.00
Total Parts (S\$)						230.00

F=Franchise part.

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

Adrian Lj
03/05/18
888