



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240



ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Table with 2 main columns: Invoice Name & Address, Owner Name & Vehicle Info. Includes details for MR SEOW HUAT YONG(XIAO FARONG) and vehicle specifications like Reg No, Date, Mileage, Chassis No, Engine No, Make/Model, and Colour/Trim.

Table with 6 columns: Account No, Terms, Date/Time Printed, CSE, Operator, WIP No. Row 1: CSM00081, Cash, 12/04/2018/ 19:08, QLD, 247 / DonBong, 26715

Main items table with columns: Description of Goods / Services, Qty, Unit Price, Disc%, Amount. Lists various car parts like BRACKET-RR BEAM LWR, COVER-RR BUMPER, HINGE ASSY-TRUNK LID, etc. Includes handwritten notes and checkmarks.

Handwritten notes and signatures: SURVEYOR NAME: Rasul-Hp 90010068, SURVEYOR SIGNATURE: [Signature], DATE: 25/04/18 @ 1030 hrs, REMARKS: 6 days, Recovery of part. Includes date stamp 24/5/18.

Summary table for 'Confirm & accepted by'. Shows Net amount 12,860.00, 7% GST on 12860.00 (900.20), and Total Payable 13,760.20. Includes a line for 'Authorized signatory and company stamp'.

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.