

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Winnie Chua Ping Ping

Date: 19 Apr 2018

Preliminary Advice

Vehicle No	: SDE1043X	Accident Date	: 16/04/2018
Make	: VOLKSWAGEN JETTA	Policy No.	: A28867306AVW
Assignment Date	: 18/04/2018	Excess	: S\$500.00
Date of Inspection	: 19/04/2018	Est. Duration of Repair	: 11 days
Inspection At	: Volkswagen Centre Singapore (HQ) 247 Alexandra Road Singapore 159934		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	17,276.48
Revised Amount	:S\$	12,546.18
Check Items (Estimated)	:S\$	234.99
Total	:S\$	12,781.17

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	88,000.00
COE / PARF Rebate	:S\$	54,822.00
Salvage Value	:S\$	
Margin for Repair	:S\$	33,178.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.