

SS. REC. BY:

REF: CS/FCL18007262 / Uls3bez2 Special Instruction:

Survivor: Marcus.

ASSIGNMENT (Office)

From (Person): CWS Karen Tan

of

FCL

Date/Time: 19/04/2018 1130am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJW 8343T

Insured:

SHA 1756X

at Workshop m/s

LBA Automotive

Tel:

6509 5521

of

Blk 1 Kaki Bukit Ave 6 #02-47

Policy No:

Claim No:

D18003036MTF5H

Sum Insured:

Excess:

Make of Veh:

D.O.A.

18/04/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'OS'

H.O.D. Endorsement:

Date/Time:

19/04/2018 1204pm

Person Contacted:

Karen

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SJW 8343T - X
	SHA 1756X - CS/MSG 17033170 / Kigbn2
20/04/18	Ⓢ 13.22 p.m. - revised to Karen Tan via email.

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

Le.1

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJW8343T

at Workshop m/s LBA

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 29k.

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SJW8343T Yr Regn: 1 1 10

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CAI

Make: Toyota wish c.c. 1797

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 98435 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 26E200017034

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 195/65-R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Kumho

Front 6 mm Rear 6 mm

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 18/4/18 D.O.I. 19/4/18

Survey held at _____

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

LTA 15376 1 yrs Ins. Rep 12th net 13624

19/4/18 Confund d/s \$10,000 with AH hai

RSD - 40%

RECEIVED 20 APR 2018

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: 6

1) Typist

☒ : Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

Photos

Others

TOTAL

Report Format: TP

Lump Sum / I.B.I. (\$) 10,000.00

615-90

170490

50

50

131

491

MOTOR SURVEY ASSIGNMENT

Date	18-04-2018	Our Ref No. D18003036MFSH
Accident Date	18-04-2018	Claim Type. Third Party
Insured Vehicle	SHA1756X	Third Party Vehicle. SJW8343T
Survey Location	1 KAKI BUKIT AVE 6 #02-47 AUTOBAY	
Contact Person.	MS KAREN	
Contact No.	65095521/0	Fax No. 65095523
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	LBA AUTOMOTIVE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

MSME18051520 / SME Motor Pte Ltd - Kaki Bukit
 ENTRY DATE & TIME: 18/04/2018 16:28
 SUBMITTED BY: Chia Pei Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/04/2018 16:28
Date Of Accident	18/04/2018 10:40
Exact Location Of Accident	BUKIT BATOK EAST AVE 2 TWDS ST 25
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJW8343T
Insured/Policyholder	
Name Of Registered Owner	RAMKRISHNA RAMIER SANKARA RAMAN
NRIC No	S7062008A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97122294
Alternative Phone No	OFFICE-97122294

Vehicle Particulars

Manufacturer	TOYOTA
Model	WISH

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA0089881
Cover Note Number	

Driver

Name of Driver	RANJINI VISWESWARAN
NRIC No	S7684541G
Date Of Birth	19/05/1976
Occupation	INDOOR
Date Of Driving Pass	28/05/2005
Driving Experience	12 YEARS AND 10 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97122294
Fax Number	
Contact Number	
EEmail Address	NOEMAIL


Sketch Plan #2 Pg. 1

SKETCH PLAN

Bulit Barde East Ave 2
 towards street 25

(A) - SHW 8343T

(B) - SHW 1956X



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along Bulit Barde East Ave 2 towards St 25.

As the vehicle in front of me stop I followed, out of the sudden

I felt an impact from the rear. I came down and found out

vehicle B hit onto my vehicle we exchange details and left.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

BA AUTOMOTIVE PTE.LTD

NO 1 KAKI BUKIT AVE 6 #02-47

AUTOBAY SINGAPORE 417883

Tel : 6509 5521 / 65095524 Fax : 6509 5523

The Motor Claims Dept.

FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD

#16-01 CITY HOUSE

SINGAPORE 068877

SHA1756X

ESTIMATE

DATE : 18.04.2018

VEHICLE NO : SJW8343T

MAKE/MODEL : TOYOTA WISH

ACC DATE : 18.04.2018

No of Amount
date
2/5 @ 10,000/-
6 days
To be paid after repair
19/4/18

PARTICULAR		UNIT PRICE	AMOUNT
QTY	LIST PRICE	S\$	S\$
1	1 (SET) REAR WINDSCREEN MOULDING	210.90	210.90
2	1 REAR TAILGATE	1,416.40	1,416.40
3	2 REAR TAILGATE HINGE RH/LH	66.35	132.70
4	2 REAR TAILGATE DAMPER RH/LH	299.40	598.80
5	1 REAR TAILGATE RUBBER	392.10	392.10
6	1 REAR TAILGATE LOCK	509.10	509.10
7	1 REAR TAILGATE LOCK CATCH	40.30	40.30
8	1 REAR TAILGATE INNER HANDLE	45.10	45.10
9	1 REAR TAILGATE INNER TRIM	680.75	680.75
10	1 REAR TAILGATE EMBLEM 'LOGO'	68.50	68.50
11	1 REAR TAILGATE EMBLEM 'VALVE MATIC'	80.50	80.50
12	2 REAR TAILGATE REFLECTOR RH/LH	281.40	562.80
13	2 REAR TAILLAMP RH/LH	359.40	718.80
14	1 REAR BUMPER	821.65	821.65
15	2 REAR BUMPER REFLECTOR RH/LH	68.55	137.10
16	2 REAR BUMPER HOLDER RH/LH	65.30	130.60
17	2 REAR BUMPER BRACKET RH/LH	85.50	171.00
18	2 REAR BUMPER SIDE RETAINER RH/LH	68.85	137.70
19	1 CENTRE EXHAUST PIPE 2611-30	2,943.50	2,943.50
20	1 REAR EXHAUST BOX	794.40	794.40
21	1 REAR EXHAUST BOX HEAT SHIELD 195-30	326.10	326.10
22	1 REAR EXHAUST BOX CHROME PIPE	129.20	129.20
23	4 REAR EXHAUST MOUNTING	65.30	261.20
24	1 REAR SPARE WHEEL CARRIER	408.10	408.10
25	1 REAR END PANEL	618.95	618.95
26	1 REAR END PANEL INNER MEMBER	454.30	454.30
27	2 REAR END PANEL INNER MEMBER SIDE EXTENSION RH/LH	145.30	290.60
28	1 REAR END PANEL GARNISH	359.10	359.10
29	1 REAR FLOOR PANEL	878.00	878.00
30	1 REAR FLOOR PANEL CARDBOARD	499.50	499.50
31	2 REAR FLOOR PANEL SIDE BOARD RH/LH	262.10	524.20
32	2 REAR FENDER INNER TRIM RH/LH	693.45	1,386.90
33	2 REAR FENDER LOWER SHIELD RH/LH	110.25	220.50
34	1 REAR KEYLESS SMART	295.40	295.40
			17,244.75
		LESS 25%	4,311.19
			12,933.56

13195.81
9996.88

LBA AUTOMOTIVE PTE LTD

PARTICULAR	UNIT PRICE	AMOUNT
QTY	S\$	S\$

SPECIAL NETT ITEMS

1	1	REAR WINDSCREEN SPONGE TAPE	20.00	rec	20.00	✓
2	1	(SET) REAR WINDSCREEN SEALANT	80.00	rec	80.00	40
3	1	(SET) REAR BUMPER REVERSE SENSOR	280.00	shnd	280.00	200
4	1	(SET) REAR BUMPER CLIP	45.00	rec	45.00	✓
5	1	(SET) REAR FLOOR PANEL SOUND INSULATOR	180.00	11	180.00	X
					605.00	

LABOUR CHARGES :

1	TO KNOCK OUT DENT, CUT/WELD REAR PANEL, REAR SPARE TYRE PANEL AND REPLACE ACCIDENT PARTS	1,400.00	850
2	TO SPRAY PAINTING ON ACCIDENT PORTION	1,200.00	1000
3	TO CHECK WIRING	30.00	✓
4	TO REMOVE, REFIX REAR WINDSCREEN	120.00	✓
5	TO TRANSFER REAR TAILGATE PARTS	100.00	60
6	TO REMOVE, REFIX CUSHION AND INNER TRIM	120.00	60
7	TO REMOVE, REPLACE REVERSE SENSOR	80.00	50
8	TO REMOVE, REPLACE REAR EXHAUST BOX	120.00	80
9	TO TUFF KOTE	90.00	60
		3,260.00	

12511.88

ESTIMATE PARTS AND LABOUR GRAND TOTAL : \$ 16,798.56

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18003036MFSH

Date: 20 April 2018

Our Ref: CS/FCI18007262/Us3b

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SJW 8343T.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 19/04/2018 at the premises of M/s LBA Automotive Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ 16,798.56
Revised Estimate Amount (Lump Sum)	: S\$ 10,000.00
"Check" Items Amount	: S\$ -
Market Value	: S\$ -
LTA Reimbursement Value	: S\$ -
Nett Value	: S\$ -

Description of Damage:
The vehicle sustained damages
at the rear portion.



Repair days: 6 Days

Comments/ Present Status:
Damages Consistent.

Yours faithfully,
Marcus Chua
Automotive Assessor

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2008A
Vehicle Details	
Vehicle No.:	SJW8343T
Vehicle to be Exported:	No
Intended De-registration Date:	20 Apr 2018
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8X A
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	22R0446413
Chassis No.:	ZGE200017034
Maximum Power Output:	106.0 kW (142 bhp)
Open Market Value:	\$21,855.00
Original Registration Date:	09 Jan 2010
First Registration Date:	09 Jan 2010
Transfer Count:	1
Actual ARF Paid:	\$21,855.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	08 Jan 2020
PARF Rebate Amount:	\$12,020.00
Intended COE Rebate Details	
COE Expiry Date:	08 Jan 2020
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$19,901.00
COE Rebate Amount:	\$3,351.00
Total Rebate Amount:	\$15,371.00

The information contained herein is correct as at 20 Apr 2018

OK

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2008A
Vehicle Details	
Vehicle No.:	SJW8343T
Vehicle to be Exported:	No
Intended De-registration Date:	19 Apr 2018
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8X A
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	2ZR0446413
Chassis No.:	ZGE200017034
Maximum Power Output:	106.0 kW (142 bhp)
Open Market Value:	\$21,855.00
Original Registration Date:	09 Jan 2010
First Registration Date:	09 Jan 2010
Transfer Count:	1
Actual ARF Paid:	\$21,855.00 10927
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	08 Jan 2020
PARF Rebate Amount:	\$12,020.00
Intended COE Rebate Details	
COE Expiry Date:	08 Jan 2020
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$19,901.00
COE Rebate Amount:	\$3,356.00
Total Rebate Amount:	\$15,376.00

The information contained herein is correct as at 19 Apr 2018

OK



Experience our new showroom at 2 Pandan Crescent Inchcape Center

**LOW INTEREST @ 2.08%
MULTI-BRANDS AVAILABLE**

\$3,000* off TOYOTA
All Toyota Certified
Pre-Owned Altis
Preferred
Certified Pre-Owned

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

New 5 Years Coe Renewal Toyota Altis 1.6A



\$2800 Downpayment Monthly
From \$688 Onwards. Lowest
3.68%P.A.@GV Cars Financing.
GV Credit Pte Ltd StarAd



Browse by Category ▼

10 vehicles

Toyota Wish

Sort b

Advanc

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mile
Search Selection	Toyota Wish		Any	Any	2010	Any	
	Toyota Wish	1.8A X	\$41,800	\$12,840 /yr	08-Sep-2010	1,797 cc	
Posted: 19-Apr-2018 Tags: 2010 Toyota Wish, Toyota Wish, Toyota, Wish, Used Toyota							
	Toyota Wish	2.0A	\$34,700	\$12,500 /yr	12-Mar-2010	1,987 cc	93
Elegant And Stunning Black Unit! Only 1 Owner With Low Mileage Done! Very Well Maintained By Meticulous Owner! Buy A Company With 30 Years Of Excellent History! Call Now For ...							
Posted: 18-Apr-2018 Tags: 2010 Toyota Wish, Toyota Wish, Toyota, Wish, Used Toyota							
	Toyota Wish	2.0A	\$30,900	\$11,440 /yr	15-Jan-2010	1,987 cc	12
PROMOTIONAL 1.99% INTEREST RATE! Beautiful Red Toyota Wish Agent Unit. 142BHP All Rounded Disc Brakes Fog Lamps Family Man, Flawless Original Paint In Perfect Showroom Condition,...							
Mayfair Motoring							
Posted: 18-Apr-2018 Tags: 2010 Toyota Wish, Toyota Wish, Toyota, Wish, Used Toyota							
	Toyota Wish	2.0A	\$33,800	\$13,000 /yr	20-Jan-2010	1,987 cc	10
Buy This Agent Unit To Enjoy The Added Borneo Motors Premium Servicing By The Owner, Original Aircon Set Replaced, Maintained By Owner, Bank/In House Loan Available. Consignment C...							
Car Search							
Posted: 10-Apr-2018 Tags: 2010 Toyota Wish, Toyota Wish, Toyota, Wish, Used Toyota							

[Car Buying](#)
[Car Selling](#)
[Car Ownership](#)
[Car Aftermarket](#)
[On The Move](#)
[Lifestyle](#)


Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 20 April 2018 1:22 PM
To: KARENTAN@MSFIRSTCAPITAL.COM.SG; 'Claim Workflow System'
Cc: 'SUR'; 'Catherine Chong (LKK Auto)'; ASSIGNMENTS@LKKAUTO.COM
Subject: RE: SURVEY ASSESSMENT - D18003036MFSH/1
Attachments: SJW 8343T - Preli Advise.pdf

Dear Karen,

Enclosed herewith preliminary advice of SJW 8343T.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Catherine Chong (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Thursday, 19 April 2018 12:05 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; ASSIGNMENTS@LKKAUTO.COM
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; 'SUR' <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18003036MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Thursday, 19 April, 2018 11:30 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; KARENTAN@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18003036MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18007262/Us3be2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 26-04-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 1756X	Veh. Inspected	SJW 8343T	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18003036MFSH	Excess (\$)	0.00	
Assign From	KAREN TAN	Assign Date	19/04/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA WISH (A)	c.c	1797	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	ZGE200017034	Colour	SILVER	
Odometer	98435	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	KUMHO	6 mm	
L/H Front Tyre	195/65 R15	KUMHO	6 mm	
R/H Rear Tyre	195/65 R15	KUMHO	6 mm	
L/H Rear Tyre	195/65 R15	KUMHO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	18/04/2018	Inspection Date	19/04/2018	
Survey held at	LBA AUTOMOTIVE PTE. LTD. 1 KAKI BUKIT AVENUE 6 #02-47 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJW 8343T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	SET REAR WINDSCREEN MOULDING	NECESSARY	210.90	210.90
1	REAR TAILGATE	BADLY DENTED	1,416.40	1,416.40
2	REAR TAILGATE HINGE RH / LH @\$66.35	NOT NECESSARY	132.70	-
2	REAR TAILGATE DAMPER RH / LH @\$299.40	NOT NECESSARY	598.80	-
1	REAR TAILGATE RUBBER	TWISTED	392.10	392.10
1	REAR TAILGATE LOCK	DENTED / JAMMED	509.10	509.10
1	REAR TAILGATE LOCK CATCH	NOT NECESSARY	40.30	-
1	REAR TAILGATE INNER HANDLE	NOT NECESSARY	45.10	-
1	REAR TAILGATE INNER TRIM	DEFORMED / CRACKED	680.75	680.75
1	REAR TAILGATE EMBLEM 'LOGO'	NECESSARY	68.50	68.50
1	REAR TAILGATE EMBLEM ' VALVE MATIC '	NECESSARY	80.50	80.50
2	REAR TAILGATE REFLECTOR RH / LH @\$281.40	O/S CRACKED	562.80	281.40
2	REAR TAILLAMP RH / LH @\$359.40	CRACKED	718.80	718.80
1	REAR BUMPER	DISTORTED	821.65	821.65
2	REAR BUMPER REFLECTOR RH / LH @\$68.55	NOT NECESSARY	137.10	-
2	REAR BUMPER HOLDER RH / LH @\$65.30	BENT	130.60	130.60
2	REAR BUMPER BRACKET RH / LH @\$85.50	BENT	171.00	171.00
2	REAR BUMPER SIDE RETAINER RH / LH @\$68.85	BENT	137.70	137.70
1	CENTRE EXHAUST PIPE	BENT / TWISTED	2,943.50	2,611.30
1	REAR EXHAUST BOX	BENT / TWISTED	794.40	794.40
1	REAR EXHAUST BOX HEAT SHIELD	BENT	326.10	195.30
1	REAR EXHAUST BOX CHROME PIPE	DENTED	129.20	60.00
4	REAR EXHAUST MOUNTING @\$65.30	NECESSARY - 2PCS ONLY	261.20	130.60
1	REAR SPARE WHEEL CARRIER	JAMMED	408.10	408.10
1	REAR END PANEL	BADLY DENTED	618.95	618.95
1	REAR END PANEL INNER MEMBER	BADLY DENTED	454.30	454.30
2	REAR END PANEL INNER MEMBER SIDE EXTENSION RH / LH @\$145.30	TO REPAIR SEE LABOUR	290.60	-
1	REAR END PANEL GARNISH	TWISTED	359.10	359.10

Report Ref No. CS/FC118007262/Us3be2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	878.00	-
1	REAR FLOOR PANEL CARDBOARD	NOT NECESSARY	499.50	-
2	REAR FLOOR PANEL SIDE BOARD RH / LH @\$262.10	O/S DENTED	524.20	262.10
2	REAR FENDER INNER TRIM RH / LH @\$693.45	CRACKED	1,386.90	1,386.90
2	REAR FENDER LOWER SHIELD RH / LH @\$110.25	NOT NECESSARY	220.50	-
1	REAR KEYLESS SMART	CRACKED	295.40	295.40
	LESS 25% DISCOUNT		-4,311.19	-3,298.96
			12,933.56	9,896.89
	<u>SPECIAL NETT ITEMS</u>			
1	REAR WINDSCREEN SPONGE TAPE (SN)	NECESSARY	20.00	20.00
1	SET REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	45.00	45.00
1	SET REAR FLOOR PANEL SOUND INSULATOR (SN)	NOT NECESSARY	180.00	-
			605.00	305.00
	<u>LABOUR</u>			
	TO KNOCK OUT DENT, CUT / WELD REAR PANEL, REAR SPARE TYRE PANEL AND REPLACE ACCIDENT PARTS. INCLUSIVE OF THE REPAIR OF REAR END PANEL INNER MEMBER SIDE EXTENSION RH / LH AND REAR FLOOR PANEL.		1,400.00	850.00
	TO SPRAY PAINTING ON ACCIDENT PORTION.		1,200.00	1,000.00
	TO CHECK WIRING.		30.00	30.00
	TO REMOVE, REFIX REAR WINDSCREEN.		120.00	120.00
	TO TRANSFER REAR TAILGATE PARTS.		100.00	60.00
	TO REMOVE, REFIX CUSHION AND INNER TRIM.		120.00	60.00
	TO REMOVE, REPLACE REVERSE SENSOR.		80.00	50.00
	TO REMOVE, REPLACE REAR EXHAUST BOX.		120.00	80.00
	TO TUFF KOTE.		90.00	60.00
			3,260.00	2,310.00
	GRAND TOTAL		16,798.56	12,511.89

Report Ref No. CS/FCI18007262/Us3be2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			10,000.00
---	--	--	-----------

Report Ref No. CS/FCI18007262/Us3be2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.