

ASS. REC. BY:

REF:

CS/CTU8007271 / Rlgbez

Special Instruction:

Surveyor
Muhmen

Rgsl

ASSIGNMENT (Office)

From (Person):

Chong Boun San

of

CTU

Date/Time:

19042018 121pm

Estimated Cost:

Bill to:

OD / U / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLE 64666

Insured:

GBE 19316

at Workshop m/s

Vermogen

Tel:

6904 4596

of

6 Bannoi Sactur

Policy No:

DMCVSN1659871701

Claim No:

SNM18D0950CM

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

14042018

CA / REV / REP. / REV 24 HRS Op

H.O.D. Endorsement:

Date/Time:

19042018 122pm

Person Contacted:

Paulo

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SLE 64666 - NA / INC16019001/r3

OIA: 06/04/16

GBE 19316 - X.

24/4/1803 05am confirmed with Baldoz Paulo is \$3900, 5 days.
(Red B 17061.76, 81%)

Signature: *P. Ram*

REF:

4597K

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SLE 6466G
at Workshop m/s: Vernohon
of: 6, Bannu Sector
Insured: CTI/UP
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res: Yes or No

Lump Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLE 6466G Yr Regn: 2016 / July
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or

Make: Honda Vezel 1.5X c.c. 1496

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 08 7297 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: Ru 31208839

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / SRim / STD A/Rim or

Tyre Size: F: 215/60 R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Road Stone

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm


L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 14/04/18 D.O.I. 19/04/18

Survey held at Vernohon

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.



Date / Time Action / Instruction

RECEIVED 26 SEP 2018

Date/Time: File Pass to?

06/09/2018

Date/Time: File Return to?

2)

☐ : Preli. Report

☐ : Final Report

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

1 S + RS SI

1 Photos

1 Others

TOTAL

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)

Report Format: HER-TP

Lump Sum / I.B.A. (\$)

3900

220

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Apr 2018		19 Apr 2018 13:21 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	M/S SAI SIA (PAINTS) CO		
Main Claimant:	LCRF PTE LTD, Co. Reg. No.: 201624597K		
Vehicle Reg. No.:	SLE6466G	Date of Loss:	14/04/2018 15:00 - :59
Claim Type:	TP / SNM18D01950C02	Policy/Cover Note No.:	DMCVSN1659871701
Vehicle Reg. No. (Insured):	GBE1931G	Policy No. (Claimant):	
		Excess:	\$50.00
Repairer:	Vermogen Ace Pte Ltd - Kaki Bukit (HQ) 8 KAKI BUKIT AVE 4, 415875 Kaki Bukit - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 30/04/2018]		
Adj Asg. Remarks:	DEAR MARCUS, PLEASE CONDUCT SURVEY, CHECK CONSISTENCY OF THE DAMAGES ON WITHOUT PREJUDICE BASIS. KINDLY LET US HAVE YOUR RECOMMENDED REPAIR AMOUNT IF THERE IS NO ESTIMATE PROVIDED DURING PRE REPAIR.		

ASSOCIATED MAIL RECEIVED View All Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Catherine Chong (LKK Auto)

From: Angie Foo <angie.foo@sg.cntaiping.com>
Sent: Thursday, 19 April, 2018 1:09 PM
To: Minoko
Cc: 'vmg.vermogenace'; vmg@vermogen-group.com; pila.vermogenace@gmail.com; 'ezel tejano'; 'juan paulo baldoz'; 'Edmond Lim jian zhi'; assignments@lkkauto.com; SUR; Admin A
Subject: RE: OUR REF: PRS/SNM18D01950C02/2 & YR REF: SLE6466G -TO CONDUCT PRE REPAIR SURVEY -SLE6466G

Without Prejudice

Dear Minoko,

We refer to your email on even date.

We have appointed Marcus Chua of M/S LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Please ensure that your client's vehicle is available for survey within 2 working days.

REMARKS:

Dear Marcus,

Please arrange to conduct survey, checking consistency of the damages on without prejudice.

Kindly take note, the claim handler on this case is Adeline Chng 6389 6155.

Thank you.

Regards,
Angie Foo
Executive
Motor Division
Claims Department
China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road #16-00
Springleaf Tower
Singapore 079909
Co.Reg.No.200208384E
DID: 6389 6186
Fax: 6224 7478 /6224 7175
Email: angie.foo@sg.cntaiping.com
Email: claimsdept@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer:

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Minoko [mailto:minokovermogenace@gmail.com]

Sent: Thursday, 19 April, 2018 11:42 AM

To: Angie Foo

Cc: 'vmg.vermogenace'; vmg@vermogen-group.com; pila.vermogenace@gmail.com; 'ezel tejano'; 'juan paulo baldoz'; 'Edmond Lim Jian zhi'

Subject: RE: OUR REF: PRS/SNM18D01950C02/2 & YR REF: SLE6466G -TO CONDUCT PRE REPAIR SURVEY -SLE6466G

Hi Angie,

We would like choose MARCUS CHUA to survey by today.

Thank you

Best Regards,

Minoko

Vermogen Ace Pte Ltd

1 Bukit Batok Crescent

#05-23 Weega Plaza

Singapore 658064

Tel: 6904 4596

Fax: 6694 4929

From: Angie Foo <angie.foo@sg.cntaiping.com>

Sent: Wednesday, April 18, 2018 10:49 AM

To: 'Minoko' <minokovermogenace@gmail.com>; 'vmg.vermogenace' <vmg.vermogenace@gmail.com>

Subject: FW: OUR REF: PRS/SNM18D01950C02/2 & YR REF: SLE6466G -TO CONDUCT PRE REPAIR SURVEY -SLE6466G

WITHOUT PREJUDICE

Gentle Reminder

Dear Minoko,

We refer to our email of 16th April 2018 pertaining to the above matter.

Kindly let us hear from you.

Thank you

Regards,

Angie Foo

Executive

Motor Division

Claims Department

China Taiping Insurance (Singapore) Pte Ltd

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

Co.Reg.No.200208384E

DID: 6389 6186

Fax: 6224 7478 /6224 7175

Email: angie.foo@sg.cntaiping.com

Email: claimsdept@sg.cntaiping.com

Website: www.sg.cntaiping.com

From: Angie Foo

Sent: Monday, 16 April, 2018 5:26 PM

To: 'Minoko'; 'vermogenace@gmail.com'

Cc: Sharon Han

Subject: OUR REF: PRS/SNM18D01950C02/2 & YR REF: SLE6466G -TO CONDUCT PRE REPAIR SURVEY -SLE6466G

WITHOUT PREJUDICE

Dear Minoko,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop.

We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

TAY BENG HEE
SAMUEL PHUN
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
DEREK OH SIONG WEE
KALVIN ANG
MARCUS CHUA
SIMON HO
LOW SAR HUEI
HONG FOOK CHOY

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Kindly let us hear from you.

REMARKS:

Kindly take note, the claim handler on this case is Adeline Chng 6389 6155.

Thank you.

Regards,
Angie Foo
Executive
Motor Division
Claims Department
China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road #16-00
Springleaf Tower
Singapore 079909
Co.Reg.No.200208384E
DID: 6389 6186
Fax: 6224 7478 /6224 7175
Email: angie.foo@sg.cntaiping.com

Email: claimsdept@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer:

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Angie Foo
Sent: Monday, 16 April, 2018 5:17 PM
To: 'Minoko'; 'vmg.vermogenace'
Cc: Sharon Han
Subject: FW: CN TAIPING: PLEASE ARRANGE TP SURVEY FOR (OUR REF:SLE6466G) YR REF:GBE1931G
DOA:14/04/2018

WITHOUT PREJUDICE

Dear Minoko,

We refer to your email on even date.

Please advised your date of accident due to your attachment date of accident dated on 06.10.2016

Kindly let us hear from you soonest possible.

Thank you.

Regards,
Angie Foo
Executive
Motor Division
Claims Department
China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road #16-00
Springleaf Tower
Singapore 079909
Co.Reg.No.200208384E
DID: 6389 6186
Fax: 6224 7478 /6224 7175
Email: angie.foo@sg.cntaiping.com
Email: claimsdept@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer:

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Minoko [<mailto:minokovermogenace@gmail.com>]
Sent: Monday, 16 April, 2018 12:07 PM
To: Claims Dept of CTI
Cc: 'pila.vermogenace'; 'ezel tejano'; 'juan paulo baldoz'; edmondvermogenace@gmail.com; vmg@vermogen-group.com; vermogenace@gmail.com
Subject: CN TAIPING: PLEASE ARRANGE TP SURVEY FOR (OUR REF:SLE6466G) YR REF:GBE1931G DOA:14/04/2018

Dear Arrange survey dept

Kindly arrange TP survey on 17/04/2018 (TUESDAY) following detail & attach here GIA report:

Survey before repair

Your Vehicle: GBE1931G

Our Vehicle: SLE6466G

DOA : 14/04/2018

AOL : JALAN TOA PAYOH TOWARDS PIE

Vehicle Location: 6 BENOI SECTOR SINGAPORE 629904

Best Regards,

Minoko
Vermogen Ace Pte Ltd
1 Bukit Batok Crescent
#05-23 Wcega Plaza
Singapore 658064
Tel: 6904 4596
Fax: 6694 4929

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Shiau Chan (LKKAUTO)

From: Baldoz Juan Paulo Bongon <paulo.b@vermogen-group.com>
Sent: Monday, 24 September 2018 11:05 AM
To: Rasul (LKKAUTO)
Cc: Vmg admin; Glorioso Eric Paul Patambang; Tezano Exequiel Dawal; Minoko Chan; Pila Ng; Desmond Kor; Edmond Lim; Lina Rosli; Luis Tan; Paul Tan; Shiau Chan (LKKAUTO)
Subject: Re: SLE6466G DOA: 14/04/2018 TO FINALISE (CHINA TAIPING TP)
Attachments: image001.jpg

Dear Rasul,

We confirmed COR @ \$3,900 bcf gst (lump sum) 5 working days.

Excluded: PRS, RS, WEEKENDS, PH.

Thank you

Best Regards,

Paulo Baldoz
Vermogen Ace Pte Ltd
Operation Address:
6 Benoi Sector Singapore 629904
Tel: 6358 3031
Fax: 6694 4929

Mailing Address:
1 Bukit Batok Crescent #04-54
Wcega Plaza Singapore 658064

On Mon, Sep 24, 2018 at 10:41 AM Rasul (LKKAUTO) <Rasul@lkkauto.com> wrote:

Hi Paulo,

Finalised amount is \$ 3,900.00 / 5 days lump sum

Kindly confirm

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Baldoz Juan Paulo Bongon [<mailto:paulo.b@vermogen-group.com>]

Sent: Friday, 21 September, 2018 10:32 AM

To: Rasul (LKKAuto)

Cc: Asher Sng (LKKAuto); Admin-D (LKKAuto); Janice Lee (LKKAuto); Hsiao Tong (LKKAuto); Veron Chen (LKKAuto); SUR; Vmg admin; Glorioso Eric Paul Patambang; Tejano Exequiel Dawal; Minoko Chan; Pila Ng; Desmond Kor; Edmond Lim; Lina Rosli; Luis Tan; Paul Tan

Subject: Re: SLE6466G DOA: 14/04/2018 TO FINALISE (CHINA TAIPING TP)

Hi Rasul,

Attached check item photos.

Kindly re-finalize and revert to us asap.

Thank you

Best Regards,

Paulo Baldoz

Vermogen Ace Pte Ltd

Operation Address:

6 Benoi Sector Singapore 629904

Tel: 6358 3031

Fax: 6694 4929

Mailing Address:

1 Bukit Batok Crescent #04-54

Wcega Plaza Singapore 658064

On Fri, Aug 24, 2018 at 12:20 PM Rasul (LKKAUTO) <Rasul@lkkauto.com> wrote:

Hi Paolo,

Kindly forward the supplementary and check item damage photos

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Save the Earth. Print only when necessary.

From: Baldoz Juan Paulo Bongon [<mailto:paulo.b@vermogen-group.com>]

Sent: Thursday, 16 August, 2018 2:25 PM

To: Asher Sng (LKKAUTO); Admin-D (LKKAUTO); Janice Lee (LKKAUTO); Hsiao Tong (LKKAUTO); Veron Chen (LKKAUTO); SUR; Rasul (LKKAUTO)

Cc: Vmg admin; Glorioso Eric Paul Patambang; Tezano Exequiel Dawal; Minoko Chan; Pila Ng; Desmond Kor; Edmond Lim; Lina Rosli; Luis Tan; Paul Tan

Subject: Fwd: SLE6466G DOA: 14/04/2018 TO FINALISE (CHINA TAIPING TP)

3RD REMINDER.

Dear Officer-in-charge,

SLE6466G DOA: 14/04/2018

Kindly check & revert to us as soon as possible, to expedite the claim.

Please send us your calculation.

Thank you

Best Regards,

Paulo Baldoz

Vermogen Ace Pte Ltd

Operation Address:

6 Benoi Sector Singapore 629904

Tel: 6358 3031

Fax: 6694 4929

Mailing Address:

1 Bukit Batok Crescent #04-54

Wcega Plaza Singapore 658064

----- Forwarded message -----

From: **Baldoz Juan Paulo Bongon** <paulo.b@vermogen-group.com>

Date: Tue, Jul 10, 2018 at 4:18 PM

Subject: Fwd: SLE6466G DOA: 14/04/2018 TO FINALISE (CHINA TAIPING TP)

To: "Asher Sng (LKKAuto)" <AsherSng@lkkauto.com>, "Catherine Chong (LKK Auto)" <admin-d@lkkauto.com>, "Janice Lee (LKKAuto)" <JaniceLee@lkkauto.com>, "Hsiao Tong (LKKAuto)" <chewht@lkkauto.com>, "Veron Chen (LKKAuto)" <veronchen@lkkauto.com>, SUR <sur@lkkauto.com>, "Rasul (LKK Auto)" <Rasul@lkkauto.com>
Cc: Vmg admin <vmg@vermogen-group.com>, Glorioso Eric Paul Patambang <eric.g@vermogen-group.com>, Tezano Exequiel Dawal <ezel.t@vermogen-group.com>, Minoko Chan <minoko@vermogen-group.com>, Pila Ng <pila@vermogen-group.com>, Edmond Lim <edmond@vermogen-group.com>, Lina Rosli <linarosli@vermogen-group.com>, Luis Tan <luis@vermogen-group.com>, Paul Tan <paul@vermogen-group.com>, Desmond Kor <desmond@vermogen-group.com>

Dear Officer-in-charge,

SLE6466G DOA: 14/04/2018

Kindly check & revert to us as soon as possible, to expedite the claim.

Please send us your calculation.

Thank you

Best Regards,

Paulo Baldoz

Vermogen Ace Pte Ltd

Operation Address:

6 Benoi Sector Singapore 629904

Tel: 6358 3031

Fax: 6694 4929

Mailing Address:

1 Bukit Batok Crescent #04-54

Wcega Plaza Singapore 658064

----- Forwarded message -----

From: **Baldoz Juan Paulo Bongon** <paulo.b@vermogen-group.com>

Date: Wed, May 2, 2018 at 5:16 PM

Subject: SLE6466G DOA: 14/04/2018 TO FINALISE (CHINA TAIPING TP)

To: "Asher Sng (LKKAuto)" <AsherSng@lkkauto.com>, "Vic (LKKAuto)" <vicalpeh@lkkauto.com>, guoqiang@lkkauto.com, "Ai Phing (LKKAuto)" <aiphing@lkkauto.com>, "Shiau Chan (LKKAuto)" <siewsc@lkkauto.com>, "Taufikh (LKK Auto)" <taufikh@lkkauto.com>, "Rasul (LKK Auto)" <Rasul@lkkauto.com>

Cc: Vmg admin <vmg@vermogen-group.com>, Glorioso Eric Paul Patambang <eric.g@vermogen-group.com>, Tejano Exequiel Dawal <ezel.t@vermogen-group.com>, Minoko Chan <minoko@vermogen-group.com>, Pila Ng <pila@vermogen-group.com>, Edmond Lim <edmond@vermogen-group.com>, Lina Rosli <linarosli@vermogen-group.com>, Luis Tan <luis@vermogen-group.com>, Paul Tan <paul@vermogen-group.com>

Dear Jason,

Please check and confirm finalise COR @ \$4,100 bef gst (lump sum) 5 working days.

Excluded: PRS, RS, WEEKENDS, PH.

Thank you

Best Regards,

Paulo Baldoz

Vermogen Ace Pte Ltd

Operation Address:

6 Benoi Sector Singapore 629904

Tel: 6358 3031

Fax: 6694 4929

Mailing Address:

1 Bukit Batok Crescent #04-54

Wcega Plaza Singapore 658064

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/04/2018 10:56
Date Of Accident	14/04/2018 15:50
Exact Location Of Accident	JALAN TOA PAYOH TOWARDS PIE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLE6466G
Insured/Policyholder	
Name Of Registered Owner	LCRF PTE LTD
Co Reg No	201624597K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-66944919

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL
Exact Purpose for which vehicle was being used at time of accident	HIRER
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995060
Cover Note Number	

Driver

Name of Driver	LEE SEOW KWAN
NRIC No	S6920868A
Date Of Birth	18/06/1969
Occupation	OUTDOOR
Date Of Driving Pass	04/09/2009
Driving Experience	8 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90106639
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	44 BENOI ROAD BLOCK B (ENTTRANCE B) ENTRANCE 6 BENOI SECTOR
Postcode	629904
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	LIGHT RAIN
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BUKIT BATOK NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 21 BUKIT BATOK EAST AVE 4 , POSTCODE: 659840 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-6659999 - FAX NO: 66655793
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER ATTACHED. THANK YOU.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBE1931G
Vehicle Make/Model/Colour	
Details Of Properties	VEH. B
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

LEE SEOW KWAN

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SLE6468G

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

Accident Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to rescind policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NIC/PIN No.:

SKETCH PLAN

- (A) SLE6466 G
- (B) GBE1931 G



Talau Toa Bayoh towards PIE

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

As per police report number
T/20186415/2030

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: LINAROSLI
NRIC/ID No.:



**SINGAPORE
POLICE FORCE**



T/20180415/2030

Police Station Of Origin:
Bukit Batok N.P.C
21 Bukit Batok East Avenue 4 SINGAPORE
659840
Tel No: 1800-6659999

1 of 4

Report No. T/20180415/2030

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 15/04/2018 11:15	Vide Report No.:	Station Diary No.: 29
--	------------------	--------------------------

Informant's Particulars

Name of Informant: LEE SEOW KWAN		Address: APT BLK 288E BUKIT BATOK STREET 25 #05-70 SINGAPORE 654288	
ID Type / ID No.: NRIC NO / S6920868A		Contact No.: Home/Office: Mobile	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 48	Date of Birth: 18/06/1969	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation: PRIVATE HIRER		Driving Licence Information: Class: 3	Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 14/04/2018 15:50	Type of Location: Straight Road
Location: Along Road 1 Traveling Toward Road 2 PAN-ISLAND EXPRESSWAY (JALAN TOA PAYOH) PAN ISLAND EXPRESSWAY Along Jalan Toa Payoh towards PIE				
Weather: Heavy rain		Road Surface: Wet	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBE1931G	Bus/Coach/Minibus				Slightly Damaged	0
SLE6466G	Car				Slightly Damaged	1

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20180415/2030

Police Station Of Origin:
Bukit Batok N.P.C
21 Bukit Batok East Avenue 4 SINGAPORE
659840
Tel No: 1800-6659999

2 of 4

Report No. T/20180415/2030

CONTINUATION OF REPORT

Driver			
Name	KOK WING KEE	ID No.	S1179389H
Related Vehicle	GBE1931G (Bus/Coach/Minibus)	Contact No.	
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	LEE SEOW KWAN	ID No.	S6920868A
Related Vehicle	SLE6466G (Car)	Contact No.	
Hospital/Clinic	LIFELINE MEDICAL GROUP	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	15/04/2018	Date Discharge	15/04/2018
No. of Days granted Medical Leave	03	Degree of Injury	Slight
Passenger			
Name	YUMIKA	ID No.	NIL
Related Vehicle	SLE6466G (Car)	Contact No.	
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 14/04/2018 at about 1550hrs, I was driving V1) SLE6466G along the 2 lane Jalan Toa Payoh, I was on the left lane. There was a public bus that was exiting the bus bay and thus I slowed down my vehicle to a complete stop. Some time passed when suddenly I felt an impact coming from the rear. I came out from V1 and made a check on V1 and found the rear door of V1 to have a large dent. The vehicle that had hit onto V1, V2) GBE1931G suffered a small dent in on the right portion of the front body. At that point in time, I felt pain on my shoulders and back. I had one passenger who sat in the rear seat and I asked her if she was injured however she said that she was not.



**SINGAPORE
POLICE FORCE**



T/20180415/2030

Police Station Of Origin:
Bukit Batok N.P.C
21 Bukit Batok East Avenue 4 SINGAPORE
659840
Tel No: 1800-6659999

3 of 4

Report No. T/20180415/2030

CONTINUATION OF REPORT



**SINGAPORE
POLICE FORCE**



T/20180415/2030

Police Station Of Origin:
Bukit Batok N.P.C
21 Bukit Batok East Avenue 4 SINGAPORE
659840
Tel No: 1800-8659999

4 of 4

Report No. T/20180415/2030

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:
J /
Sgt 3 MUHAMMAD NURSYAZWAN BIN RASIDI

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / AEIT /
Staff Sgt WONG SIEU LUI
Contact No: 65478151

Authentication Stamp
NP168

Signature Of Informant:

Date/Time:
15/04/2018 11:15

Classification Of Case:

IC AND LICENSE





SLE6466G

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6904 4596 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : CHINA TAIPING
OWN INSURER : AIG
CLAIM TYPE : TP
Date of Accident : 14/04/2018

Vehicle Reg. No. : SLE6466G
Vehicle Reg. Date: 28/07/2016
Make / Model : VEZEL 1.5X HYBRID
Engine No. : LEB5908852
Chassis No. : RU31208839

COST OF CLAIMS

Parts Cost / List Items : \$ 17,039.70
Plus/Less 20% \$ 3,407.94
Total Cost / List : \$ 13,631.76
Special Nett Items : \$ 910.00
Total Parts Amount : \$ 14,541.76
Total Labour Amount : \$ 6,420.00
Gross Total : \$ 20,961.76
GST % : 7% \$ 1,467.32
Nett Amount : \$ 22,429.08

Surveyor Name and Company :

RASUL CLKK7
Date of survey : 19/04/18 @ 1655
Part by Part Lump Sum 5 days
Resurvey Before Paint / After Paint
Authorize/Not Authorize/Without Prejudice
Email : rasul@kkauto.com
Fax No : _____
HP No : 90010068

This claim is handled by : MINOKO

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6904 4596 | Fax No : 6694 4929

Vehicle Reg. No. : **SLE6466G**

Vehicle Reg. Date: **28/07/2016**

Make / Model : **VEZEL 1.5X HYBRID**

Engine No. : **LEB5908852**

Chassis No. : **RU31208839**

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Tailgate	BT	\$ 1,620.00		
2	1	Tailgate outer garnish	X Svc	\$ 285.00		
3	1set	Tailgate outer garnish clips	X new M	\$ 40.00		
4	1	Tailgate logo	new	\$ 52.00		
5	1	Tailgate emblem 'VEZEL'	new	\$ 56.20		
6	1	Tailgate lamp LH	X	\$ 490.00		
7	1	Tailgate lamp RH	X	\$ 490.00		
8	2set	Tailgate lamp clips	X	\$ 50.00		
9	1	Tailgate outer handle switch	X	\$ 180.00		
10	1	Tailgate reverse camera	X M	\$ 600.00		
11	1	Tailgate damper LH	X	\$ 212.00		
12	1	Tailgate damper RH	X	\$ 212.00		
13	1	Tailgate inner handle	X	\$ 74.00		
14	1	Tailgate inner lock	BT	\$ 245.00		
15	1	Tailgate lock sensor (antenna)	? new CDA	\$ 220.00		
16	1	Tailgate striker	BT	\$ 32.00		
17	1	Tailgate trimboard	? CDA	\$ 295.00		
18	1set	Tailgate trimboard clips	new	\$ 45.00		
19	1	Tailgate weatherstrip	cut	\$ 145.00		
20	1set	Tailgate windscreen moulding	new	\$ 164.00		
21	1	Rear bumper	DE	\$ 885.00		
22	1set	Rear bumper clips	new	\$ 50.00		
23	1	Rear bumper retainer LH	X	\$ 72.00		
24	1	Rear bumper retainer RH	X	\$ 72.00		
25	1	Rear bumper bracket LH	X	\$ 116.00		
26	1	Rear bumper bracket RH	X	\$ 116.00		
27	1	Rear bumper reflector LH	X	\$ 167.00		
28	1	Rear bumper reflector RH	X M	\$ 167.00		
29	1	Rear bumper cover LH	X	\$ 210.00		
30	1	Rear bumper cover RH	X	\$ 210.00		
31	1set	Rear bumper cover clips	X	\$ 50.00		
32	1	Rear bumper cover retainer LH	X	\$ 42.00		
33	1	Rear bumper cover retainer RH	X	\$ 42.00		
34	1	Rear end panel outer	R	\$ 585.00		
35	1	Rear end panel inner	X CDA	\$ 396.00		
36	1	Rear end panel top garnish	DE	\$ 184.00		
37	1set	Rear end panel top garnish clips	new	\$ 25.00		
38	1	Spare tyre panel	X Svc	\$ 1,230.00		
39	1	Spare tyre panel tool insulator	? new CDA	\$ 240.00		
40	1	Spare tyre panel top board	X Svc	\$ 420.00		

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6904 4596 | Fax No : 6694 4929

Vehicle Reg. No.: **SLE6466G**

Vehicle Reg. Date: **28/07/2016**

Make / Model: **VEZEL 1.5X HYBRID**

Engine No.: **LEB5908852**

Chassis No.: **RU31208839**

PAGE 2

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	1	Tail lamp LH	X	\$ 489.00		
42	1	Tail lamp RH	X	\$ 489.00		
43	2sets	Tail lamp clips	X	\$ 36.00		
44	1	Exhaust muffler	X	\$ 855.00		
45	1set	Exhaust muffler mounting	X	\$ 79.50		
46	1	Exhaust muffler heat shield	X	\$ 165.00		
47	2	Rear fender	X	\$ 1,900.00		
48	2	Rear fender arch garnish	X	\$ 230.00		
49	2	Rear fender arch garnish clips	X	\$ 100.00		
50	2	Rear fender inner water shield	X	\$ 320.00		
51	2	Rear fender inner water shield clips	X	\$ 160.00		
52	2	Rear fender inner lower trim board	X	\$ 730.00		
53	2	Rear fender inner trim board clips	X	\$ 160.00		
54	2	Rear fender inner upper trim board	X	\$ 320.00		
55	2	Rear fender inner upper trim board clips	X	\$ 60.00		
56	2	Rear fender mudflap	X	\$ 160.00		
57	1	Reverse sensor	X	\$ 300.00		200 X 50
58	1	Rear end panel sealant	X	\$ 80.00		
59	1	Spare tyre panel sealant	X	\$ 80.00		
60	1	Tail lamp sealant	X	\$ 80.00		
61	2	Tail lamp pad LH/RH	X	\$ 80.00		
62	1	Tailgate sealant	NE	\$ 80.00		60
63	1	Tail gate windscreen sealant	NE	\$ 80.00		60
64	1	Tail gate windscreen inner seal	NE	\$ 80.00		60
65	1	Rear number plate with case	X	\$ 50.00		
66	0	0				
67	0	0				
68	0	0				
69	0	0				
70	0	0				
71	0	0				
72	0	0				
73	0	0				
74	0	0				
75	0	0				
76	0	0				
77	0	0				
78	0	0				
79	0	0				
80	0	0				

Tel : 6904 4596 | Fax No : 6694 4929

Chassis No. : RU31208839

Estimates on Labour

[illegible]



SLE6466G

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6904 4596 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : CHINA TAIPING
OWN INSURER : AIG
CLAIM TYPE : TP
Date of Accident : 14/04/2018

Vehicle Reg. No. : SLE6466G
Vehicle Reg. Date: 28/07/2016
Make / Model : VEZEL 1.5X HYBRID
Engine No. : LEB5908852
Chassis No. : RU31208839

COST OF CLAIMS

Parts Cost / List Items :	\$	17,039.70
Plus/Less 20%	\$	3,407.94
Total Cost / List :	\$	13,631.76
Special Nett Items :	\$	910.00
Total Parts Amount :	\$	14,541.76
Total Labour Amount :	\$	6,420.00
Gross Total :	\$	20,961.76
GST % : 7%	\$	1,467.32
Nett Amount :	\$	22,429.08

Surveyor Name and Company :

RASUL CLKK
Date of survey : 19/04/18 @ 1655
Part by Part Lump Sum 5 days
Resurvey Before Paint / After Paint
Authorize/Not Authorize/Without Prejudice
Email : rasul@kkantb.com
Fax No : _____
HP No : 90010068

This claim is handled by : MINOKO

P = 4408.20
- 20%
3526.56
SM = 140
L = 1500
5166.56
- 20%
4133.25

145 = 4100

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6904 4596 | Fax No : 6694 4929

Vehicle Reg. No. : **SLE6466G**

Vehicle Reg. Date: **28/07/2016**

Make / Model : **VEZEL 1.5X HYBRID**

Engine No. : **LEB5908852**

Chassis No. : **RU31208839**

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Tailgate	OK /	\$ 1,620.00	1250	
2	1	Tailgate outer garnish	X	\$ 285.00		
3	1set	Tailgate outer garnish clips	X new	\$ 40.00	1204	
4	1	Tailgate logo	new /	\$ 52.00		
5	1	Tailgate emblem 'VEZEL'	new /	\$ 56.20		
6	1	Tailgate lamp LH	X	\$ 490.00		
7	1	Tailgate lamp RH	X	\$ 490.00		
8	2set	Tailgate lamp clips	X	\$ 50.00		
9	1	Tailgate outer handle switch	X	\$ 180.00		
10	1	Tailgate reverse camera	X	\$ 600.00		
11	1	Tailgate damper LH	X	\$ 212.00		
12	1	Tailgate damper RH	X	\$ 212.00		
13	1	Tailgate inner handle	X	\$ 74.00		
14	1	Tailgate inner lock	OK /	\$ 245.00		
15	1	Tailgate lock sensor (Carferra)	? OK new	\$ 220.00		
16	1	Tailgate striker	OK /	\$ 32.00		
17	1	Tailgate trimboard	? OK new	\$ 295.00		
18	1set	Tailgate trimboard clips	new /	\$ 45.00		
19	1	Tailgate weatherstrip	cut /	\$ 145.00		
20	1set	Tailgate windscreen moulding	new /	\$ 164.00		
21	1	Rear bumper	DE /	\$ 885.00		
22	1set	Rear bumper clips	new /	\$ 50.00		
23	1	Rear bumper retainer LH	X	\$ 72.00		
24	1	Rear bumper retainer RH	X	\$ 72.00		
25	1	Rear bumper bracket LH	X	\$ 116.00		
26	1	Rear bumper bracket RH	X	\$ 116.00		
27	1	Rear bumper reflector LH	X	\$ 167.00		
28	1	Rear bumper reflector RH	X	\$ 167.00		
29	1	Rear bumper cover LH	X	\$ 210.00		
30	1	Rear bumper cover RH	X	\$ 210.00		
31	1set	Rear bumper cover clips	X	\$ 50.00		
32	1	Rear bumper cover retainer LH	X	\$ 42.00		
33	1	Rear bumper cover retainer RH	X	\$ 42.00		
34	1	Rear end panel outer	R	\$ 585.00		
35	1	Rear end panel inner	X	\$ 396.00		
36	1	Rear end panel top garnish	DE /	\$ 184.00		
37	1set	Rear end panel top garnish clips	new /	\$ 25.00		
38	1	Spare tyre panel	X	\$ 1,230.00		
39	1	Spare tyre panel tool insulator	? OK new	\$ 240.00		
40	1	Spare tyre panel top board	X	\$ 420.00		

* TAIL GATE BUZZER

\$150 ~~new~~ /

P=4408.20

4038.20

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6904 4596 | Fax No : 6694 4929

Vehicle Reg. No. : **SLE6466G**

Vehicle Reg. Date: **28/07/2016**

Make / Model : **VEZEL 1.5X HYBRID**

Engine No. : **LEB5908852**

Chassis No. : **RU31208839**

PAGE 2

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	1	Tail lamp LH	X	\$ 489.00		
42	1	Tail lamp RH	X	\$ 489.00		
43	2sets	Tail lamp clips	X	\$ 36.00		
44	1	Exhaust muffler	X	\$ 855.00		
45	1set	Exhaust muffler mounting	X	\$ 79.50		
46	1	Exhaust muffler heat shield	X	\$ 165.00		
47	2	Rear fender	X	\$ 1,900.00		
48	2	Rear fender arch garnish	X	\$ 230.00		
49	2	Rear fender arch garnish clips	X	\$ 100.00		
50	2	Rear fender inner water shield	X	\$ 320.00		
51	2	Rear fender inner water shield clips	X	\$ 160.00		
52	2	Rear fender inner lower trim board	X	\$ 730.00		
53	2	Rear fender inner trim board clips	X	\$ 160.00		
54	2	Rear fender inner upper trim board	X	\$ 320.00		
55	2	Rear fender inner upper trim board clips	X	\$ 60.00		
56	2	Rear fender mudflap	X	\$ 160.00		
57	1	Reverse sensor	X	\$ 300.00		200 X
58	1	Rear end panel sealant	X	\$ 80.00		
59	1	Spare tyre panel sealant	X	\$ 80.00		
60	1	Tail lamp sealant	X	\$ 80.00		
61	2	Tail lamp pad LH/RH	X	\$ 80.00		
62	1	Tailgate sealant	new /	\$ 80.00		60
63	1	Tail gate windscreen sealant	new /	\$ 80.00		60
64	1	Tail gate windscreen inner seal	new /	\$ 80.00		60
65	1	Rear number plate with case	X	\$ 50.00		
66	0	0				
67	0	0				
68	0	0				
69	0	0				
70	0	0				
71	0	0				
72	0	0				
73	0	0				
74	0	0				
75	0	0				
76	0	0				
77	0	0				
78	0	0				
79	0	0				
80	0	0				

SN = 140

Tel : 6904 4596 | Fax No : 6694 4929

PAGE 1

[illegible]

4038.20
20%
3230.56
140.00
1500.00

4870.56
20%
3896.44
L/S - 3,900 5 days

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Apr 2018		19 Apr 2018 13:21 Edit Adj Rpt	S\$3,900.00 Edit Estimates	S\$3,900.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	M/S SAI SIA (PAINTS) CO. Co. Reg. No.: -								
Main Claimant:	LCRF PTE LTD, Co. Reg. No.: 201624597K								
Vehicle Reg. No.:	SLE6466G	Date of Loss:	14/04/2018 15:00 - :59 [20 Months and 17 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D01950C02	Policy/Cover Note No.:	DMCVSN1659871701						
Vehicle Reg. No. (Insured):	GBE1931G	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Vermogen Ace Pte Ltd - Kaki Bukit (HQ) 8 KAKI BUKIT AVE 4, 415875 Kaki Bukit - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 30/04/2018]								
Adj Asg. Remarks:	DEAR MARCUS,PLEASE CONDUCT SURVEY, CHECK CONSISTENCY OF THE DAMAGES ON WITHOUT PREJUDICE BASIS. KINDLY LET US HAVE YOUR RECOMMENDED REPAIR AMOUNT IF THERE IS NO ESTIMATE PROVIDED DURING PRE REPAIR.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLE6466G (SNM18D01950C02)
[GBE1931G]
TP
LCRF PTE LTD
Apr 14 2018 3:00PM
[M/S SAI SIA (PAINTS) CO]
Vermogen Ace Pte Ltd - Kaki Bukit

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images							3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail			Print			
1	26/09/18 15:12	Odometer Reading			Load JPG		☒			
2	26/09/18 15:12	Chassis Number			Load JPG		☒			
3	26/09/18 15:12	General View			Load JPG		☒			
4	26/09/18 15:12	General View			Load JPG		☒			
5	26/09/18 15:12	General View			Load JPG		☒			
6	26/09/18 15:12	General View			Load JPG		☒			
7	26/09/18 15:12	General View			Load JPG		☒			
8	26/09/18 15:12	General View			Load JPG		☒			
9	26/09/18 15:12	General View			Load JPG		☒			
10	26/09/18 15:12	General View			Load JPG		☒			
11	26/09/18 15:12	General View			Load JPG		☒			
12	26/09/18 15:12	General View			Load JPG		☒			
13	26/09/18 15:12	General View			Load JPG		☒			
14	26/09/18 15:12	General View			Load JPG		☒			
15	26/09/18 15:12	General View			Load JPG		☒			
16	26/09/18 15:12	General View			Load JPG		☒			
17	26/09/18 15:12	General View			Load JPG		☒			
18	26/09/18 15:12	General View			Load JPG		☒			
19	26/09/18 15:12	General View			Load JPG		☒			
20	26/09/18 15:12	General View			Load JPG		☒			
21	26/09/18 15:12	General View			Load JPG		☒			
22	26/09/18 15:12	General View			Load JPG		☒			
23	26/09/18 15:12	General View			Load JPG		☒			
24	26/09/18 15:12	General View			Load JPG		☒			
25	26/09/18 15:12	General View			Load JPG		☒			
26	26/09/18 15:12	General View			Load JPG		☒			
27	26/09/18 15:12	General View			Load JPG		☒			
28	26/09/18 15:12	General View			Load JPG		☒			
29	26/09/18 15:12	General View			Load JPG		☒			
30	26/09/18 15:12	General View			Load JPG		☒			
31	26/09/18 15:12	General View			Load JPG		☒			
32	26/09/18 15:12	General View			Load JPG		☒			
33	26/09/18 15:12	General View			Load JPG		☒			
34	26/09/18 15:12	General View			Load JPG		☒			
35	26/09/18 15:12	General View			Load JPG		☒			
36	26/09/18 15:12	General View			Load JPG		☒			
37	26/09/18 15:12	General View			Load JPG		☒			

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	26/09/18 15:12	General View	 Load JPG	☒
39	26/09/18 15:12	General View	 Load JPG	☒
40	26/09/18 15:12	General View	 Load JPG	☒
41	26/09/18 15:12	General View	 Load JPG	☒
42	26/09/18 15:12	General View	 Load JPG	☒
43	26/09/18 15:12	General View	 Load JPG	☒
44	26/09/18 15:12	General View	 Load JPG	☒
45	26/09/18 15:12	General View	 Load JPG	☒
46	26/09/18 15:12	General View	 Load JPG	☒
47	26/09/18 15:12	General View	 Load JPG	☒
48	26/09/18 15:13	Reinspection Photo	 Load JPG	☒
49	26/09/18 15:13	Reinspection Photo	 Load JPG	☒
50	26/09/18 15:13	Reinspection Photo	 Load JPG	☒
51	26/09/18 15:13	Reinspection Photo	 Load JPG	☒
52	26/09/18 15:13	Reinspection Photo	 Load JPG	☒
53	26/09/18 15:13	Reinspection Photo	 Load JPG	☒
54	26/09/18 15:13	Reinspection Photo	 Load JPG	☒
55	26/09/18 15:13	Reinspection Photo	 Load JPG	☒
56	26/09/18 15:13	Reinspection Photo	 Load JPG	☒
57	26/09/18 15:13	Reinspection Photo	 Load JPG	☒
58	26/09/18 15:13	Reinspection Photo	 Load JPG	☒
59	26/09/18 15:13	Reinspection Photo	 Load JPG	☒
60	26/09/18 15:13	Reinspection Photo	 Load JPG	☒
61	26/09/18 15:13	Reinspection Photo	 Load JPG	☒
62	26/09/18 15:13	Reinspection Photo	 Load JPG	☒
63	26/09/18 15:13	Reinspection Photo	 Load JPG	☒
64	26/09/18 15:13	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	19/04/18 13:23	THIRD PARTY SAS REPORT SLE6466G	 Load PDF	
2	19/04/18 13:23	THIRD PARTY SLE6466G -PRS EMAIL BTW CIC AND VERMOGEN ACE	 Load PDF	
3	26/04/18 11:43	INSURED SAS REPORT	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/10/18 12:56	Supplementary	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd

(Co.Reg No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118007271/R1QBE2

Date: 01/10/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN1659871701
Claimant Vehicle No :	SLE6466G	Insured Vehicle No :	GBE1931G
Date of Loss:	14/04/2018	Nature of Claim:	TP
		Claim No:	SNM18D01950C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLE6466G	Engine No:	LEB5908852
Make & Model:	HONDA VEZEL, 1.5 (A)	Chassis No:	RU31208839
Reg. Date:	28/07/2016 (Man. Year: 2016)	Odometer:	87297 km
Colour:	Red		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Roadstone 5 mm	Rear Left Side:	Roadstone 5 mm
Front Right Side:	Roadstone 5 mm	Rear Right Side:	Roadstone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,661.76	3,370.56	11,291.20	77.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,420.00	1,500.00	4,920.00	76.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,081.76	4,870.56	16,211.20	76.90
Approved Total (Overridden) (S\$)		3,900.00		
(S\$)	21,081.76	3,900.00	17,181.76	81.50
+ GST 7.00/7.00% (S\$)	1,475.72	273.00	1,202.72	81.50
Nett Amount (S\$)	22,557.48	4,173.00	18,384.48	81.50

INSPECTION

Date of Assignment:	19/04/2018	
Date Inspected:	19/04/2018 Inspected At:	6 Benoi Sector Repairer : Vermogen Ace Pte Ltd - Kaki Bukit (HQ)
Estimated Period of Repair:	5.0 days	

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Oct 2018)
Parts:	M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLE6466G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	1,620.00 FL	*1,250.00 FL
2	1		*TAILGATE OUTER GARNISH	Serviceable	285.00 FL	*- FL
3	1		*SET TAILGATE OUTER GARNISH CLIPS	Not Necessary	40.00 FL	*- FL
4	1		*TAILGATE LOGO	Necessary	52.00 FL	*52.00 FL
5	1		*TAILGATE EMBLEM VEZEL	Necessary	56.20 FL	*56.20 FL
6	1		*TAILGATE LAMP LH	Not Necessary	490.00 FL	*- FL
7	1		*TAILGATE LAMP RH	Not Necessary	490.00 FL	*- FL
8	2		*SET TAILGATE LAMP CLIPS	Not Necessary	50.00 FL	*- FL
9	1		*TAILGATE OUTER HANDLE SWITCH	Not Necessary	180.00 FL	*- FL
10	1		*TAILGATE REVERSE CAMERA	Not Necessary	600.00 FL	*- FL
11	1		*TAILGATE DAMPER LH	Not Necessary	212.00 FL	*- FL
12	1		*TAILGATE DAMPER RH	Not Necessary	212.00 FL	*- FL
13	1		*TAILGATE INNER HANDLE	Not Necessary	74.00 FL	*- FL
14	1		*TAILGATE INNER LOCK	Bent	245.00 FL	*245.00 FL
15	1		*TAILGATE LOCK SENSOR (ANTENNA)	Cracked	220.00 FL	*220.00 FL
16	1		*TAILGATE STRIKER	Bent	32.00 FL	*32.00 FL
17	1		*TAILGATE TRIMBOARD	Cracked	295.00 FL	*295.00 FL
18	1		*SET TAILGATE TRIMBOARD CLIPS	Necessary	45.00 FL	*45.00 FL
19	1		*TAILGATE WEATHERSTRIP	Cut	145.00 FL	*145.00 FL
20	1		*SET TAILGATE WINDSCREEN MOULDING	Necessary	164.00 FL	*164.00 FL
21	1		*REAR BUMPER	Deformed	885.00 FL	*885.00 FL
22	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
23	1		*REAR BUMPER RETAINER LH	Not Necessary	72.00 FL	*- FL
24	1		*REAR BUMPER RETAINER RH	Not Necessary	72.00 FL	*- FL
25	1		*REAR BUMPER BRACKET LH	Not Necessary	116.00 FL	*- FL
26	1		*REAR BUMPER BRACKET RH	Not Necessary	116.00 FL	*- FL
27	1		*REAR BUMPER REFLECTOR LH	Not Necessary	167.00 FL	*- FL
28	1		*REAR BUMPER REFLECTOR RH	Not Necessary	167.00 FL	*- FL
29	1		*REAR BUMPER COVER LH	Not Necessary	210.00 FL	*- FL
30	1		*REAR BUMPER COVER RH	Not Necessary	210.00 FL	*- FL
31	1		*SET REAR BUMPER COVER CLIPS	Not Necessary	50.00 FL	*- FL
32	1		*REAR BUMPER COVER RETAINER LH	Not Necessary	42.00 FL	*- FL
33	1		*REAR BUMPER COVER RETAINER RH	Not Necessary	42.00 FL	*- FL
34	1		*REAR END PANEL OUTER	Repair	585.00 FL	*- FL
35	1		*REAR END PANEL INNER	Serviceable	396.00 FL	*- FL
36	1		*REAR END PANEL TOP GARNISH	Deformed	184.00 FL	*184.00 FL
37	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	25.00 FL	*25.00 FL
38	1		*SPARE TYRE PANEL	Serviceable	1,230.00 FL	*- FL
39	1		*SPARE TYRE PANEL TOOL INSULATOR	Cracked	240.00 FL	*240.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*SPARE TYRE PANEL TOP BOARD	Serviceable	420.00 FL	*- FL
41	1		*TAIL LAMP LH	Not Necessary	489.00 FL	*- FL
42	1		*TAIL LAMP RH	Not Necessary	489.00 FL	*- FL
43	2		*SETS TAIL LAMP CLIPS	Not Necessary	36.00 FL	*- FL
44	1		*EXHAUST MUFFLER	Not Necessary	855.00 FL	*- FL
45	1		*SET EXHAUST MUFFLER MOUNTING	Not Necessary	79.50 FL	*- FL
46	1		*EXHAUST MUFFLER HEAT SHIELD	Not Necessary	165.00 FL	*- FL
47	2		*REAR FENDER	Not Necessary	1,900.00 FL	*- FL
48	2		*REAR FENDER ARCH GARNISH	Not Necessary	230.00 FL	*- FL
49	2		*REAR FENDER ARCH GARNISH CLIPS	Not Necessary	100.00 FL	*- FL
50	2		*REAR FENDER INNER WATER SHIELD	Not Necessary	320.00 FL	*- FL
51	2		*REAR FENDER INNER WATER SHIELD CLIPS	Not Necessary	160.00 FL	*- FL
52	2		*REAR FENDER INNER LOWER TRIM BOARD	Not Necessary	730.00 FL	*- FL
53	2		*REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	160.00 FL	*- FL
54	2		*REAR FENDER INNER UPPER TRIM BOARD	Not Necessary	320.00 FL	*- FL
55	2		*REAR FENDER INNER UPPER TRIM BOARD CLIPS	Not Necessary	60.00 FL	*- FL
56	2		*REAR FENDER MUDFLAP	Not Necessary	160.00 FL	*- FL
57	1		*REVERSE SENSOR	Serviceable	300.00 FS	*- FS
58	1		*REAR END PANEL SEALANT	Not Necessary	80.00 FS	*- FS
59	1		*SPARE TYRE PANEL SEALANT	Not Necessary	80.00 FS	*- FS
60	1		*TAIL LAMP SEALANT	Not Necessary	80.00 FS	*- FS
61	2		*TAIL LAMP PAD LH / RH	Not Necessary	80.00 FS	*- FS
62	1		*TAIL GATE SEALANT	Necessary	80.00 FS	*60.00 FS
63	1		*TAIL GATE WINDSCREEN SEALANT }	Necessary	80.00 FS	*80.00 FS
64	1		*TAIL GATE WINDSCREEN INNER SEAL }	Necessary	80.00 FS	*- FS
65	1		*REAR NUMBER PLATE WITH CASE	Not Necessary	50.00 FS	*- FS
66	1		*TAILGATE BUZZER	Cracked	150.00 FL	*150.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	18,099.70	4,178.20
- List Item Discount on L Items 20.00/20.00% (\$\$)	3,437.94	807.64
Total Parts (\$\$)	14,661.76	3,370.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO STRAIGHTEN AND PANEL BEATING ACCIDENT AREA. REAR PORTION	New	2,500.00	500.00
2	TO PUTTY, RESPRAY PAINTING AND POLISH ACCIDENT AREA. REAR PORTION	New	2,500.00	600.00
3	TO CHECK AND RECTIFY WIRING AFTER DISCONNECT AND CONNECT	New	180.00	0.00
4	TO REMOVE AND REFIT INTERIOR TRIMS AND UPHOLSTERY	New	250.00	80.00
5	TO REMOVE AND TRANSFER TAILGATE COMPONENTS	New	180.00	80.00
6	TO REMOVE AND REFIT TAILGATE WINDSCREEN	New	180.00	120.00
7	TO REMOVE AND REFIT EXHAUST PIPE AND ALIGN	New	250.00	0.00
8	TO REMOVE AND REFIT REVERSE SENSOR	New	180.00	60.00
9	TO RUST PROOF AFFECTED AREAS	New	200.00	60.00
Gross Labour Cost (S\$)			6,420.00	1,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >