

	SERVICE REQUESTS	MESSAGES	CLAIMS	ACTION			AMOUNT	COMMENT	REMOVE
				Reviewing	0	NOT NECESSARY			

-  **SERVICE REQUESTS**
-  **MESSAGES**
-  **CLAIMS**

  1

PART NAME	LABOUR H&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS. PANEL BEAT, CUT & WELD IF NECESSARY AND ALIGN ALL PANEL AND REINSTALL ALL DAMAGED PARTS.	800	0	0	Reviewing		
PROVIDE SKILL LABOUR & MATERIAL TO PUTTY ALL DAMAGED PARTS & PANEL & TO RESPRAY WITH 2K PAINT WITH OVEN SPRAY BOOTH FACILITIES.	650	0	0	Reviewing		
PROVIDE SKILL LABOUR TO DISCONNECT AND CHECK ELECTRICAL WIRING.	30	0	0	Reviewing		
REMOVE AND REFIT REAR WINDSCREEN.	0	0	0	Reviewing		
REMOVE AND REFIT REAR END PANEL LINING AND GARNISH TO FACILITATE REPAIR.	0	0	0	Reviewing		
REMOVE AND REPLACE BUMPER SENSORS.	50	0	0	Reviewing		
REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING AND/OR UPHOLSTERY TO FACILITATE REPAIRS.	80	0	0	Reviewing		
PROVIDE SKILL LABOUR TO REALIGN CHASSIS ALIGNMENT BENCH.	0	0	0	Reviewing		
REMOVE AND REFIT EXHAUST PIPE / SYSTEM TO FACILITATE REPAIR.	0	0	0	Reviewing		

																	SERVICE REQUESTS		MESSAGES		CLAIMS		BOOT LID HINGE RH		Repair		0		0		Reviewing					
																		11	1											Serviceable	0	0	0	0	Reviewing	
																		12	1											Repair	0	0	0	0	Reviewing	
																		13	1											Serviceable	0	0	0	0	Reviewing	
																		14	1											Cracked	196.2	0	196.2	0	Reviewing	
																		15	1											Serviceable	0	0	0	0	Reviewing	
																		16	1											Bent	404.7	0	404.7	0	Reviewing	
																		17	1											Serviceable	0	0	0	0	Reviewing	
																		18	1											Serviceable	0	0	0	0	Reviewing	
																		19	1											Damaged	39.22	0	39.22	0	Reviewing	
																		20	1											Damaged	56.4	0	56.4	0	Reviewing	
																		21	1											Serviceable	0	0	0	0	Reviewing	
																		22	1											Repair	0	0	0	0	Reviewing	



SERVICE REQUESTS

MESSAGES

CLAIMS

Claim Portal

ASSESSMENT INFORMATION

CATEGORY

FNOL INFORMATION

POST SURVEY INFORMATION

License Expiration Date

Address

Singapore

Address type

Personal Correspondence

Gender

Male

Marital status

Unknown

Identification #

S7466512H

English (default) * LKK AUTO CONSULTANTS PTE LTD (TP) *

HOME SERVICE REQUESTS MESSAGES CLAIMS

	SUB-TYPE	AUTHOR	DATE UPLOADED
ns / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	June 11, 2018
Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	June 11, 2018
Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	May 2, 2018
Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	April 25, 2018
Letters and Correspondence	Workshop	VISHNU BATHAM Shekhar	April 19, 2018

 LETTER TO OI.pdf Immediate Advice.pdf TP ESTIMATE- MARKED.pdf TP GJA.msg