



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 539216 Officer in Charge : ALVIN LOW WAI LUN Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax :
---	---

Quotation No : QO18/04-1190	Quotation Date : 16/04/2018	Terms : 30 DAYS
Vehicle No : SLM3920P	Chassis No : JM6BN22A8H0149817	Third Party Insurer :
Model : MAZDA 3		Date of Accident :
Remarks : TP INSURER: AXA, TP INSURED VEHICLE NO: SJW1712H, DOA: 14.04.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	REAR BUMPER	1	1,075.0000	1,075.00
2	REAR BUMPER REFLECTOR	2	51.0000	102.00
3	REAR BUMPER CLIPS	5	5.0000	25.00
4	REAR BUMPER REINFORCEMENT	1	538.0000	538.00
5	REAR BUMPER SIDE RETAINER	2	92.0000	184.00
6	REAR BUMPER SIDE HOLDER	2	74.0000	148.00
7	REAR BUMPER SIDE HOLDER RIVETS	4	6.0000	24.00
8	REAR BUMPER CENTRE BRACKET	1	12.5000	12.50
9	REAR BUMPER TOW COVER	2	17.0000	34.00
10	REAR END PANEL	1	506.0000	506.00
11	REAR END PANEL INNER TRIM	1	86.0000	86.00
12	LESS 20%(ITEM 1 - 11)	1	-546.9000	-546.90
13	REAR BUMPER PARKING SENSOR	1	280.0000	280.00
14	TO REINSTALL OF REAR BUMPER PARKING SENSOR.	1	100.0000	100.00
15	TO CHECK ELECTRICAL LIGHTING CONCERNED.	1	60.0000	60.00
16	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	1	700.0000	700.00
17	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	1	680.0000	680.00

Sub Total	4,007.60
GST(7.00%)	280.53
Total (SGD)	4,288.13

Please conduct the survey at
Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216