

ASS. REC. BY: Adrian Ling

REF:

CC3/Ath/8007322 / Avbn2

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. 2100441707 - 02

Claims No. _____

Sum Insured: _____ Excess: 0

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 93k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 887 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SDV 7585U Yr Regn: 2015, Nov

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Audi A3 c.c. 1395

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 19910 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAUZZZ8V0G1037584

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R: 205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. 14/4/18 D.O.I. 19/04/18

Survey held at Premium

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>7 P AIG</u>
<u>20/7/18</u>	<u>Final fig \$ 8207.12 (Red 5609.88, 41%) confirmed by email</u>
	<u>RECEIVED 17 JUL 2018</u>
	<u>RECEIVED 20 AUG 2018</u>

Date/Time, File Pass to?

: Preli. Report

Days Of Repair: 7

1)

: Final Report

Resurvey No. of Trip: -

Date/Time, File Return to?

2) 20/8 - typist

Add Fee: : Site Insp (\$)

: Interview. (\$)

: Tech. Invs (\$)

: Weekend (\$)

Survey Fee:

Transportation: 200

S + RS: 10

Photos

Others

TOTAL

210

Report Format: merimen


Lump Sum / I.B.I: (\$) 8207.12

Surveyor: ADRIAN

DOI: ASSIGNMENT 19/4/18

Date / Time: 19/4/18
Registered in Merimen: 19/4/18

Pre-assign / CCU / FTE



Insured Vehicle No. : SLB 1528K
Name of Insured : _____
Insured Tel No. : _____ HP: _____
Excess Sec II :SS _____ D.O.A: 14/4/18
Is driver the owner? (YES / NO) Nature of Accident : _____

Claim No. : _____
Policy No. : _____
Make / Model : _____
Place of Accident : _____

If NO, Driver Name / Age : _____
Driver Tel No. : _____ (V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO
Insured Liability : % Final ? Yes / No

SDV 7585U →



INSRS: _____
WSP: Premier
Tel : _____
Liability : _____
RMKS: _____



INSRS: _____
WSP: _____
Tel : _____
Liability : _____
RMKS: _____



INSRS: _____
WSP: _____
Tel : _____
Liability : _____
RMKS: _____



INSRS: _____
WSP: _____
Tel : _____
Liability : _____
RMKS: _____

Date/ Time	STAGE	DATE / PIC
	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	<input type="checkbox"/> <input type="checkbox"/>
	After call ltr to OI:	<input type="checkbox"/> <input type="checkbox"/>
	Authorisation To Act:	<input type="checkbox"/> <input type="checkbox"/>
	Release Voucher:	<input type="checkbox"/> <input type="checkbox"/>
	Final Repair Bill:	<input type="checkbox"/> <input type="checkbox"/>
	Car Rental Invoice:	<input type="checkbox"/> <input type="checkbox"/>
	Towing Invoice:	<input type="checkbox"/> <input type="checkbox"/>
	LTA / GIA :	<input type="checkbox"/> <input type="checkbox"/>
	Medical Bill:	<input type="checkbox"/> <input type="checkbox"/>
	PIR:	<input type="checkbox"/> <input type="checkbox"/>
	Mandate/Reject Instruction:	<input type="checkbox"/> <input type="checkbox"/>
	LOD	<input type="checkbox"/> <input type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/> <input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/> <input type="checkbox"/>
	Others:	<input type="checkbox"/> <input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: _____ Sent By: _____

FINALIZATION Date/Time: _____ Confirm with: _____ Confirm by: _____
 Repair Cost: S\$ _____ (_____ days) Reduction: _____ % Email Call

FINAL SETTLEMENT Date/Time: _____ Confirm with: _____ Email Call

Final Liability: % (Agreed / Assessed) BOLA S/N No. : _____ If NO or B 28, Ass. Lia : _____
 Repair Cost: S\$ _____
 Loss of Rental (LOR): S\$ _____ (_____ days)
 Loss of Use (LOU): S\$ _____ (\$ x _____ days)
 Loss of Income (LOI): S\$ _____ (\$ x _____ days)
 LOR only LOU only LOR + LOU LOR + LOI [Tick only one]
 GIA/LTA Search: S\$ _____
 Medical: S\$ _____
 Disbursement: S\$ _____ (e.g. Tow/ Independent)
 Legal Cost: S\$ _____

Total: S\$ _____ **Global Sum S\$:** _____
 Email Call

FINAL PAYMENT Date/Time: _____ Confirm with: _____ Email Call

Payee 1: S\$ _____ Name 1: _____
 Payee 2: (Strike if N.A.) S\$ _____ Name 2: _____
 Payee 3: (Strike if N.A.) S\$ _____ Name 3: _____

View Received Message

This mail is associated with :

***SDV7585U (9389816306SG)**

OD

Apr 14 2018 1:30PM

[KHOO LAY PING]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on **20/07/2018 12:14 PM**.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$8207.12) - SDV7585U - Claim Handler: Dally Amri, Mimi Zarina

Approved:8207.12:Submit first advise. Re-inspection to be done for damage check and supplementary items / labour.

DOCUMENTS SUMMARY

There are no documents.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 9 May 2018 9:10 AM
To: Claims; SUR
Subject: RE: SDV 7585 U Own Damage Claims

Dear Tony,

Vehicle excess \$0

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims [mailto:claims@premiumauto.com.sg]
Sent: Wednesday, 9 May 2018 9:00 AM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: claims@premiumauto.com.sg
Subject: RE: SDV 7585 U Own Damage Claims

Dear Veron,

Any update on the excess amount?

Thank you.

Best Regards,

Tony Foong
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



http://www.audi.com.sg/sea/brand/sg/audi_promotions/promotions/car_promotions/new-audi-q2-2017.html

Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Veron Chen (LKKAuto) [<mailto:veronchen@lkkauto.com>]
Sent: Tuesday, 24 April, 2018 3:31 PM
To: Claims <claims@premiumauto.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SDV 7585 U Own Damage Claims

Dear George,

As instructed by our client , please proceed to repair the insured vehicle **SDV 7585U (Excess TBA/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims [<mailto:claims@premiumauto.com.sg>]
Sent: Tuesday, 24 April 2018 10:54 AM
To: SUR <sur@lkkauto.com>
Cc: claims@premiumauto.com.sg
Subject: RE: SDV 7585 U Own Damage Claims

Dear all,

We 're sorry for missed out the video footage.

Attached the video footage for your kind reference.

Survey was carried out on 19 of April.

Kindly assist in the Own Damage Claim approval for the above mentioned vehicle.

Thank you

Best regards,
George Wong

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 66900293 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged. If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Claims Dept <claims@premiumauto.com.sg>

Sent: Thursday, April 19, 2018 12:25 PM

To: sur@lkkauto.com

Cc: 'Claims Dept' <claims@premiumauto.com.sg>

Subject: SDV 7585 U Own Damage Claims

Dear all,

Kindly assist in the Own Damage Claim approval for the above mentioned vehicle.

Survey was carried out earlier this morning.

Many thanks!

Best regards,
Jeffery Tan

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged. If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 24 April 2018 3:31 PM
To: 'Claims'; SUR
Subject: RE: SDV 7585 U Own Damage Claims

Dear George,

As instructed by our client , please proceed to repair the insured vehicle **SDV 7585U (Excess TBA/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims [mailto:claims@premiumauto.com.sg]
Sent: Tuesday, 24 April 2018 10:54 AM
To: SUR <sur@lkkauto.com>
Cc: claims@premiumauto.com.sg
Subject: RE: SDV 7585 U Own Damage Claims

Dear all,

We 're sorry for missed out the video footage.

Attached the video footage for your kind reference.

Survey was carried out on 19 of April.

Kindly assist in the Own Damage Claim approval for the above mentioned vehicle.

Thank you

Best regards,
George Wong

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 66900293 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Claims Dept <claims@premiumauto.com.sg>

Sent: Thursday, April 19, 2018 12:25 PM

To: sur@lkkauto.com

Cc: 'Claims Dept' <claims@premiumauto.com.sg>

Subject: SDV 7585 U Own Damage Claims

Dear all,

Kindly assist in the Own Damage Claim approval for the above mentioned vehicle.

Survey was carried out earlier this morning.

Many thanks!

Best regards,
Jeffery Tan

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9415F
Vehicle Details	
Vehicle No.:	SDV7585U
Vehicle to be Exported:	No
Intended De-registration Date:	24 Apr 2018
Vehicle Make:	AUDI
Vehicle Model:	A3 SEDAN 1.4 TFSI (AMBIENTE)
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	CZC291365
Chassis No.:	WAUZZZ8V0G1037584
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	\$27,650.00
Original Registration Date:	25 Nov 2015
First Registration Date:	25 Nov 2015
Transfer Count:	0
Actual ARF Paid:	\$20,710.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Nov 2025
PARF Rebate Amount:	\$15,532.00
Intended COE Rebate Details	
COE Expiry Date:	24 Nov 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$59,200.00
COE Rebate Amount:	\$44,893.00
Total Rebate Amount:	\$60,425.00

The information contained herein is correct as at 24 Apr 2018

OK

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1659415F



Name

KHOO LAY PING

邱丽冰

Race

CHINESE

Date of Birth

Sex

23-01-1964

F

Country of Birth

SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENCE



License Number S1659415F

KHOO LAY PING

Birth Date 23 Jan 1964

Issue Date 07 Oct 2008



1148142



NRIC No. S1659415F

Blood Group Date of issue

O+ 30-07-1993

93 MEYER ROAD #03-01
SINGAPORE 437886
NRIC No: S1659415F


Date: 30/12/2017

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

PASS DATE

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

26 Nov 1990



License No: S1659415F

NP 428A

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : KHOO LAY PING
Period of Insurance : 25 Nov 2017 To 24 Nov 2018
Engine No. : CZC291365
Chassis No. : WAUZZZ8V0G1037584

Vehicle No. : SDV7585U
Policy No. : 2100441707-02
Endorsement No. : 000000000158400
Issued Date : 13 Nov 2017

ABOUT THE COVER

Make/Model : AUDI A3 SEDAN 1.4 TFSI (AMBIENTE)
Engine Capacity/Tonnage : 1,395.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2015
Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive* :

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2
Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

KHOO LAY PING - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1 Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download 'AIG SG' from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: NA

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

1504125201

PREMIUM LEASING - DL
81 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938



AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/463/2018/GW
Date : 18-Apr-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms. Khoo Lay Ping
Address : 93 Mayer Road
#03-01
Singapore 437986
Telephone : HP +65 97351218
Type of Claim : Third Party Claims
Policy No. : 2100441707-02
Vehicle No : **SDV 7585 U**
Model Code : Audi A3 Sedan 1.4 TFSI
Model / Year : Nov-15
Engine No : CZC 291365
Chassis No : WAUZZZ8V0G1037584
Mileage : -
Date In : -
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 14-Apr-18
Place of Accident : Changi Rd After Junc Of Changi Rd&Telok Kurau Rd

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SDV 7585 U.

S/N	Nature of Jobs	Estimated Charges
1	To remove and transfer rhs front and rear door's multi-lock system and power window devices.	S/N \$ 560.00 ✓ ✓
2	To dismantle and renew rhs front and rear doors, align to position. Repair rhs sill panel, rhs B-pillar and rear fender . Reinstall all parts removed.	\$ 3,000.00 1500 ✓
3	To respray rhs front and rear doors, rhs sill panel, rhs B- pillar and rhs rear fender . X ✓	\$ 3,800.00 2200 ✓
4	To carry out diagnostic check.	S/N \$ 192.00 ✓ ✓
TOTAL LABOUR CHARGES		: \$ <u>7,552.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDV 7585 U.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT DOOR-RH <i>Distorted</i>	\$ 2,190.00	✓ 1752
2	FRONT OUTER DOOR SEAL-RH <i>new</i>	\$ 139.00	✓ 111.00
3	BONDING AGENT <i>Not new</i>	\$ 43.00	? X
4	CLEANING SOLUTION <i>Not new</i>	\$ 64.00	? X
5	FRONT DOOR CATCH <i>new</i>	\$ 92.00	+
6	FRONT DOOR HANDLE-RH <i>Not new</i>	\$ 207.00	+
7	FRONT DOOR MOUNTING BAR-RH <i>Not new</i>	\$ 143.00	+
8	FRONT WINDOW REGULATOR WITHOUT MOTOR-RH	\$ 232.00	+
9	FRONT WINDOW REGULATOR MOTOR-RH	\$ 212.00	+
10	FRONT DOOR CONTROL UNIT-RH	\$ 438.00	+
11	REAR DOOR-RH <i>Distorted</i>	TBC	✓ 1752
12	REAR DOOR OUTER DOOR SEA-RH <i>new</i>	\$ 139.00	✓ 111.00
13	BONDING AGENT <i>Not new</i>	\$ 43.00	? X
14	CLEANING SOLUTION <i>Not new</i>	\$ 64.00	? X
15	REAR DOOR CATCH <i>new</i>	\$ 82.00	+
16	DATA PLATE FOR TYRE PRESSURE <i>new</i>	\$ 25.00	✓ 19.76
17	SUNDRIES <i>new</i>	\$ 400.00	? 8.96
TOTAL SPARE PARTS		\$ 4,513.00	
TOTAL LABOUR CHARGES		\$ 7,552.00	
GRAND TOTAL		\$ 12,065.00	

13,817

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King
Surveyed Date : 19/04/18.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 06 Pys.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/463/2018/GW
Date : 18-Apr-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

*Hi Adrian
you recommended 6 days
We took 7 days exclude 1 Sunday
jb 25 Jun 18*

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms. Khoo Lay Ping
Address : 93 Mayer Road
#03-01
Singapore 437986
Telephone : HP +65 97351218
Type of Claim : Third Party Claims
Policy No. : 2100441707-02
Vehicle No : **SDV 7585 U**
Model Code : Audi A3 Sedan 1.4 TFSI
Model / Year : Nov-15
Engine No : CZC 291365
Chassis No : WAUZZZ8V0G1037584
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 14-Apr-18
Place of Accident : Changi Rd After Junc Of Changi Rd&Telok Kurau Rd

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SDV 7585 U.

S/N	Nature of Jobs	Estimated Charges	
1	To remove and transfer rhs front and rear door's multi-lock system and power window devices.	S/N \$ 560.00	\$ 560.00
2	To dismantle and renew rhs front and rear doors, align to position. Repair rhs sill panel, rhs B-pillar and rear fender . Reinstall all parts removed.	\$ 3,000.00	\$ 1,500.00
3	To respray rhs front and rear doors, rhs sill panel, rhs B- pillar and rhs rear fender .	\$ 3,800.00	\$ 2,200.00
4	To carry out diagnostic check.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 7,552.00	\$ 4,452.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDV 7585 U.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT DOOR-RH	\$ 2,190.00	\$ 1,752.00
2	FRONT OUTER DOOR SEAL-RH	\$ 139.00	\$ 111.20
3	BONDING AGENT	\$ 43.00	
4	CLEANING SOLUTION	\$ 64.00	
5	FRONT DOOR CATCH	\$ 92.00	
6	FRONT DOOR HANDLE-RH	\$ 207.00	
7	FRONT DOOR MOUNTING BAR-RH	\$ 143.00	
8	FRONT WINDOW REGULATOR WITHOUT MOTOR-RH	\$ 232.00	
9	FRONT WINDOW REGULATOR MOTOR-RH	\$ 212.00	
10	FRONT DOOR CONTROL UNIT-RH	\$ 438.00	
11	REAR DOOR-RH	\$ 2,190.00	\$ 1,752.00
12	REAR DOOR OUTER DOOR SEA-RH	\$ 139.00	\$ 111.20
13	BONDING AGENT	\$ 43.00	
14	CLEANING SOLUTION	\$ 64.00	
15	REAR DOOR CATCH	\$ 82.00	
16	DATA PLATE FOR TYRE PRESSURE	\$ 25.00	\$ 19.76
17	SUNDRIES	\$ 400.00	\$ 8.96
	TOTAL SPARE PARTS	\$ 6,703.00	\$ 3,755.12
	TOTAL LABOUR CHARGES	\$ 7,552.00	\$ 4,452.00
	GRAND TOTAL	\$ 14,255.00	\$ 8,207.12

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 20 July 2018 1:46 PM
To: 'Carrine Leong'; SUR
Cc: 'Chang Chee Sing'; jiyee.yap@premiumauto.com.sg
Subject: RE: FINAL REVISION - SDV7585U - OD AIG - SURVEYED 19 APR 18

Dear Carrine,

Confirm repair cost of \$8207.12 before GST @ 7 days of repairs

Kindly send us invoice and discharge voucher for us to close file

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Carrine Leong [mailto:carrine.leong@premiumauto.com.sg]
Sent: Monday, 16 July 2018 3:36 PM
To: Adrian Ling (LKKAuto) <adrianling@lkkauto.com>; Veron Chen (LKKAuto) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Chang Chee Sing' <claims@premiumauto.com.sg>; jiyee.yap@premiumauto.com.sg
Subject: RE: FINAL REVISION - SDV7585U - OD AIG - SURVEYED 19 APR 18


Dear Adrian and all,

Reminder

We have yet receive your confirmation of repair cost and days of repair for above vehicle.
Revised estimate was mailed to you on 24 Jun 2018.
We sincerely appreciate your early closure.

Thanks & Best Regard
Carrine Leong
Claims Administrator

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9925 f. +65 6841 1183
e. carrine.leong@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Boo seng yak [<mailto:boojohnny@gmail.com>]

Sent: Sunday, 24 June, 2018 3:24 PM

To: Adrian Ling <adrianling@lkkauto.com>; Veron Chen <veronchen@lkkauto.com>; sur@lkkauto.com; Carrine Leong <carrine.leong@premiumauto.com.sg>; jiayee.yap@premiumauto.com.sg; Nora Khai <nora.khai@premiumauto.com.sg>

Subject: FINAL REVISION - SDV7585U - OD AIG - SURVEYED 19 APR 18

Hi Adrian and all,

Revised estimate is attached.

Please confirm repair cost of \$8207.12 @ 7 days of repairs exclude 1 Sunday.

Your early closure is well appreciated.

Best regards - jb

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Motor Claims Dept
Yr Ref: SDV 7585 U

Norah Khai
6768 9911
6841 1183

Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0463/2018/MAS

14 Aug 2018

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

total pages

Dear Sir,

RE: INSURANCE CLAIM FOR SDV 7585 U, Audi A3 Sedan 1.4 TFSI

With reference to the above mentioned vehicle, no. **SDV 7585 U**, claimant, **Ms. Koo Lay Ping**, please find the related document as per attached.

1. A copy of the Original invoice no. 85012804 - \$8,781.62
2. A copy of letter of Discharge duly signed by client

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer generated document. No signature is required.

Norah Khai

Claims Dept

Encls

AIG Insurance – SDV 7585 U

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 684 11183

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Apr 2018		24 Apr 2018 13:07 Edit Adj Rpt	S\$8,207.12 Edit Estimates	S\$8,207.12 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	KHOO LAY PING, ID: S1659415F, Tel: +6597351218, Email: CHANYK@SINGNET.COM.MY		
Vehicle Reg. No.:	SDV7585U	Date of Loss:	14/04/2018 13:00 - :59 [28 Months and 20 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 9389816306SG	Policy/Cover Note No.:	2100441707-02 (Comprehensive)
		Excess:	S\$0.00
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Dally Amri, Mimi Zarina] MimiZarina.DallyAmri@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 04/05/2018]		
Driver/Custodian:	KHOO LAY PING (54 / Female), NRIC: S1659415F, Tel: +6597351218		
ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
<ul style="list-style-type: none"> AIG_SG (20/07/2018): Alert - Adj Mandate Approved (S\$8207.12) - SDV7585U - Claim Handler: Dally Amri,... AIG_SG (24/04/2018): SDV7585U / OD / 14/04/2018 / Coverage & Excess update 			
ALL ASSOCIATED TASKS		View All	Search Tasks
		Create New Task	Complete
Due Date	Priority	Type	Task Group
			Subject
			Handler
			Assigned By
			Completed On
			Created On
			Done?
No results.			

Claim Documents

***SDV7585U (9389816306SG)**
OD
Apr 14 2018 1:30PM
[KHOO LAY PING]
Premium Automobiles Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View Use Viewer	
Video										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Autocare Centre (Alexandra)						Thumbnail	Print		
1	14/04/18 17:38	Video - Accident [Linked Accident Report Documents]							Load MP4		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	24/04/18 13:40	Video - Accident							Load MP4		
Photos/Images										3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	24/04/18 13:37	General View							Load JPG	<input checked="" type="checkbox"/>	
2	24/04/18 13:37	General View							Load JPG	<input checked="" type="checkbox"/>	
3	24/04/18 13:37	General View							Load JPG	<input checked="" type="checkbox"/>	
4	24/04/18 13:37	General View							Load JPG	<input checked="" type="checkbox"/>	
5	24/04/18 13:37	General View							Load JPG	<input checked="" type="checkbox"/>	
6	24/04/18 13:37	General View							Load JPG	<input checked="" type="checkbox"/>	
7	24/04/18 13:37	General View							Load JPG	<input checked="" type="checkbox"/>	
8	24/04/18 13:37	General View							Load JPG	<input checked="" type="checkbox"/>	
9	24/04/18 13:37	General View							Load JPG	<input checked="" type="checkbox"/>	
10	24/04/18 13:37	General View							Load JPG	<input checked="" type="checkbox"/>	
11	24/04/18 13:37	General View							Load JPG	<input checked="" type="checkbox"/>	
12	24/04/18 13:37	General View							Load JPG	<input checked="" type="checkbox"/>	
13	24/04/18 13:37	General View							Load JPG	<input checked="" type="checkbox"/>	
14	24/04/18 13:37	General View							Load JPG	<input checked="" type="checkbox"/>	
15	24/04/18 13:37	General View							Load JPG	<input checked="" type="checkbox"/>	
16	24/04/18 13:37	General View							Load JPG	<input checked="" type="checkbox"/>	
17	24/04/18 13:37	General View							Load JPG	<input checked="" type="checkbox"/>	
18	24/04/18 13:37	General View							Load JPG	<input checked="" type="checkbox"/>	
19	24/04/18 13:37	General View							Load JPG	<input checked="" type="checkbox"/>	
20	24/04/18 13:37	General View							Load JPG	<input checked="" type="checkbox"/>	
21	24/04/18 13:37	General View							Load JPG	<input checked="" type="checkbox"/>	
22	24/04/18 13:37	General View							Load JPG	<input checked="" type="checkbox"/>	
23	24/04/18 13:37	General View							Load JPG	<input checked="" type="checkbox"/>	
24	24/04/18 13:37	General View							Load JPG	<input checked="" type="checkbox"/>	
Documentation										1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	24/04/18 13:35	Singapore Accident Statement							Load PDF		
2	24/04/18 13:35	Insured's Driving License							Load PDF		
3	24/04/18 13:35	MARK ESTIMATE							Load PDF		
4	20/08/18 13:50	WORKSHOP INVOICE							Load PDF		
5	20/08/18 13:50	DISCHARGE VOUCHER							Load PDF		

Linked Accident Report Documents

Video										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Autocare Centre (Alexandra)						Thumbnail	Print		
1	14/04/18 17:38	Video - Accident							Load MP4		

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Autocare Centre (Alexandra)	Thumbnail	Print
1	14/04/18 18:35	Accident Statement		Load HTM

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Autocare Centre (Alexandra)	Thumbnail	Print
1	14/04/18 18:23	Accident Photo		Load JPG
2	14/04/18 18:23	Accident Photo		Load JPG
3	14/04/18 18:23	Accident Photo		Load JPG
4	14/04/18 18:23	Accident Photo		Load JPG
5	14/04/18 18:23	Accident Photo		Load JPG
6	14/04/18 18:23	Accident Photo		Load JPG
7	14/04/18 18:23	Accident Photo		Load JPG
8	14/04/18 18:23	Accident Photo		Load JPG
9	14/04/18 18:23	Accident Photo		Load JPG
10	14/04/18 18:23	Accident Photo		Load JPG
11	14/04/18 18:23	Accident Photo		Load JPG
12	14/04/18 18:23	Accident Photo		Load JPG
13	14/04/18 18:23	Accident Photo		Load JPG

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Autocare Centre (Alexandra)	Thumbnail	Print
1	14/04/18 18:22	Sketch Plan		Load JPG
2	14/04/18 18:22	Sketch Plan #2		Load JPG

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<p>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</p> <div style="border: 1px solid gray; height: 100px; width: 100%;"></div>			
<p>Show Remarks To: <input type="checkbox"/> Handling Insurer</p> <p><small>Note: Remarks are private unless you show it to other parties.</small></p>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG18007322/AVBN2
Date: 20/08/2018

REFERENCE

Insured/Claimant: KHOO LAY PING **Policy No:** 2100441707-02
Date of Loss: 14/04/2018 **Nature of Claim:** OD **Claim No:** 9389816306SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SDV7585U
Make & Model: AUDI A3, 1.4 SEDAN TFSI (AMBIENTE) (A) **Engine No:** CZC291365
Reg. Date: 25/11/2015 (Man. Year: 2015) **Chassis No:** WAUZZZ8V0G1037584
Colour: White **Odometer:** 19910 km
Engine Capacity: 1395 cc
Market Value/New Car Price: S\$93,000.00
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes
Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:** Yes

CONDITION OF TYRES

Front Tyre Size: 205/55R16 **Rear Tyre Size:** 205/55R16
Front Left Side: Pirelli 6 mm **Rear Left Side:** Pirelli 6 mm
Front Right Side: Pirelli 6 mm **Rear Right Side:** Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,265.00	3,755.12	2,509.88	40.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,552.00	4,452.00	3,100.00	41.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	13,817.00	8,207.12	5,609.88	40.60
+ GST 7.00/7.00% (S\$)	967.19	574.50	392.69	40.60
Nett Amount (S\$)	14,784.19	8,781.62	6,002.57	40.60

INSPECTION

Date of Assignment: 24/04/2018
Date Inspected: 19/04/2018 **Inspected At:** Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT DOOR-RH	Distorted	2,190.00 FS	*1,752.00 FS	
2	1		*FRONT OUTER DOOR SEAL-RH	Necessary	139.00 FS	*111.20 FS	
3	1		*BONDING AGENT	Not Necessary	43.00 FS	*- FS	
4	1		*CLEANING SOLUTION	Not Necessary	64.00 FS	*- FS	
5	1		*FRONT DOOR CATCH	Not Necessary	92.00 FS	*- FS	
6	1		*FRONT DOOR HANDLE-RH	Not Necessary	207.00 FS	*- FS	
7	1		*FRONT DOOR MOUNTING BAR-RH	Not Necessary	143.00 FS	*- FS	
8	1		*FRONT WINDOW REGULATOR WITHOUT MOTOR-RH	Not Necessary	232.00 FS	*- FS	
9	1		*FRONT WINDOW REGULATOR MOTOR-RH	Not Necessary	212.00 FS	*- FS	
10	1		*FRONT DOOR CONTROL UNIT-RH	Not Necessary	438.00 FS	*- FS	
11	1		*REAR DOOR-RH	Distorted	1,752.00 FS	*1,752.00 FS	
12	1		*REAR DOOR OUTER DOOR SEAL-RH	Necessary	139.00 FS	*111.20 FS	
13	1		*BONDING AGENT	Not Necessary	43.00 FS	*- FS	
14	1		*CLEANING SOLUTION	Not Necessary	64.00 FS	*- FS	
15	1		*REAR DOOR CATCH	Not Necessary	82.00 FS	*- FS	
16	1		*DATA PLATE FOR TYRE PRESSURE	Necessary	25.00 FS	*19.76 FS	
17	1		*SUNDRIES	Necessary	400.00 FS	*8.96 FS	
					Total Parts (S\$)	6,265.00	3,755.12

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER RHS FRONT AND REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES	New	560.00	560.00
2	TO DISMANTLE AND RENEW RHS FRONT AND REAR DOORS,ALIGN TO POSITION.REPAIR RHS SILL PANEL,RHS B-PILLAR AND REAR FENDER.REINSTALL ALL PARTS REMOVED	New	3,000.00	1,500.00
3	TO RESPRAY RHS FRONT AND REAR DOORS,RHS SILL PANEL,RHS B-PILLAR AND RHS REAR FENDER	New	3,800.00	2,200.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			7,552.00	4,452.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >