



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

Customer: WZH023 / SOMPO INSURANCE**Document No:** SVO18024747**Chassis No:** JHMRC1890GC205992**Printed By:** ARYCHUA**License No:** SLE9879D**Order Date:** 30. April 2018**Mileage:** 47000**Order Time:** 9:01:37 AM**Engine No:** K24W72012643**Service Advisor:** ARY CHUA WAI NGEE

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 70329)						
	OWNER: GEORGE NG						
	OWNER INSURER: LIBERTY INSURANCE PTE LTD						
	ACC DATE: 16/04/2018@21.45PM						
	SURVEYED BY: ADRAIN LING (LKKAUTO)20/04/2018@10.10						
	REF NO: CMTD1801657						
	TP INSURER: SOMPO INSURANCE SINGAPORE PTE LTD						
	TP VEH: SJK5249R						
04656-T6A-310ZZ	PAN SET,3RD SEAT	1	331.30	25	248.47	17.39	265.86
66100-T6A-Q00ZZ	PANEL COMP,REAR	1	451.70	25	338.77	23.71	362.48
68100-T6A-Q10ZZ	TAILGATE COMP	1	1,049.80	25	787.35	55.11	842.46
74440-T6A-003	WEATHERSTRIPTAILGATE	1	115.10	25	86.32	6.04	92.36
74800-TF0-J02	LOCKTAILGATE	1	181.70	25	136.27	9.54	145.81
74890-T6A-J01	GARNISH ASSYRR.LICENSE	1	225.90	25	169.42	11.86	181.28
74891-T6A-003	MOLDING ASSYRR.LICENSE GARN	1	172.10	25	129.07	9.03	138.10
73214-T6A-003	MOLDINGRR.WINDSHIELD SIDE	2	17.60	25	26.40	1.85	28.25
73215-T6A-003	MOLDINGRR.WINDSHIELD CORNER	1	16.60	25	12.45	0.87	13.32
73216-T6A-003	MOLDINGL.RR.WINDSHIELD CORNER	1	16.60	25	12.45	0.87	13.32
73221-SR4-000	SPACERRR.W/SHIELD	4	3.90	25	11.70	0.82	12.52
73226-SZW-000	DAMPERSTD 5X5	2	8.30	25	12.45	0.87	13.32
84615-T6A-N72ZD	LINING COMP,R.RR.SIDE	1	705.40	25	529.05	37.03	566.08
84665-T6A-N72ZD	LINING COMPL.RR.SIDE	1	705.40	25	529.05	37.03	566.08
84640-T6A-003ZA	LINING ASSYRR.PANEL	1	101.60	25	76.20	5.33	81.53
84431-T6A-J01ZA	LINING ASSYTAILGATE LOWER	1	202.20	25	151.65	10.62	162.27
75701-T6A-000	EMBLEMH	1	25.80	25	19.35	1.35	20.70
34150-T6A-003	LIGHT ASSYR.LID	1	378.60	25	283.95	19.88	303.83
34155-T6A-003	LIGHT ASSYL.LID	1	378.60	25	283.95	19.88	303.83
38387-SLE-003	ANTENNA ASSY,L.RR.	1	59.40	25	44.55	3.12	47.67
74940-TR0-003	BUZZER ASSYSMART	1	58.90	25	44.17	3.09	47.26
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00		320.00	22.40	342.40
04715-T6A-900ZZ	FACERR.BUMPER	1	557.20	25	417.90	29.25	447.15
33505-SLJ-013	REFLECTOR ASSYR.RR.	1	44.50	25	33.37	2.34	35.71
33555-SLJ-013	REFLECTOR ASSYL.RR.	1	44.50	25	33.37	2.34	35.71
71502-T6A-003ZK	FACE,R.RR.BUMPER	1	75.30	25	56.47	3.95	60.42
71507-T6A-003ZK	FACE,L.RR.BUMPER	1	75.30	25	56.47	3.95	60.42
71512-T6A-921ZF	SPOILER ASSYR.RR.SIDE	1	111.80	25	83.85	5.87	89.72
71517-T6A-921ZF	SPOILER ASSYL.RR.SIDE	1	111.80	25	83.85	5.87	89.72
71593-T6A-003	SPACERRR.BUMPER SIDE	1	18.70	25	14.02	0.98	15.00
71598-T6A-003	SPACERL.RR.BUMPER SIDE	1	18.70	25	14.02	0.98	15.00
91505-TM8-003	CLIPBUMPER	7	2.00	25	10.50	0.74	11.24
72841-SH3-315	OILSHEET	1	39.90	25	29.92	2.09	32.01
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
	SUM PARTS:				5,146.78	360.25	5,507.03
BOSUN	0672	1	30.00		30.00	2.10	32.10
	SUNDRIES						
BOBC	EXT-YBH	1	100.00		100.00	7.00	107.00
	BODY UNDERSIDE COATING (N)						
BOJSE	0672	1	100.00		100.00	7.00	107.00
	BODY JOINT SEALANT.						

WD=10



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZH023 / SOMPO INSURANCE
Chassis No: JHMRC1890GC205992
License No: SLE9879D
Mileage: 47000
Engine No: K24W72012643

Document No: SVO18024747
Printed By: ARYCHUA
Order Date: 30. April 2018
Order Time: 9:01:37 AM
Service Advisor: ARY CHUA WAI NGEE

BA02R	EXT-YJ REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	140.00	140.00	9.80	149.80
BML02I	EXT-YJ INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)	1	180.00	180.00	12.60	192.60
BP00R	EXT-YBH APPLY BODY UNDERSIDE COATING (N).	1	250.00	250.00	17.50	267.50
BMI03D	EXT-YJ REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES.(N)	1	280.00	280.00	19.60	299.60
BOMISC1	0672 REMOVE & INSTALL REVERSE LANE CAMERA & CALIBRATION	1	300.00	300.00	21.00	321.00
BKOT00R	EXT-YJ REMOVE & RENEW RR FLOOR INSULATOR.(N)	1	300.00	300.00	21.00	321.00
BG02D	EXT-YJ REMOVE & INSTALL RR. WINDSCREEN. (N)	1	300.00	300.00	21.00	321.00
BOMISC1	0672 RESET VEHICLE SMART KEY ACCESS/ENTRY SYSTEM DOORS	1	300.00	300.00	21.00	321.00
BKTG02R	EXT-YJ REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)	1	450.00	450.00	31.50	481.50
BP01R	EXT-YBH SPRAY PAINT ON REPAIRED/REPLACED AREAS.(10PX\$450)	1	2,700.00	2,700.00	189.00	2,889.00
BKRP21M	EXT-YJ CUT OFF & RENEW RR PANEL RR L FENDER. STRAIGHTEN ALIGN RR CHASSIS & RENEW DAMAGE PARTS.	1	3,360.00	3,360.00	235.20	3,595.20
		SUM LABOUR:		8,790.00	615.30	9,405.30
BO-TOW-SW	TOWING SERVICE	1	60.00	60.00	4.20	64.20
		SUM EXT SERVICE:		60.00	4.20	64.20
		TOTAL SGD		13,996.78	979.75	14,976.53

Total Payable (SGD)

14,976.53

GST Amount is calculated from individual line(s)