

ASS. REC. BY:

REF: CS/FCI18007369/Kvbhz

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): CWS Lurene Jaw of FCI Date/Time: 20042018 911am

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLP 2618D Insured: SHB 4677R

at Workshop m/s Optima Werkz Tel: 6484 9919

of 9A Serangoon North Ave 5

Policy No: Claim No: D18002914MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 14042018
(Client's Record)

CA / REV / REP. / REV 24 HRS Wp: H.O.D. Endorsement:

Date/Time: 20042018 919am Person Contacted: RIZA Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLP 2618D - X
	SHB 4677R - NS / ZNC15002556 / H11vb1k3 DUA: 691215
23/4/18	Email pres. revised to FCI
	no BY nam photos ??

Company

REF: FCL

ASSIGNMENT

From: _____ Date: 20042018

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLP 2618D

at Workshop m/s: Optima Westz

of: 9A Serangoon North Ave 5

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

Veh No: SLP 2618D Yr Regn: 05, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toy A909 C.C. 1496

Colour: M.P. white A/C: Insured / Std / NI / NA

Sp. Reading: 65246 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: N14P10 6594693

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: Kapsen R: Dun 175/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

<input checked="" type="checkbox"/>	<input type="checkbox"/>
N/S	O/S

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: B 76k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS W/P

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Front _____ Rear _____

R/Bal. 8 mm R/Bal. 3 mm

L/Bal. 8 mm L/Bal. 3 mm

D.O.A. 14/4/18 D.O.I. 20/4/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S/P

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
23/4	File pass to Catherine
31/5/18	LS \$3450 confirmed by email (Recd 1926.03, 369)

RECEIVED 31 MAY 2018

Date/Time, File Pass to? : Preli. Report

1) : Final Report

Date/Time, File Return to? _____

2) 31/5 - typist

Report Format: CWS

Lump Sum / I.B.I. (\$) 3450/2

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee: 140

Transportation: 50

S + RS: 50

Photos: 24

Others: _____

TOTAL: 264

Add Fee: Site Insp (\$)

Interview (\$)

Tech. Invs (\$)

Weekend (\$)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18002914MFSH

Our ref: CS/FCII8007369/Kvb

Date : 23/4/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLP 2618D


We thank for your instruction on 20/4/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 20/4/2018 at the premises of M/s OPTIMA WERKZ PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$5,376.03
Revised Estimate Amount	: S\$4,341.28
"Check" Items Amount	: S\$125.10
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the n/s front portion.



Comments/Present Status:
Damages Consistent

Yours faithfully,

Kenneth Kong
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	17-04-2018	Our Ref No. D18002914MFSH
Accident Date	14-04-2018	Claim Type. Third Party
Insured Vehicle	SHB4677R	Third Party Vehicle. SLP2618D
Survey Location	6 KUNG CHONG ROAD	
Contact Person.	RIZA	
Contact No.	64849919/ 0	Fax No. 68811011
Survey Type	WITHOUT PREJUDICE: PENDING ID'S VF	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	OPTIMA WERKZ PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 23 April 2018 12:31 PM
To: 'Claim Workflow System'
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18002914MFSH/1, SLP 2618D
Attachments: SLP 2618D PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SLP 2618D
Date of survey: 20/4/2018
Number of days:4 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Friday, 20 April 2018 9:20 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18002914MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 20 April, 2018 9:11 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18002914MFSH/1

Dear Sir/Mdm,

We refer to the above reference.
Please find attached the necessary documents for survey.
Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 31 May 2018 10:32 AM
To: 'Lily Loi'
Cc: OW_Winson; SUR
Subject: RE: Finalise - SLP2618D DOA: 14.04.18 (REF:TP#651)

Dear Lily,

Noted with thanks.

Final invoice and all supporting documents sent over to First Capital Ins Ltd

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Lily Loi [mailto:Lily.Loi@ow.sg]
Sent: Thursday, 31 May 2018 9:56 AM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Cc: OW_Winson <winson@ow.sg>
Subject: Re: Finalise - SLP2618D DOA: 14.04.18 (REF:TP#651)

Hi Veron,

We confirm to accept Lump Sum \$3450 @ 4 working days.

Thanks & Best Regards,

Lily Loi (Ms)
Motor Claims

OPTIMA WERKZ PTE LTD
6 Kung Chong Road Singapore 159143 | Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112 |
9A Serangoon North Avenue 5 Singapore 554500 | Tel: (+65) 6486 9919 | Fax: (+65) 6481
1011 |
551 Upp Thomson Road Singapore 574415 | Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223 |
www.ow.sg
www.facebook.com/optimawerkz

On 30/5/2018 8:29 AM, Veron Chen (LKKAuto) wrote:

Dear Lily,

?

WITHOUT PREJUDICE

?

Offer Lump Sum \$3450 @ 4 working days.

?

Please confirmed.

?

?

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

?

From: Lily Loi [<mailto:Lily.Loi@ow.sg>]

Sent: Monday, 28 May 2018 3:00 PM

To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>

Cc: OW_Winson <winson@ow.sg>

Subject: Re: Finalise - SLP2618D DOA: 14.04.18 (REF:TP#651)

?

Veron Chen,

We have only photos after paint.

?

Thanks & Best Regards,

?

Lily Loi (Ms)

Motor Claims

?

OPTIMA WERKZ PTE LTD

6 Kung Chong Road Singapore 159143 | Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112 |

9A Serangoon North Avenue 5 Singapore 554500 | Tel: (+65) 6486 9919 | Fax: (+65) 6481 1011 |

551 Upp Thomson Road Singapore 574415 | Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223 |

www.ow.sg

www.facebook.com/optimawerkz

On 28/5/2018 12:32 PM, Veron Chen (LKKAuto) wrote:

Dear Lily,

?

Please forward us before paint photos.

?

?

?

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

?

From: Veron Chen (LKKAuto)

Sent: Friday, 18 May 2018 2:33 PM

To: 'Lily Loi' <Lily.Loi@ow.sg>; winson@ow.sg; adeline@ow.sg

Subject: RE: Finalise - SLP2618D DOA: 14.04.18 (REF:TP#651)

?

Dear Lily,

?

Will check and revert.

?

?

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

?

From: Lily Loi [<mailto:Lily.Loi@ow.sg>]

Sent: Friday, 18 May 2018 2:24 PM

To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; winson@ow.sg;
adeline@ow.sg

Subject: Finalise - SLP2618D DOA: 14.04.18 (REF:TP#651)

?

Dear Veron,

Please refer to attach for finalisation -? SLP2618D

Thank you

?

Thanks & Best Regards,

?

Lily Loi (Ms)

Motor Claims

?

OPTIMA WERKZ PTE LTD

6 Kung Chong Road Singapore 159143 | Tel: (+65) 6472 1313 |

Fax: (+65) 6472 2112 |

9A Serangoon North Avenue 5 Singapore 554500 | Tel: (+65) 6486

9919 | Fax: (+65) 6481 1011 |

551 Upp Thomson Road Singapore 574415 | Tel: (+65) 6452 6868 |

Fax: (+65) 6452 9223 |

www.ow.sg

www.facebook.com/optimawerkz

?

----- Forwarded Message -----

Subject:KINDLY ASSIST TO FINALIZE

Date:Fri, 11 May 2018 08:14:07 +0000

From:Veron Chen (LKKAuto) <veronchen@lkkauto.com>

To:riza@ow.sg <riza@ow.sg>, Sharon Peh <sharon@ow.sg>

?

Dear Riza/Sharon,

?

Kindly advise vehicle status.

?

If vehicle has been repaired, please finalize with us.

?

?

? 1.? EF 88G-DOA: 24/1/18 (MSIG OD)

? 2.? SKX 2658H-DOA: 1/1/18 (MSIG OD)

? 3.? SLP 2618D-DOA: 14/4/18 (FCIL TP)

?

?

?

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax:

6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1,

#02-25 | S(408933)

?

?

?

?

Veron Chen (LKKAuto)

From: Lily Loi <Lily.Lo@ow.sg>
Sent: Friday, 18 May 2018 2:24 PM
To: Veron Chen (LKKAuto); winson@ow.sg; adeline@ow.sg
Subject: Finalise - SLP2618D DOA: 14.04.18 (REF:TP#651)
Attachments: SLP2618D - FINALISE.pdf

Dear Veron,

Please refer to attach for finalisation -? SLP2618D

Thank you

Thanks & Best Regards,

Lily Loi (Ms)
Motor Claims

OPTIMA WERKZ PTE LTD
6 Kung Chong Road Singapore 159143 | Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112 |
9A Serangoon North Avenue 5 Singapore 554500 | Tel: (+65) 6486 9919 | Fax: (+65) 6481
1011 |
551 Upp Thomson Road Singapore 574415 | Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223 |
www.ow.sg
www.facebook.com/optimawerkz

----- Forwarded Message -----

Subject:KINDLY ASSIST TO FINALIZE
Date:Fri, 11 May 2018 08:14:07 +0000
From:Veron Chen (LKKAuto) <veronchen@lkkauto.com>
To:riza@ow.sg <riza@ow.sg>, Sharon Peh <sharon@ow.sg>

Dear Riza/Sharon,

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

1. EF 88G-DOA: 24/1/18 (MSIG OD)
2. SKX 2658H-DOA: 1/1/18 (MSIG OD)
3. SLP 2618D-DOA: 14/4/18 (FCIL TP)

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date:	17 April 2018	Third Party Insurer:	FIRST CAPITAL
Vehicle No:	SLP2618D	Third Party Veh No:	SHB4677R
Model:	TOYOTA AQUA HYBRID 1.5S	Date of Accident:	14/04/2018
Chassis:	NHP10-6594693		

ESTIMATE

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$	
1	FRONT BUMPER		<i>Per</i> \$1,124.50	✓
1	FRONT BUMPER SIGNAL LAMP LH		<i>Per</i> \$185.70	✓
1	FRONT BUMPER FOG LAMP COVER LH		<i>Per</i> \$81.20	✓
1	FRONT BUMPER LOWER RUBBER MOULDING		<i>SVL</i> \$166.80	7X
1	FRONT BUMPER SIDE RETAINER LH		<i>Per</i> \$115.20	✓
8	FRONT BUMPER CLIP	\$6.50	<i>Per</i> \$52.00	✓
1	FRONT BUMPER TOP RUBBER SEAL 'STICK ON'		<i>Per</i> \$28.90	✓
3	FRONT BUMPER TOP RUBBER SEAL CLIP	\$5.50	<i>Per</i> \$16.50	X
1	FRONT FENDER LH		<i>Per</i> \$609.70	X
1	FRONT FENDER HYBRID EMBLEM LH		<i>Per</i> \$89.20	✓
1	FRONT HEADLAMP LH		<i>Per</i> \$2,965.00	✓
SUB TOTAL			\$5,434.70	
Less 25%			-\$1,358.68	
PARTS TOTAL			\$4,076.03	

LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION	\$600.00	<i>400</i>
TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION	\$600.00	<i>400</i>
TO TUFF KOTE / ANTI-RUST	<i>Per</i> \$40.00	X
TO CHECK WIRING, REPLACED WITH FOCUS HEADLAMP & WATER LEAKAGE TEST	\$60.00	<i>20</i>

LABOUR TOTAL \$1,300.00

WINSON TOTAL \$5,376.03

LK Auto Consultants hence notify the Reparer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Reparer

Signature: _____

Date: _____

*Not withered
L1 Lamp & ?
Resurvey After Paint
4 days*

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date:	17 April 2018	Third Party Insurer:	FIRST CAPITAL
Vehicle No:	SLP2618D	Third Party Veh No:	SHB4677R
Model:	TOYOTA AQUA HYBRID 1.5S	Date of Accident:	14/04/2018
Chassis:	NHP10-6594693		

ESTIMATE

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$	
1	FRONT BUMPER		<i>Am</i> \$1,124.50	✓
1	FRONT BUMPER SIGNAL LAMP LH		<i>Sm</i> \$185.70	✓
1	FRONT BUMPER FOG LAMP COVER LH		<i>Am</i> \$81.20	✓
1	FRONT BUMPER LOWER RUBBER MOULDING		<i>Sm</i> \$166.80	7X
1	FRONT BUMPER SIDE RETAINER LH		<i>D11</i> \$115.20	✓
8	FRONT BUMPER CLIP	\$6.50	<i>Am</i> \$52.00	✓
1	FRONT BUMPER TOP RUBBER SEAL 'STICK ON'		<i>Am</i> \$28.90	✓
3	FRONT BUMPER TOP RUBBER SEAL CLIP	\$5.50	<i>Am</i> \$16.50	X
1	FRONT FENDER LH		<i>R</i> \$609.70	X
1	FRONT FENDER HYBRID EMBLEM LH		<i>Am</i> \$89.20	✓
1	FRONT HEADLAMP LH		<i>Am</i> \$2,965.00	✓
SUB TOTAL			\$5,434.70	4641.70 ✓
Less 25%			-\$1,358.68	1160.42 ✓
PARTS TOTAL			\$4,076.03	3481.28 ✓

LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION	\$600.00	<i>400</i>
TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION	\$600.00	<i>480</i>
TO TUFF KOTE / ANTI-RUST	<i>Am</i> \$40.00	X
TO CHECK WIRING, REPLACED WITH FOCUS HEADLAMP & WATER LEAKAGE TEST	\$60.00	<i>20</i>
LABOUR TOTAL	\$1,300.00	<i>860.00</i>

WINSON	TOTAL	\$5,376.03
--------	-------	------------

*Not withered
L1 Pump & ?
Assembly After Paint
4 days*

*P- 3481.28
L- 860
4,341.28 P/P*



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18007369/Kvbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 31-05-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHB 4677R	Veh. Inspected	SLP 2618D
Policy No.		Coverage (\$)	0.00
Claim No.	D18002914MFSH	Excess (\$)	0.00
Assign From	LURENE	Assign Date	20/04/2018
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA AQUA (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	NHP106594693	Colour	METALLIC PEARL WHITE
Odometer	65246	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	175/65 R15	KAPSEN	8 mm
L/H Front Tyre	175/65 R15	KAPSEN	8 mm
R/H Rear Tyre	175/65 R15	DUNLOP	3 mm
L/H Rear Tyre	175/65 R15	DUNLOP	3 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	14/04/2018	Inspection Date	20/04/2018
Survey held at	OPTIMA WERKZ PTE LTD 9A SERANGOON NORTH AVE 5 SINGAPORE 554500		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLP 2618D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	BUCKLED	1,124.50	1,124.50
1	FRONT BUMPER SIGNAL LAMP LH	SCRATCHED	185.70	185.70
1	FRONT BUMPER FOG LAMP COVER LH	CUT	81.20	81.20
1	FRONT BUMPER LOWER RUBBER MOULDING	SERVICEABLE	166.80	-
1	FRONT BUMPER SIDE RETAINER LH	DISTORTED	115.20	115.20
8	FRONT BUMPER CLIP @\$6.50	NECESSARY	52.00	52.00
1	FRONT BUMPER TOP RUBBER SEAL "STICK ON"	NECESSARY	28.90	28.90
3	FRONT BUMPER TOP RUBBER SEAL CLIP @\$5.50	NOT NECESSARY	16.50	-
1	FRONT FENDER LH	TO REPAIR SEE LABOUR	609.70	-
1	FRONT FENDER HYBRID EMBLEM LH	NECESSARY	89.20	89.20
1	FRONT HEADLAMP LH	CUT	2,965.00	2,965.00
	LESS 25% DISCOUNT		-1,358.67	-1,160.43
			4,076.03	3,481.27
LABOUR				
	TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION. INCLUSIVE OF THE REPAIR OF FRONT FENDER LH.		600.00	400.00
	TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION.		600.00	440.00
	TO TUFF KOTE/ANTI-RUST.	NOT NECESSARY	40.00	-
	TO CHECK WIRING. REPLACED WITH FOCUS HEADLAMP & WATER LEAKAGE TEST.		60.00	20.00
			1,300.00	860.00
GRAND TOTAL			5,376.03	4,341.27
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,450.00

Report Ref No. CS/FCI18007369/Kvbn2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.