



FALCON-AIR

WYSA CARS
194 WESTWOOD AVE #08-30
WESTWOOD RESIDENCES SINGAPORE 648152

Attention : Motor Claim Department
Contact : 98183836

Estimate : ES003160

Date : 20/04/2018
Vehicle Num. : SLQ9887S
Make/Model : HONDA JAZZ
Chassis/Eng# : JHMGK5850FX202582
Accident Date : 19/04/2018
Claim No. :
Reference : TP NTUC VS AXA
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	TAILGATE		814.00
2.	1	TAILGATE GLASS		625.60
3.	1	TAILGATE GLASS MOULDING		95.00
4.	1	TAILGATE LOCK		157.10
5.	1	TAILGATE WEATHERSTRIP		92.30
6.	1	TAILGATE CHROME		193.80
7.	1	TAILGATE EMBLEM 'JAZZ'		33.00
8.	1	TAILGATE INNER TRIM BOARD		62.10
9.	2	TAILLAMP LH/RH	214.70	429.40
10.	2	TAILGATE GARNISH	97.80	195.60
11.	2	REAR FENDER TRIMBOARD	165.60	331.20
12.	1	REAR END PANEL		314.00
13.	1	REAR END PANEL TOP GARNISH		60.80
14.	1	SPARE TYRE PANEL BOARD		186.00
15.	1	REAR BUMPER		492.60
16.	2	REAR BUMPER SIDE RETAINER LH/RH	13.00	26.00
17.	1	SPARE TYRE PANEL		697.00
18.	1	REAR BUMPER GARNISH		18.00
19.	1	EXHAUST HEAT SHIELD		16.00
20.	1	BONNET		527.00
21.	1	REAR TOP CARGO TRAY		203.50
22.	1	TOOLS COMPARTMENT/ SPONGE		101.65

CONTINUE / ...

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 ■ No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg **E-mail:** email@falconair.com.sg



FALCON-AIR

FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D

WYSA CARS
194 WESTWOOD AVE #08-30
WESTWOOD RESIDENCES SINGAPORE 648152

Attention : Motor Claim Department

Contact : 98183836

Estimate : ES003160

Date : 20/04/2018
Vehicle Num. : SLQ9887S
Make/Model : HONDA JAZZ
Chassis/Eng# : JHMGK5850FX202582
Accident Date : 19/04/2018
Claim No. :
Reference : TP NTUC VS AXA
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
23.	2	BONNET HINGES LH/RH	24.90	49.80
24.	2	HEADLAMP	1,118.60	2,237.20
25.	1	RADIATOR SUPPORT PANEL		374.30
26.	1	RADIATOR		1,187.40
27.	1	AIRCON CONDENSER		704.40
28.	1	BONNET LOCK		99.70
29.	2	HEADLAMP LOWER BRACKET LH/RH	24.00	48.00
30.	1	FRONT GRILLE ASSY		288.90
31.	1	FRONT BUMPER		494.70
32.	2	FRONT BUMPER SIDE RETAINER	11.00	22.00
33.	1	FRONT BUMPER REINFORCEMENT		219.40
34.	1	FRONT BUMPER LOWER GRILLE CENTRE		27.50
35.	2	FOG LAMP GARNISH	23.30	46.60
36.	1	FRONT NUMBER PLATE BASE		50.90
37.	2	REAR FENDER	659.30	1,318.60
38.	2	TAILLAMP PANEL LH/RH	95.30	190.60
List TotalS\$:				13,031.65
20.00% Discount S\$:				2,606.33
				10,425.32
1.	3	SPECIAL NETT ITEMS : SEALANT	40.00	120.00

CONTINUE / ...

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 ■ No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg **E-mail:** email@falconair.com.sg



FALCON-AIR

FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D

WYSA CARS
194 WESTWOOD AVE #08-30
WESTWOOD RESIDENCES SINGAPORE 648152

Attention : Motor Claim Department

Contact : 98183836

Estimate : ES003160

Date : 20/04/2018
Vehicle Num. : SLQ9887S
Make/Model : HONDA JAZZ
Chassis/Eng# : JHMGK5850FX202582
Accident Date : 19/04/2018
Claim No. :
Reference : TP NTUC VS AXA
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
2.	1	REVERSE SENSOR (4PCS)		300.00
3.	1	REAR CAMERA, CONNECTION WIRES & INSTALLATION		600.00
4.	1	FRONT NUMBER PLATE		45.00
5.	20	ASSORTED CLIPS	3.00	60.00

Special Nett Total S\$: 1,125.00

LABOUR :	
TOWING CHARGE	70.00
TO REMOVE/REPLACE AIRCON CONDENSER VACUUM & REGAS	120.00
TO FOCUS HEADLAMP / CHECK LIGHT SYSTEM	30.00
TO TRANSFER TAILGATE PARTS/MECHANISM	50.00
TO REMOVE/REPLACE REAR WINDSCREEN GLASS	120.00
TO REMOVE/REFIX CUSHION SEAT, CARPET, GARNISH, WIRING	150.00
TO RUSTPROOF ON ACCIDENT DAMAGE AREAS	150.00
TO REALIGN EXHAUST BOX / PIPE	80.00
TO REMOVE / REPLACE REVERSE SENSOR/ CAMERA CHECK WIRING	120.00
SPRAY PAINTING FRONT PORTION	800.00
TO CUT/OUT REWELD RADIATOR SUPPORT PANEL, REPAIR FRONT CHASSIS, FRONT FENDERS LH/RH INCLUDES KNOCKING & REPLACEMENT OF PARTS	750.00
SPRAY PAINTING REAR ACCIDENT DAMAGED AREAS	1,600.00
TO REMOVE/REFIX PETROL TANK TO FACILITATE THE REPAIRS	80.00
TO CUT/OUT REWELD REAR END PANEL, SPARE TYRE PANEL,	

CONTINUE / ...

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg **E-mail:** email@falconair.com.sg



FALCON-AIR

WYSA CARS

194 WESTWOOD AVE #08-30

WESTWOOD RESIDENCES SINGAPORE 648152

Attention : Motor Claim Department

Contact : 98183836

FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D

GST REG. NO.: 19-9501140-D

Estimate : ES003160

Date : 20/04/2018

Vehicle Num. : SLQ9887S

Make/Model : HONDA JAZZ

Chassis/Eng# : JHMGK5850FX202582

Accident Date : 19/04/2018

Claim No. :

Reference : TP NTUC VS AXA

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		REAR FENDER RH/LH , TAIL LAMP PANEL, REPAIR FLOORBOARD		
		REAR CHASSIS INCLUDES KNOCKING & REPLACEMENT OF PARTS		1,800.00
		TO REMOVE/ REFIX REAR FENDER GLASS \$80 X2		160.00
		Labour Total S\$:		6,080.00

E. & O.E.

Total S\$: 17,630.32

=====

for FALCON AIR AUTO SERVICES PTE LTD



FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 ■ No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1111

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg



RECORDS MANAGEMENT CENTRE

GENERAL INSURANCE ASSOCIATION OF SINGAPORE

RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-059522

Date of Request: 19/04/2018

Your Ref No:

Online Purchase

Falcon-Air Auto Services Pte Ltd
176 Sin Ming Drive #01-06
Sin Ming Autocare
Singapore 575721

Dear Sir/Madam,

Enquiry Date 19/04/2018

Enquiry By Francis Ng

TP Vehicle No. SKE2530S

Accident Date 19/04/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SKE2530S	AXA Insurance Pte Ltd	20/02/2018-19/02/2019	6338 7288

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.