

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Catherine Thia Shi Yi

Date: 30 Apr 2018

Preliminary Advice

Insured Vehicle No	: SJP7026C		
TP Vehicle No	: SJR6883R	Accident Date	: 28/03/2018
Make	: TOYOTA VIOS EA	Assignment Date	: 23/04/2018
Date of Inspection	: 25/04/2018	Est. Duration of Repair	: 3 days
Inspection At	: Borneo Motors (singapore) Pte Ltd - (pandan) (HQ) Toyota Bodycare Centre, No. 2 Pandan Crescent Singapore 128462		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,341.30
Revised Amount	:S\$	2,814.90
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,814.90

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.