ASS. REC. B	č: I	REF: CS/ASMI	8007455 /Tle	d307 Special Instruction	on:	
Surveyor :	Tauskh		MENT (Office)			
From (Person	DE Richard Ana	of	ASM	Date/Time	23042018	253 pm
Estimated Co	ost;		Bill to:			
To Inspect V	STTP RES / OD RES	/EVA/INV/MV P 6077J	7 CS	Insured:		
at Workshop	m/s			Tel: 4755	7336	
of	29 Tai	ijong Penjuru				
Policy No:		9 7 1.9	Claim No:	98M00E44		
Sum Insured			Excess:	A CIM IN		
Make of Veh (Client's Recor				D.O.A	16042018	
CA / REV	/ REP. / REV 24 HR	S 24	81 OC P	H.O.D. En	dorsement:	
Date/Time:	23042018 5.16pm	_ Person Contacte	d: Lewei	Vehicle (IN)	TUCL	
Date/Time	Action/Instruction (/) Estima	te			
	X- [FF1099]					
25/4/18	Perent thm sn	nart - claim.				
	Authorise repair	and inform	Le Wei thru	email.		
		, ,				
				_		

1 55

	REF: ASM			
smurt claim	AS	SIGNMENT		
From:	Date: 34047018	Veh No: YPG0775 Type: M.Car / M.Cycle / Bus / Van /	Yr Regn: 20/7/ W	fail.
Estimated Cost:		Truck / Trailer or	Edity / Taxi / Time meter /	
DD) TP / WS / TP RES / O	CFFOD 9Y		w FEB71c.c 29	90
To Inspect Vehicle No:		. 1. 40	A/C: Insured / Std / NI /	
at Workshop m/s	Goldbell	Sp.Reading 77448		
of	of Tunjong Penjuru		made made at a carrier	
Insured:		Eng/No: FER 7/E	A 20393.	
Policy No.		Gen. Cond: Good / Fair / Poor / Bu		
Claims No.	- h 200 000	- X		
Sum Insured:	Excess: 4800.00	Brake: Inorder / Jammed / Leak		
(Client's Record)	Lewer - 9765 7336	0		
Make of Veh:	acci cell ism's	Modi: Nij / S/Rim / STD A/Rim	-125812-	
(Policy Condition)		Tyre Size: F: 21	5/75KIZ-5	
Remark: The veh had con repair at the tim		Do i Doill Britte III I I I I I I I	ZAIMICIOHTSUIPIRISUMII	
Bal. or Market Value:	990K.	Front	Rear (//	
IDAC Accident Rport:	Consistent? : Yes or No	R/Bal. 6 mm	R/Bal.	mm
GIA / PR Seen:	Consistent? : Yes or No	L/Bal. 6 mm	L/Bal. 6/~	mm
Est. Repairs:	days Res.: Yes or No	D.O.A.	D.O.I. 24 4 18	2150
Lum Sum:	% 3 Val.: Yes or No	Survey held at	bell to Renjum	
CA LAND LABOR L	24 HRS	Des. of Damages : Frt Rear / O	S / N/S / U/C / Rooftop or	
Date: Per	Vehicle: IN / O		ody Structure affected due to coll	lision.
Date / Time Action /	Instruction			
6/5/19 \$/0	8,149.14 ,8dgs -	evoil to Resurs	(Red. 4492,24, 30%)
	O			
	-			
Date/Time, File Pass to?	: Preli. Report	Days Of Repair:		
1)	: Final Report	Resurvey No. of Trip: 3	Survey Fee: 250	
Date/Time, File Return to?			Transportation:	

Date/Time, File Pass to?	: Preli. Report	Day	s Of Repair:		
1)	: Final Report	Res	urvey No. of Trip: 3	Survey Fee:	250
Date/Time, File Return to?				Transportation:	
2)		Add Fee:	: Site Insp (\$)S+RSSI	
•			: Interview (\$) Photos	
Report Format :	0.0		: Tech. Invs (\$) Others	
Lump Sum / I(B.I) (\$))	
	10 11 (1)	-		TOTAL	250

Celine Fong (LKKAuto)

From:

Ramesh < Ramesh@goldbell.com.sg >

Sent:

Wednesday, 8 May 2019 12:33 PM

To:

Taufikh (LKKAuto)

Cc:

Celine Fong (LKKAuto)

Subject:

RE: 2nd email YP6077J (AXA Own Damage Claim) DOA 16/4/2018 - before repair photos

Dear Taufikh,

We accepted your offer COR \$10,149.14 - 8 days.

Thank you.

Ramesh | Goldbell Engineering Pte Ltd ×

Senior Executive, Motor Claims

DID: +65 6864 0695 | Tel: +65 6861 0007 | Fax: +65 6863 0425 |

Mobile: +65 8157 8014 | Web: http://www.goldbell.com.sg

Address: Goldbell Engineering Pte Ltd (Tuas)

¹8 Tuas Ave 18 Singapore 638894

From: Taufikh (LKKAuto) [mailto:Taufikh@lkkauto.com]

Sent: Monday, May 6, 2019 12:10 PM To: Ramesh < Ramesh@goldbell.com.sg>

Cc: Celine Fong (LKKAuto) <celinefong@lkkauto.com>

Subject: RE: 2nd email YP6077J (AXA Own Damage Claim) DOA 16/4/2018 - before repair photos

Hi Ramesh,

COR \$10,149.14, 8 days.

Regards Taufikh

Lkk Auto

From: Ramesh [mailto:Ramesh@goldbell.com.sg]

Sent: Friday, 3 May 2019 4:03 PM

To: 'Taufikh (LKKAuto)'

Subject: 2nd email YP6077J (AXA Own Damage Claim) DOA 16/4/2018 - before repair photos

Before paint photos.

Bro

That's all we have.

Please help to suggest an amount.

We can help each other to work out an amount.

Thanks.



Re: IA UPLOADED

Type

Q Question

Message

Hi Jannice, please proceed to authorise repairs. Thank you.

Reply

Janice Lee (LKKAuto)

From:

Janice Lee (LKKAuto)

Sent:

Thursday, April 26, 2018 5:41 PM

To:

Li Lewei

Cc:

Ashlyn Chng; Derek Chow Zhi Da; SUR

Subject:

YP 6077J AXA OD DOA: 16.04.2018

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle YP 6077J (excess \$800/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>janicelee@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Menu



Service Request Details

Claim

S8M00E44

Reference

None 🧳

Loss Date

April 16, 2018

Request Date

April 23, 2018

Due Date

April 30, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated workshop survey

Actions Next Step Agree to perform service Decline Work Accept Work

Vehicle Information

Incident Vehicle Registration #

YP6077J

Make

MITSUBISHI

Menu

Service Address

51 Ubi Avenue 1 #01-25 Paya Ubi, , , 408933

Primary Contact/Insured

GREATSOLUTIONS PTE LTD 8 LOYANG WAY 4, 507604, Singapore 66942668 xiuling.xian@greatsolutions.com.sg

Claim Handler

ANG Richard

richard.angbs@axa.com.sg

Additional Instructions

Excess - \$800

Messages Invoices History Documents Assessment Metrics Notes

New Message



 $51\ UBI\ AVE\ 1,\#01-25\ PAYA\ UBI\ INDUSTRIAL\ PARK, SINGAPORE\ 408933\ \ TEL: (065)\ 62563561\ \ FAX: (065)\ 62564315$

Immediate Advice

Date: 25/04/2018

To: AXA Insurance Pte Ltd

Survey details

Date of loss	16.04.2018	
Date of appointment	24.04.2018	
Date of survey	24.04.2018	
Location of survey	Goldbell Engineering	

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	YP 6077J
Make and Model	Mitsubishi Canter FEB71ER4SDEC
Date of registration	06-Apr-17
Excess	\$800.00
Market Value	\$90,000.00
Parf Rebate	\$43,840.00
Nett Loss	\$46,160.00

Repair details

Initial Estimate	\$14,641.38

Proposed/Revised repair cost:

Revised Estimate Amount	\$8,295.90
"Check" item (Estimated)	\$2,803.08
Total Repair (Estimated)	\$11,098.98
Lump Sum(if applicable)	\$

Number of days of repair	8

Remarks:

The vehicle sustained damages at the front portion

Damages consistent Repair cost economical

We have not authorise repair.

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company	
Owner ID:	3793H	
Vehicle Details	3,7011	
Vehicle No.:	YP6077J	
Vehicle to be	No	
Exported:		
Intended De-	25 Apr 2018	
registration Date:		
Vehicle Make:	MITSUBISHI	
Vehicle Model:	CANTER	
	FEB71ER4SDEC	
	(CBU)	
Primary Colour:	White	
Manufacturing Year:	2016	
Engine No.:	4P10C49317	
Chassis No.:	FEB71EA20393	
Maximum Power	-	
Output:		
Open Market Value:	\$37,264.00	
Original Registration	06 Apr 2017	
Date:		
First Registration	06 Apr 2017	
Date:		
Transfer Count:	0	
Actual ARF Paid:	\$1,864.00	
Intended PARF Rebate	Details	
PARF Eligibility:	No	
PARF Eligibility Expiry	•	
Date:		
PARF Rebate Amount:	\$0.00	
Intended COE Rebate I	Details	
COE Expiry Date:	05 Apr 2027	
COE Category:	C - Goods Vehicle &	
	Bus	
COE Period(Years):	10	
QP Paid:	\$49,002.00	
COE Rebate Amount:	\$43,840.00	
Total Rebate Amount:	\$43,840.00	

The information contained herein is correct as at 25 Apr 2018

REPUBLIC OF SINGAPORE IDENTITY CARD NO. \$1622853B



Name

ZAINUDIN BIN ABDUL RAHMAN


زينودين بن ابدول رامن

MALAY Date of birth

16-12-1963 M

8 16 Z2B530

Country of birth SINGAPORE



4366993



NRIC No. S1622853B



10-03-2009

APT BLK 815 TAMPINES AVENUE 4 #05-235

SINGAPORE 520815

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE 01 Feb 1983

Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

Heavy Motor Cars and Motor Tractors the Class 4

13 May 1985 weight of which unladen exceeds 2500 kilograms 05 Sep 1985

Motor Vehicles which are not constructed themselves to carry any load and the weight Class 5

of which unladen exceeds 7250 kilograms

Licence No: \$1622853B

NP 428A

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

aforesaid.	
	ACCIDENT STATEMENT
Date Of Report	16/04/2018 12:08
Date Of Accident	16/04/2018 08:40
Exact Location Of Accident	ALONG LENTOR AVE TOWARDS YISHUN
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	YP6077J
Insured/Policyholder	
Name Of Registered Owner	GREATSOLUTIONS PTE LTD
Co Reg No	201203793H
Email Address	ENQUIRIES@GREATSOLUTIONS.COM.SG
Mobile Phone No	(LOCAL) +65-97354194
Alternative Phone No	OFFICE-66942668
Vehicle Particulars	
Manufacturer	MITSUBISHI
Model	FEB71ER4SDEC CBU MT
Exact Purpose for which vehicle was being used at time of accident	WORK
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number VCA/P1920367

Cover Note Number

Driver

Name of Driver ZAINUDIN BIN ABDUL

 NRIC No
 \$1622853B

 Date Of Birth
 16/12/1963

 Occupation
 OUTDOOR

 Date Of Driving Pass
 01/02/1983

Driving Experience 35 YEARS AND 2 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-97354194

Fax Number Contact Number

EMail Address NOEMAIL

Address

BLK 815 TAMPINES AVENUE 4 #05-235

Postcode .

520815

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

NO

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

2

Passenger 1

NAME:

: ABDUL RAZAK

GENDER:

: MALE

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

ON 16/04/2018 AT ABOUT 0840HRS, I WAS DRIVING VEHICLE 'A' (YP6077J) ALONG LENTOR AVE TOWARDS YISHUN, AS I WAS APPROACHING THE TRAFFIC LIGHT UNDER SLE BRIDGE, THERE WAS VEHICLE 'B' (GBG1947B) STOPPPING AT THE TRAFFIC LIGHT. I COULD NOT STOP MY VEHICLE IN TIME, HENCE I HIT ONTO 'B'. NO ONE WAS INJURED.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

GBG1947B

Vehicle Make/Model/Colour

TOYOTA DYNA

Details Of Properties

REAR

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

LIM CHEW

NRIC/Passport Number

S7912454J

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's S gnature

Date & Time:

Driver's Signature (If driver is not the policyholder)

Date & Time:

16/04/2018

Reporting Centre Personnel's Signature

Name: Lile Wen

NRIC/FIN NO .: S9324217]

GIARIAC SkotchPlanForm VI

OLDA



Industrial Vehicles. 20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 18 Singapore 638894 Tel +65 6861 0007 Fax +65 6861 3676 (Sales) Fax +65 6863 0425 (Service) +65 6862 1347 (Parts) Website: www.goldbell.com.sg Co Reg No. 198003963G

> Page 1 / 2

ESTIMATE

Date : 23/04/2018

To AXA INSURANCE SINGAPORE PTE LTD

Attn.

Office / Mobile

Email Address

From

Attn. Office / Mobile

: +65 6864 0637

Email / Fax No.

: LILEWEI

: LiLewei@goldbell.com.sg

: GOLDBELL ENGINEERING PTE LTD

Reg No

YP6077J

Model

FEB71ER4SDEC CBU MT

Chassis No

FEB71EA20393 4P10C49317

Engine No

D.O.P.

Ref. No.

: GBE/SVC/SALES-4623/180418 16/04/2018

D.O.A. Policy No. Claim Type

: VCA/P1920367

OD CLAIM

Workshop 29 TANJONG PENJURU

S/N	Part No	Description	Oty	U/Price	%	Net Price	Ext Price
1	MC978516	BUMPER ASSY, FRONT	1	929.76	-25	697.32	697.3265
2	MK618527	COVER,FR BMPR CORNER,RH	1	325.54	-25	244.16	244.16 7/44
3	MK618521	COVER, FR BMPR CORNER, LH	1	325.54	-25	244.16	244.16× 44
4	MK618510	STAY,FR BUMPER,LH	1	186.95	-25	140.21	140.21 bt
5	MK618511	STAY,FR BUMPER,RH	1	186.95	-25	140.21	140.21 ht
6	MC978571	GRILLE, RADIATOR	1	1,053.14	-25	789.86	789.86EN
7	MK614805	BRKT,FR GRILLE	1	24.96	-25	18.72	18.72 67
8	MK707621	PANEL, FRONT	1	1,069.13	-25	801.85	801.85 ht
9	MK580551	HEADLAMP L	1	461.45	-25	346.09	346.09 ove
10	MK580552	HEADLAMP (1	461.45	-25	346.09	346.09
11	MK580527	SIGNAL LAMP ASSY -LH	1	245.15	-25	183.86	183.86 500-
12	MK580528	SIGNAL LAMP ASSY -RH	1	245.15	-25	183.86	183.86
13	MK580530	GARNISH, HEADLAMP RH	1	211.96	-25	158.97	158.97 au
14	MX929408	HORN / R70 12V HIGH TONE73	1	92.77	-25	69.58	69.58 61
15	ML223091	COVER,HORN	1	31.46	-25	23.60	23.60 41-
16	ML219850	C/MBR ASSY,FR.FLOOR	1	453.57	-25	340.18	340.1861
17	MK622456	BRKT,CAB HINGE	1	879.38	-25	659.54	659.5461-
18	MK622457	BRKT,CAB HINGE	1	784.36	-25	588.27	588.2761
19	MK622472	BUSH	1	17.53	-25	13.15	13.15 de
20	MK622528	RUBBER ASSY,FR.CAB MTG	1	211.89	-25	158.92	158.92 de
21	MK622765	BAR, TORSION	1	571.71	-25	428.78	428.78 66-
22	MK583365	HEATER UNIT	1	2,337.68	-25	1,753.26	1.753.26 X WY
23	MK583357	BOX,AIR INTAKE	1	829.06	-25	621.80	621 80 × nn
24	MK654863	HOSE, HEATER WATER	1	22.08	-25	16.56	16 5657
25	MK450980	HOSE, HEATER WATER	1	19.99	-25	14.99	14 99 5/
26	MK377925	PIPE ASSY, HEATER WATER	1	70.24	-25	52.68	52.68 h1
27	MK623518	HOSE, SUCTION	1	435.69	-25	326.77	326.77 64
28	MK589130	CLAMP,PIPE	1	10.59	-25	7.94	7.94 ans
			PARTS	TOTAL:			9,371.38

SPECIAL NETT ITEMS

1

FRONT LICENSE PLATE

1

20.00 b

PARTS TOTAL:

20.00









Industrial Vehicles 20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 18 Singapore 538894 Tel +65 6861 0007 Fax +65 6861 3676 (Sales) Fax. +65 6863 0425 (Service) +65 6862 1347 (Parts) Website: www.goldbell.com.sg Co Reg No. 198003963G

> Page 2 / 2

ESTIMATE

Date : 23/04/2018

AXA INSURANCE SINGAPORE PTE LTD

: GOLDBELL ENGINEERING PTE LTD

Attn.

To

Office / Mobile

Email Address

From Attn.

Office / Mobile

Email / Fax No.

LILEWEI : +65 6864 0637

: LiLewei@goldbell.com.sg

Reg No

YP6077J

Model Chassis No FEB71ER4SDEC CBU MT

Engine No

FEB71EA20393 4P10C49317

D.O.P.

Ref. No.

D.O.A. 16/04/2018

Policy No. Claim Type VCA/P1920367 OD CLAIM

Workshop

29 TANJONG PENJURU

GBE/SVC/SALES-4623/180418

2400 LABOUR CHARGES TO REMOVE AND REFIX DAMAGED 3600.00 1 PARTS, CUT, WELD, PANEL BEAT, 150. STRAIGHTEN & REALIGN, ETC. 2 TO CHECK AND RECTIFY WIRING 200.00 FAULTS, TO CARRY OUT DIAGNOSTICS 1225 CHECK 3 TO PUTTY, CLEAN, SPRAY PAINT & 3,50 1400.00 POLISH, ETC. 30 4 SUNDRIES 50.00

LABOUR TOTAL:

5,250.00

SUB-TOTAL:

14,641.38

GST @ 7% for \$ 14,641.38

1,024.90

GRAND TOTAL (S\$):

15,666.28

PREPARED BY: LILEWEI

DATE / TIME :

SURVEYOR :

MOBILE NO : OFFICE FAX NO:

EMAIL ADDRESS :

EXCESS AMOUNT:

REPAIR TYPE :

AUTHORISATION:

RE-SURVEY: NO. OF DAYS :

REMARKS :

PART-BY-PART / LUMPSUM

AUTHORISED / NOT AUTHORISED

BEFORE PAINT /

Sur P Wantown

TER PAINT

LKK Auto Consultants hence notify the Repairer of the following: . To resurvey before/after spray painting

- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:







D	_	FINALISATIO	N REPORT				
Date	:	02/04/2019	Reg No	:	YP6077	7)	
То	:	AXA INSURANCE SINGAPORE PTE LTD	Model	:	FEB718	ER4SDEC CBI	J MT
Attn.	:		Chassis No	:	FEB71E	EA20393	
Office / Mobile	:		Engine No	:	4P10C4	49317	
Email Address	:		Quotation	No. :	60373		
			Ref. No.	:	GBE/S\	/C/SALES-46	23/180418
From	:	GOLDBELL ENGINEERING PTE LTD	0.04		16/04/	2010	
Attn.	:	RAMESH	D.O.A.	:	16/04/		
Office / Mobile	:		Policy No.	:	0	.920367	
Email / Fax No.			Claim Type		OD CLA		
			Workshop	:	8 TUAS	AVE 18	
S/N Part No		Description	Oty	U/Price	%	Net Price	Ext Price
1 MC978516		BUMPER, FR	1	929.76		697.32	697.32
2 MK618510	1	STAY,FR BUMPER -LH	1	186.95	-25	140.21	140.21
3 MK618511		STAY,FR BUMPER -RH	1	186.95		140.21	140.21
4 MC978571		GRILLE, RADIATOR	1	1,053.14		789.86	789.86
5 MK614805	ĺ	BRKT, RADIATOR GRILLE -CTR	1	24.96		18.72	18.72
6 MK707621		PANEL, FRONT	1	1,069.13		801.85	801.85
7 MK580551		HEADLAMP ASSY -LH	1	461.45		346.09	346.09
8 MK580552		HEADLAMP ASSY -RH	1	461.45		346.09	346.09
9 MK580528		LAMP ASSY, TURN SIGNAL, FR -RH	1	245.15		183.86	
10 MK580530		GARNISH, HEADLAMP -RH	1	211.96		158.97	183.86
11 MX929408		HORN / R70 12V HIGH TONE73	1	92.77			158.97
12 ML223091		COVER,HORN	1	31.46		69.58	69.58
13 ML219850		C/MBR ASSY,FR.FLOOR	1			23.60	23.60
14 MK622456		BRKT,CAB HINGE		453.57		340.18	340.18
15 MK622457		BRKT,CAB HINGE	1	879.38		659.54	659.54
16 MK622472		BUSH	1	784.36		588.27	588.27
17 MK622528		RUBBER ASSY,FR.CAB MTG	1	17.53		13.15	13.15
18 MK622765		BAR, TORSION	1	211.89		158.92	158.92
19 MK654863		HOSE, HEATER WATER	1	571.71		428.78	428.78
20 MK450980			1	22.08		16.56	16.56
21 MK377925		HOSE, HEATER WATER	1	19.99	0.0000000000000000000000000000000000000	14.99	14.99
		PIPE ASSY, HEATER WATER	1	70.24		52.68	52.68
22 MK623518 23 MK589130		HOSE, A/C PIPING,NO.3	1	435.69	-25	326.77	326.77
23 MK203130		CLAMP,PIPE	1	10.59	-25	7.94	7.94
			DARTO	TOTAL	-		
SPECIAL NETT	ITE	us.	PARTS	TOTAL:	-		6,324.14
1		FRONT LICENSE PLATE					
-		THOM ELECTIVE PEATE	1				20.00
			PARTS TO	ται .	_		20.00
LABOUR CHARG	ES		17/13/10	INL.			20.00
		TO REMOVE AND REFIX DAMAGED PA	DTC				
1		CUT, WELD, PANEL BEAT, STRAIGHTE	N &				3400.00
		REALIGN, ETC.					2400.00
2		TO CHECK AND RECTIFY WIRING FAU	LTS,				150.00
		TO CARRY OUT DIAGNOSTICS CHECK					150.00
		TO DUTTY CLEAN CORNER -	VID 4 1177				
3		TO PUTTY, CLEAN, SPRAY PAINT & PO ETC.	LISH,				1225.00
3		ETC.					1225.00
		SUNDRIES					30.00
4					0-		
				TOTAL .	_		3,805.00
			LABOUR 7	IOIAL .			3,003.00
					_		
			SUB-TOTA	AL:	-		10,149.14
			SUB-TOTA		- 149.14		

•



Industrial Vehicles. 20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 18 Singapore 638894
Tel: +65 6861 0007 Fax: +65 6861 3676 (Sales)
Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)
Website: www.goldbell.com.sg
Co. Reg. No. 1980039636

Page 1 / 1

AXA INSURANCE SINGAPORE PTE LTD

8 SHENTON WAY #27-01 AXA TOWER SINGAPORE 068811 TAX INVOICE

GST Reg No.

M9-0002514-E

Invoice No.

EXI001711636

Invoice Date

09-05-2019

Account No.

C00000371

Quotation No.

60373

Work Order No :

590535

PARTICULARS

AMOUNT SGD

Reg No

YP6077J

Chassis No

FEB71EA20393

Engine No

4P10C49317

Model No

FEB71ER4SDEC CBU MT

Mileage

39172

SRR No

*1

ACCIDENT REPAIER -

DATE OF LOSS: 16/04/2018

POLICY NUMBER. : VCA/P1920367

OD CLAIM - AXA

PARTS AND LABOUR CHARGES LESS EXCESS PAID BY OWNER <u>U/Price</u> <u>Disc</u> <u>Net Price</u> 10149.14 N 10149.14

Net Price Ext Price 10149.14 10149.14

.b T-4-1

800.00

800.00 800.00

Sub Total GST @ 7.00 % 9349.14 654.43

TOTAL

10003.58









Industrial Vehicles. 20,000 Served. And Counting.

GREATSOLUTIONS PTE. LTD.

SINGAPORE

GOLDBELL ENGINEERING PTE LTD

Main Office: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6861 3676 Finance: 18 Tuas Avenue 10 Singapore 639142 Tel: 6861 0007 Fax: 6862 3500 Website: www.goldbell.com.sg Co. Reg. No.: 198003963G

Page

1 / 1

TAX INVOICE

GST Reg No.

: M9-0002514-E

Invoice No.

: EXI00118965

Invoice Date.

23-05-2018

Account No.

C00008087

Quotation No.

:

Work Order No.

: 604994

Service Centre.

29 TANJONG PENJURU

Agreement No.

: GBE~17356

PARTICULARS AMOUNT SGD Reg No YP6077J Chassis No FEB71EA20393

Engine No Model No

FEB71ER4SDEC CBU MT

4P10C49317

Mileage

39172

SRR No

ACCIDENT REPAIR: GBE/SVC/SALES-4623/180418

D.O.L.: 16/04/2018

POLICY NO.: VCA/P1920367

**** BEING \$800 EXCESS FOR OWN DAMAGE CLAIM - AXA ****

EXCESS CHARGES

Parts/Materials:

Description

QTY

800,00

Disc

Net Price

Ext Price

800.00 Parts Charges:

800.00 800.00

Sub Total:

TOTAL

800.00

GST @ 7.00 %

56.00

856.00

Please make all cheques payable to GOLDBELL ENGINEERING PTE LTD. When making payment, please quote our invoice numbers.

No receipts will be issued for Cheque Payments.

Terms and conditions of sales

Interest at 1.5% per month will be charged on overdue account

DBS: 006054

Levei 48

- 6 AUG 7018

GOLDBELL (HQ) / MOTORVIVA

This is a computer generated document. No signature is required,

E. & O. E

38 ODODY 4856





GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 18 Singapore 638894 Tel: 6861 0007 Fax: 6861 3676 Website: www.goldbell.com.sg Co. Reg. No.: 198003963G

Industrial Vehicles. 20,000 Served. And Counting.

SATISFACTION VOUCHER

To: Goldbell Engineering Pte Ltd.

10 Tuas Avenue 18 Singapore 638894 Date: 31/07/2018

Reference: 590535

We hereby confirm the receipt of the our vehicle in good and working condition from the repairer; M/s Goldbell Engineering Pte Ltd., and that all necessary repairs resulting from the below mentioned accident had been completed to our satisfactory.

Vehicle Number: YP6077J

Make & Model: MITSUBISHI FEB71ER4SDEC CBU MT

Chassis Number: FEB71EA20393

Engine Number: 4P10C49317

Accident Date : 16/04/2018

Claim Reference : GBE/SVC/SALES-4623/180418

Remarks : OD CLAIM - AXA

On behalf of M/s : GREAT SOLUTIONS PTE. LTD.

Signature:

Name :

Date :

Francis oug

