



Co Reg No : 196700086Z  
GST Reg No : MR-8500000-9

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

## ESTIMATE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :  
[www.toyotasingsapore.com.sg](http://www.toyotasingsapore.com.sg)  
Toyota Bodycare Centre  
17 Ubi Road 4  
Singapore 409611  
Tel no.: 6631 1188

| Account Detail    | Account No                  | Customer Detail                                                                                                      |
|-------------------|-----------------------------|----------------------------------------------------------------------------------------------------------------------|
| THIRD PARTY CLAIM | S1000020 / TPCLAIM          | M/s Eone Diesel Pte Ltd<br>31 Bukit Batok Crescent<br>#01-26 The Splendour<br>Singapore 658070<br><br>Work: 66439970 |
|                   | Document No<br>0            |                                                                                                                      |
|                   | Document Date<br>12/04/2018 |                                                                                                                      |

| Year              | Make       | Model  | Reg Date    | Veh Reg No       | Kilometers | WIP No       | Order No/Remarks    |
|-------------------|------------|--------|-------------|------------------|------------|--------------|---------------------|
| 12                | PFXQK      | F2     | 03/05/2012  | SJT0990T         | 158570     | 16333        | 7DS/SJT0990T/23031: |
| Chassis No        | Engine No  | TWC No | Terms       | Service Engineer | Vehicle In | Collected On |                     |
| JTEGD21H808216694 | 2AZH860320 | 60     | Sam San Joi | 12/04/2018       | 8.00       | --/--/----   | 0.00                |

| L  | Cd | Job/Parts Description                                                                                                                                                  | Qty | Unit Price | Disc % | Amount |
|----|----|------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|------------|--------|--------|
| 1  | Z  | BP-SUNDRY SUNDRIES TP-DIRECT SETTLEMENT<br>TP-SKD3299J ACC DATE:23/03/2018<br>DRIVE IN:11/04/2018<br>DATE-IN: DATE SURVEY:<br>NO OF REPAIR DAYS:<br>BY: AUTHORIZED ON: |     |            |        | 30.00  |
| 2  | S  | BP-SUBLET DRILL HOLE & INSTALL REVERSE SENSOR                                                                                                                          |     |            |        | 169.50 |
| 3  | S  | BP-SUBLET SEALANT - TAILGATE, REAR END PANEL                                                                                                                           |     |            |        | 160.00 |
| 4  | S  | BP-SUBLET CHECK LIGHTING & CONDUCT WATER LEAK TEST                                                                                                                     |     |            |        | 169.50 |
| 5  | S  | BP-SUBLET TRANSFER & INSTALL COMPONENTS TO NEW TAILGATE                                                                                                                |     |            |        | 339.00 |
| 6  | S  | BP-SUBLET REMOVE & INSTALL REAR REVERSE CAMERA                                                                                                                         |     |            |        | 339.00 |
| 7  | S  | BP-SUBLET REPLACE & INSTALL REAR WINDSCREEN GLASS                                                                                                                      |     |            |        | 436.00 |
| 8  | S  | BP-SUBLET SUPPLY & INSTALL REAR WINDSCREEN 3M SOLAR FILM                                                                                                               |     |            |        | 400.00 |
| 9  | S  | BP-SUBLET REMOVE & INSTALL TAILGATE TOP SPOILER                                                                                                                        |     |            |        | 127.13 |
| 10 | S  | BP-SUBLET REMOVE & INSTALL SEAT, CARPET, GARNISH AND TRIMMING TO ASSIST REPAIR                                                                                         |     |            |        | 678.00 |
| 11 | B  | BP-MECH RESET ECU AND REPROGRAMME                                                                                                                                      |     |            |        | 508.50 |

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

| For & on behalf of<br>Borneo Motors | Customer Signature                    | Change Summary    | Total      |
|-------------------------------------|---------------------------------------|-------------------|------------|
|                                     | Please acknowledge receipt of vehicle | Parts             |            |
|                                     |                                       | Labour            |            |
|                                     |                                       | Materials         |            |
|                                     |                                       | Lubrication/Fluid |            |
|                                     |                                       | Others            |            |
|                                     |                                       |                   | Amount Due |

PLEASE TEAR ALONG PERFORATED LINE

3639733

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED  
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 12/04/2018  
TIME 15:44

3639733

VEHICLE NO SJT0990T

CUSTOMER

SIGNATURE  
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Co Reg No : 196700086Z  
GST Reg No : MR-8500000-9

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

## ESTIMATE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :  
[www.toyotasingapore.com.sg](http://www.toyotasingapore.com.sg)  
Toyota Bodycare Centre  
17 Ubi Road 4  
Singapore 409611  
Tel no.: 6631 1188

| Account Detail    | Account No                  | Customer Detail                                                                                                      |
|-------------------|-----------------------------|----------------------------------------------------------------------------------------------------------------------|
| THIRD PARTY CLAIM | S1000020 /TPCLAIM           | M/s Eone Diesel Pte Ltd<br>31 Bukit Batok Crescent<br>#01-26 The Splendour<br>Singapore 658070<br><br>Work: 66439970 |
|                   | Document No<br>0            |                                                                                                                      |
|                   | Document Date<br>12/04/2018 |                                                                                                                      |

| Year              | Make       | Model  | Reg Date    | Veh Reg No       | Kilometers | WIP No       | Order No/Remarks    |
|-------------------|------------|--------|-------------|------------------|------------|--------------|---------------------|
| 12                | PFXQK F2   | ANH20R | 03/05/2012  | SJT0990T         | 158570     | 16333        | 7DS/SJT0990T/23031: |
| Chassis No        | Engine No  | TWC No | Terms       | Service Engineer | Vehicle In | Collected On |                     |
| JTEGD21H808216694 | 2AZH860320 | 60     | Sam San Joi | 12/04/2018       | 8.00       | --/--/----   | 0.00                |

| L  | Cd | Job/Parts Description                                                                                | Qty   | Unit Price | Disc % | Amount  |
|----|----|------------------------------------------------------------------------------------------------------|-------|------------|--------|---------|
| 12 | S  | BP-SUBLET REPLACE REAR BUMPER, REAR TAILGATE, ETC<br>STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS |       |            |        | 4068.00 |
| 13 | S  | BP-SUBLET RESPRAY JOB ON REAR ACCIDENT AFFECTED AR<br>EAS                                            |       |            |        | 3336.00 |
| 14 | 1  | T52159-58916 COVER, RR BUMPER                                                                        | 1.00  | 614.80     |        | 614.80  |
| 15 | 2  | T52153-58020 BAR, RR BUMPER, LH                                                                      | 1.00  | 57.20      |        | 57.20   |
| 16 | 3  | T52156-58020 L/R SIDE BPR SUPPORT,                                                                   | 1.00  | 78.00      |        | 78.00   |
| 17 | 4  | T52152-58010 R/R BUMPER EXTENSION,                                                                   | 1.00  | 57.30      |        | 57.30   |
| 18 | 5  | T52155-58030 R/R SIDE BPR SUPPORT,                                                                   | 1.00  | 78.00      |        | 78.00   |
| 19 | 6  | T52165-58020 E1 COVER, RR BUMPER                                                                     | 1.00  | 198.40     |        | 198.40  |
| 20 | 7  | S52161-0K040 CLIPS                                                                                   | 10.00 | 3.90       |        | 39.00   |
| 21 | 8  | T52162-58010 E1 PLATE, RR BUMPER                                                                     | 1.00  | 15.20      |        | 15.20   |
| 22 | 9  | T81910-13022 R/REAR BPR REFLECTOR,                                                                   | 1.00  | 58.00      |        | 58.00   |
| 23 | 0  | T58307-58038 PANEL SUB-ASSY, BODY                                                                    | 1.00  | 1019.20    |        | 1019.20 |
| 24 | 1  | T57081-58020 R/REAR BUMPER BRACKET,                                                                  | 1.00  | 106.30     |        | 106.30  |
| 25 | 2  | T67005-58120 REAR BACK DOOR PANEL,                                                                   | 1.00  | 1869.50    |        | 1869.50 |
| 26 | 3  | T67881-58020 RR BACK DOOR W/STRIP,                                                                   | 1.00  | 395.10     |        | 395.10  |
| 27 | 4  | T68105-58091 REAR BACK DOOR GLASS,                                                                   | 1.00  | 1168.50    |        | 1168.50 |
| 28 | 5  | T76801-58110 E0 GARNISH SUB-ASSY,                                                                    | 1.00  | 1994.60    |        | 1994.60 |
| 29 | 6  | T67750-58061 A0 BOARD ASSY, BACK                                                                     | 1.00  | 684.60     |        | 684.60  |

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply

| For & on behalf of<br>Borneo Motors | Customer's Signature                  | Change Summary                                              | Total      |
|-------------------------------------|---------------------------------------|-------------------------------------------------------------|------------|
|                                     | Please acknowledge receipt of vehicle | Parts<br>Labour<br>Materials<br>Lubrication/Fluid<br>Others | Less       |
|                                     |                                       |                                                             | Amount Due |

PLEASE TEAR ALONG PERFORATED LINE

3639734

TO SECURITY GUARD

3639734

PLEASE ALLOW THE UNDERMENTIONED  
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 12/04/2018  
TIME 15:44

VEHICLE NO SJT0990T

CUSTOMER

SIGNATURE  
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Co Reg No : 196700086Z  
GST Reg No : MR-8500000-9

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

## ESTIMATE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :  
[www.toyotasingapore.com.sg](http://www.toyotasingapore.com.sg)  
Toyota Bodycare Centre  
17 Ubi Road 4  
Singapore 409611  
Tel no.: 6631 1188

| Account Detail    |  | Account No         | Customer Detail                                                                                                      |  |
|-------------------|--|--------------------|----------------------------------------------------------------------------------------------------------------------|--|
| THIRD PARTY CLAIM |  | S1000020 / TPCLAIM | M/s Eone Diesel Pte Ltd<br>31 Bukit Batok Crescent<br>#01-26 The Splendour<br>Singapore 658070<br><br>Work: 66439970 |  |
|                   |  | Document No        |                                                                                                                      |  |
|                   |  | Document Date      |                                                                                                                      |  |
|                   |  | 0                  |                                                                                                                      |  |
|                   |  | 12/04/2018         |                                                                                                                      |  |

| Year | Make     | Model  | Reg Date   | Veh Reg No | Kilometers | WIP No | Order No/Remarks   |
|------|----------|--------|------------|------------|------------|--------|--------------------|
| 12   | PFXQK F2 | ANH20R | 03/05/2012 | SJT0990T   | 158570     | 16333  | 7DS/SJT0990T/23031 |

| Chassis No        | Engine No  | TWC No | Terms       | Service Engineer | Vehicle In | Collected On    |
|-------------------|------------|--------|-------------|------------------|------------|-----------------|
| JTEGD21H808216694 | 2AZH860320 | 60     | Sam San Joi | 12/04/2018       | 8.00       | --/--/---- 0.00 |

| L  | Cd | Job/Parts Description |                                 | Qty  | Unit Price | Disc % | Amount |
|----|----|-----------------------|---------------------------------|------|------------|--------|--------|
| 30 | 7  | T67750-58061 A0       | BOARD ASSY, BACK                | 1.00 | 684.60     |        | 684.60 |
| 31 | 8  | T69350-28161          | REAR BACK DR LOCK ASSY (W/PWR D | 1.00 | 475.10     |        | 475.10 |
| 32 | 9  | T69430-28050          | STRIKER ASSY, BACK              | 1.00 | 39.60      |        | 39.60  |
| 33 | 0  | T90975-02066          | TOYOTA SYMBOL EMBLEM,           | 1.00 | 72.20      |        | 72.20  |
| 34 | 1  | T75441-58030          | " ALPHARD" EMBLEM,              | 1.00 | 66.20      |        | 66.20  |
| 35 | 2  | T89348-64030 E1       | RETAINER, ULTRASONIC            | 1.00 | 17.10      |        | 17.10  |
| 36 | 3  | T89341-76010 E2       | SENSOR, ULTRASONIC              | 1.00 | 385.50     |        | 385.50 |
| 37 | 4  | T89348-30030 E3       | RETAINER, ULTRASONIC            | 1.00 | 17.10      |        | 17.10  |
| 38 | 5  | T89341-76010 E2       | SENSOR, ULTRASONIC              | 1.00 | 385.50     |        | 385.50 |
| 39 | 6  | T67935-58022 A0       | PLATE, BACK DOOR                | 1.00 | 176.00     |        | 176.00 |
| 40 | 7  | T04562-12010          | FRT W/SCREEN DAM KIT,           | 1.00 | 101.00     |        | 101.00 |
| 41 | 8  | T08826-08609          | SUPER FAST URETHANE BLACK       | 2.00 | 90.08      |        | 180.16 |
| 42 | 9  | T08826-08682          | SINGLE STEP PRIMER              | 2.00 | 173.44     |        | 346.88 |

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply

|                                                                                     |                                       |                   |           |            |           |
|-------------------------------------------------------------------------------------|---------------------------------------|-------------------|-----------|------------|-----------|
| For & on behalf of<br>Borneo Motors                                                 | Customer's Signature                  | Change Summary    |           | Total      | 22,141.27 |
|  | Please acknowledge receipt of vehicle | Parts             | 11,380.64 | GST 7.00%  | 1,549.89  |
|                                                                                     |                                       | Labour            | 538.50    |            |           |
|                                                                                     |                                       | Materials         | 10,222.13 | Less       | 0.00      |
|                                                                                     |                                       | Lubrication/Fluid | 0.00      |            |           |
|                                                                                     |                                       | Others            | 0.00      |            |           |
|                                                                                     |                                       |                   |           | Amount Due | 23,691.16 |

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED  
VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO SJT0990T

CUSTOMER

DATE 12/04/2018  
TIME 15:44

SIGNATURE  
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Inchcape