

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE\*

VEHICLE NO : SHD 3877B

DATE 4/21/2018 9:07

MAKE :

MODEL : HYUNDAI SONATA

*Handwritten initials*

*Larry*

*AG*

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper ✓			\$ 578.40
	Rear Bumper Reinforcement ✓			\$ 483.30
	Rear Bumper Clip ✓			\$ 22.00
	Rear Bumper Sponge ✓			\$ 137.40
	Rear Bumper Under Cover ✓			\$ 185.80
	Rear Bumper Protector (LH/RH) <i>x repair</i>		\$ 38.00	\$ 76.00
	Rear Panel <i>x repair</i>			\$ 391.80
	Rear Panel Garnish <i>x</i>			\$ 95.80
	<b>SUB TOTAL</b>			<b>\$ 1,970.50</b>
	<b>LESS 20%</b>			<b>\$ 394.10</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$ 1,576.40</b>
	Rear Bumper Reverse Sensor <i>x</i>			\$ 135.70
	Rear Bumper Advertisement Logo ✓			\$ 50.00
	Rear Fender Advertisement Logo (LH/RH) ✓		\$ 100.00	\$ 200.00
				<b>\$ 385.70</b>
	<b>Labour Charge</b>			
	Panel Beating			\$ <del>250.00</del> <sup>200</sup>
	Spray Painting Charge			\$ <del>250.00</del> <sup>200</sup>
	Wiring Charge			\$ <del>30.00</del> <sup>x</sup>
	Remove/Refix Reverse Sensor			\$ <del>120.00</del> <sup>x</sup>
	<b>TOTAL LABOUR</b>			<b>\$ 650.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 2,612.10</b>

Nett  
Nett  
Nett

*Kabe (Clay)*  
*23/4/18 11.10L*  
*3/3*  
*4/3*  
*After Repair p 4.*

*Larry Ng*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) allowed
- Supplementary parts must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.