

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Lionel Tan Tian Pei

Date: 26 Apr 2018

Preliminary Advice

Insured Vehicle No : SJV8781S

TP Vehicle No : SFV85T

Accident Date : 22/04/2018

Make : VOLKSWAGEN SHARAN

Assignment Date : 24/04/2018

Date of Inspection : 25/04/2018

Est. Duration of Repair : 5.00

Inspection At : VOLKSWAGEN CENTRE SINGAPORE (HQ)
247 ALEXANDRA ROAD
SINGAPORE 159934

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,819.60
Revised Amount	:S\$	8,522.46
Check Items (Estimated)	:S\$	51.94
Total	:S\$	8,574.40

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.