

AXIA

REPAIR ESTIMATE*

VEHICLE NO : SHA 4650Y

DATE 23/4/2018 12:28

MAKE :

Ju

MODEL : HYUNDAI SONATA

LS

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Door (RH) ✓			\$ 1,345.00
	Front Door Outer Handle (RH) X			\$ 37.00
	Front Door Protector (RH) ✓			\$ 74.90
	<i>for door (RH) x repair</i>			
	SUB TOTAL			\$ 1,456.90
	LESS 20%			\$ 291.38
	DISCOUNTED TOTAL			\$ 1,165.52
	Front Fender Advertisement Logo (RH) ✓			\$ 100.00
	Front Door Comfort Logo (RH) ✓			\$ 75.00
	Front Door Advertisement Logo (RH) ✓			\$ 100.00
	<i>for door Logo Comfort (RH) ✓</i>			\$ 80
				\$ 275.00
	Labour Charge			
	Panel Beating			\$ 250.00 ²⁰⁰
	Spray Painting Charge-Fender/Door			\$ 500.00 ⁴⁰⁰
	Tuff Kote			\$ 50.00 ²⁰
	TOTAL LABOUR			\$ 800.00
	ESTIMATE TOTAL			\$ 2,240.52
	<i>Ka Lian (LCC)</i>			
	<i>24/4/18 1030hrs</i>			
	<i>2 Pgs</i>			
	<i>4s</i>			
	<i>Attn Rep-2p LL</i>			

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.