

**COMFORTDELGRO ENGINEERING PTE LTD**

**REPAIR ESTIMATE\***

VEHICLE NO : *SHA30915*

DATE: *23/4/18*

*F2*

MAKE :

MODEL : **HYUNDAI SONATA**

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid			\$ 1,349.50
	Boot Lid Rubber X			\$ 110.90
	Boot Lid Lock Upper X			\$ 132.10
	Boot Lid Lock Lower X			\$ 30.30
	Boot Lid Key Lock X			\$ 78.20
	Boot Lid Sonata Plate -			\$ 43.60
	Boot Lid Hyundai Plate -			\$ 24.20
	Boot Lid 'H' Emblem -			\$ 26.10
	Boot Lid CRDI Plate -			\$ 22.70
	Boot Lid Lamp (LH/RH) <i>LH ✓ RH x</i>		\$ 230.20	\$ 460.40
	Licence Lamp (LH/RH) X		\$ 32.50	\$ 65.00
	Boot Lid Trimboard 0			\$ 165.40
	Boot Lid Trimboard Clips (10pcs) X			\$ 10.00
	Rear Bumper			\$ 578.40
	Rear Bumper Reinforcement -			\$ 483.30
	Rear Bumper Clip -			\$ 22.00
	Rear Bumper Sponge -			\$ 137.40
	Rear Bumper Under Cover X			\$ 185.80
	Rear Bumper Protector (LH/RH) <i>X 144</i>		\$ 38.00	\$ 76.00
	Tail Lamp (LH/RH) ?		\$ 344.00	\$ 688.00
	Rear Panel <i>X 144-2</i>			\$ 391.80
	Rear Panel Garnish ?			\$ 95.80
	Exhaust Pipe Insulator ?			\$ 56.10
	Exhaust Silencer ?			\$ 723.00
	Exhaust Pipe Hanger ?			\$ 56.10
	<b>SUB TOTAL</b>			<b>\$ 6,012.10</b>
	<b>LESS 20%</b>			<b>\$ 1,202.42</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$ 4,809.68</b>
	Boot Lid Comfort Logo & Tel No. Sticker			\$ 30.00 <b>Nett</b>
	Rear No. Plate X			\$ 25.00 <b>Nett</b>
	Rear Bumper Reverse Sensor -			\$ 135.70 <b>Nett</b>
	Rear Fender Advertisement Logo (LH/RH)		\$ 200.00	\$ 200.00 <b>Nett</b>
	<b>Labour Charge</b>			<b>\$ 390.70</b>
	Panel Beating			\$ 1,500.00
	Spray Painting Charge			\$ 1,000.00 <i>600</i>
	Wiring Charge			\$ 50.00 <i>20</i>
	Tuff Kote			\$ 100.00 <i>20</i>
	Remove/Refix Reverse Sensor			\$ 120.00 <i>20</i>
	Remove/Refix Exhaust Pipe			\$ 150.00 <i>30</i>
	<b>TOTAL LABOUR</b>			<b>\$ 2,920.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 8,120.38</b>

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

*1 Cab...*  
*23/4/18 1520h.*  
*3 Pys.*  
*45*  
*Ash R...*

**Nett**  
**Nett**  
**Nett**  
**Nett**