

INS. CASE OWNER:

CC4 / LPC1800

LKK:

IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :S\$

Is driver the owner?

If NO, Driver Name / Age:

Driver Tel No.:

(YES / NO)

Nature of Accident:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

11/18/18 VPOB 010563

210 VPOB 012312

F1A

B/K NATEBAN GARDENS RD

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

SLR3877D



INSRS:

WSP:

Tel:

Liability:

RMKS:

SK



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time	STAGE	DATE / PIC
20/4/18	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call Of:	
	After call ltr to Of:	
	Documentation Check List:	Handler Typist
3.5.18	Notification ltr (if non-pickup):	
	After call ltr to Of:	
	Authorisation To Act:	
	Release Voucher:	
	Final Repair Bill:	
	Car Rental Invoice:	
	Towing Invoice:	
	LTA / GIA:	
	Medical Bill:	
	PIR:	
	Mandate/Reject Instruction:	
	LOD:	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	
17/7/18	PRELIMINARY ADVICE	Date/Time: 13.7.18 Sent By: AMH
17/7/18	FINALIZATION	Date/Time: 13.7.18 Confirm with: Confirm by: bwp
17/7/18	FINAL SETTLEMENT	Date/Time: Confirm with: Email ☒ Call ☐
17/7/18	FINAL PAYMENT	Date/Time: Confirm with: Email ☐ Call ☐

Kindly assess liability by proceeding to a Ds as insured is alleging that there was no collision.
 PENDING FOR TP EVIDENCE.
 RECD TP VIDEO SAVE IN (V. ASST: 2018) VIDEO SHOW DID DRIVE PASS AND HIT TP PARKED VEH.
 EMAIL WSP LIABILITY CLAIM.
 FILE PASS TO TYPE MANDATE
 FILE PASS TO LSP TO CLOS
 SEEK MANDATE WITH TP VIDEO.

Repair Cost: SS3,900 (3 days) Reduction: 85 %
 Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: NIL
 Repair Cost: (w/1627) SS 3638.00
 Loss of Rental (LOR): SS 400.00 (4 days) x \$100
 Loss of Use (LOU): SS - (\$ x days)
 Loss of Income (LOI): SS - (\$ x days)
 LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ (Tick only one)
 GIA/LTA Search SS 2.00
 Medical: SS -
 Disbursement: SS - (e.g. Tow/ Independent)
 Legal Cost SS -
 Total: SS 4040.00 Global Sum SS:
 Payee 1: SS 4040.00 Name 1: SK Automobile Pte Ltd
 Payee 2: (Strike if N.A.) SS Name 2:
 Payee 3: (Strike if N.A.) SS Name 3:

1) Claim status: Normal/Reject/Private Settle
 2) Report Format: TP
 3) Survey fee: \$450

ASS. REC. BY: Adrian Ling

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLR3817D Yr Regn: 2010, JulyType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Volkswagen Scirocco c.c. 1390Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 115389 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WVW 222 132 AV 446119Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 225/40 R18R: 225/40 R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 24/04/18Survey held at SKDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Con PacL/S: +3,400 (RED: +19,159.13 85%)

Date/Time, File Pass to?

☐

Preli. Report

☐

Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CC4/LPC18007566/Aeb3	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 24-04-2018	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJU 5324D	Veh. Inspected	SLR 3817D	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	24/04/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	20/04/2018	Inspection Date	24/04/2018	
Survey held at	SK AUTOMOBILE PTE LTD 23 KAKI BUKIT AVE 4 # 03-01 SINGAPORE 415933			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

SK Automobile Pte Ltd
(Co Reg. No. 201500047H)
23 Kaki Bukit Ave 4, #03-01
Vicom Inspection Centre (S415933)
Tel: 6789 5155 Fax : 6783 5155

TO	: LONPAC	DATE	: 23-Apr-18
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>OWNER'S PARTICULAR</u>		<u>VEHICLE DETAILS</u>	
NAME	: <i>Aches</i>	VEHICLE NO	: SLR3817D
ADDRESS	:	MODEL	: VOLKWAGEN SCIROCCO
TEL. NO.	:	CHASSIS NO	: <i>WVW222132A14461A</i>
OWNER'S INSURANCE	:		
POLICY NO.	:		
<u>ACCIDENT DETAILS</u>	DATE :		
	TIME :		
THIRD PARTY REQUESTOR / CONTACT : DAUD/93911482			

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BONNET	1	\$ 987.33	\$ 987.33
2	BONNET LOGO	1	\$ 83.75	\$ 83.75
3	BONNET HINGE	2	\$ 70.99	\$ 141.98
4	BONNET BOTTOM LOCK	1	\$ 212.20	\$ 212.20
5	BONNET WEATHERSTRIP	1	\$ 40.33	\$ 40.33
6	FRONT GRILLE COVER	1	\$ 200.97	\$ 200.97
7	FRONT GRILLE	2	\$ 325.20	\$ 650.40
8	FRONT BUMPER	1	\$ 1,428.31	\$ 1,428.31
9	FRONT BUMPER SIDE LAMP	2	\$ 189.90	\$ 379.80
10	FRONT BUMPER SIDE LAMP RING	2	\$ 112.10	\$ 224.20
11	FRONT BUMPER FOGLAMP	2	\$ 398.50	\$ 797.00
12	FRONT BUMPER FOGLAMP COVER	2	\$ 130.97	\$ 261.94
13	FRONT BUMPER REINFORCEMENT	1	\$ 531.70	\$ 531.70
14	FRONT BUMPER SIDE RETAINER	2	\$ 48.70	\$ 97.40

1207
189.90
112.10
398.50
130.97

15	FRONT BUMPER LOWER GRILLE <i>at</i>	1	\$ 385.62	\$ 385.62	
16	FRONT BUMPER SPONGE <i>conced</i>	2	\$ 198.40	\$ 396.80	<i>198.40</i>
17	FRONT BUMPER LOWER LID <i>3 given</i>	1	\$ 521.20	\$ 521.20	<i>+</i>
18	FRONT FENDER COWLING	2	\$ 179.75	\$ 359.50	<i>+</i>
19	HEADLAMP <i>LH conced</i>	2	\$ 1,259.20	\$ 2,518.40	<i>680. 1259.20</i>
20	HEADLAMP TOP PANEL	2	\$ 145.20	\$ 290.40	<i>+</i>
21	FRONT SUPPORT PANEL	1	\$ 1,528.80	\$ 1,528.80	<i>+</i>
22	FRONT SUPPORT PANEL TOP GARNISH	1	\$ 321.20	\$ 321.20	<i>+</i>
23	FRONT SUPPORT PANEL LOWER GARNISH	1	\$ 289.20	\$ 289.20	<i>+</i>
24	FRONT AIR GUIDE GARNISH	2	\$ 68.20	\$ 136.40	<i>+</i>
25	FRONT AIR DUCT	1	\$ 112.50	\$ 112.50	<i>+</i>
26	AIRCON CONDENSOR	1	\$ 1,210.20	\$ 1,210.20	<i>+</i>
27	RADIATOR <i>N-P</i>	1	\$ 1,598.60	\$ 1,598.60	<i>+</i>
28	RADIATOR BRACKET	2	\$ 49.77	\$ 99.54	<i>+</i>
29	RADIATOR TOP GARNISH	1	\$ 40.31	\$ 40.31	<i>+</i>
30	HORN	2	\$ 148.00	\$ 296.00	<i>+</i>
31	WIPER WASHER TANK	1	\$ 259.20	\$ 259.20	<i>+</i>
32	WIPER WASHER TANK MOTOR	1	\$ 212.30	\$ 212.30	<i>+</i>
33	ENGINE TOP COVER	1	\$ 347.35	\$ 347.35	<i>+</i>
34	ENGINE UNDER COVER	1	\$ 358.30	\$ 358.30	<i>+</i>

Front Bumpers Inner Bracket Conced
189.

TOTAL PRICE \$17,319.13
LESS 0% \$
SUB TOTAL PRICE \$17,319.13

360036

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT NUMBER PLATE <i>Missing</i>	1	\$ 50.00	\$ 50.00	<i>✓</i>
2	BONNET INSULATOR CLIP (SET) <i>2000</i>	1	\$ 50.00	\$ 50.00	<i>+</i>
3	FRONT BUMPER CLIP (SET) <i>2000</i>	1	\$ 50.00	\$ 50.00	<i>30</i>
4	FRONT GRILLE COVER CLIP (SET) <i>2000</i>	1	\$ 30.00	\$ 30.00	<i>10</i>
5	FRONT GRILLE (UPPER) CLIP (SET) <i>2000</i>	1	\$ 30.00	\$ 30.00	<i>+</i>
6	FRONT GRILLE (LOWER) CLIP (SET) <i>2000</i>	1	\$ 30.00	\$ 30.00	<i>✓</i>
7	FRONT FEENDER COWLING CLIPS (SET) <i>2000</i>	1	\$ 50.00	\$ 50.00	<i>+</i>
8	FRONT AIR GUIDE GARNISH CLIP (SET) <i>2000</i>	1	\$ 50.00	\$ 50.00	<i>+</i>
9	ENGINE UNDER COVER CLIP (SET) <i>2000</i>	1	\$ 50.00	\$ 50.00	<i>+</i>
10	COOLANT	1	\$ 80.00	\$ 80.00	<i>90</i>

TOTAL \$470.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,600.00	300
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,400.00	250
3	TUFF COAT	\$ 550.00	x
4	WIRING AND BULB CHECK	\$ 80.00	30
5	REFOCUS HEADLAMP BEAM	\$ 60.00	x
6	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL GAS	\$ 120.00	x
7	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ 80.00	x
8	RESET ENGINE LIGHT ON	\$ 350.00	x
9	S.R.S RESET	\$ 350.00	x
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x

TOTAL

\$4,770.00

580

ESTIMATE REPORT

TOTAL PARTS COST : \$17,789.13
TOTAL LABOUR COST : \$4,770.00
TOTAL REPAIR COST : \$22,559.13

22789.13

APPROVED DETAILS

EXCESS :
NO. OF DAYS :
RE-SURVEY :

PART BY PART OR LUMP SUM :

DATE & TIME OF SURVEY :
SURVEYED BY :
CONTACT NUMBER :
FAX NUMBER :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lim. tel 4270.36
L/S 24/09/18. c/s: 3AK.
03 Days.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 3400Z

Vehicle Details

Vehicle No.: SLR3817D
Vehicle to be Exported: No
Intended De-registration Date: 23 Apr 2018
Vehicle Make: VOLKSWAGEN
Vehicle Model: SCIROCCO 1.4L AT TSI 1372Q5
Primary Colour: Grey
Manufacturing Year: 2010
Engine No.: CAV192205
Chassis No.: WVVZZZ13ZAV446119
Maximum Power Output: 118.0 kW (158 bhp)
Open Market Value: \$24,377.00
Original Registration Date: 29 Jul 2010
First Registration Date: 29 Jul 2010
Transfer Count: 2
Actual ARF Paid: \$24,377.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 28 Jul 2020
PARF Rebate Amount: \$14,626.00

Intended COE Rebate Details

COE Expiry Date: 28 Jul 2020
COE Category: A - Car (1600cc & below)
COE Period(Years): 10
QP Paid: \$34,001.00
COE Rebate Amount: \$7,695.00
Total Rebate Amount: \$22,321.00

The information contained herein is correct as at 23 Apr 2018

OK \$ 35800
 - 22321
 13479



Posted: 09-Mar-2018 Tags: 2010 Volkswagen Scirocco, Volkswagen Scirocco, Volkswagen, Scirocco, Used Volkswagen



Volkswagen Scirocco 1.4A TSI \$30,800 \$9,260 /yr 26-Apr-2010 1,390 cc 110,782 km Sports Available

100% Guaranteed Accident Free, Full Stock, 1 Owner, Full Agent Service Records, Genuine Low Mileage 110,782KM, ARF \$25K, 80% Loan At 2.78%, Guaranteed Loan For Bad Credit/Ex Bankruptcy, View After Lun...

Posted: 04-Apr-2018 Tags: 2010 Volkswagen Scirocco, Volkswagen Scirocco, Volkswagen, Scirocco, Used Volkswagen



Volkswagen Scirocco 1.4A TSI \$33,800 \$10,160 /yr 08-Jun-2010 1,390 cc 87,000 km Sports Available

One Owner Only, Flexible Loan And Low Down Payment Available! Accident Free And Well Maintained! Trade In Welcome! Call Now For Viewing And Test Drive This Beauty Before Its Gone!

Posted: 20-Apr-2018 Tags: 2010 Volkswagen Scirocco, Volkswagen Scirocco, Volkswagen, Scirocco, Used Volkswagen



That Special Number In Your Heart

Want to remember the good times? Need to earn some brownie points? Got a lucky number or a special date you want embedded on your car plate? Find out if they are on sale and it could just be yours!

Find out more!



Volkswagen Scirocco GT 2.0A TSI \$41,500 \$12,650 /yr 28-Jun-2010 1,984 cc 106,500 km Sports Available

Accelerate Your Passion. Interest Rates 2.18%. Come View This Meticulously Maintained By MBM Wheels Power. Accident Free. Scirocco GT Compromise 3 Modes, Comfort, Normal And Sport. Sport Mode Stiffens...

Edmund Motor Pte Ltd

Posted: 25-Mar-2018 Tags: 2010 Volkswagen Scirocco, Volkswagen Scirocco, Volkswagen, Scirocco, Used Volkswagen



Volkswagen Scirocco 1.4A TSI \$35,800 \$10,420 /yr 29-Jul-2010 1,390 cc 110,200 km Sports Available

Down Payment \$3,580! From \$990 Monthly. Up To 90% Flexible Loan Available With One Of The Lowest Rate. Extremely Well Maintained With No Repair Needed! This Is Your Chance To Own This German Hot Hatch...

Dynamic Motoring

Posted: 21-Apr-2018 Tags: 2010 Volkswagen Scirocco, Volkswagen Scirocco, Volkswagen, Scirocco, Used Volkswagen



Volkswagen Scirocco 1.4A TSI \$31,000 \$8,340 /yr 05-Aug-2010 1,390 cc 130,000 km Sports Available

Look No Further! Direct Owner's Beautiful Sporty Championship White 2010 VW Scirocco 1.4A TSi With Nice Matching Brown Leather Upholstery And 18" Black Alloy Rims. Expanding Family Hence Current Owner...

Posted: 23-Apr-2018 Tags: 2010 Volkswagen Scirocco, Volkswagen Scirocco, Volkswagen, Scirocco, Used Volkswagen



Volkswagen Scirocco 2.0A TSI \$44,800 \$12,610 /yr 20-Aug-2010 1,984 cc 119,000 km Sports Available

Stop Searching, This Is The Unit You Looking For. Brand New 4 Tyres Changed September 2017. Accessories Worth Of Above \$15k Jetex LTA Approved Quad Tail Exhaust Systems And New ABS Module. Functional ...

Car Search

Posted: 10-Apr-2018 Tags: 2010 Volkswagen Scirocco, Volkswagen Scirocco, Volkswagen, Scirocco, Used Volkswagen



Volkswagen Scirocco 1.4A TSI \$35,900 \$10,140 /yr 24-Aug-2010 1,390 cc 140,000 km Sports Available

Selling On Behalf Of Private Owner, Please Call To Arrange Before Viewing!

Posted: 10-Apr-2018 Tags: 2010 Volkswagen Scirocco, Volkswagen Scirocco, Volkswagen, Scirocco, Used Volkswagen



Volkswagen Scirocco 1.4A TSI \$37,500 \$10,570 /yr 30-Aug-2010 1,390 cc - Sports Available

Extremely Well Maintained, Come View To Appreciate This Gorgeous White Knight! Price Negotiable.

Posted: 26-Feb-2018 Tags: 2010 Volkswagen Scirocco, Volkswagen Scirocco, Volkswagen, Scirocco, Used Volkswagen



Volkswagen Scirocco 1.4A TSI \$36,800 \$10,390 /yr 13-Sep-2010 1,390 cc 68,000 km Sports Available

1 Owner Vehicle. Prestige Condition With No Modification Done. Well Taken Care Unit With No Expenses Spared! All Wear And Tear Done Up, New Owner To Drive At Ease! Accident Free Unit. Perfect Combinat...

Posted: 16-Apr-2018 Tags: 2010 Volkswagen Scirocco, Volkswagen Scirocco, Volkswagen, Scirocco, Used Volkswagen



Volkswagen Scirocco 1.4A TSI \$48,000 \$14,400 /yr 22-Oct-2010 1,390 cc 65,700 km Sports Available

Sporty Red. Price Negotiable! Accident Free! Low Mileage Done, Stock Condition. Single Owner. Balloon Scheme Available. High Loan/Insurance Available. Trade In Welcome. Call Now For A Viewing Appointm...

Prem Roy Motoring

Posted: 23-Mar-2018 Tags: 2010 Volkswagen Scirocco, Volkswagen Scirocco, Volkswagen, Scirocco, Used Volkswagen

Volkswagen Scirocco 1.4A TSI \$35,800 \$9,350 /yr 02-Nov-2010 1,390 cc 124,331 km Sports Available

Catherine Chong (LKK Auto)

From: ERIC WOO JUN KIAT <ericwoo@lonpac.com>
Sent: Tuesday, 24 April, 2018 12:34 PM
To: assignments@lkkauto.com
Cc: MT_Claim_SG; admin@skauto.com.sg
Subject: FW: Our Ref: 17/18/18/VP05/020563 Arrange surveyor for SLR3817D Your Ref: SJU5324D DOA: 20/4/18
Attachments: SLR3817D GIA.PDF; SLR3817D ARRANGE.pdf

Dear Catherine / Nivitha,

Kindly refer to our attachment.

Please proceed to conduct a survey of the vehicle SLR 3817D on without Prejudice Basis.

We look forward to receiving your report soon.

Thank you.

Best Regards,
Eric Woo
Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6279 9253 | Fax: (65) 6296 3767

24/04/2018 @ 1:29 pm
Ah Xiong rhn
Ackn.

From: SK Admin [mailto:admin@skauto.com.sg]
Sent: Tuesday, 24 April, 2018 10:30 AM
To: MT_Claim_SG; GERALD POH WEE BIN
Cc: JING XIONG KHOO; md daud nadzim
Subject: Arrange surveyor for SLR3817D Your Ref: SJU5324D

Dear Sir / Mdm,

We the repairers of motor vehicle no. SLR3817D
Please provide a list of surveyor for further inspection.

Location : 8 Kaki Bukit Ave 4#08-46
Premier @ Kaki Bukit
Singapore 415875

Contact No : 8121 0478 Xiong

We appreciate your early reply.
Thanks.

--
Regards,
Huey Lee
SK Automobile Pte Ltd
Tel: 6789 5155 Fax: 6783 5155

Shu Pei (LKKAUTO)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Thursday, 26 April 2018 9:17 AM
To: Shu Pei (LKKAUTO)
Cc: MT_Claim_SG
Subject: RE: Our Ref: 17/18/18/VP05/020563 Arrange surveyor for SLR3817D Your Ref:SJU5324D DOA: 20/4/18 ***LKK REF:CC4/LPC18007566/Aeb3
Attachments: 26042018074042.pdf

Dear Shu Pei,

We attached a copy of insured's GIA report for your attention.

Kindly assess liability before proceeding to a direct settlement as our insured is alleging that there was no collision.

If there is a need to verify with our insured, kindly arrange for the case handler to engage her.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]

Sent: Wednesday, 25 April, 2018 5:32 PM

To: ERIC WOO JUN KIAT; GERALD POH WEE BIN; ONG LI LI

Cc: MT_Claim_SG; Admin A; Asher Sng (LKKAUTO)

Subject: RE: Our Ref: 17/18/18/VP05/020563 Arrange surveyor for SLR3817D Your Ref:SJU5324D DOA: 20/4/18 ***LKK REF:CC4/LPC18007566/Aeb3

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SLR 3817D at M/s SK Automobile Pte Ltd.

Please be informed that estimated cost of repair and preliminary advice is not ready yet.

Kindly let us have a copy of your insured's GIA report for our necessary action.

Our case handler in-charge is Asher and she can be contacted at DID: 6841 6051.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Tuesday, 24 April 2018 1:30 PM

To: 'ERIC WOO JUN KIAT' <ericwoo@lonpac.com>; assignments <assignments@lkkauto.com>

Cc: 'MT_Claim_SG' <mt_claim@lonpac.com>; Admin A <admin-a@lkkauto.com>

Subject: RE: Our Ref: 17/18/18/VP05/020563 Arrange surveyor for SLR3817D Your Ref: SJU5324D DOA: 20/4/18

Dear Eric,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ERIC WOO JUN KIAT [<mailto:ericwoo@lonpac.com>]

Sent: Tuesday, 24 April, 2018 12:34 PM

To: assignments@lkkauto.com

Cc: MT_Claim_SG <mt_claim@lonpac.com>; admin@skauto.com.sg

Subject: FW: Our Ref: 17/18/18/VP05/020563 Arrange surveyor for SLR3817D Your Ref: SJU5324D DOA: 20/4/18

Dear Catherine / Nivitha,

Kindly refer to our attachment.

Please proceed to conduct a survey of the vehicle SLR 3817D on without Prejudice Basis.

We look forward to receiving your report soon.

Thank you.

Best Regards,

Eric Woo

Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6279 9253 | Fax: (65) 6296 3767

From: SK Admin [<mailto:admin@skauto.com.sg>]

Sent: Tuesday, 24 April, 2018 10:30 AM

To: MT_Claim_SG; GERALD POH WEE BIN

Cc: JING XIONG KHOO; md daud nadzim

Subject: Arrange surveyor for SLR3817D Your Ref: SJU5324D

Dear Sir / Mdm,

We the repairers of motor vehicle no. SLR3817D
Please provide a list of surveyor for further inspection.

Location : 8 Kaki Bukit Ave 4#08-46
Premier @ Kaki Bukit
Singapore 415875

Contact No : 8121 0478 Xiong

We appreciate your early reply.
Thanks.

--
Regards,
Huey Lee
SK Automobile Pte Ltd
Tel: 6789 5155 Fax: 6783 5155



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC18007566/Adb3s2

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 27-11-2019



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJU 5324D	Veh. Inspected	SLR 3817D
Policy No.	Z16VP05012712	Coverage (\$)	0.00
Claim No.	17/18/18/VP05/020563	Excess (\$)	0.00
Assign From	GERALD POH	Assign Date	24/04/2018

2. Vehicle Particulars & Condition

Make & Model	VOLKSWAGEN SCIROCCO	c.c	1390
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	WVWZZZ13ZAV446119	Colour	GREY
Odometer	115389	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/40 R18	WEST LAKE	6 mm
L/H Front Tyre	225/40 R18	WEST LAKE	6 mm
R/H Rear Tyre	225/40 R18	WEST LAKE	6 mm
L/H Rear Tyre	225/40 R18	WEST LAKE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	20/04/2018	Inspection Date	24/04/2018
Survey held at	SK AUTOMOBILE PTE LTD 23 KAKI BUKIT AVE 4 # 03-01 SINGAPORE 415933		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 3817D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BONNET	NOT NECESSARY	987.33	-
1	BONNET LOGO	NOT NECESSARY	83.75	-
2	BONNET HINGE @ \$70.99	NOT NECESSARY	141.98	-
1	BONNET BOTTOM LOCK	NOT NECESSARY	212.20	-
1	BONNET WEATHERSTRIP	NOT NECESSARY	40.33	-
1	FRONT GRILLE COVER	CUT	200.97	200.97
2	FRONT GRILLE @ \$325.20	NOT NECESSARY	650.40	-
1	FRONT BUMPER	DEFORMED	1,428.31	1,207.00
2	FRONT BUMPER SIDE LAMP @ \$189.90	N/S CRACKED	379.80	189.90
2	FRONT BUMPER SIDE LAMP RING @ \$112.10	N/S CUT	224.20	112.10
2	FRONT BUMPER FOGLAMP @ \$398.50	N/S CRACKED	797.00	398.50
2	FRONT BUMPER FOGLAMP COVER @ \$130.97	N/S CUT	261.94	130.97
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	531.70	-
2	FRONT BUMPER SIDE RETAINER @ \$48.70	NECESSARY	97.40	97.40
1	FRONT BUMPER LOWER GRILLE	CUT	385.62	385.62
2	FRONT BUMPER SPONGE @ \$198.40	CRACKED	396.80	198.40
1	FRONT BUMPER LOWER LID	NOT NECESSARY	521.20	-
2	FRONT FENDER COWLING @ \$179.75	NOT NECESSARY	359.50	-
2	HEADLAMP @ \$1259.20	N/S CRACKED	2,518.40	680.00
2	HEADLAMP TOP PANEL @ \$145.20	NOT NECESSARY	290.40	-
1	FRONT SUPPORT PANEL	NOT NECESSARY	1,528.80	-
1	FRONT SUPPORT PANEL TOP GARNISH	NOT NECESSARY	321.20	-
1	FRONT SUPPORT PANEL LOWER GARNISH	NOT NECESSARY	289.20	-
2	FRONT AIR GUIDE GARNISH @ \$68.20	NOT NECESSARY	136.40	-
1	FRONT AIR DUCT	NOT NECESSARY	112.50	-
1	AIRCON CONDENSER	NOT NECESSARY	1,210.20	-
1	RADIATOR	NOT NECESSARY	1,598.60	-
2	RADIATOR BRACKET @ \$49.77	NOT NECESSARY	99.54	-
1	RADIATOR TOP GARNISH	NOT NECESSARY	40.31	-
2	HORN @ \$148.00	NOT NECESSARY	296.00	-
1	WIPER WASHER TANK	NOT NECESSARY	259.20	-

Report Ref No. CC4/LPC18007566/Adb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	WIPER WASSHER TANK MOTOR	NOT NECESSARY	212.30	-
1	ENGINE TOP COVER	NOT NECESSARY	347.35	-
1	ENGINE UNDER COVER	NOT NECESSARY	358.30	-
1	FRONT BUMPER INNER BRACKET	CRACKED	189.00	189.00
	LESS 5% DISCOUNT		-	-189.49
			17,508.13	3,600.37
	SPECIAL NETT ITEMS			
1	FRONT NUMBER PLATE (SN)	MISSING	50.00	50.00
1	SET BONNET INSULATOR CLIP (SN)	NOT NECESSARY	50.00	-
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	50.00	30.00
1	SET FRONT GRILLE COVER CLIP (SN)	NECESSARY	30.00	10.00
1	SET FRONT GRILLE (UPPER) CLIP (SN)	NOT NECESSARY	30.00	-
1	SET FRONT GRILLE (LOWER) CLIP (SN)	NOT NECESSARY	30.00	-
1	SET FRONT FENDER COWLING CLIPS (SN)	NOT NECESSARY	50.00	-
1	SET FRONT AIR GUIDE GARNISH CLIP (SN)	NOT NECESSARY	50.00	-
1	SET ENGINE UNDER COVER CLIP (SN)	NOT NECESSARY	50.00	-
1	COOLANT (SN)	NOT NECESSARY	80.00	-
			470.00	90.00
	LABOUR			
	TO PANEL BEAT, REMOVE AND REPLACE PARTS.		1,600.00	300.00
	TO SPRAY PAINT AFFECTED AREA.		1,400.00	250.00
	TUFF COAT.	NOT NECESSARY	550.00	-
	WIRING AND BULB CHECK.		80.00	30.00
	REFOCUS HEADLAMP BEAM.	NOT NECESSARY	60.00	-
	REMOVE AND REFIX AIRCON CONDENSER AND REFILL GAS.	NOT NECESSARY	120.00	-
	TO REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST.	NOT NECESSARY	80.00	-
	RESET ENGINE LIGHT ON.	NOT NECESSARY	350.00	-
	S.R.S RESET.	NOT NECESSARY	350.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHCEK DIAGNOSTIC OF VEHICLE MANAGEMENT / CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	NOT NECESSARY	180.00	-
			4,770.00	580.00
GRAND TOTAL			22,748.13	4,270.37
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,400.00

Report Ref No. CC4/LPC18007566/Adb3s2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.