26/4/17 @ 10:5 26/4/17 @ mail	570W Authoris	VINDON 4	ny Victor ki Jemium authi	on's repair ex	us to
Part la	1 Part 4828.	08; (le	d: 825092 ECEIVED 19	: 63%)	
Date/Time, File Pass to?	: Preli. Report	Day	s Of Repair:	Survey Fee:	200)
Date/Time, File Return to?		Add Fee:	: Site Insp (\$	Transportation:)S+RSSI	(0
Report Format :	OD		: Interview (\$: Tech. Invs (\$) Photos) Others	
Lump Sum / I.B.I: (\$	4828.00		: Weekend (\$	TOTAL	210



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DESCRIPTION OF THE PERSON OF T		ernationale Des Experts En Auto	mobile			
AIG ASIA PACIFIC II	NSURANCE PTE LTD	Ref : CC3/AIG1800	7582/Atb			
78 SHENTON WAY # CHARTIS BUILDING SINGAPORE 079120		Date: 24-04-2018 Code: AIG				
1.	Policy Par	ticulars :- OWN DAMAGE				
Insured Veh.		Veh. Inspected	SKT 6110R			
Policy No.	2100416177	Coverage (\$)	0.00			
Claim No.		Excess (\$)	0.00			
Assign From		Assign Date	24/04/2018			
2.	Vehicle I	Particulars & Condition				
Make & Model		c.c	0			
Engine No.	HIDDEN	Year of Reg.	WPA.			
Chassis No.		Colour				
Odometer	일	Steering				
Brakes		Modification				
General						
3.	Co	nditions of Tyres				
	Size	Make	Balance			
R/H Front Tyre	K		mm			
L/H Front Tyre			mm			
R/H Rear Tyre			mm			
L/H Rear Tyre			mm			
	Desc	ription of Damages	建			
La Francisco	The state of the second Committee of the	neral Information				
Accident Date	20/04/2018	Inspection Date	24/04/2018			
Survey held at	PREMIUM AUTOMOBILES	PTE LTD				
	55 UBI ROAD 1 . SINGAPORE 408699					
ā.		Remarks				
A)THE MARKET V	VALUE IS S\$(EST. A	AVERAGE)	FRANCE			
A)THE MARKET \ B)IN ACCORDAN	VALUE IS S\$(EST. A CE TO YOUR INSTRUCTION	AVERAGE) S, WE HAVE AUTHORISED R	EPAIRS.			

Denise Tay (LKKAuto)

From:

Denise Tay (LKKAuto)

Sent:

Thursday, 26 April 2018 1:55 PM

To:

Claims; SUR

Subject:

RE: SKT 6110 R Own Damage Claims (Vehicle IN)

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle SKT 6110R (Excess \$0/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAuto)

Sent: Thursday, 26 April 2018 9:07 AM

To: Claims <claims@premiumauto.com.sg>; SUR <sur@lkkauto.com>

Subject: RE: SKT 6110 R Own Damage Claims (Vehicle IN)

Dear Sir,

Still pending AIG approval

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims [mailto:claims@premiumauto.com.sg]

Sent: Thursday, 26 April 2018 9:03 AM

To: SUR < sur@lkkauto.com > Cc: claims@premiumauto.com.sg

Subject: RE: SKT 6110 R Own Damage Claims (Vehicle IN)

Dear all.

View Received Message

This mail is associated with:

*SKT6110R (4455369411SG)

OD
Apr 20 2018 11:30AM
[YAP TIONG PENG]
Premium Automobiles Pte Ltd

Reply Reply All Mark as Unread Print Message Delete Message Forward

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 26/04/2018 10:58 AM.

To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$5273.00) - SKT6110R - Claim Handler: Dally Amri, Mimi Zarina

Approved:5273.00:Re-inspection to be done for damage check and supplementary items / labour.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

AIG Asia Pacific Insurance Pte. Ltd.

AIG Building

78 Shenton Way #07-16 Singapore 079120

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn:

Date: 25 Apr 2018

Preliminary Advice

Vehicle No

: SKT6110R

Accident Date

: 20/04/2018

Make

: AUDI A6

Policy No.

: 2100416177-02000

Assignment Date

: \$\$0.00

: 24/04/2018

Excess

:S\$

Date of Inspection

: 24/04/2018

Est. Duration of Repair

138,000.00

86,916.00

: 4.00

Inspection At

: PREMIUM AUTOMOBILES PTE LTD (UBI)

55 UBI ROAD 1

SINGAPORE 408699

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,079.00
Revised Amount	:S\$	5,273.00
Check Items (Estimated)	:S\$	450.00
Total	:S\$	5,723.00

Lump Sum Repair

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	

:S\$ COE / PARF Rebate

:S\$ Salvage Value

:S\$ 51,084.00 Margin for Repair

Remarks

(×)	The vehicle is repairable at our	adjusted amour	nt. We have	also confirmed	excess and	policy covera	age. Kindly
	let us have your authorisation.						

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		
Owner ID Type:	Singapore NRIC	
Owner ID: Vehicle Details	6126C	
Vehicle No.:	SKT6110R	
Vehicle to be Exported:	No	
Intended De-registration Date:	25 Apr 2018	
Vehicle Make:	AUDI	
Vehicle Model:	A6 1.8 TFSI S TRONIC	
Primary Colour:	Black	
Manufacturing Year:	2015	
Engine No.:	CYG002664	
Chassis No.:	WAUZZZ4G9FN053412	
Maximum Power Output:	140.0 kW (187 bhp)	
Open Market Value:	\$44,607.00	
Original Registration Date:	17 Jun 2015	
First Registration Date:	17 Jun 2015	
Transfer Count:	0	
Actual ARF Paid: Intended PARF Rebate Details	\$44,450.00	
PARF Eligibility:	Yes	
PARF Eligibility Expiry Date:	16 Jun 2025	
PARF Rebate Amount: Intended COE Rebate Details	\$33,337.00	
COE Expiry Date:	16 Jun 2025	
COE Category:	B - Car above 1600cc or 97kW (130bhp)	
COE Period(Years):	10	
QP Paid:	\$75,000.00	
COE Rebate Amount:	\$53,579.00	
Total Rebate Amount:	\$86,916.00	

The information contained herein is correct as at 25 Apr 2018

ОК

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

By the lodgement of this report to the insurers, you hereby consaforesaid.	ent to the archiving of this report at the centre and to copies of the report being made available
A Company of the Comp	ACCIDENT STATEMENT
Date Of Report	21/04/2018 13:47
Date Of Accident	20/04/2018 11:30
Exact Location Of Accident	JUNCTION OF OUTRAM RD AFTER CANTONMENT COMPLEX
Country/State of Loss	SINGAPORE
D	ETAILS OF OWN VEHICLE
Vehicle Registration Number	SKT6110R
Insured/Policyholder	
Name Of Registered Owner	YAP TIONG PENG
NRIC No	S7836126C
Email Address	TIONGYAP@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-91293915
Alternative Phone No	OTHERS-91293915
Vehicle Particulars	
Manufacturer	AUDI
Model	A6 1.8 TFSI ULTRA S
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Vehicle Category PRIVATE CAR

Insurance Company

AIG ASIA PACIFIC INSURANCE PTE. LTD. Name of Insurance Company

COMPREHENSIVE Type Of Coverage

Fleet Policy NO

2100416177-02000 Policy Number

Cover Note Number

Driver

CAROLINE LEE MEI FOONG Name of Driver

S7619468H NRIC No Date Of Birth 18/06/1976 INDOOR Occupation 18/07/1996 Date Of Driving Pass

21 YEARS AND 9 MONTHS Driving Experience

FEMALE Gender

(LOCAL) +65-94230618 Mobile Number

Fax Number

Contact Number

NOEMAIL **EMail Address**

Address

8 BALMORAL CRESCENT

#10-04

Postcode

259928

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

SPOUSE

Vehicle Registration Number of Driver's Own

Vehicle

2

Insurance Company of Driver's Own Vehicle

ै

General Information of the Accident

Type Of Accident

SIDE SWIPE

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

NO

ambulance?

YES

Was any other material or property damaged?

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO THE ACCIDENT STATEMENT

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SLS4731E

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- Piease report correctly the details of the accident to speed up the claims process.
- This Form most be completed by the Policyholder and/or the Authorised Driver.
- information provided must be an truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties
- 7. By the ladgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8 Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims,
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me. which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents[including their lawyers/law firms], which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature Name: Tony Found

NRIC/FIN No.

G7040197X

Sketch Plan #2

SKETCH PLAN

A- SKTGHOR

I was driving	straight and slow, careful of
the coadworks	at this busy junction. Suddenly
a white car	side swept my car, I heard a
grating noise	. Our car has in-car camera

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature Date & Time:

Driver's Signature (If driver is not the policyholder) Date & Time.

Reporting Centre Personnel's Signature
Name: Town Loves
NRIC/FIN No. 676 401 478





Accident Photo



REPUBLIC OF SINGAPORE DRIVING LICENCE Licenson Navideer S7619468H CAROLINA LEE MEI FOONG (CAROLINA LI MEIFENG) Birth Date 18 Jun 1976 Issue Date 20 Jul 2003 000669135C

REPUBLIC OF SINGAPORE IDENTITY CARD NO. \$7619468H





CAROLINA LEE MEI FOONG

凤

CHINESE

18-06-1976

57619466H

Country of birth SINGAPORE

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

NP 428A



NC No. S7619468H

06-09-2006

8 BALMORAL CRESCENT #10-04 SINGAPORE 259928

S7619468H

06/04/2018

NRIC No:



CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT(CHAPTER 189) MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960 ROAD TRANSPORT ACT, 1987 (MALAYSIA) MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

M.X.1

AUDI AUTO PROTECTOR

CERTIFICATE NO. 2100416177-02000

OWN DAMAGE EXCESS WINDSCREEN EXCESS

S\$800.00(I) S\$100.00

SUM INSURED

Market Value

INSURING WITH COE/PARF

SKT6110R

1) VEHICLE REGISTRATION NO.

2) NAME OF INSURED

YAP TIONG PENG

3) EFFECTIVE DATE OF THE COMMENCEMENT OF INSURANCE FOR THE PURPOSES OF THE ACT 17 Jun 2017

4) DATE OF EXPIRY OF INSURANCE

16 Jun 2018

5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE * SUBJECT TO AGE CONDITION :35 years old and above

b) Any other person who is driving on the Insured's order or with his permission.

A Young and/or Inexperienced Driver Excess ("YIDR") of \$\$3,000.00, in additional to the

Policy Excess, applies to You and any Authorised Driver (named or unnamed) if You are or the said

Authorised Driver is below the age of 23 and/or has less than 2 years' driving experience.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6) LIMITATION AS TO USE *

Use only for social, domestic and pleasure purposes and for the Insured's business. The Policy does not cover use for hire or rewards, tuition, driving test, racing, pace-making, reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

APPROVED REPORTING CENTRES / AUDI AUTHORISED REPAIRERS

1. Audi Customer Service Center - 55 Ubi Road 1 (Tel: 63662323)
APPROVED REPORTING CENTRES / AIG AUTHORISED REPAIRERS (FOR CLAIMS-RELATED REPAIRS)

2. ComfortDelgro Engrg - 205 Braddell Rd (Tel: 63837118) 3. DPS Body & Paint Workshop - 209 Pandan Gardens (Tel: 65684501) 4. Ethoz - 30 Bukit Batok Cres(Tel:66547777) 5. Glass-Fix - 52 Ubi Ave 3 (Tel: 62780887) - For windscreen only 6. Kan Fook Sing Motor - 61 Defu Lane 12 (Tel: 67479560) 7. Lai Huat (Meng Kee) Motor - 21 Sin Ming Ind (Tel: 64538110) 8. Mova Automotive - 1008 Bukit Merah Lane 3 (Tel: 62723892) 9. Progressive Automotive - 3022A Ubi Rd 1 (Tel: 67415336) 10. SME Motor - 1 Kaki Bukit Ave 6 Blk D (Tel: 67476106)

LOSS OF USE Loss Of Use 15 days Replacement Car only for repairs at Audi Customer Service Centre

NAMED DRIVER

NA

HIRE PURCHASE COMPANY DBS BANK LTD / EMPLOYER'S LOAN

Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued At Singapore

12 Jun 2017

AIG Asia Pacific Insurance Pte. Ltd.

PREMIUM LEASING - SP 281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE SINGAPORE 159938

AUTHORISED REPRESENTATIVE

SSPLIC

Reg. No. 201009404N

GEN041-02/13

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

 Estimate
 : Accident Repairs

 Workshop
 : Ubi Road 1

 Contact No
 : 6366 2323

 Fax No
 : 6841 1183

Reference : PA/OD/0478/2018/GW

Date : 24-Apr-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Yap Tiong Peng
Address : 8 Balmoral Crescent

#10-04

Singapore 259928 HP +65 91293915

 Telephone
 : HP +65 91293915

 Type of Claim
 : Own Damage Claim

 Policy No.
 : 2100416177-02000

 Vehicle No
 : SKT 6110 R

Model Code : Audi A6 1.8 TFSI Ultra S

Model / Year : Jun-15 Engine No : CYG 002664

Chassis No : WAUZZZ4G9FN053412

Mileage : Date In :
Liability : Excess Cost : -

Estimated By : Johnny Boo / Allan Wu

Accident Date : 20-Apr-18

Place of Accident : Junction Of Outram Rd After Cantonment Complex

Premium Automobiles 55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKT 6110 R.

			Estimated
Nature of Jobs			Charges
To remove and transfer front wire harness for headlights, horns, fog lmaps, outside temperature sensor, headlight washer assy and front parking aid.	S/N	\$	480.00
400			
To dismantle and renew front bumper and lhs front fender. Re-organise front crash management components.reinstall all parts removed.		\$	2,100.00 /000
To remove lhs front door panel trims, dismantle and renew lhs wing mirror assy.	S/N	\$	350.00 ×
To respray front bumper and rhs front fender.		\$	1,600.00 1100
To renew lhs front rim and carry out wheel alignment.	S/N	\$	280.00
To carry out diagnostic check.	S/N	\$	192.00
TOTAL LABOUR CHARGES	:	\$	5,002.00
	To remove and transfer front wire harness for headlights, horns, fog Imaps, outside temperature sensor, headlight washer assy and front parking aid. To dismantle and renew front bumper and Ihs front fender. Re-organise front crash management components.reinstall all parts removed. To remove Ihs front door panel trims, dismantle and renew Ihs wing mirror assy. To respray front bumper and rhs front fender. To renew Ihs front rim and carry out wheel alignment. To carry out diagnostic check.	To remove and transfer front wire harness for headlights, horns, fog Imaps, outside temperature sensor, headlight washer assy and front parking aid. To dismantle and renew front bumper and Ihs front fender. Re-organise front crash management components.reinstall all parts removed. To remove Ihs front door panel trims, dismantle and renew Ihs wing mirror assy. To respray front bumper and rhs front fender. To renew Ihs front rim and carry out wheel alignment. S/N To carry out diagnostic check. S/N	To remove and transfer front wire harness for headlights, horns, fog Imaps, outside temperature sensor, headlight washer assy and front parking aid. To dismantle and renew front bumper and lhs front fender. Re-organise front crash management components.reinstall all parts removed. To remove lhs front door panel trims, dismantle and renew lhs wing mirror assy. To respray front bumper and rhs front fender. S/N \$ To renew lhs front rim and carry out wheel alignment. S/N \$

Premium Automobiles 55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKT 6110 R.

1 2 3 4	FRONT BUMPER FIXING PARTS FRONT BUMPER GUIDE PIECE-LH FRONT BUMPER BRACE-LH FRONT FENDER-LH FRONT FENDER-LH Sexted.	\$ \$ \$ \$	3,321.00 × 43.00 × 32.00 ×	REMARKS
2	FRONT BUMPER FIXING PARTS FRONT BUMPER GUIDE PIECE-LH FRONT BUMPER BRACE-LH	\$	43.00÷	¢-
2	FRONT BUMPER FIXING PARTS FRONT BUMPER GUIDE PIECE-LH FRONT BUMPER BRACE-LH	\$	43.00÷	ζ.
3	FRONT BUMPER GUIDE PIECE-LH	\$	32.00 *	
(5)	FRONT BUMPER BRACE-LH			
4		\$	100000 00000 1000	
	FRONT FENDER-LH Deuted		25.00	
5		\$	1,220.00	- 976
6	FRONT FENDER ATTACHEMENT PART-LH ALL NEC .	\$	88.00 ?	
7	FRONT STONE GUARD FILM-LH Kleen	\$	105.00	- 83.60
8	FRONT FENDER BRACE-LH Best	\$	72.00	- 57.28
9	FRONT WHEEL SPOILER-LH	\$	232.00	e.
10	FRONT WHEEL HOUSING LINER-LH NOT NO	\$	246.00	*
11	WHEEL HOUSING LINER ATTACHMENT PART HOLD NO	c \$	62.00	?
12	FRONT EXTERIOR MIRROR MOUNTING-LH	\$	1,237.00	T
13	FRONT EXTERIOR MIRROR HOUSING-LH Pers	\$	159.00 >	e
14	TURN SIGNAL INDICATOR	\$	111.00 5	c
15	FRONT ALUMINIUM RIM -LH Cut	\$	824.00	C59.20
16	SUNDRIES RHE NCC.	\$	300.00	? 631770
	TOTAL SPARE PARTS :	\$	8,077.00	
	TOTAL LABOUR CHARGES :	\$	5,002.00	
	GRAND TOTAL :	\$	13,079.00	

All charges are not inclusive of GST.

Legend :

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

: Adrian

Surveyed Date

: 24/04/18.

Authorised Date Excess Cost

:

Liability

Remarks

: Not Authorised, 04 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey beforecaste, spray painting
- To display damaged partis) during resurvey.
- · Parts prices the sime it to confirmation
- . Third party survey is on a "Without Prejudice" basis.
- . No illegal modification(s) is allowed
- Supplementary demis) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

: This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully, Premium Automobiles Pte Ltd

Johnny Boo Body Repair Manager Allan Wu Claims Consultant

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate

Accident Repairs

Workshop

Ubi Road 1

6841 1183

Contact No

6366 2323

Fax No Reference

PA/OD/0478/2018/GW

Date

: 24-Apr-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name

Mr. Yap Tiong Peng

Address

8 Balmoral Crescent

#10-04

Singapore 259928

Telephone

HP +65 91293915

Type of Claim

Own Damage Claim

Type of Clan

2100416177-02000

Policy No.

2100410177-02000

Vehicle No

SKT 6110 R

Model Code

Audi A6 1.8 TFSI Ultra S

Model / Year

Jun-15

Engine No

CYG 002664

Chassis No

WAUZZZ4G9FN053412

Mileage

.

Date In

...

Liability

:

Excess Cost

.

Estimated By

Johnny Boo / Allan Wu

Accident Date

20-Apr-18

Place of Accident

Junction Of Outram Rd After Cantonment Complex

Hi Adrian

4 days - ok - jb 23 Jun 18

Premium Automobiles 55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKT 6110 R.

	Nature of Jobs		Estimated Charges	
S/N	To remove and transfer front wire harness for headlights, horns, fog Imaps, outside temperature sensor, headlight washer assy and front parking aid.	S/N	\$ 480.00	\$ 480.00
2	To dismantle and renew front bumper and lhs front fender. Re-organise front crash management components reinstall all parts removed.		\$ 2,100.00	\$ 1,000.00
3	To remove lhs front door panel trims, dismantle and renew lhs wing mirror assy.	S/N	\$ 350.00	
4	To respray front bumper and rhs front fender.		\$ 1,600.00	\$ 1,100.00
5	To renew lhs front rim and carry out wheel alignment.	S/N	\$ 280.00	\$ 280.00
6	To carry out diagnostic check.	S/N	\$ 192.00	\$ 192.00
	TOTAL LABOUR CHARGES	:	\$ 5,002.00	\$ 3,052.00

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKT 6110 R.

			Damage Pa	rts (& Prices
S/N	Parts Description		S/NETT		REMARKS
Ont					
1	FRONT BUMPER		\$ 3,321.00		
2	FRONT BUMPER FIXING PARTS		\$ 43.00		
3	FRONT BUMPER GUIDE PIECE-LH		\$ 32.00		
4	FRONT BUMPER BRACE-LH		\$ 25.00		
5	FRONT FENDER-LH		\$ 1,220.00	\$	976.00
6	FRONT FENDER ATTACHEMENT PART-LH		\$ 88.00		
7	FRONT STONE GUARD FILM-LH		\$ 105.00	\$	83.60
8	FRONT FENDER BRACE-LH		\$ 72.00	\$	57.28
9	FRONT WHEEL SPOILER-LH		\$ 232.00		
10	FRONT WHEEL HOUSING LINER-LH		\$ 246.00		
11	WHEEL HOUSING LINER ATTACHMENT PART		\$ 62.00		
12	FRONT EXTERIOR MIRROR MOUNTING-LH		\$ 1,237.00		
13	FRONT EXTERIOR MIRROR HOUSING-LH		\$ 159.00		
14	TURN SIGNAL INDICATOR		\$ 111.00		
15	FRONT ALUMINIUM RIM -LH		\$ 824.00	\$	659.20
16	SUNDRIES		\$ 300.00		
	TOTAL SPARE PARTS	:	\$ 8,077.00	\$	1,776.08
	TOTAL LABOUR CHARGES	:	\$ 5,002.00	\$	3,052.00
	GRAND TOTAL		\$ 13,079.00	\$	4,828.08

All charges are not inclusive of GST.

Legend:

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Name

:

Surveyed Date

Authorised Date

•

Excess Cost

- -

Liability Remarks

•

Please Note

: This estimate is based on visual inspection of the affected vehicle.

Should we require further labour charges and spare parts in the

progress of repair, we shall inform you accordingly.

For inspection of vehicle, please refer to Ms Norah Khai at

Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo Body Repair Manager Allan Wu Claims Consultant

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Motor Claims Dept

Yr Ref: SKT 6110 R

Norah Khai 6768 9911 6841 1183 Nora.khai@premiumauto.com.sg Body & Paint Dept PA/OD/0478/2018/MAS

17 July 2018

from

Telephone +65-Telefax +65-

EMail

Our department

Our Ref Your Ref

total pages

Date

Dear Sir,

RE: INSURANCE CLAIM FOR SKT 6110 R, Audi A6 1.8 TFSI Ultra S-Tro

With reference to the above-mentioned vehicle, no SKT 6110 R, claimant, Mr. Yap Tiong Peng, please find the related document per attached.

- A copy of the Original invoice no. 85012705 S\$5,166.05
- 2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai Claims Dept

Enels

AIG - SKT 6110 R

Premium Automobiles Pte Ltc Showroom 9 Leng Kee Road Singapore 159090

Telephone (65) 6566 1111 Telefax (65) 6471 3733

Service & Parts Centres 55 Ubi Rd 1 Singapore 408699 Telephone (65) 6336 2323 Telefax (65) 684 11183

...CLAIM SUBFOLDER...(Pending for Survey Report)

-w/2022	Notified	Ext C	bmitted	Adi Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status	
Case	25 Apr 2018 14:04	ESUSI	omitted	24 Apr 2018 17:56 Edit Adj Rpt	S\$4,828.08 Edit Estimates	5\$4,828.08 View Rpt		Report Cancel Case	
	Main		Ref	erence	Claim De	tails	Documents	Show All	
CI ATM S	SUBFOLDER DE	TATLS	S-C-0 N-1 N-1		The state of the s	Harman Street, St. Co., St. Co	[Create	d by insurer]	
and the second second	OBI OLDER DE		YAP TI	ONG PENG, ID:	S7836126C, Tel:	+6591293915	100000000000000000000000000000000000000		
Insured: Vehicle Reg. No.:			SKT61		Date of	Date of Loss:		20/04/2018 12:00 - :59 [34 Months and 3 Days From LTA Reg Date (Man Yr)]	
Claim Ty	ne'		OD / 4455369411SG		Policy/C	Policy/Cover Note No.:		2100416177 (Comprehensive)	
Cidiiii (y)	pe.			Excess: S			S\$0.00	4.0.10.0	
Repairer:			Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911						
Handling Insurer:			AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 [Handled by Dally Amri, Mimi Zarina] MimiZarina.DallyAmri@aig.com LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 [Handled by ADRIAN LING] [Final Rpt						
Adjuster:			due 04	1/05/2018]					
Driver/Ci	ustodian:		CAROLI	NE LEE MEI FOON	G (41 / Female),	NRIC: S7619468H,	Tel: +6594230	618	
ASSOCI	ATED MAIL RE	CEIVED	,				View All	Compose Case Mail	
- 410 6	C /26/04/2018\:	Alert -	Adi Mano	date Approved (5 / 20/04/2018 /	\$\$5273.00) - SKT / Coverage & Exc	6110R - Claim Han ess update	dler: Dally Amr	l _r	
E ALL AS	SOCIATED TAS	KS			Vie	ew All Search Tas	sks Create	New Task Complete	
Due D	0	Туре	Task G	iroup Subject	Handler /	Assigned By Co	ompleted On	Created On Done	


Claim Documents

*SKT6110R (4455369411SG)
OD
Apr 20 2018 12:00PM
[YAP TIONG PENG]
Premium Automobiles Pte Ltd

- 3	Upload Documents	Upload Photos Compose New Letter Upload Video Upload Audio	1	nage 🔻	V
Vide	80	1000 0000 W. Comment	1 per p	Thumbnail	
No	Finalized On	Premium Automobiles Pte Ltd (UBI) Video - Accident	-	TO CONTRACTOR OF	Print
1	21/04/18 13:53	0	Load MP4		
Ass	essment Reports		1 per p		V
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	25/04/18 14:12	Adjuster Immediate Advice	0	Load HTM	
Pho	otos/Images		3 per	page 🔻	V
	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
No 1	25/04/18 13:59	General View	0	Load JPG	V
2	25/04/18 13:59	General View	0	Load JPG	V
3	25/04/18 13:59	General View	0	Load JPG	V
71.500	25/04/18 13:59	General View	0	Load JPG	V
4	Formation to the company	General View	0	Load JPG	[7]
5	25/04/18 13:59	General View	0	Load JPG	V
6	25/04/18 13:59	General View	0	Load 3PG	V
7	25/04/18 13:59	General View	0	Load JPG	V
8	25/04/18 13:59	S 2000 100 100 100 100 100 100 100 100 10	0	Load JPG	V
9	25/04/18 13:59	General View	0	Load JPG	V
10	25/04/18 13:59	General View	0	Load JPG	V
11	25/04/18 13:59	General View	0	Load JPG	[V]
12	25/04/18 13:59	General View	0	SESSION BOS	V
13	25/04/18 13:59	General View		Load JPG	1
14	25/04/18 13:59	General View	0	Load JPG	V
15	25/04/18 13:59	General View	0	Load JPG	V
16	25/04/18 13:59	General View	0	Load JPG	V
17	25/04/18 13:59	General View	0	Load JPG	V
18	25/04/18 13:59	General View	0	Load JPG	V
19	25/04/18 13:59	General View	0	Load JPG	V
20	25/04/18 13:59	General View	0	Load JPG	V
21	25/04/18 13:59	General View	0	Load JPG	V
22	70200000000000000000000000000000000000	General View	0	Load JPG	U
	3 25/04/18 13:59	General View	0	Load JPG	V
			1 ne	r page 🔻	7
Do	Documentation Pto Ltd (HO)		. pc	Thumbna	and the same
N	The state of the s	LKK Auto Consultants Pte Ltd (HQ) Certificate of Insurance	6	The second second second second	-
1		Driver's Driving License	0		
2		ESTIMATE	6	Load PDF	el l
3		Singapore Accident Statement	0		
4		WORKSHOP INVOICE	6		2
- 5	20/07/18 10:31	DISCHARGE VOUCHER	0		8

Linked Accident Report Documents

		View Use Viewer	
Video		1 per page	
Video		Thumbnail	Print
No Finalized On	Premium Automobiles Pte Ltd (UBI)		1



Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	*
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Email: sur@lkkauto.com;assignments@lkkauto.com Tel: 6256-3561 Fax: 6844-8805

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.

AIG Building, 78 Shenton Way #07-16

Singapore 079120

Our File No:

CC3/AIG18007582/ATBN2

Date:

20/07/2018

REFERENCE

Insured/Claimant: Date of Loss:

YAP TIONG PENG

20/04/2018

Policy No: Nature of Claim: 2100416177 OD

Claim No:

4455369411SG

WAUZZZ4G9FN053412

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SKT6110R

Make & Model:

AUDI A6, 1.8 TFSI Ultra (PI) (NAV) (A)

17/06/2015 (Man. Year: 2015)

Engine No: Chassis No: Odometer:

CYG002664

25921 km

Reg. Date: Colour:

Price:

Black 1798 cc

CONDITION OF VEHICLE AT THE TIME OF SURVEY

Engine Capacity: Market Value/New Car

S\$138,000.00

Sum Insured (S\$):

Market Value/New Car Price

Yes Footbrake (Serviceable):

Handbrake (Serviceable):

Steering (Serviceable): Yes Engine Modification:

Pre-accident Condition:

Yes

CONDITION OF TYRES

Front Tyre Size:

General Condition:

245/45R18

Rear Tyre Size:

245/45R18

Front Left Side:

Bridgestone 6 mm

Rear Left Side:

Bridgestone 6 mm

Front Right Side:

Bridgestone 6 mm

Rear Right Side:

Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS Parts Miscellaneous Items	Repairer's 8,077.00 0.00	Adjuster's 1,776.08 0.00	6,300.92 0.00	78.01
Labour	5,002.00	3,052.00	1,950.00	38.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	13,079.00	4,828.08	8,250.92	63.09
+ GST 7.00/7.00% (S\$)	915.53	337.97	577.56	63.08
Nett Amount (S\$)	13,994.53	5,166.05	8,828.48	63.09

INSPECTION

Date of Assignment:

24/04/2018

Date Inspected:

24/04/2018 Inspected At:

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1 Singapore 408699

Estimated Period of Repair:

4.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

No.		mended Parts Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER *FRONT BUMPER FIXING PARTS	Repair Not Necessary	3,321.00 FS 43.00 FS	*-FS
3	1	*FRONT BUMPER GUIDE PIECE-LH *FRONT BUMPER BRACE-LH	Not Necessary Not Necessary	32.00 FS 25.00 FS	*-FS *-FS
5	1	*FRONT FENDER-LH *FRONT FENDER ATTACHMENT PART-LH	Dented Not Necessary	1,220.00 FS 88.00 FS	*976.00 FS *- FS
6 7	1	*FRONT STONE GUARD FILM-LH *FRONT FENDER BRACE-LH	Necessary Bent	105.00 FS 72.00 FS	*83.60 FS *57.28 FS
9	1	*FRONT WHEEL SPOILER-LH *FRONT WHEEL HOUSING LINER-LH	Not Necessary Not Necessary	232.00 FS 246.00 FS	*- FS *- FS
10 11 12	1	*WHEEL HOUSING LINER ATTACHMENT PART *FRONT EXTERIOR MIRROR MOUNTING-LH	Not Necessary Not Necessary	62.00 FS 1,237.00 FS	
13	1	*FRONT EXTERIOR MIRROR HOUSING-LH *TURN SIGNAL INDICATOR	Repair Not Necessary	159.00 FS 111.00 FS	
15 16	1	*FRONT ALUMINIUM RIM-LH *SUNDRIES	Cut Not Necessary	824.00 FS 300.00 FS	
	F=Franchise part. S=SpcNett.		Total Parts (S\$)	8,077.00	1,776.08

Recommended Miscellaneous Items There are no new miscellaneous items selected.

Recommended	Labour
Recommended	Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			480.00
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	(1.000 cultical)
2	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS FRONT FENDER.RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,100.00	1,000.00
3	TO REMOVE LHS FRONT DOOR PANEL TRIMS.DISMANTLE AND RENEW LHS WING MIRROR ASSY	New	350.00	-
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	1,600.00	1,100.00
5	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
	Gross Labor	ır Cost (S\$)	5,002.00	3,052.00
	Report was unsubmitted duri	ng this print-out.		

< END OF ESTIMATES >