

51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref: AM1-ylv-INS-E25-100174-16-pmv

Date: 15th May 2018

Our Ref: CS1/LAW18007583/Arbe2

M/s VISION LAW LLC*
133 NEW BRIDGE ROAD #18-01/02
CHINATOWN POINT
SINGAPORE 059413

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:

SKU 9797J

INSURED VEHICLE: SKR 9224L ACCIDENT DATE: 01/03/2016

We thank you for your instruction on 23/04/2018.

We acknowledge receipt of the following documents:-

a) Automobile Inspection Report of SKU 9797J from M/s Gtg Appraiser Services Llp.

b) Survey report by Infiniti Appraisal service.

c) Singapore Accident Statement of Vehicles SKU 9797J and SKR 9224L.

d) Colour damaged vehicle photographs of SKU 9797J.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number

: SKU 9797J

Make & Model

: Volvo XC90 V8 A

Year of Registration

: 2007

Chassis Number

: YV1CZ855671366820

- 2. We recommend that the repairs of the entire damage require about <u>8 (eight)</u> working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.