

## Thin Thin (LKKAUTO)

---

**From:** Thin Thin (LKKAUTO)  
**Sent:** Tuesday, 17 July 2018 7:17 PM  
**To:** Md Noor, Norsiah  
**Subject:** ACCIDENT ON 21/04/2018 INVOLVING VEHICLES EZ 58M AND SKL 1025D

Your Ref: 3089532283SG  
Our Ref: CC3/AIG18007584/R1ua3

Dear Norsiah,

### **ACCIDENT ON 21/04/2018 INVOLVING VEHICLES EZ 58M AND SKL 1025D**

We refer to the above matter.

Please be inform that we have inspected the vehicle SKL 1025D on 27/04/2018, at Performance Motors Limited and up-to-date there was no response from TP repairer due to liability unclear.

In view of the above, we are intending to temporary close our file and submit W/P report to your good office.

If there are any new developments in future, kindly inform us and we will follow up if necessary.

Best Regards,

**Thin Thin Hlaing** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2360 | email: [thinthin@lkkauto.com](mailto:thinthin@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)