



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18007606/R1vbn2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 02-07-2018



Code : FCI2

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SKG 6985B
Policy No. D-17088618MVPC	Coverage (\$)	0.00
Claim No. D18003241MVPC	Excess (\$)	0.00
Assign From HARMINDER KAUR	Assign Date	25/04/2018

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ C 180	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	WDD2040312A741947	Colour	GREY
Odometer	76184	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R17	CONTINENTAL	6 mm
L/H Front Tyre	225/45 R17	CONTINENTAL	6 mm
R/H Rear Tyre	225/45 R17	CONTINENTAL	6 mm
L/H Rear Tyre	225/45 R17	CONTINENTAL	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	23/04/2018	Inspection Date	25/04/2018
Survey held at	CYCLE & CARRIAGE INDUSTRIES (1986) PL 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE MARKET VALUE IS S\$74,000.00 (EST. AVERAGE)
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**