23/03/2002 /a/S. RF.C. BY:		REF:	Cs/FC	1007600811	/RIVb	na Specia	il Instructio	n:		
Surveyor =	Rasul		ASSIG	NMENT (C	office)					
From (Person);	Harminder	Kaur	of	fa		Da	ate/Time	25042616	8 11 Bian)
Estimated Cost:				Bill to						
To Inspect Vehi			1/1NV/1			Insured:				
at Workshop m/	8	-	0	Corriage		Tel:	91	86 5109		
of		18	is kunul	on Loup		01000	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	box Dr		
Policy No:				Cla	im No: _	D1800 ◆ O) ३ गर्मा	MALC		-
Sum Insured:				E	xcess:				•	
Make of Veh: (Client's Record)	REP. / REV	24 HRS				D)304201 pdorsement:_	8	
Date/Time:	15047018 12	USpm P	erson Cont	ncted:	(ik	Ve	hicld ID	LOUT		
Date/Time	Action/Instruc	1	,	imate						
	SKG 6985	B- NA	and the same of th	007508/hl				DO4:)	3042018	
26/4/18	Email	oreli r	evised	to FCI						
21/6/18			And the second of the second	1 forware		finalise	rd			
28/6/18		fig \$	9448	(Red :	2694.8	> >>90) (on	firmal !	by ema	il

STANDOLL SAME REE:		45912
STANDA AL	ASSIGNMENT	
From Date:	Veh No. SKG 6985	B Yr Regn: 2012 / 868
) 10m.	Type M.Car / M.Cycle / Bus / Van	
Estimated Cost: OP TP //WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or	
To Inspect Vehicle No: SKG 6985B	Make: MERCENES Pro	2 (180 BE: 1595
at Workshop m/s CYCLE	Colour GREY	A/C: Insured / Std / NI / NA
of PANDAN WAS	Sp.Reading 76 184	T/Radio: Insured / Std / NI / NA
rul	Eng/No:	880
	C/No. WDO 20403	312A741947
Policy No.	Gen. Cond: Good / Pay / Poor / B	
Claims No. Sum Insured: Excess: O	Steering: Inforder / Jammed / Leal	ked/Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leal	ked / Burnt or
(Client's Record) Make of Veh:	Modi: Nil / SRIM / STD A/Rin	n or
27	Tyre Size: F: 2	25/45RIT
(Policy Condition)	R:	1 4
Remark: The veh had commenced its	O/S BS/DUN/EXNOVA/GY/FS/L	IZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO / YOKO or	CONTINENTAL
Bal. or Market Value: 74K	Front	Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. mm	R/Bal. 6 mm
GIA / PR Seen: Consistent?: Yes or No	L/Bal. mm	L/Bal. 6 mm
Est Repairs: 6 days Res,: Yes or No	D.O.A. 23/04/18	D.O.I. 25/04/18
Lum Sum: % 3 Val.: Yes or No	Survey held at C&C	(PL)
	Des, of Damages : Frt / Rear /	O/S / N/S / U/C / Rooftop or
CA) REV / REP. / 24 HRS	e: IN/OUT	SFRT
Date: Person Contacted:		Body Structure affected due to collision.
Date / Time Action / Instruction		
RECEIVED 2 8	HIN 2018	
KECLIVED 2 0	3011 2010,	
Date/Time, File Pass to? : Preli. Report	Days Of Repair: 6	2 الله علاد
Final Report	Resurvey No. of Trip:	Survey Fee: 170+ 30
1) : Final Report Date/Time, File Return to?		Transportation 50
2) 2816- typist	Add Fee: : Site Insp (\$)*S+RS,SI 30
Sh.	: Interview (\$) Photos 35
Report Format : OS	: Tech. Invs (\$) Others
Lump Sum / I.B.I: (\$ 9448 2)	: Weekend (\$)
Lumn Sum / LB L L3 CHECK L		



Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your ref:

D18003241MVPC

Our Ref:

CS/FCI18007606/R1vb

Date: 26/4/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.SKG 6985B

We thank you for your instruction on

25/4/2018

Please be informed that we had conducted the inspection of the above mentioned

25/4/2018

at the premises of M/s

CYCLE & CARRIAGE INDUSTRIES (1986) PL

and have the following to report:-

Workshop Estimate Amount

: S\$11,912.62

Revised Estimate Amount

\$\$4,479.06

"Check" Items Amount

: S\$6,473.56

Market Value

: S\$74,000.00

LTA Reimbursement Value

: S\$53,578.00

Nett Value

\$\$20,422.00


Description of Damage:

The vehicle sustained damages at the

n/s front portion

nearside

rear



front

Comments/Present Status:

Damages Consistent

Repair Cost Economical

Yours faithfully,

MOHAMMED RASUL Automotive Assessor

Veron Chen (LKKAuto)

From:

Veron Chen (LKKAuto)

Sent:

Thursday, 28 June 2018 10:35 AM

To:

'Dennis Yap Kian Meng'; Yik Chan Hoe; Rasul (LKKAuto)

Cc:

SUR

Subject:

RE: SKG6985B final bill

Dear Mr Yik,

WITHOUT PREJUDICE

Confirmed amount \$9448 before GST @ 6 working days.

Final invoice and all supporting documents sent over to First Capital Ins Ltd.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Dennis Yap Kian Meng [mailto:dennis.yap@cyclecarriage.com.sg]

Sent: Wednesday, 27 June 2018 6:29 PM

To: Yik Chan Hoe <chanhoe.yik@cyclecarriage.com.sg>; Rasul (LKKAuto) <Rasul@lkkauto.com>

Cc: SUR <sur@lkkauto.com> Subject: RE: SKG6985B final bill

Hi Yik,

As requested

With thanks & best regards

Dennis Yap

Technical Executive

Mercedes-Benz Body Care & Repair Center

Cycle & Carriage Industries Pte Ltd 188 Pandan Loop Service Center

TEL: 67778388 | DID 67714434 | HP 94506582

Wedsite: www.mercedes-benz.com.sg

----Original Message-----

From: Yik Chan Hoe

Sent: Friday, 22 June, 2018 11:37 AM

To: Rasul@Ikkauto.com; Dennis Yap Kian Meng

Cc: 'sur@lkkauto.com' Subject: SKG6985B final bill

Hi Rasul,

Fyna.

Hi Dennis,

Please forward the ? item photos to Rasul.

Thanks & Regards,

Yik Chan Hoe Mercedes-Benz Body Care & Repair Center Cycle & Carriage Industries Pte Ltd Pandan Loop Service Center Mobile: 9186 5109 | DID: 6771 4353 | Fax: 6872 1272

Website: www.mercedes-benz.com.sg

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

Catherine Chong (LKK Auto)

From:

Harminder Kaur < Harminder@msfirstcapital.com.sg>

Sent:

Wednesday, 25 April, 2018 11:59 AM

To:

assignments@lkkauto.com

Cc:

Joanne Yong Lai fong

Subject:

OUR REF D18/3241M/PTE/JY

Attachments:

MSA.pdf; SKG6985B OD Claim (843 KB); MT00013605 is Approved (2.39 KB)

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly forward us your report by email only to Surveyor@first-insurance.com.sg within the next 14 days.

Thank you.

Best Regards, Harminder Kaur Motor Claims

MS First Capital Insurance Ltd

A Member of MS&AD Insurance Group



Change of email address

harminder@msfirstcapital.com.sg

36 Robinson Road, #16-01 City House, Singapore 068877 | Tel: 6507 3848 | Fax: 6507 3849 | Reg. No. 195000106C

Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data. Please refer to http://www.msfirstcapital.com.sg for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged. If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it. If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No.195000106C GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date

25/04/2018

Our Ref No.

D18003241MVPC

Accident Date

23-04-2018

Claim Type

Own Damage

Insured Vehicle

SKG6985B

Third Party Vehicle

Survey Location

CYCLE & CARRIAGE

Contact Person

CHAN HOE

INDUSTRIES PTE LTD PANDAN LOOP SERVICE

CENTER 188 PANDAN LOOP (S)

128378

Contact No.

91865109

Fax No.

Survey Type

Authorise if in order

Appointed

Surveyor

LKK AUTO CONSULTANTS PTE LTD

Contact Person

Fax No. 68416315

Contact Number

62563561

EXCESS APPLICATION FOR OWN DAMAGE CLAIM ADDITIONAL \$500.00 FOR INSURED VEHICLE INSTALLED WITH CNG TANKER

Basic	Y/I Driver	Total
SO.	\$0	\$0

Encl. Accident Reports & Estimate \$12746.50

Cc: Workshop CYCLE & CARRIAGE INDUSTRIES PTE LTD

Attention CHAN HOE

Officer Incharge JOANNEY

IMPORTANT NOTE

Kindly submit the survey report by email only to surveyor@first-insurance.com.sg within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Veron Chen (LKKAuto)

From:

Veron Chen (LKKAuto)

Sent:

Thursday, 21 June 2018 2:36 PM

To:

'Joanne Yong Lai fong'

Cc:

SUR

Subject:

RE: OUR REF D18/3241M/PTE/JY, SKG 6985B

Dear Joanne,

We are pending finalise from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Joanne Yong Lai fong [mailto:Joanneyong@msfirstcapital.com.sg]

Sent: Thursday, 21 June 2018 2:21 PM

To: Veron Chen (LKKAuto) < veronchen@lkkauto.com>

Cc: SUR <sur@lkkauto.com>

Subject: RE: OUR REF D18/3241M/PTE/JY, SKG 6985B

Dear Veron,

Any update on the report?

Thank you

Regards,

Joanne Yong Motor Claim Department



Change of email address

joanneyong@msfirstcapital.com.sg

First Capital Insurance Limited

A Member of MS&AD Insurance Group 36 Robinson Road #16-01 City House Singapore 068877 Tel: 6507 3846

Fax: 6507 3849

Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data. Please refer to www.first-insurance.com.sg for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged. If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it. If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

From: Harminder Kaur

Sent: Thursday, 26 April, 2018 2:41 PM

To: Veron Chen (LKKAuto) < veronchen@lkkauto.com >; Joanne Yong Lai fong < Joanneyong@msfirstcapital.com.sg >

Cc: SUR < sur@lkkauto.com>

Subject: RE: OUR REF D18/3241M/PTE/JY, SKG 6985B

Dear Joanne,

FYI.

Thank you.

Best Regards, Harminder Kaur **Motor Claims**

MS First Capital Insurance Ltd

A Member of MS&AD Insurance Group



Change of email address

harminder@msfirstcapital.com.sg

36 Robinson Road, #16-01 City House, Singapore 068877 | Tel: 6507 3848 | Fax: 6507 3849 | Reg. No. 195000106C

Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data. Please refer to http://www.msfirstcapital.com.sg for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged. If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it. If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]

Sent: Thursday, April 26, 2018 1:59 PM

To: Harminder Kaur < Harminder@msfirstcapital.com.sg >

Cc: Joanne Yong Lai fong < Joanneyong@msfirstcapital.com.sg>; SUR < sur@lkkauto.com>

Subject: RE: OUR REF D18/3241M/PTE/JY, SKG 6985B

Dear Harminder,

Enclosed preliminary revised of vehicle SKG 6985B

Date of survey: 25/4/2018 Number of days:5-6 days

We have authorize repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Wednesday, 25 April 2018 12:11 PM

To: 'Harminder Kaur' < Harminder@msfirstcapital.com.sg>; assignments < assignments@lkkauto.com>

Cc: 'Joanne Yong Lai fong' < Joanneyong@msfirstcapital.com.sg>; SUR < sur@lkkauto.com>

Subject: RE: OUR REF D18/3241M/PTE/JY

Dear Harminder,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Harminder Kaur [mailto:Harminder@msfirstcapital.com.sg]

Sent: Wednesday, 25 April, 2018 11:59 AM

To: assignments@lkkauto.com

Cc: Joanne Yong Lai fong < Joanneyong@msfirstcapital.com.sg>

Subject: OUR REF D18/3241M/PTE/JY

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly forward us your report by email only to Surveyor@first-insurance.com.sg within the next 14 days.

Thank you.

Best Regards, Harminder Kaur **Motor Claims**

MS First Capital Insurance Ltd

A Member of MS&AD Insurance Group



Change of email address

harminder@msfirstcapital.com.sg

36 Robinson Road, #16-01 City House, Singapore 068877 | Tel: 6507 3848 | Fax: 6507 3849 | Reg. No. 195000106C

Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data. Please refer to http://www.msfirstcapital.com.sg for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged. If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it. If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

Veron Chen (LKKAuto)

From:

Veron Chen (LKKAuto)

Sent:

Thursday, 26 April 2018 1:59 PM

To:

'Harminder Kaur'

Cc:

'Joanne Yong Lai fong'; SUR

Subject:

RE: OUR REF D18/3241M/PTE/JY, SKG 6985B

Attachments:

SKG 6985B PRELI ADVISED.pdf

Dear Harminder,

Enclosed preliminary revised of vehicle SKG 6985B

Date of survey: 25/4/2018 Number of days:5-6 days

We have authorize repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Wednesday, 25 April 2018 12:11 PM

To: 'Harminder Kaur' <Harminder@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>

Cc: 'Joanne Yong Lai fong' <Joanneyong@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>

Subject: RE: OUR REF D18/3241M/PTE/JY

Dear Harminder,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Harminder Kaur [mailto:Harminder@msfirstcapital.com.sg]

Sent: Wednesday, 25 April, 2018 11:59 AM

To: assignments@lkkauto.com

Cc: Joanne Yong Lai fong < Joanneyong@msfirstcapital.com.sg>

Subject: OUR REF D18/3241M/PTE/JY

Dear Sir/Mdm.

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly forward us your report by email only to Surveyor@first-insurance.com.sg within the next 14 days.

Thank you.

Best Regards, Harminder Kaur **Motor Claims**

MS First Capital Insurance Ltd A Member of MS&AD Insurance Group



Change of email address harminder@msfirstcapital.com.sg

36 Robinson Road, #16-01 City House, Singapore 068877 | Tel: 6507 3848 | Fax: 6507 3849 | Reg. No. 195000106C

Personal Data Protection Act 2012 ("PDPA"): Under the PDPA, there are various requirements that regulate the processing of your personal data. Please refer to http://www.msfirstcapital.com.sg for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged. If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it. If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail. Enquire PARF/COE Rebate for Registered Vehicle

Enquire PARF/COE Rebate for Registered) venicle	
Vehicle Owner Particulars	Singapore NRIC	
Owner ID Type:	2. 04 d Torrior	
Owner ID: Vehicle Details	4591Z	
Vehicle No.:	SKG6985B	
Vehicle to be Exported:	No	
Intended De-registration Date:	26 Apr 2018	
Vehicle Make:	MERCEDES BENZ	
Vehicle Model:	C 180 BLUEEFFICIENCY	
Primary Colour:	Silver	
Manufacturing Year:	2012	
Engine No.:	27491030002748	
Chassis No.:	WDD2040312A741947	
Maximum Power Output:	115.0 kW (154 bhp)	
Open Market Value:	\$30,136.00	
Original Registration Date:	28 Sep 2012	
First Registration Date:	28 Sep 2012	
Transfer Count:	0	
Actual ARF Paid: Intended PARF Rebate Details	\$30,136.00	
PARF Eligibility:	Yes	
PARF Eligibility Expiry Date:	27 Sep 2022	
PARF Rebate Amount: Intended COE Rebate Details	\$21,095.00	
COE Expiry Date:	27 Sep 2022	
COE Category:	A - Car (1600cc & below)	
COE Period(Years):	10	
QP Paid:	\$73,501.00	
COE Rebate Amount:	\$32,483.00	
Total Rebate Amount:	\$53,578.00	

The information contained herein is correct as at 26 Apr 2018

ОК

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C GST Reg. No. M2-0001676-9

CERTIFICATE OF INSURANCE

ORIGINAL

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 Road Transport Act, 1987 (Malaysia) Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

Type of Policy.

PRIVATE MOTOR CAR INSURANCE

Type of Cover.

: Comprehensive

Certificate No.

: D-17088618MVPC

Vehicle No / Chassis No

SKG6985B / WDD2040312A741947

Name of Insured

LEE LOK PENG @ LEE GEOK PENG

Period Of Insurance

: 28.09.2017 To 27.09.2018

Insured Estimated Value

: Market Value At Time Of Loss

NIL EXCESS FOR INSURED AND NAMED DRIVERS SGD750.00 EXCESS FOR UNNAMED DRIVERS SGD3,500.00 SECTION I & II SEPARATELY IS IMPOSED ON THOSE DRIVERS WHO ARE BELOW 22 YEARS OLD AND/OR WHO HAVE LESS THAN 2 YEARS OF DRIVING EXPERIENCE

Authorised Driver*

LEE LOK PENG @ LEE GEOK PENG, KER SIN TZE AND KER RUI XIN JUSTIN

Persons or classes of persons entitled to drive*

1) The Insured.

The Insured may also drive a Motor Car not belonging to or hired (under a hire purchase agreement or otherwise) to him or his employer or his partner.

Any other person who is driving on the Insured's order or with his permission.

 Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle

Limitations as to use*

Use only for social, domestic and pleasure purposes and for the Insured's business.

The Policy does not cover use for hire or reward, racing, pacemaking, reliability trial, speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/We HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

First Capital Insurance Limited (Approved Insurers)

KARENS/D0004/MX1F

Issued at Singapore on 22.08.2017

Authorised Signature

THE PROPERTY OF THE PRIVING LICENCE



Licence Number: S 8 0 3 0 9 8 8 J

KER RUI XIN, JUSTIN



Birth Date: 08 Oct 1980 Issue Date: 01 Dec 2004



FOR CACUSE ONLY

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 3

Motor cars =< 3000 kg with =< 7 passengers, exclusive of the driver; and motor tractors /yehicles =< 2500 kg

01 Dec 2004

FORCACUSEONLY



NP 428A



Mercedes-Benz

ts hence notify

the Repairer of the following:

. To resurvey be Cycle & Carriage 9 . To display daming distries Pte Limited

Parts prices aracularised Dealer mation

Third party sur Company No. 196409347/frice" basis
 Ost Reg No. MR-8500117-X
 No illegal modification(s) is allowed.

Supplementary item(s) must be resurveyed and Vehicle & Document Information rance Company

23126

SKG6985B / 28/09/2012

J 0

WDD2040312A741947 Chassis No

Reg No/Reg Date

Date In/Mileage

27491030002748 Engine No

Make/Model

WIP No

MB/C 180 CGI BlueEFFICIENCY

Colour/Trim

027 775 Iridium sil/ 042 228 Leather Alp

count No	Terms	Date/Time Printed	CSE	Operator				
001862	Credit	24/04/2018/ 18:	48 YK	395 / Yik Chan			277-28	
		Description of	Goods / Services		Qty	Unit Price	Disc%	Amount
BPNSUN		N. C. office process	0.01.00		TA	VII	13/1/	NICE
POLICY N	O/ACC DATE	: D-17088618MVP	C // 23/04/2018	H-H-1(.1/	(1/Ac. 1	LA II	VV	リレレニ
DRIVE IN	/EXCESS	: TOW IN 23/04/	2018 // TBA	1 1 1 50 17	CASAC		-	
	DATE SURVE	Υ:			11.00	10/8	1	
BY/AUTH	RIZED ON	:			HP 101	X00 68	V. 1	150.0
BPNSUB					150	3 1	./	
TOWING	CHARGES				6501	Dans	× 1)	440 1800-0
BPILAB	TATING TO I	DEDATE AFFECTED A	REAS. REMOVE AN	D REPLACE WITH NEW	1/3/6	o oury		, , ,
PANEL DI	NELS WITH	REFINISH.	inchies inchies the	- N	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\		- VI.	2000
BPIRES	NECS WITH	ALI INI DII I		~ [1] IL	25/04/1	801/3	5	1800.0
RESPRAY	FRONT BUM	PER AND LEFT FROM	IT FENDER	1/1////	~ Pri ili	0 (10)	0.10	√ 380.0
DOTLAR			- 1	777771717			0.10	300.
USING X	ENTRY SYST	EM TO CHECK CONTR	OL UNITS, RESET	MEMORY 10	EXO	er?: 0		/
STANDAR	D SETTINGS		~ II	170	1 .1	0		120.
BPILAB		THE FRANCE AND THE THE	NT NETT		1.14	Milan	1	m 7
	EADLAMP WI	TH FOCUS ADJUSTME	MI.NEH		HWI ~	0.1250	1	920? 2400.
BPILAB	UNDEDCADDI	AGE FROM VEHTCLE	FOR THE REPLACE	EMENT OF COMPONENT	s /O	after	riper	
REMOVE	ONDERCORNI	AGE TROTT TELETOPE	3		Resurve	1 971201	7	V 540
BPILAB		1			10)	100	540.
INSPECT	& CONDUCT	WHEEL ALIGNMENT	.NETT	- /	**			MAX 60.
BPNSUB				and the same	2			2. /
TRANSFE	R TYRE OVE	R TO NEW RIM		1 his	1.00	523.64	00.00	DA 7 523.
	ONT CROSS			7 //	1.00	80.26		X142? 80.
		ARM HYDROMOUNT		U,	1.00	449.48	00.00	W 2 449.
	ONT STRUT			85	1.00	490.23	00.00	490.
	ONT WHEEL	NG KNUCKLE			1.00	775.72		7775.
1 LEFT FF	ONT TORSIC	N BAR LINK			1.00		00.00	69.
I LEFT FE	ONT SHOCK-	ABSORBER STRUT			1.00	639.67	0.000	639.
	ADLAMP UNI				1.00	1045.29	00.00	1045.
	RONT DISK V			Hoe malid	1.00	589.06	00.00	SUJ 589.
			Ch.	An Hoe Industries Pic Lid Repair Center Repair Center 186 5100 Fax: 6872 132 186 5100 Fax: 6872 132 186 cyclecarriage.com.sg	12	12 6	42.87	
	& accepted to	у	o Carriago	Industries (Industries (1872-1872) Repair Center (1872-1872)		121 11		
Confirmed			Cycle of Care	9186 510 Accamage			Nett	11,912.
Confirmed				The second secon	70/ 6	CT am 4	1912.62	833.
Confirmed			4353	K(0) C2	7% C	ST on 1	1012.02	000.
Confirmed		0	Cycle & Carriage Body Care & ID: 6711 4353 HP: Email: chanhoe,y	Repair Center 6872 14 Repair Center 6872 14 9186 5109 Fax: 6872 14 9186 520 Fax: 6872 14	7% G	351 On 1	1012.02	12,746.

ESTIMATE FOR SKG6985B

MOTOR CLAIM DEPARTMENT

36 ROBINSON ROAD #16-01

CITY HOUSE

65073848

SINGAPORE 068877

MS FIRST CAPITAL INSURANCE LIMITED

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS

Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 www.mercedes-benz.com.sg



ESTIMATE FOR SKG6985B

Finalization

Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877 65073848

Vehicle & Document Information

23126 WIP No

Reg No/Reg Date

SKG6985B / 28/09/2012

Date In/Mileage

25/04/2018/-76184 WDD2040312A741947

Chassis No

Engine No

27491030002748 MB/C 180 CGI BlueEFFICIENCY

Make/Model Colour/Trim

Operator

027 775 Iridium sil/ 042 228 Leather Alp

CSE

Date/Time Printed Account No Terms 395 / Yik Chan Hoe VK

22/06/2018/ 11:32

WF001862	Credit 22/06	/2018/ 11:32	YK	395 /	YIK Chan Hoe	Zelpen wegen iwe		8/5 / SUIT	The second second	
MI GOLOGE		escription of Good	s / Services	W		90	Unit Price	Disc%	Amount	
M BPNSUN				COMM NORS	I A ALELO		1411A	22 30	NOF	
DRIVE IN	NO ACC DATE : 0 1 NATE SURVEY: 25/	IN#23 #04/2018	// RASUL LA	K .		- N	orking D	∦ V € ays	DICE	
A DOTLAD	RIZED ON : 25/ EATING TO REPAIR				WITH NEW	255	3		1440.00	
BODY PA	NELS WITH REFINIS	H.	, KENOTE IIII		70	7/ 15			1200.00	
A BRYLAD	FRONT BUMPER AND			_ [a 101	" // ,		0.10	380.00	
USING X STANDAR	ENTRY SYSTEM TO C	HECK CONTROL U	INITS, RESEL	MEMORY		>			120.00	
	HEADLAMP WITH FOCU	- 11		Πn.	U				1920.00	
A BPILAB REMOVE	UNDERCARRIAGE FRO	M-VEHTCLE EOR	THE REPLACE	MENT OF	COMPONENTS /				540.00	
A BPILAB	T & CONDUCT WHEEL	ALIGNMENT-NET	T .						150.00	
S BPNTOW ACCIDEN	NT TOWING FROM 31 KING DOLLEY AND S	NANYANG LINK	TO PLSC PARK CHARGE						100.00	
WO: 200	0208664								60.00	
S BPNSUB	TO REMOVE AND IN	STALL TYRE FROM	M RIM,							
WHEEL I	BALANCE AND INSTA ROSS STRUT ARM	LL NEW VALVE H	EAD			1.00	523.64 449.48		523.64 449.48	
	RONT STRUT ARM					1.00	449.48		490.23	
X LEFT F	RONT WHEEL HUB					1.00	775.72	3.77 T T T T T T T T T T T T T T T T T T	775.72	
X LEFT F	RONT STEERING KNU	CKLE				1.00	639.67		639.67	
X LEFT F	RONT SHOCK-ABSORB	ER STRUT				1.00	589.06	00.00	589.06	
X LEFT F	RONT DISK WHEEL									

Confirmed & accepted by

Yik Chan Hoe Cycle & Carriage Industries Pte Ltd Body Care & Repair Center DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272 Email; chanhoe.yik@cyclecarriage.com.sg

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worm or damaged parts are discovered after work has started and meeded for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS

Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 www.mercedes-benz.com.sg CAD



Finalization

Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

Vehicle & Document Information

25/04/2018/-76484

WDD2040312A741947

27491030002748

ESTIMATE FOR SKG6985B

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877 65073848

WIP No

Reg No/Reg Date

Date In/Mileage

Chassis No

Engine No Make/Model

Colour/Trim

23126

SKG6985B

MB/C 180 CGI BlueEFFICIENCY 027 775 Iridium sil/ 042 228 Leather Alp

/ 28/09/2012

Account No	Terms	Date/Time Printed	CSE	Operator				
WF001862	Credit	22/06/2018/ 11:32	YK	395 / Yik Chan Hoe				
		Decedation of Cood	s / Services		Qty	Unit Price	Disc%	Amount
Y LEFT FROM	NT BUMPER	CHROME MOULDING -	B II 450	FFICIAL	1.00	85.10	00.00	85.10
XI RIGHT FR	ONT BUMBE	CHRONE MOULDING	NO	PELCIAL	1.00	X85.14	AA	UIUE

STIMART

Yik Chan Hoe

Cycle & Carriage Industries Pte Ltd Body Care & Repair Center DID: 6771 4353 HP: 9186 5109 Fax; 6872 1272 Email: chanhoe.yik@cyclecarriage.com.sg

Confirmed & accepted by

Nett 9448.00

9,448.00

7% GST on

661.36

Total Payable

10,109.36

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worm or damaged parts are discovered after work has started and meeded for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS

Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 www.mercedes-benz.com.sg



ESTIMATE FOR SKG6985B

SUPPLEMENTARY

Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

Reg No/Reg Date

Date In/Mileage

Chassis No

Engine No

Make/Model

Colour/Trim

1573年15日 1873年 1874年 1875年 18 MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877 65073848

Vehicle & Document Information

23126

SKG6985B / 28/09/2012

25/04/2018/-76484 WDD2040312A741947

27491030002748

MB/C 180 CGI BlueEFFICIENCY

027 775 Iridium sil/ 042 228 Leather Alp

CSE Operator Date/Time Printed Terms Account No 395 / Yik Chan Hoe YK 22/06/2018/ 11:33 Credit WF001862 Amount Disc% Qty Unit Price Description of Goods / Services

WIP No

M BPNSUN POLIC NOZACO DATE DRIVE THANKEXCESS : D-17088618MVPC / 23/04/2018 : TOW 1N-23/04/2018 // NA

DATE IN/DATE SURVEY: 25/04/2018 @ 1635 // RASUL LKK

: 25/04/2018 @ 1635 // RASUL LKK BY/AUTHRIZED ON S BPNSUB

LABOUR TO REMOVE AND INSTALL TYRE FROM RIM, WHEEL BALANCE AND INSTALL NEW VALVE HEAD LEFT FRONT BUMPER CHROME MOULDING

RIGHT FRONT BUMPER CHROME MOULDING

85.10 00.00 85.10 00.00 85.10 nu 85.10 Au

60.00

Yik Chan Hoe

Cycle & Carriage Industries Pte Ltd Body Care & Repair Center DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272 Email: chanhoe.yik@cyclecarriage.com.sg

Confirmed & accepted by

Nett 230.20 230.20

7% GST on

16.11

Total Payable

246.31

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, We would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS

Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 www.mercedes-benz.com.sg



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internat	ionale Des Experts En Autom	obile
IRST	CAPITAL INSUR		Ref : CS/FCI1800760	
6 RO	BINSON ROAD	NGAPORE 068877	Date: 02-07-2018 Code: FCI2	
		Policy Partic	ulars :- OWN DAMAGE	
_	Insured Veh.		Veh. Inspected	SKG 6985B
\dashv	Policy No.	D-17088618MVPC	Coverage (\$)	0.00
-	Claim No.	D18003241MVPC	Excess (\$)	0.00
	Assign From	HARMINDER KAUR	Assign Date	25/04/2018
2.	riong	Vehicle Pa	rticulars & Condition	
4.	Make & Model	MERCEDES BENZ C 180	c.c	1595
	Engine No.	HIDDEN	Year of Reg.	2012
	Chassis No.	WDD2040312A741947	Colour	GREY
	Odometer	76184	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3.		Con	ditions of Tyres	
		Size	Make	Balance
	R/H Front Tyre	225/45 R17	CONTINENTAL	6 mm
	L/H Front Tyre	225/45 R17	CONTINENTAL	6 mm
	R/H Rear Tyre	225/45 R17	CONTINENTAL	6 mm
	L/H Rear Tyre	225/45 R17	CONTINENTAL	6 mm
4.			ption of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE ETAILS.		
5.		Gen	eral Information	
	Accident Date	23/04/2018	Inspection Date	25/04/2018
	Survey held at	CYCLE & CARRIAGE INDU	STRIES (1986) PL	
		188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)		
5a.			Remarks	Washington and the second
		NSISTENT TO ACCIDENT RE VALUE IS \$\$74,000.00 (EST. ICE TO YOUR INSTRUCTION	S, WE HAVE AUTHORISE	REPAIRS.
		Estin	nate Days of Repair	
5b.			6 Working D	0693634



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKG 6985B

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
4	LEFT FRONT CROSS STRUT ARM (SN)	BENT	523.64	523.64
	LEFT FRONT STRUT ARM HYDROMOUNT (SN)	SERVICEABLE	80.26	-
	LEFT FRONT STRUT ARM (SN)	BENT	449.48	449.48
	LEFT FRONT WHEEL HUB (SN)	BENT	490.23	490.23
	LEFT FRONT STEERING KNUCKLE (SN)	BENT	775.72	775.72
	LEFT FRONT TORSION BAR LINK (SN)	SERVICEABLE	69.27	
	LEFT FRONT HOCK-ABSORBER STRUT (SN)	BENT	639.67	639.67
	LEFT HEADLAMP UNIT (SN)	SERVICEABLE	1,045.29	
	LEFT FRONT DISK WHEEL (SN)	SCRATCHED	589.06	589.06
1	LEFT FRONT BUMPER CHROME MOULDING (ADDITIONAL)(SN)	NECESSARY	85.10	85.10
1	RIGHT FRONT BUMPER CHROME MOULDING (ADDITIONAL)(SN)	NECESSARY	85.10	85.10
			4,832.82	3,638.00
	LABOUR		150.00	150.00
	TOWING CHARGES		1,800.00	
	PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH.		1,800.00	1,440.00
	RESPRAY FRONT BUMPER AND LEFT FRONT FENDER.		1,800.00	1,200.00
	USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET MEMORY TO STANDARD SETTINGS.		380.00	
	CHECK HEADLAMP WITH FOCUS ADJUSTMENT.		120.0	
	REMOVE UNDERCARRIAGE FROM VEHICLE FOR THE REPLACEMENT OF COMPONENTS.		2,400.0	
	INSPECT & CONDUCT WHEEL ALIGNMENT.		540.0	0 540.00
	TRANSFER TYRE OVER TO NEW RIM	NOT NECESSARY	60.0	(1) 100 march
	LABOUR TO REMOVE AND INSTALL TYRE FROM RIM, WHEEL BALANCE AND INSTALL NEW VALVE HEAD.		60.0	0 60.00
	(ADDITIONAL)		7,310.0	5,810.00
	GRAND TOTAL		12,142.8	9,448.00

Report Ref No. CS/FCI18007606/R1vbn2



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS

9,448.00

Report Ref No. CS/FCI18007606/R1vbn2

MRB

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

St. S.

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.