

ASS. REC. BY:

REF: CS/FCL 8007616 / Asst/ber

Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person): CWS Sitthara of FCL Date/Time: 24/04/2018 530pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKS 4513E Insured: SHD 8553C

at Workshop m/s First Autoworks Tel: 6844 1985

of 23 Kaki Bukit Ave 4 #04-01

Policy No: Claim No: D1800 2947MFSH

Sum Insured: Excess:

Make of Veh: (Client's Record) D.O.A. 17/04/2018

CA / REV / REP. / REV 24 HRS w/p H.O.D. Endorsement:

Date/Time: 25/04/2018 1023am Person Contacted: Ronnie Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKS 4513E - X
	SHD 8553C - X

ASS. REC. BY: Adrian King

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SKS4S13E Yr Regn: 2015, April
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Opel Corsa c.c. 1388
 Colour: Red A/C: Insured / Std / NI / NA
 Sp. Reading: 89315 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WUOXEP68F4087311
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 185/65R15
 R: 185/65R15
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____

N/S	O/S

(Policy Condition)
 Remark: **The veh had commenced its repair at the time of inspection.**
 Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Front _____ Rear _____
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 26/04/18
 Survey held at First Outwork
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP 1st Cap.</u>
	<u>MV: 58.51C 58.51C</u>
	<u>PV: 51C</u>
	<u>Nett: 7.51C 7.51C</u>
	<u>(\$ 14,297.30 Red - 51%)</u>

Date/Time, File Pass to? 25/07/18
 1) Typist
 Date/Time, File Return to?
 2) _____
 Report Format : _____
 Lump Sum / I.B.I: (\$ 13,533.70 P/P)

Days Of Repair: 6
 Resurvey No. of Trip: 1
 Add Fee: Site Insp (\$ _____)
 Interview (\$ _____)
 Tech. Invs (\$ _____)
 Weekend (\$ _____)

Survey Fee: 170+255
 Transportation: 50
 S + RS: 50
 Photos: 105
 Others: 550
 TOTAL: 2615
26/04/18

17x15 = 255
170+255
50
50
105
550
2615

MOTOR SURVEY ASSIGNMENT

Date 18-04-2018 **Our Ref No.** D18002947MFSH

Accident Date 17-04-2018 **Claim Type.** Third Party

Insured Vehicle SHD8553C **Third Party Vehicle.** SKS4513E

Survey Location 23 Kaki Bukit Ave 4 #04-01 (South Wing)

Contact Person. RONNIE TAN

Contact No. 68441985/ 0 **Fax No.** 68445185

Survey Type WITHOUT PREJUDICE:

Appointed Surveyor LKK AUTO CONSULTANTS PTE LTD

Contact Person NA **Fax No.** 68416315

Contact Number. NA

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop FIRST AUTOWORKS **Attention.** NIL

Cc : TP Solicitor NA **TP Solicitor Fax No.** NA

Officer Incharge SITHARA

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Free Car Valuation

Unsure of how much your car is worth?

Let us tell you how much is the value - no charges & no obligations!

Post an Advertisement
Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

Cheapest In Market! Call Fast!



Cheapest In Market! Call Fast!
Net Link Partners StarAd

Lake View Credit Pte Ltd [view our cars](#)

- > Low prices guaranteed
- > Specialist in Japanese cars
- > Easy loan approval
- > All terms are negotiable

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

Browse by Category Sort by Date Posted | 20 results/page

2 vehicles

opel Corsa

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
opel Corsa		Any	Any	Any	Any	Any	Any	Available
	Opel Corsa 1.4A 5DR	\$59,000	\$7,970 /yr	27-May-2015	1,398 cc	16,000 km	Hatchback	Available
1 Careful Owner, Low Depreciation, Tip Top Condition, Free Servicing By Agent, Low Mileage Done, Full Agent Serviced With Service Record, Call For Viewing/Test Drive Now.								
Posted: 20-Apr-2018 Tags: 2015 Opel Corsa, Opel Corsa, Opel, Corsa, Used Opel								
	Opel Corsa-D 1.4A	\$19,800	\$6,920 /yr	22-Dec-2009	1,364 cc	113,000 km	Hatchback	Available
Low Down Payment At \$2888. Alpine White. Low Depreciation At \$6K. Neat And Clean Interior. Bank Or In-House Loan Available. Test Drive Welcome.								
Posted: 14-Apr-2018 Tags: 2009 Opel Corsa-D, Opel Corsa-D, Opel, Corsa-D, Used Opel								

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view [Expired ads](#)

20 results/page

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used Opel Corsa, Opel Corsa Singapore, used Opel Corsa Singapore, used Opel Corsa, used vehicles Singapore or even buy used Opel Corsa Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2018 sgCarMart. All rights reserved.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3483E
Vehicle Details	
Vehicle No.:	SKS4513E
Vehicle to be Exported:	Yes
Intended De-registration Date:	26 Apr 2018
Vehicle Make:	OPEL
Vehicle Model:	CORSA 5DR 1.4 A/T
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	B14XER19GN3338
Chassis No.:	W0L0XEP68F4087311
Maximum Power Output:	66.0 kW (88 bhp)
Open Market Value:	\$14,125.00
Original Registration Date:	16 Apr 2015
First Registration Date:	16 Apr 2015
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Apr 2025
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	15 Apr 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$67,749.00
COE Rebate Amount:	\$47,233.00
Total Rebate Amount:	\$50,983.00

The information contained herein is correct as at 26 Apr 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/04/2018 15:14
Date Of Accident	17/04/2018 10:15
Exact Location Of Accident	PIE TWDS TUAS EXITING KALLANG BAHRU
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKS4513E
Insured/Policyholder	
Name Of Registered Owner	ALPINE CAR RENTAL PTE LTD
Co Reg No	199003483E
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-65532122

Vehicle Particulars

Manufacturer	OPEL
Model	CORSA-1.2 EASYTRONIC (A)
Exact Purpose for which vehicle was being used at time of accident	WORK USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5093615112
Cover Note Number	

Driver

Name of Driver	MAZLI NIZAM BIN AHMAD
NRIC No	S7470914A
Date Of Birth	31/05/1974
Occupation	INDOOR
Date Of Driving Pass	17/04/2002
Driving Experience	16 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-85119256
Fax Number	
Contact Number	
E Mail Address	NOEMAIL

Address	BLK 103 TOA PAYOH LOR 1 #02-343
Postcode	310103
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Report please refer to sketch plan

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHD8553C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	TAN
NRIC/Passport Number	
Contact Number	96675815
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLF406P
Vehicle Make/Model/Colour	

Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver SAN KARAN LAKSHMANAN
NRIC/Passport Number
Contact Number 86795690
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name MAZLI NIZAM BIN AHMAD
Approximate Age 44
Injuries Sustain NECK & BACK PAIN
Injured person in which vehicle? SKS4513E
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



 Policyholder's Signature
 Date & Time:






 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:



 Reporting Centre Personnel's Signature
 Name: RUMIC
 NRIC/FIN No.: S131809C



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

As I was driving (SKS 4513 E) towards Kallang Exit a car in front of me (SLF 406P) stopped abruptly I was brudding half a car distance manage to stopped on time but the taxi (SHD 8553C) hit me thus pushing my car forward and hit the car in front. The taxi front was attached to my rear car when the accident happened. The impact caused my neck and back pain.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]
 Policyholder's Signature
 Date & Time:



[Signature]
 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:
 17/4/18 1135 am

[Signature]
 Reporting Centre Personnel's Signature
 Name: *[Signature]*
 NRIC/FIN No.: 571319090

Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
 MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
 ROAD TRANSPORT ACT, 1987 (MALAYSIA)
 MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number: 5093615112

Cover : Third Party

- | | |
|---|-----------------------------|
| 1. Index mark and Registration Number of Vehicle | : SKS4513E |
| Chassis Number | : W0L0XEP68F4087311 |
| 2. Name of Policyholder | : ALPINE CAR RENTAL PTE LTD |
| 3. Effective Date of Insurance | : 01 Sep 2017 |
| 4. Expiry Date of Insurance | : 31 Aug 2018 |
| 5. Persons or Classes of Persons entitled to drive# | |
| (a) The Policyholder. | |
| (b) Any other person who is driving on the Policyholder's order or with his/her permission. | |
| Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. | |
| 6. Limitations as to Use# | |
| (a) Use for social domestic and pleasure purposes and in connection with the Policyholder's or Hirer's business. | |

This Policy does not cover

- (a) Use for racing, pace-making, reliability trial or speed-testing.
- (b) Use for the carriage of goods (other than samples) in connection with any trade or business.
- (c) Use for any purpose in connection with the Motor Trade.

Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: N/A
EXCESS (SECTION 2)	: S\$1,400
ADDITIONAL EXCESS	: N/A
UNNAMED DRIVER EXCESS	: N/A
REPAIR AT OWNER'S PREFERRED WORKSHOP	: NO
INSURE WITH COE	: N/A
NCD PROTECTION	: NO
PRIMARY DRIVER	: N/A
NAMED DRIVER (1)	: N/A
NAMED DRIVER (2)	: N/A
HIRE PURCHASE COMPANY	: N/A
SUM INSURED	: N/A

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : ALPINE CREDIT PTE LTD (00000615424)
 Date of Issue : 21 Aug 2017 11:57 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED



Countersigned By:

 Authorised Officer



 Chief Executive

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: **S7470914A**
Name: **MAZLI NIZAM BIN AHMAD**

Birth Date: **31 May 1974**
Issue Date: **17 Feb 2015**

002397872H

SC 50



REPUBLIC OF SINGAPORE
IDENTITY CARD NO. **S7470914A**

Name: **MAZLI NIZAM BIN AHMAD**

Race: **BOYANESE**
Date of birth: **31-05-1974**
Country/Place of birth: **MALAYSIA**

Sex: **M**



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

	EFFECTIVE DATE
Class 2B Motorcycles =< 200 cc	23 Mar 1994
Class 2A Motorcycles between 201 cc and 400 cc	02 Apr 1996
Class 2 Motorcycles > 400 cc	21 Aug 2001
Class 3 Motor Cars=< 3000kg with =<7 passengers, exclusive of the driver; and other motor vehicles =< 2500kg	17 Apr 2002
Class 4 *Motor vehicles which are constructed to carry load or passengers and the unladen weight > 2500kg *Motor vehicles which are not constructed to carry load and the unladen weight < 7250kg	31 Aug 2002
Class 5 Motor vehicles not constructed to carry any load and the unladen weight > 7250kg	30 Sep 2002



NP 428A

9363109



NRIC No. S7470914A



Nationality
MALAYSIAN
Date of Issue
24-02-2015

Address
APT BLK 103 LORONG 1 TOA PAYOH
#02-343
SINGAPORE 310103

Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
 MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
 ROAD TRANSPORT ACT, 1987 (MALAYSIA)
 MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number: 5093615112

Cover : Third Party

- | | |
|--|---|
| 1. Index mark and Registration Number of Vehicle | : SKS4513E |
| Chassis Number | : WOLOXEP68F4087311 |
| 2. Name of Policyholder | : ALPINE CAR RENTAL PTE LTD |
| 3. Effective Date of Insurance | : 01 Sep 2017 |
| 4. Expiry Date of Insurance | : 31 Aug 2018 |
| 5. Persons or Classes of Persons entitled to drive# | |
| (a) The Policyholder. | |
| (b) Any other person who is driving on the Policyholder's order or with his/her permission. | |
| | Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. |
| 6. Limitations as to Use# | |
| (a) Use for social domestic and pleasure purposes and in connection with the Policyholder's or Hirer's business. | |

This Policy does not cover

- (a) Use for racing, pace-making, reliability trial or speed-testing.
- (b) Use for the carriage of goods (other than samples) in connection with any trade or business.
- (c) Use for any purpose in connection with the Motor Trade.

Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: N/A
EXCESS (SECTION 2)	: S\$1,400
ADDITIONAL EXCESS	: N/A
UNNAMED DRIVER EXCESS	: N/A
REPAIR AT OWNER'S PREFERRED WORKSHOP	: NO
INSURE WITH COE	: N/A
NCD PROTECTION	: NO
PRIMARY DRIVER	: N/A
NAMED DRIVER (1)	: N/A
NAMED DRIVER (2)	: N/A
HIRE PURCHASE COMPANY	: N/A
SUM INSURED	: N/A

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)


Agency : ALPINE CREDIT PTE LTD (00000615424)
 Date of Issue : 21 Aug 2017 11:57 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED



Countersigned By:

 Authorised Officer



 Chief Executive

FIRST AUTOWORKS

Repair Estimate

Date : 23/03/2018

Reference: SKS 4513E

To Whom It May Concern

Make: OPEL

Corsa

Dear Sir,

TP 1st Cap
Shirley.

RE: VEHICLE : SKS 4513E

CHASSIS NO.: W0L0XEP68F4087311

ENGINE NO.: B14XER19GN3338

Name of insured : Alpine Car Rental Pte Ltd

Date of accident: 17/04/2018

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

Front

No.	Qty	Part Description	Price (SGD)
1	1	FRT BONNET	1900.00 +
2	1	FRT BONNET LOCK	80.00 +
3	1	FRT BONNET LOCK CABLE	90.00 +
4	1	FRT BUMPER	1600.00 ✓
5	1	FRT BUMPER TOW COVER	50.00 ✓
6	1	FRT BUMPER LOW LIP RH	45.00 +
7	1	FRT BUMPER LOW LIP LH	45.00 +
8	1	FRT BUMPER CLIP	50.00 ✓
9	1	FRT BUMPER SIDE RETAINER LH - GUIDE	35.00 ✓
10	1	FRT BUMPER SIDE RETAINER LH - UPP	25.00 ✓
11	1	FRT BUMPER SIDE RETAINER RH - GUIDE	35.00 ✓
12	1	FRT BUMPER SIDE RETAINER RH - UPP	25.00 ✓
13	1	FRT BUMPER BRACKET LH	50.00 ✓
14	1	FRT BUMPER BRACKET RH	50.00 ✓
15	1	FRT BUMPER BRACKET TOP CENTRE	60.00 ✓
16	1	FRT BUMPER SPONGE	160.00 ✓
17	1	FRT BUMPER REINFORCEMENT	698.00 ✓
18	1	FRT GRILLE BASE	537.00 ✓
19	1	FRT GRILLE CHROME MOLDING RH	256.00 ✓
20	1	FRT GRILLE CHROME MOLDING LH	256.00 ✓
21	1	FRT GRILLE LOGO	120.00 X
22	1	FRT LOW CENTRE GRILLE	92.00 X
23	1	RH HEADLAMP	948.00 ✓
24	1	LH HEADLAMP	948.00 ✓
25	1	LH FOG LAMP	278.00 X
26	1	LH FOG LAMP COVER	84.00 X
27	1	RH FOG LAMP	278.00 ✓
28	1	RH FOG LAMP COVER	84.00 ✓

Rear

<u>34</u>	1	REAR BUMPER <i>reband</i>	1680.00	✓
<u>35</u>	1	REAR BUMPER TOW COVER <i>reband</i>	63.00	✓
<u>36</u>	1	REAR BUMPER REINFORCEMENT <i>reband</i>	562.00	✓
<u>37</u>	1	REAR BUMPER GUIDE LH - Outer <i>reband</i>	40.00	✓
<u>38</u>	1	REAR BUMPER GUIDE LH - Inner <i>reband</i>	40.00	✓
<u>39</u>	1	REAR BUMPER GUIDE RH - Outer <i>reband</i>	50.00	✓
<u>40</u>	1	REAR BUMPER GUIDE RH - Inner <i>reband</i>	50.00	✓
<u>41</u>	1	REAR BUMPER GUIDE CENTER <i>reband</i>	60.00	✓
<u>42</u>	1	REAR END PANEL, Lower <i>reband</i>	560.00	✓
<u>43</u>	1	REAR END PANEL TRIM <i>reband</i>	70.00	✓
<u>44</u>	1	REAR TAILGATE <i>reband</i>	2403.00	✓
<u>45</u>	1	LHR TAILLAMP <i>reband</i>	525.00	✓
<u>46</u>	1	RHR TAILLAMP <i>reband</i>	525.00	✓
<u>47</u>	1	LHR TAILGATE LAMP <i>reband</i>	325.00	✓
<u>48</u>	1	RHR TAILGATE LAMP <i>reband</i>	325.00	✓
<u>49</u>	1	OPEL EMBLEM w handle tailgate <i>reband</i>	110.00	✓
<u>50</u>	1	REVERSE SENSOR <i>reband</i>	373.00	✓

Parts Total: 16,640.00**Less 10%: 1,664.00****Total : 14,976.00****Labour**

<u>No.</u>	<u>Labour Description</u>	<u>Price (SGD)</u>
------------	---------------------------	--------------------

Front

<u>1</u>	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	2,000.00 <i>650 1300</i>
<u>2</u>	Carry out spray painting on accident affected area (Frt Bumper)	1,800.00 <i>550 1100</i>
<u>3</u>	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	80.00 <i>30</i>

Rear

<u>1</u>	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	2800.00 <i>650</i>
<u>2</u>	Carry out spray painting on accident affected area. (Rear Tailgate, Rear bumper, Rear end panel)	2500.00 <i>550</i>
<u>3</u>	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	80.00 <i>30</i>
<u>4</u>	To conduct transfer of parts from old tailgate to new tailgate	150.00 <i>x</i>
<u>5</u>	Remove and refit reverse sensor (Labour)	130.00 <i>60</i>
<u>6</u>	To remove and refix rear windscreen	180.00 <i>x</i>
<u>7</u>	To conduct anti rust of under carriage tuff coat	80.00 <i>x</i>
<u>8</u>	To conduct 4 wheel alignment	180.00 <i>x</i>

Labour Total : 9,980.00

Other

No.	Other Description	Price (SGD)
1	Sealant <i>ME</i>	50.00 ✓
2	Front number plate <i>could</i>	40.00 ✓
3	Rear number plate <i>could</i>	40.00 ✓
4	Frt Bumper Clip Set <i>3m</i>	60.00 ³⁰
5	Rear Bumper Clip Set	60.00 ³⁰

Other Total : 250.00

Total : \$25,206.00 *27,831.00*
 Gst (7%) : \$1,764.42
GRAND TOTAL: \$26,970.42

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

27568.50

Yours faithfully



Service Advisor
 Ronnie Tan
 DID: 6844 1985 Fax:6844 5185

Adrian Lij
P/P 26/04/18

06 Days.

\$7.5k (Nett Value).

LKK Auto Services Quality

the Repairs

- To repair work with...
- To dist... resurvey
- Part... to...
- The... "no Prejudice" basis
- No... work
- Supplement... reserved and is subject to... Insurance Company

Acknowledged
 Signature
 Date

FIRST AUTOWORKS

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933 Tel: 68441985 Fax: 68445185

TAX INVOICE

First Capital Insurance Singapore
36, Robinson Road, #16-01
City House
Singapore 068877

GST Ref. No: M2-0111811-5

Vehicle No: SKS 4513E
Chassis No : W0L0XEP68F4087311
Engine No: B14XER19GN3338

Invoice No:

Invoice Date:

DESCRIPTION	AMOUNT SGD
-------------	---------------

Parts

No.	Qty.	Description	Price (SGD)
<u>1</u>	1	FRT BUMPER	1600.00
<u>2</u>	1	FRT BUMPER TOW COVER	50.00
<u>3</u>	1	FRT BUMPER CLIP	50.00
<u>4</u>	1	FRT BUMPER SIDE RETAINER LH - GUIDE	35.00
<u>5</u>	1	FRT BUMPER SIDE RETAINER LH - UPP	25.00
<u>6</u>	1	FRT BUMPER SIDE RETAINER RH - GUIDE	35.00
<u>7</u>	1	FRT BUMPER SIDE RETAINER RH - UPP	25.00
<u>8</u>	1	FRT BUMPER BRACKET LH	50.00
<u>9</u>	1	FRT BUMPER BRACKET RH	50.00
<u>10</u>	1	FRT BUMPER BRACKET TOP CENTRE	60.00
<u>11</u>	1	FRT BUMPER SPONGE	160.00
<u>12</u>	1	FRT BUMPER REINFORCEMENT	698.00
<u>13</u>	1	FRT GRILLE BASE	537.00
<u>14</u>	1	FRT GRILLE CHROME MOLDING RH	256.00
<u>15</u>	1	FRT GRILLE CHROME MOLDING LH	256.00
<u>16</u>	1	RH HEADLAMP	948.00
<u>17</u>	1	LH HEADLAMP	948.00
<u>18</u>	1	RH FOG LAMP	278.00
<u>19</u>	1	RH FOG LAMP COVER	84.00

Rear

<u>20</u>	1	REAR BUMPER	1680.00
<u>21</u>	1	REAR BUMPER TOW COVER	63.00
<u>22</u>	1	REAR BUMPER GUIDE LH - Outer	40.00
<u>23</u>	1	REAR BUMPER GUIDE LH - Inner	40.00
<u>24</u>	1	REAR BUMPER GUIDE RH - Outer	50.00
<u>25</u>	1	REAR BUMPER GUIDE RH - Inner	50.00

Supplementary Items

<u>26</u>	1	Radiator <i>Best</i>	880.00 ✓
<u>27</u>	1	A/C Condenser <i>Best</i>	990.00 ✓
<u>28</u>	1	Condenser Top Air Guide <i>could</i>	130.00 ✓
<u>29</u>	1	Condenser Air Guide LH <i>could</i>	120.00 ✓
<u>30</u>	1	Condenser Air Guide RH	120.00 ✓
<u>31</u>	1	Frt Bumper Crash Limiter, Frt End, Lower (Plastic) <i>Good</i>	385.00 ✓

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 (South Wing) Next to Vicom Building, Singapore 415933 Tel : 6844 1985 Fax : 6844 5185

Total: 10693.00
 Less 10%: 1069.30
 Parts Total : 9623.70

Labour

Front

<u>No.</u>	<u>Description</u>	<u>Price (SGD)</u>
<u>1</u>	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate & align repair / replacement parts	1300.00
<u>2</u>	Carry out spray painting on accident affected area (Frt Bumper)	1100.00
<u>3</u>	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	30.00

Rear

<u>No.</u>	<u>Description</u>	<u>Price (SGD)</u>
<u>1</u>	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate & align repair / replacement parts	650.00
<u>2</u>	Carry out spray painting on affect area rear portion (Rear bumper)	550.00
<u>3</u>	To disconnect front wire harness of electrical component to facilitate repair, reconnect & check electrical function after repair	30.00
<u>4</u>	Remove and refit reverse sensor (Labour)	60.00

Labour Total : 3720.00

Other

<u>No.</u>	<u>Other Description</u>	<u>Price (SGD)</u>
<u>1</u>	Sealant	50.00
<u>2</u>	Front number	40.00
<u>3</u>	Rear number	40.00
<u>4</u>	Frt Bumper Clip Set	30.00
<u>5</u>	Rear Bumper Clip Set	30.00

Other Total : 190.00

Total : 13533.70
 GST (7%) 947.36
Grand Total: 14481.06

Yours Faithfully,



Ronnie Tan
 Service Advisor
 Tel: 68441985 Fax:68445185

E & O E

- ALL CHEQUE PAYMENTS SHOULD BE CROSSED AND MADE PAYABLE TO "1 ST AUTOWORKS PTE LTD".
- PLEASE INDICATE THE INVOICE NO. ON THE REVERSE SIDE.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18007616/Asbe2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 06-08-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 8553C	Veh. Inspected	SKS 4513E
Policy No.		Coverage (\$)	0.00
Claim No.	D18002947MFSH	Excess (\$)	0.00
Assign From	SITHARA	Assign Date	24/04/2018
2. Vehicle Particulars & Condition			
Make & Model	OPEL CORSA	c.c	1398
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	W0L0XEP68F4087311	Colour	RED
Odometer	89315	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185/65 R15	YOKOHAMA	6 mm
L/H Front Tyre	185/65 R15	YOKOHAMA	6 mm
R/H Rear Tyre	185/65 R15	YOKOHAMA	6 mm
L/H Rear Tyre	185/65 R15	YOKOHAMA	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	17/04/2018	Inspection Date	26/04/2018
Survey held at	1ST AUTOWORKS PTE LTD 23 KAKI BUKIT AVE 4 #04-01 (SOUTH WING) SINGAPORE 415933		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKS 4513E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRT BONNET	NOT NECESSARY	1,900.00	-
1	FRT BONNET LOCK	NOT NECESSARY	80.00	-
1	FRT BONNET LOCK CABLE	NOT NECESSARY	90.00	-
1	FRT BUMPER	DEFORMED	1,600.00	1,600.00
1	FRT BUMPER TOW COVER	DEFORMED	50.00	50.00
1	FRT BUMPER LOW LIP RH	NOT NECESSARY	45.00	-
1	FRT BUMPER LOW LIP LH	NOT NECESSARY	45.00	-
1	FRT BUMPER CLIP	NECESSARY	50.00	50.00
1	FRT BUMPER SIDE RETAINER LH - GUIDE	NECESSARY	35.00	35.00
1	FRT BUMPER SIDE RETAINER LH - UPP	NECESSARY	25.00	25.00
1	FRT BUMPER SIDE RETAINER RH - GUIDE	NECESSARY	35.00	35.00
1	FRT BUMPER SIDE RETAINER RH - UPP	NECESSARY	25.00	25.00
1	FRT BUMPER BRACKET LH	CRACKED	50.00	50.00
1	FRT BUMPER BRACKET RH	CRACKED	50.00	50.00
1	FRT BUMPER BRACKET TOP CENTRE	CRACKED	60.00	60.00
1	FRT BUMPER SPONGE	CRACKED	160.00	160.00
1	FRT BUMPER REINFORCEMENT	BENT	698.00	698.00
1	FRT GRILLE BASE	CRACKED	537.00	537.00
1	FRT GRILLE CHROME MOLDING RH	CRACKED	256.00	256.00
1	FRT GRILLE CHROME MOLDING LH	CRACKED	256.00	256.00
1	FRT GRILLE LOGO	NOT NECESSARY	120.00	-
1	FRT LOW CENTRE GRILLE	NOT NECESSARY	92.00	-
1	RH HEADLAMP	CRACKED	948.00	948.00
1	LH HEADLAMP	CRACKED	948.00	948.00
1	LH FOG LAMP	NOT NECESSARY	278.00	-
1	LH FOG LAMP COVER	NOT NECESSARY	84.00	-
1	RH FOG LAMP	CRACKED	278.00	278.00
1	RH FOG LAMP COVER	CRACKED	84.00	84.00
1	REAR BUMPER	DEFORMED	1,680.00	1,680.00
1	REAR BUMPER TOW COVER	DEFORMED	63.00	63.00
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	562.00	-

Report Ref No. CS/FCI18007616/Asbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BUMPER GUIDE LH - OUTER	NECESSARY	40.00	40.00
1	REAR BUMPER GUIDE LH - INNER	NECESSARY	40.00	40.00
1	REAR BUMPER GUIDE RH - OUTER	NECESSARY	50.00	50.00
1	REAR BUMPER GUIDE RH - INNER	NECESSARY	50.00	50.00
1	REAR BUMPER GUIDE CENTER	NOT NECESSARY	60.00	-
1	REAR END PANEL, LOWER	TO REPAIR SEE LABOUR	560.00	-
1	REAR END PANEL TRIM	NOT NECESSARY	70.00	-
1	REAR TAILGATE	NOT NECESSARY	2,403.00	-
1	LHR TAILLAMP	NOT NECESSARY	525.00	-
1	RHR TAILLAMP	NOT NECESSARY	525.00	-
1	LHR TAILGATE LAMP	NOT NECESSARY	325.00	-
1	RHR TAILGATE LAMP	NOT NECESSARY	325.00	-
1	OPEL EMBLEM W HANDLE TAILGATE	NOT NECESSARY	110.00	-
1	REVERSE SENSOR	NOT NECESSARY	373.00	-
1	RADIATOR (ADDITIONAL)	BENT	880.00	880.00
1	A/C CONDENSER (ADDITIONAL)	BENT	990.00	990.00
1	CONDENSER TOP AIR GUIDE (ADDITIONAL)	CRACKED	130.00	130.00
1	CONDENSER AIR GUIDE LH (ADDITIONAL)	CRACKED	120.00	120.00
1	CONDENSER AIR GUIDE RH (ADDITIONAL)	CRACKED	120.00	120.00
1	FRT BUMPER CRASH LIMITER, FRT END, LOWER (PLASTIC) (ADDITIONAL)	DAMAGED	385.00	385.00
	LESS 10% DISCOUNT		-1,926.50	-1,069.30
			17,338.50	9,623.70
	<u>SPECIAL NETT ITEMS</u>			
1	SEALANT (SN)	NECESSARY	50.00	50.00
1	FRONT NUMBER PLATE (SN)	CRACKED	40.00	40.00
1	REAR NUMBER PLATE (SN)	CRACKED	40.00	40.00
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	60.00	30.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	60.00	30.00
			250.00	190.00

Report Ref No. CS/FCI18007616/Asbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION, TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS.		2,000.00	1,300.00
	CARRY OUT SPRAY PAINTING ON ACCIDENT AFFECTED AREA (FRT BUMPER).		1,800.00	1,100.00
	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR.		80.00	30.00
	TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION, TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS. INCLUSIVE OF THE REPAIR OF REAR END PANEL, LOWER.		2,800.00	650.00
	CARRY OUT SPRAY PAINTING ON ACCIDENT AFFECTED AREA. (REAR TAILGATE, REAR BUMPER, REAR END PANEL).		2,500.00	550.00
	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR.		80.00	30.00
	TO CONDUCT TRANSFER OF PARTS FROM OLD TAILGATE TO NEW TAILGATE.	NOT NECESSARY	150.00	-
	REMOVE AND REFIT REVERSE SENSOR (LABOUR).		130.00	60.00
	TO REMOVE AND REFIX REAR WINDSCREEN.	NOT NECESSARY	180.00	-
	TO CONDUCT ANTI RUST OF UNDER CARRIAGE TUFF COAT.	NOT NECESSARY	80.00	-
	TO CONDUCT 4 WHEEL ALIGNMENT.	NOT NECESSARY	180.00	-
			9,980.00	3,720.00
	GRAND TOTAL		27,568.50	13,533.70
RECOMMENDED COST OF REPAIRS				13,533.70

Report Ref No. CS/FC118007616/Asbe2

MARKET VALUE: \$58,500.00(EST)-LTA REIMBURSEMENT VALUE: \$51,000.00=NETT VALUE: \$7,500.00

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.