

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO : 67038511
REFERENCE : 096/IC/TCAC/CCR/2018
DATE : 24-APR-2018

AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
S(068811)
TEL : 68804741
FAX : 68804838
ATTN:MOTOR CLAIM MANAGER VALENCIA

OWNER'S NAME : TAN CHIA HOE
ADDRESS : BLK 950 HOUGANG ST 91
#02-306
S(530950)
TELEPHONE NO : 96731032

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : A 28983846 QMY
VEHICLE NO : SKU708B
MODEL CODE : BDRAREZL33EYA---D-
MODEL/YEAR : TEANA 2.0XL CVT
ENGINE NO : MR20041026R
CHASSIS NO : MNTBBAL33Z0004784
MILEAGE : 98349 KM
DATE IN : 24/04/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SHAWN CHUA CHU RONG
ACCIDENT DATE : 23/04/2018

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SKU708B

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	
2	RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	55.00	
3	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	
4	ZZ/001	RENEW REAR BUMPER,UPPER PANEL,LEFT TAIL LAMP PANELS & REAPIR	750.00	
5	ZZ/002	RESPRAY REAR BUMPER,UPPER PANEL,REAR LEFT FENDER	800.00	
6	ZZ/003	QC, RETUNE & CONSULT CHECK		
7	ZZ/004	WASH & VACUUM, POLISH & WAX, SHINE ALL TYRES	120.00	
		TOTAL LABOUR CHARGES	1945.00	

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKU708B

		DAMAGED PARTS & PRICES				
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	REMARKS
1	REVERSE SENSOR	SENSOR-TE5140			360.00	
2	CLIP (\$2.50 EA X 3)	01553-09241	7.50			
3	LEFT BUMPER BRACKET	85221-3TS0A	52.60			
4	REAR BUMPER	85022-3TD4H	867.60			
5	REAR UPPER PANEL	G9110-3TUMA	475.20			
6	LEFT TAIL LAMP (FENDER)	26555-3TS0B	401.70			
SUB TOTAL			1804.60	0.00	360.00	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			360.92	0.00	0.00	
GRAND TOTAL			1443.68	0.00	360.00	
OVERALL TOTAL			1803.68			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SKU708B

TOTAL LABOUR CHARGES	1945.00
TOTAL SPARE PARTS CHARGES	1803.68
GRAND TOTAL	3748.68 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.