

REPAIR DETAILS**Reference****Part Source:** (Last Synchronised: 08 Aug 2018)**Parts:** N/A MITSUBISHI CANTER 3.0 D FEB21ER3SDEB (M) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Sng Ah Tee Motor & Panel Service Pte Ltd/YN8528Y/08/08/2018 18:03**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*TO REFILL AIRCON GAS	0.00	0.00	*50.00 F
Total Parts (\$\$)						50.00

F=Franchise part.

Sng Ah Tee Motor & Panel Service Pte Ltd/YN8528Y/08/08/2018 18:03. Not valid without Reference section.
Generated using Merimen e-Claims IEAS