

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6

#01-46/48/50 Autobay

SINGAPORE 417883

VEHCILE NO:SLD 7643K

Not Authorised
like
u/s \$5600/-
4 dy.

QTY	PARTICULAR	AMOUNT
1 PCS	FRONT BUMPER 843.45'	\$1,452.32
1 PCS	FRONT BUMPER SIDE HOLDER N/S	\$95.60
1 SET	FRONT BUMPER CLIPS	\$50.00
1 PCS	FRONT BUMPER REINFORCEMENT	\$381.12
1 PCS	FRONT BUMPER FOG LAMP N/S	\$366.50
1 PCS	HEADLAMP N/S 2071.80	\$2,201.00
1 PCS	FRONT FENDER N/S 648.35	\$922.30
1 PCS	FRONT FENDER INNER SHIELD N/S 245.30	\$288.50
1 SET	FRONT FENDER INNER SHIELD CLIPS N/S	\$50.00
1 PCS	FRONT SHOCK ABSORBER N/S	\$688.20
1 PCS	FRONT LOWER ARM N/S 392.30	\$545.50
1 PCS	FRONT TORSON ARM N/S	\$388.10
1 PCS	FRONT KNUCKLE ARM N/S 403.95	\$1,022.30
1 PCS	FRONT KNUCKLE ARM BEARING N/S 402.15'	\$488.50
1 PCS	FRONT SPORT RIM N/S	\$950.00
1 PCS	FRONT DOOR N/S	\$1,450.00
1 PCS	FRONT DRIVE SHAFT N/S	\$1,245.00

5691
5406.65
\$12,584.94

LABOUR CHARGES:

TO CHECK WIRING	\$80.00	20
TO DISMENTLE & REPLACING FRONT UNDERCARRIAGE	\$280.00	120
TO CONDUCT WHEEL Alignment	\$150.00	80
TO TRANSFER FRONT DOOR MECHANISM	\$100.00	X
TO REFILL AIRCON GAS	\$180.00	X
TO SPRAY RUST PROOFING	\$80.00	30
LABOUR FOR PANEL BEATING & REPLACING PARTS	\$680.00	300
TO PUTTY & SPRAY PAINTING	\$1,200.00	450

TOTAL \$15,334.94

7006-65
5605

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer