

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :
PEGASUS ENGINEERING & TRADING PTE LTD
C/O 51 DEFU LANE 10
SINGAPORE 539216

Officer in Charge : WEE TZE FAH
Tel :
Email :

Customer : *not Authorized*
GRAB RENTALS PTE LTD
18 SIN MING LANE
#01-08 MIDVIEW CITY
SINGAPORE 573960

Attn : *confirmed with manager 25/04/2018 @ 1:50*
Tel : *2250*
Fax : *25/4/18*

Quotation No : QO18/04-1270	Quotation Date : 23/04/2018	Terms : 30 DAYS
Vehicle No : SLP827E	Chassis No : JM6BN22A8H0153500	Third Party Insurer :
Model : MAZDA 3	Date of Accident :	
Remarks : TP INSURER: AIG, INSURED'S VEH NO: SLK3102U, DATE OF ACCIDENT: 21.04.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	BOOTLID <i>R</i>	1	958.0000	958.00 <i>X</i>
2	BOOTLID MAZDA 3 BADGE <i>nel</i>	1	54.0000	54.00 <i>✓</i>
3	BOOTLID SKYACTIV BADGE <i>nel</i>	1	64.0000	64.00 <i>✓</i>
4	BOOTLID CENTRE EMBLEM BADGE <i>nel</i>	1	75.0000	75.00 <i>✓</i>
5	REAR BUMPER <i>DD/Re</i>	1	1,075.0000	1,075.00 <i>✓</i>
6	REAR BUMPER REINFORCEMENT <i>buy</i>	1	538.0000	538.00 <i>✓</i>
7	REAR BUMPER CLIPS <i>nel</i>	6	5.0000	30.00 <i>✓</i>
8	REAR BUMPER REFLECTOR <i>11</i>	2	51.0000	102.00 <i>X</i>
9	REAR BUMPER CENTRE BRACKET <i>11</i>	2	10.0000	20.00 <i>X</i>
10	REAR BUMPER SIDE RETAINER <i>nel</i>	2	37.0000	74.00 <i>✓</i>
11	REAR BUMPER SIDE HOLDER <i>11</i>	2	46.0000	92.00 <i>X</i>
12	REAR BUMPER SIDE HOLDER RIVETS <i>11</i>	4	5.0000	20.00 <i>X</i>
13	REAR END PANEL <i>n</i>	1	506.0000	506.00 <i>X</i>
14	REAR END PANEL INNER TRIM <i>11</i>	1	86.0000	86.00 <i>X</i>
15	REAR LAMP <i>11</i>	2	509.0000	1,018.00 <i>X</i>
16	LESS 20% (ITEM 1 - 15)	1	-942.4000	-942.40
17	REAR BUMPER PARKING SENSOR <i>set</i>	1	450.0000	450.00 <i>200</i>
18	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	1	780.0000	780.00 <i>400</i>
19	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	1	800.0000	800.00 <i>600</i>
20	TO CHECK ELECTRICAL LIGHTING CONCERNED	1	50.0000	50.00 <i>20</i>
21	TO REINSTALL OF REAR BUMPER PARKING SENSOR	1	120.0000	120.00 <i>50</i>

C/F 0.00
Page 1 of 2

*1910
1528
2858*

*1910
1528
2858*

2286.40



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :
PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 SINGAPORE 539216 Officer in Charge : WEE TZE FAH Tel : Email :

Customer :
GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax :

Quotation No : QO18/04-1270	Quotation Date : 23/04/2018	Terms : 30 DAYS
Vehicle No : SLP827E	Chassis No : JM6BN22A8H0153500	Third Party Insurer :
Model : MAZDA 3	Date of Accident :	
Remarks : TP INSURER: AIG, INSURED'S VEH NO: SLK3102U, DATE OF ACCIDENT: 21.04.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
				B/F 0.00
22	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR	1	140.0000	62 140.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sub Total	6,109.60
GST(7.00%)	427.67
Total (SGD)	6,537.27

Please conduct the survey at
Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216