

Surveyor: xxl.

REF:


ASSIGNMENT

(-2021)

Front: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No: _____
at Workshop m/s Torque 5
of _____
Insured _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: \$54k
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 4 days Res: Yes or No
Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SDK 72L Yr Regn: 15 Apr 2011
Type: C / M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Merce C180k c.c. 1597
Colour: Brown A/C: Insured / Std / NI / NA
Sp. Reading: 196328 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WDD 2040 452 A 522836

Gen. Cond: C / Fair / Poor / Burnt

Steering: C / In order / Jammed / Leaked / Burnt or

Brake: C / In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / C / Rim or

Tyre Size: F: 25/45R17
R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front Rear
R/Bal: 6 mm R/Bal: 6 mm
L/Bal: 6 mm L/Bal: 6 mm
D.O.A. D.O.I. 24-04-18

Survey held at W/S 3pm
Des. of Damages: Frt / C / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
	45: +5.800 (RD: +11.838.10 617/1)

Date/Time, File Pass to? ☐ : Prel. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) _____

Report Format :

Lump Sum / I.B.I: (\$ _____)

Days Of Repair:

Resurvey No. of Trip: _____

Add Fee: ☐ Site Insp (\$ _____)

☐ Interview (\$ _____)

☐ Tech. Invs (\$ _____)

☐ Weekend (\$ _____)

Survey Fee

Transportation

) \$ + RE \$

) Photos

) Others

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	1618F

Vehicle Details

Vehicle No.:	SDK72L
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Sep 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	C180K
Primary Colour:	Brown
Manufacturing Year:	2011
Engine No.:	27191031343220
Chassis No.:	WDD2040452A522836
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$30,295.00
Original Registration Date:	15 Apr 2011
First Registration Date:	15 Apr 2011
Transfer Count:	0
Actual ARF Paid:	\$30,295.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Apr 2021
PARF Rebate Amount:	\$18,177.00

Intended COE Rebate Details

COE Expiry Date:	14 Apr 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$42,600.00
COE Rebate Amount:	\$10,884.00
Total Rebate Amount:	\$29,061.00

The information contained herein is correct as at 25 Sep 2018

OK



No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

Torque 5 Pte Ltd

ESTIMATION REPORT

Vehicle No : SDK72L
Make & Model : MERCEDES
BENZ,C180K,WDD2040452A522836
Year of Manufacture : 2011

Estimation No. : E18040063
DOA : 23/04/2018

No	Description	Qty	U/P	Amt
Section: List Items				
1	Rear bootlid / BT	1.00	1,900.00	1,900.00 1,350.00
2	Rear bootlid logo / MC	1.00	98.00	98.00
3	Rear bootlid emblem - C180 /	1.00	133.90	133.90
4	Rear bootlid emblem - Cycle & Carriage / } MC	1.00	133.90	133.90
5	Rear bootlid emblem - Kompressor /	1.00	133.90	133.90
6	Rear bootlid lock X	1.00	637.00	637.00
7	Rear bootlid weather strip X } NN	1.00	270.00	270.00
8	Rear bumper / Re.	1.00	1,672.00	1,672.00 1,448.64
9	Rear bumper clip / MC	10.00	5.00	50.00
10	Rear bumper retainer (LH) / MC	1.00	76.00	76.00
11	Rear bumper retainer (RH) / MC	1.00	76.00	76.00
12	Rear bumper bracket (RH) X	1.00	45.00	45.00
13	Rear bumper reinforcement X	1.00	715.00	715.00
14	Rear bumper reinforcement bracket/garnish X	1.00	0.00	0.00
15	Rear bumper inner centre garnish / Re	1.00	377.00	377.00
16	Rear bumper reverse sensor / 2pc sensor	4.00	294.00	1,176.00 40 (54)
17	Rear bumper reverse sensor harness X NN	1.00	196.30	196.30
18	Rear bumper chrome pieces / MC	3.00	476.00	1,428.00
19	Rear bumper towing cap / MC	1.00	96.00	96.00
20	Rear bumper air duct (LH) X	1.00	60.00	60.00
21	Rear bumper air duct (RH) X	1.00	60.00	60.00
22	Tail lamp (RH) / CHA	1.00	684.00	684.00
23	Tail lamp clip (RH) / MC	2.00	5.00	10.00
24	Tail lamp panel (RH) X NN	1.00	187.20	187.20
25	Rear fender (RH) Repair X	1.00	1,600.00	1,600.00

Continue on next page...



Torque 5 Pte Ltd
 No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
 Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SDK72L
Make & Model : MERCEDES
 BENZ,C180K,WDD2040452A522836
Year of Manufacture : 2011

Estimation No. : E18040063
DOA : 23/04/2018

No	Description	Qty	U/P	Amt
26	Rear fender cowl (RH) / TN	1.00	220.00	220.00
27	Rear fender cowl clip (RH) / MBL	10.00	5.00	50.00
28	Rear end panel X	1.00	1,464.00	1,464.00
29	Rear end panel top garnish X	1.00	168.90	168.90
30	Rear end panel top garnish clip X	10.00	5.00	50.00

Amt S\$ 13,768.10
Discount (0.00%) S\$ 0.00
Subtotal S\$ 13,768.10

Section: Special Nett Items

31	Rear number plate X	1.00	50.00	50.00
32	Rear end panel sealant X	1.00	80.00	80.00

Amt S\$ 130.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 130.00

Section: Labour Items

33	To R&R accident affected areas	1.00	1,300.00	1,300.00	400
34	To putty & respray accident affected areas	1.00	1,250.00	1,250.00	600
35	To rust proof accident affected areas	1.00	60.00	60.00	40
36	To R&R rear boot mechanism	1.00	80.00	80.00	60
37	To R&R rear luggage compartment	1.00	200.00	200.00	X NN
38	To R&R rear bumper reverse sensor & check function	1.00	80.00	80.00	40
39	To check wiring layout of tail lamp	1.00	80.00	80.00	30
40	To check, diagnose & reset any fault codes	1.00	380.00	380.00	X
41	To check wheel alignment	1.00	180.00	180.00	X
42	To check for water seepage	1.00	80.00	80.00	X NN

Continue on next page...



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SDK72L
Make & Model : MERCEDES
BENZ,C180K,WDD2040452A522836
Year of Manufacture : 2011

Estimation No. : E18040063
DOA : 23/04/2018

No	Description	Qty	U/P	Amt
				Amt S\$ 3,690.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 3,690.00

4 Days.
Wing Sun repair.
After repair photos.
Guo Qian - 8288 082
24/4/18.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

List Items Subtotal	S\$ 13,768.10
Special Nett Items Subtotal	S\$ 130.00
Labour Items Subtotal	S\$ 3,690.00
Total	S\$ 17,588.10



Torque 5 Pte Ltd

No.8 Kall Bukit Ave 4, Premier @ Kall Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

SUPPLEMENTARY
ESTIMATION REPORT

Vehicle No : SDK72L
Make & Model : MERCEDES
BENZ,C180K,WDD2040452A522836
Year of Manufacture : 2011

Estimation No. : E18040068
DOA : 23/04/2018

No	Description	Qty	U/P	Amt
<u>Section: List Items</u>				
1	Tail lamp bracket (RH) <i>pel</i>	1.00	0.00	0.00
				<i>17,000</i>
Amt				S\$ 0.00
Discount (0.00%)				S\$ 0.00
Subtotal				S\$ 0.00

Caro Conf.
25/4/18

List Items Subtotal S\$ 0.00
Total S\$ 0.00

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	25 Apr 2018 18:19	Cim Veh Model Changed	(202610) MERCEDES-BENZ C180K 1.6 (A).	[A] HOW MEI KWAN
2	25 Apr 2018 18:19	Cim Created	Reg No: SDK72L. Acct Date: 2018/04/23. Claim Type: TP. Insurer: FWD Singapore Pte. Ltd. (HQ). TP Insurer: AXA Insurance Pte Ltd (HQ). Workshop: Torque 5 Pte Ltd (Kaki B ukit)	[A] HOW MEI KWAN
3	25 Apr 2018 18:19	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ); RR Region: FWD - Ext Auto Adj Assignment. Suggested Adj. : Infiniti Appraisal Service.	[A] HOW MEI KWAN
4	25 Apr 2018 18:19	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/05/07	[A] HOW MEI KWAN
5	25 Apr 2018 18:19	Adj Mandate Set	Approved:0.00,Reinsp:Adj decides.	[A] HOW MEI KWAN
6	25 Apr 2018 18:20	Adj Adjuster Assigned	[None] -> XING GUO QIANG	[A] HOW MEI KWAN
7	25 Apr 2018 19:00	Cim Registration Modified	PoI No:->PNMC2017-00000410.	[I] Clara Li Zi Rong
8	26 Sep 2018 18:56	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/05/07	[A] HOW MEI KWAN
9	26 Oct 2018 14:32	Label Added	(20005):Direct Settlement .	[A] Asher Sng Rong Yi
10	21 Jan 2019 15:09	Adj Rpt Initiated		[A] JOANNE LEE KHANG MIN
11	21 Jan 2019 15:09	Cim Dtl Modified	JPJ Reg. Date: -> 2011/04/15.	[A] JOANNE LEE KHANG MIN
12	21 Jan 2019 15:09	Cim Details Notified		[A] JOANNE LEE KHANG MIN
13	14 Feb 2019 09:11	Adj Mandate Request	Cur.Reg:6972.00:LIABILITY: 100% B:NIL OTHER PARTY HIT OID, OID HIT TP QUANTUM: (a) COR w/GST: \$6,206.00 + (b) LOR w/GST: \$749.00 (7day x \$100) + (c) LTA :\$17.00 Total: a+b+c = \$6,972.00 PLEASE REVERT WITH YOUR APPROVAL / MANDATE / INSTRUCTIONS, IF	[A] Asher Sng Rong Yi

Date From



Date To



Audit Type

None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1928113	26/09/2018 18:56	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SDK72L	FBD5955S	10.70

Print Received Message

This mail is associated with :

***SDK72L (1201800005085)**
[FBD5955S]

TP

LEE TOON SEN

Apr 23 2018 10:00AM

[Muhammad Zaki Bin Seman]

Torque 5 Pte Ltd

From FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on 25/02/2019 17:58 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$6723.00) - SDK72L - Claim Handler: Josey Loh

Approved:6723.00:Hi Please offer LOR at 5 days

Print Received Message

This mail is associated with :

***SDK72L (1201800005085)**
[FBD5955S]

TP

LEE TOON SEN

Apr 23 2018 10:00AM

[Muhammad Zaki Bin Seman]

Torque 5 Pte Ltd

From FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on 13/03/2019 13:52 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$6743.00) - SDK72L - Claim Handler: Josey Loh

Approved:6743.00.

Asher Sng (LKKAuto)

From: Torque 5 Claims <claims@torque5.com>
Sent: Tuesday, 13 November 2018 12:24 PM
To: Vivian Lau (LKKAuto); Asher Sng (LKKAuto)
Cc: claims@torque5.com; Admin A
Subject: Accident Involving SDK 72 L & FBD 5955 S on 23/04/2018. Our Ref: SDK72L
Attachments: image010.wmz; SDK 72L - 23042018 LOD.pdf

WITHOUT PREJUDICE

Dear Sir/Mdm,

Attached is the Cost of Repair, Rental agreement, LTA fee and GIA fee of the above mentioned vehicle.

Claim amount as per below:-

1. Cost of Repair	\$ 6,206.00
2. Loss of Rental for 07 Days x \$180/-x per day	\$ 1,348.20 (Inclusive GST)
3. LTA/GIA Fee	\$ 17.00
TOTAL:	\$ 7,571.20

The above settlement is in respect of our client's claim for damages pertaining to his motor vehicle and shall not prejudice our client's claim in respect of damages and consequential loss in relation of his personal injuries.

Kindly acknowledge by replying to this email and let us have your offer soon.

Your assistance is greatly appreciated.



Thank you.

Warmest Regards,

Rachel Wu

Claims Officer | Motor Claims Department

Hotline (65) 6452 4457 EXT 112 | Fax (65) 6452 4584

Address 8 Kaki Bukit Ave 4, #01-49/50/51/52/53/54
Premier @ KB, Singapore 415875

www.torque5.com





Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. Reg. No.: 201313221G

LETTER OF AUTHORISATION

Accident on 23/04/2018 along CTE Tuas City (before PIE Changi Exit)
Involving vehicles SDK 72L, FBD 5955, FBL 33452, SLL 715R

In consideration of Torque 5 Pte Ltd, 8 Kaki Bukit Ave 4, Premier @ Kaki Bukit #01-50 Singapore 415875, repairing my/our motor vehicle no SDK 72L at my request, I/We, Lee Toon Sen ("the claimant") of 30 Sembawang Drive #11-07 S(757713) (address) bearing NRIC No S0021618F the owner of motor vehicle no SDK 72L, hereby authorize them to demand claim, settle and receive whatever amount settle payable by the insurance company or third party or commence legal proceeding for cost of repairs, loss of use and etc to any of their appointed solicitors to act for me/us in respect of the said accident/claim and all the amount claimed or settled shall belong and make payable to them absolutely by the insurance company of the third party. I/We further authorized them to give an absolute discharge on my/our behalf and to sign discharge voucher(s) and any other documents necessary or incidentals to the conduct and disposal of my/our above claims.

I/We further agree to fully co-operate and attend all court hearings related to this accident that are necessary to prosecute the claims maintained by Torque 5 Pte Ltd.

I/We further agree and undertake to indemnify them against my/our claim for costs which arise therewith. In the event that my/our claim is unsuccessful due to untruthful statements from me/us, I/we undertake to pay to Torque 5 Pte Ltd the cost of repairs to my/our vehicle.

In the event that the settlement/payment cheque is being made in my/our favour, I/we hereby undertake to return the full amount to Torque 5 Pte Ltd account, within 7 days from receiving and clearance of the said settlement/payment cheque. Failing which, Torque 5 Pte Ltd will have the legal rights to take legal proceedings against me/us to recover the said sum, with further costs and disbursements to be incurred by me/us.

I/We further authorize Torque 5 Pte Ltd to settle the aforesaid claim in a manner that you deem fit and to utilize the monies to pay your charges without further reference to me/us. The payment to Torque 5 Pte Ltd shall amount to a good discharge of Torque 5 Pte Ltd obligation to me/us in respect of the settlement monies. This authorisation shall remain in force until revoked by me/us in writing to you, subject to terms and condition being agreed by both parties. I/We further understand that revocation is not allowed once your workshop has commenced on the repair of my/our vehicle.

Dated this 23 day of April (month) 20 18 (year)

Signed by "the claimant"

Name: Lee Toon Sen

NRIC No: S0021618F



Signed by Torque 5 Pte Ltd

Name: Michelle

RELEASE

Claim Reference:	1201800005085
Surveyor's Reference:	CC4/FWD18007653/Gea3
TP Reference:	SDK 72L

We, TORQUE 5 PTE LTD ("Workshop") hereby agree and confirm that we are authorized by the owner ("Claimant") of motor vehicle SDK 72L ("Vehicle") to accept the sum of \$6,743.00, being the amount claimed for \$6,206.00 (repair costs), \$535.00 (loss of rental/ use), \$ - (loss of income), \$2.00 (search fees) as compensation for the loss of or damage to the Vehicle, as a result of an accident ("Accident") which occurred on 23/04/2018 (date of accident) at / along CTE (CITY) BEFORE PIE (CHANGI) EXIT (location) involving vehicle no/s. SDK 72L and FBD 5955S.

This is pursuant to the inspection conducted on 24/04/2018 (date) at the Workshop.

We confirm that this acceptance is in full and final settlement of all claims arising from the damage to the Vehicle (whether now or hereafter to become manifest), to the intent that FWD Singapore Pte. Ltd. and all other persons, in particular the driver of FBD 5955S be absolutely and finally exonerated and discharged from all claims of every nature and kind whatsoever which have been made or which may be made in respect of this Accident.

We also declare that we are authorized by the Claimant to receive the above compensation and we have full authority to make the claim as set out above and to settle the matter on behalf of the Claimant in any manner we deem fit.

This settlement is reached on a without prejudice and without admission of liability basis. As such, this Release is not to be construed as an admission of liability on the part of FWD Singapore Pte Ltd, their policyholder and / or authorised driver and shall not be used as evidence in any claims and / or action which may be lodged by any of them.

Dated this 13 day of March 2019

CLAIMANT



[Signed by the "Workshop" with Co. Stamp]

For and on behalf of the "Claimant"



XGQ

[FWD's appointed surveyor with Co. Stamp]

For and on behalf of FWD Singapore Pte. Ltd.

my execution of this Discharge Voucher is only
for my claim for property damage and not prejudicial
to any other claims arising from the same accident.

**Torque 5 Pte Ltd**

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

Tax Invoice

FWD Insurance Singapore
6 Temasek Boulevard
#18-01 Suntec Tower Four
Singapore 038986
Tel: 6820 8888

Inv. No. : T51903095
Inv. Date : 13 Mar 2019
Ref : 23/04/2018
Terms : 30 Days
Veh. No. : SDK72L
Make & Model : MERCEDES BENZ
C180K

#	Description	Qty	UOM	Unit Price	Disc	Amt
1	TO SUPPLY SPARE PARTS AND LABOUR FOR ACCIDENT REPAIR PARTS LUMP SUM AMOUNT	1.00		5,800.00	0.00	5,800.00

*I agree to the price as listed above and
affirm that the goods are received in good
condition.*

(Customer's Signature and Company Stamp)

Subtotal : S\$ 5,800.00
GST 7.0% : S\$ 406.00
Total : S\$ 6,206.00

For **TORQUE 5 PTE. LTD.**

(Authorised Signature)





TAX INVOICE

GST REG. NO.: 200106276D

INVOICE TO
C/O TORQUE 5 PTE LTD LEE TOON SEN 30 SEMBAWANG DRIVE #11-07 SINGAPORE 757713

DATE	INVOICE NO.
09-May-2018	A 37685

DESCRIPTION	VHA NO.	DUE DATE	VEH. NO.
	A 37685	09-May-2018	SKL 1197 R
DESCRIPTION	NO. OF DAYS	RATE	AMOUNT
RENTAL FROM 23 APRIL 2018 TO 30 APRIL 2018 (TOYOTA CAMRY) YOUR REF: SDK 72 L	7	220.00	1,540.00
GST @ 7%			\$107.80
TOTAL			\$1,647.80

*All cheques must be made payable to BKW Rent A Car Pte Ltd.
Please write the vehicle and invoice number on the reserve.*



HIRER'S PARTICULARS

Name (as in IC): *LEE TION SEN*
NRIC/Passport No: *S0021618F* Date of Birth: *9/5/1952*
Address: *30, SEMBAWANG DRIVE* Age: *73*
#11-07 S(*731113*)
Name & Address of Employer: _____
Occupation: _____ Driving Exp: *17/11/1978*
Driving Licence No: _____ Passed Date: _____
D/L Type: Local/Int'l/Other: _____
Tel(O) _____ (R) _____ HP: *96816776*
DRIVER'S PARTICULARS

Name (as in IC): _____
NRIC/Passport No: _____ Date of Birth: _____
Address: _____ Age: _____
S()
Occupation: _____ Driving Exp: _____ Yrs
Driving Licence No: _____ Passed / Expiry Date: _____
D/L Type: Local/Int'l/Other: _____ Contact No: _____

Hirer's Own Vehicle No: *50672L* Replace Veh No: _____
Loan Vehicle No: *SKL 197R* VR No: _____
Make & Model: *CAMRY 1.8* Auto/Manual Group: _____
CHARGES \$ cts
Daily *7* day @ \$ *220* Per day *\$1540*
Weekly/Monthly week @ \$ Per week/Monthly
Others
CDW/PAI @ \$ Per day/Monthly
Delivery/Collection Svc
GST *7%* *\$107* *80*
OR No: (A) SUB-TOTAL *1647* *80*
Petrol Level & Surcharge
OUT E 1/4 1/2 3/4 F
IN
First _____ km FREE per day GST
Excess mileage is chargeable at _____ cents per km TOTAL CHARGES

Security Deposit : \$ Bank:

CASH/NETS/VISA/MC/AMEX/CHQ No:

Expiry Date: Card ID No:

Name as in Card:


NON WAIVER EXCESS (Subject to GST): \$ *3000*
ACCESSORIES CHECK
☐ Data Cards ☐ Camera Systems ☐ Hub Cap ☐ Radio / CD Cartridge
☐ Jack ☐ Tyre Opener ☐ Petrol Cap ☐ Spare Tyre

Hirer's Signature :

Additional Driver's Signature :

SINGAPORE Use Only
INDICATE:

- A - Accidents
-
- D - Dents
-
- S - Scratches
-
- X - Crack



I have read and agree to the terms and condition on both sides of this agreement. If I have presented a charge/credit card for payment, I agree that all amounts payable under this agreement and for parking and traffic infringements may be billed to that account and my signature above will be considered to have been made on the charge/credit card voucher. All information I have been given by BKW Rent A Car Pte Ltd in connection with this agreement is true.

IMPORTANT

- The Hirer and the authorized driver must be over 23 years of age and under 65 years and be holding valid driving licenses and have a minimum of 2 years regular and qualified driving experience. Failure to observe stipulation may return all damages costs to be borne by the Hirer/the Authorized Driver.
- All vehicles are supplied with petrol and should be returned with petrol level likewise. A service charge of \$5 on top of a petrol surcharge is payable by the hirer should he fail to return the vehicle at the appropriate petrol level.
- No refund for early return of vehicle. The hirer shall be liable for additional charges for any late return at the rate shown per hour per day, inclusive of CDW and/or PAI where applicable. Any returns after our operation hours will be charged as a full day rental.
- Use of the vehicle for illegal purpose (For instance: in connection with theft, drug peddling or trafficking, smuggling), is strictly prohibited.
- Vehicle strictly for Singapore use only and may not be driven out of Singapore without prior written consent of BKW Rent A Car Pte Ltd. The hirer is liable for a penalty fee of \$200 in addition to the appropriate insurance top up in the case of non-disclosure of Malaysia usage.
- The hirer and/or driver shall be responsible for all damages or losses howsoever caused, all traffic violations, fines and penalties imposed on the vehicle for whatsoever reason in respect of or in connection with its use or operation.
- The hirer and/or driver shall be responsible for all claims, damages, losses, increased insurance premiums, non-waiver excess and cost expense (including

- legal costs on a full indemnity basis), whatsoever and howsoever brought against, suffered or incurred by you in respect of the vehicle or the use or the operation of the vehicle. Full excess amount have to be paid immediately in the event of an accident. The owner reserve the right not to replace an replacement vehicle if an accident occurred. Any damage to the car will be repair at BKW authorized workshop.
- Smoke or permit smoking and transport of pets in the vehicle are not allowed. Any offensive smell e.g. cigarette, durian or pet's smell, the hirer and/or driver shall bear the cost of removing the offensive smell or pet's hair between \$200 - \$400.
- The Hirer agrees that a punctured tyre, empty petrol tank, loss of vehicle's key or locked keys inside of vehicle, by itself, does not constitute a breakdown and that in the event the owner's 24-Hours Emergency Service is called upon to respond to such occurrence, the Hirer shall bear the cost of such response at \$50.00 per trip.
- In case of accident, the hirer shall report to rental office immediately. An accident report must be made within 24 hours. Failure to comply, the hirer will have to borne all liability from all parties claim. Full excess amount have to be paid immediately in the event of an accident.
- The hirer/Driver also have the responsibility to ensure that the radiator water level in the car is sufficient and do not drive when the vehicle is stall and does not have sufficient water. Any damage to the engine will be bear by the hirer/Driver.
- All customers' data will be kept strictly confidential and is solely used for the purpose of completing the sales transactions and other relating matters.
- I understand and agree to the personal data collection statement stated on the Terms and Conditions Page.

Date Out	Time Out	Mileage	Check By	Remarks
<i>03/4/18</i>	<i>12:45</i>	<i>82596</i>	<i>LA</i>	

Hirer's/Driver Signature

Return Of Vehicle: The Hirer Driver is Required To Sign In The Column "Signature Of Hirer Driver Failing Which The Day And Time Inserted Below Shall Be Deemed To Be The Day And Time The Vehicle Is Returned To BKW Rent A Car Pte Ltd And The Same Shall Be Accepted As Conclusive Evidence Of The Same And Shall Not Be Challenged Or Questioned On Any Account Whatsoever. And I had cleared my belonging items from the rental vehicle (cashcard, parking coupons, etc)"

Date In	Time In	Mileage	Check By	Remarks
<i>11/3/18</i>	<i>1:00</i>	<i>82537</i>	<i>LA</i>	

Hirer's/Driver Signature

4/23/2018

Invoice



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-061252
Date of Request: 23/04/2018

Your Ref No: Online Purchase

Torque 5 Pte Ltd
No. 8 Kaki Bukit Ave 4,
#01-50
Singapore 415875

Dear Sir/Madam,

Enquiry Date: 23/04/2018
Enquiry By: Stephanie Teo Wan Ting
TP Vehicle No: FBD5955S
Accident Date: 23/04/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
FBD5955S	FWD Singapore Pte. Ltd.	29/06/2017-28/06/2018	6727 5700

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

4/23/2018

Invoice



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-061252
Date of Request: 23/04/2018

Your Ref No: Online Purchase

Torque 5 Pte Ltd
No. 8 Kaki Bukit Ave 4,
#01-50
Singapore 415875

Dear Sir/Madam,

Enquiry Date: 23/04/2018
Enquiry By: Stephanie Teo Wan Ting
TP Vehicle No: FBD5955S
Accident Date: 23/04/2018

SPK 72 L

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

SEARCH RESULTS

Our Ref No: GR-18-062981

Date of Request: 25/04/2018

Your Ref No:

Online Purchase

Torque 5 Pte Ltd
No. 8 Kaki Bukit Ave 4,
#01-50
Singapore 415875

Dear Sir/Madam,

Your Search Criteria:

Date of Accident: 23/04/2018

Place of Accident: CTE TOWARDS CITY B4 PIE CHANGI

Client Vehicle No: SDK72L

With reference to your search criteria for the accident report, the following documents were found to closely match your search criteria:

REQ. VEHICLE	ACCIDENT LOCATION	ACCIDENT DATE
FBD5955S	No match found.	
FBL3345Z	No match found.	
SLL715R	CTE TOWARDS AYE BRADDELL ROAD EXIT	23/04/2018 10:10

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Apr 2018 Edit Reg		23 Apr 2018 00:00 Edit Adj Rpt	S\$5,800.00 Edit Estimates	S\$5,800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	Muhammad Zaki Bin Seman, ID: S8129563H								
Main Claimant:	LEE TOON SEN, ID: S0021618F								
Vehicle Reg. No.:	SDK72L	Date of Loss:	23/04/2018 10:00 - :59 [84 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1201800005085	Policy/Cover Note No.:	PNMC2017-00000410 (TP, Fire & Theft)						
Vehicle Reg. No. (Insured):	FBD59555	Policy No. (Claimant):	DMPCSN3021361801						
		Excess:							
Repairer:	Torque 5 Pte Ltd (Kaki Bukit) No. 8 Kaki Bukit Ave 4, #01-50, 415875 Kaki Bukit - Tel: 64524457								
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Josey Loh]								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 07/05/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- FWD_SG (13/03/2019): Alert - Adj Mandate Approved (S\$6743.00) - SDK72L - Claim Handler: Josey Loh - FWD_SG (25/02/2019): Alert - Adj Mandate Approved (S\$6723.00) - SDK72L - Claim Handler: Josey Loh									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SDK72L (1201800005085)
[FBD5955S]
TP
LEE TOON SEN
Apr 23 2018 10:00AM
[Muhammad Zaki Bin Seman]
Torque 5 Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Letters/Correspondences							1 per page		☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail		Print	
1	(Draft)	Third Party Express Settlement – Payment Breakdown							Edit	
Assessment Reports							1 per page		☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail		Print	
1	26/09/18 18:56	Adjuster Immediate Advice							Load HTM	
Photos/Images							3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail		Print	
1	26/10/18 14:32	General View							Load JPG	
2	26/10/18 14:32	General View							Load JPG	
3	26/10/18 14:32	Odometer Reading							Load JPG	
4	26/10/18 14:32	Chassis Number							Load JPG	
5	26/10/18 14:32	General View							Load JPG	
6	26/10/18 14:32	General View							Load JPG	
7	26/10/18 14:32	General View							Load JPG	
8	26/10/18 14:32	General View							Load JPG	
9	26/10/18 14:32	General View							Load JPG	
10	26/10/18 14:32	General View							Load JPG	
11	26/10/18 14:32	General View							Load JPG	
12	26/10/18 14:32	General View							Load JPG	
13	26/10/18 14:32	General View							Load JPG	
14	26/10/18 14:32	General View							Load JPG	
15	26/10/18 14:32	General View							Load JPG	
16	26/10/18 14:32	General View							Load JPG	
17	26/10/18 14:32	General View							Load JPG	
18	26/10/18 14:32	General View							Load JPG	
19	26/10/18 14:32	General View							Load JPG	
20	26/10/18 14:32	General View							Load JPG	
21	26/10/18 14:32	General View							Load JPG	
22	26/10/18 14:32	General View							Load JPG	
23	26/10/18 14:32	General View							Load JPG	
24	26/10/18 14:32	General View							Load JPG	
25	26/10/18 14:32	General View							Load JPG	
26	26/10/18 14:32	General View							Load JPG	
Documentation							1 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail		Print	
1	25/04/18 18:21	ACKNOWLEDGEMENT EMAIL TO FWD DD 23.04.2018							Load PDF	
2	25/04/18 18:21	TP GIA REPORT							Load PDF	

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
3	25/04/18 18:21	TP SAS REPORT	Load PDF	
4	26/04/18 17:58	EMAIL - FWD TO OI DD 26.04.2018	Load PDF	
5	28/09/18 15:37	TP ESTIMATE - MARKED	Load PDF	
6	21/01/19 15:25	RENTAL RECEIPT	Load PDF	
7	21/01/19 15:25	LOD	Load PDF	
8	19/03/19 16:50	WORKSHOP INVOICE	Load PDF	
9	19/03/19 16:50	AUTHORISATION TO ACT FORM	Load PDF	
10	19/03/19 16:50	Release Voucher	Load PDF	
11	19/03/19 16:50	GIA SEARCH	Load PDF	
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	10/05/18 16:46	OI GIA Report	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	FBD5955S (Insd veh)	Model:	MERCEDES-BENZ C180K 1.6
	SDK72L (TP veh)		(A)
Date of Accident:	23/04/2018		

Global Sum Settlement	: [] Yes	: [X] No	
Repair Estimate	: \$		18,947.67
Final Repair Cost	: \$		6,206.00
Loss of Use	: \$		_____ days at \$0.00 per day
Rental (if any)	: \$		535.00 5 days
LTA / GIA Search Fee	: \$		2.00
Others:	: \$		0.00
	: \$		
Final Settlement Sum	: \$		6,743.00

Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Torque 5 Pte Ltd	: \$	6,743.00
2)		: \$	
3)		: \$	

JOANNE LEE KHANG MIN

19 Mar
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD18007653/GEA3Q2

Date: 19/03/2019

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNMC2017-00000410

Claimant Vehicle No: SDK72L Insured Vehicle No: FBD5955S

Date of Loss: 23/04/2018 Nature of Claim: TP Claim No: 1201800005085

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SDK72L**
 Make & Model: MERCEDES-BENZ C180K, 1.6 (A) Engine No: 27191031343220
 Reg. Date: 15/04/2011 (Man. Year: 2011) Chassis No: WDD2040452A522836
 Colour: Brown Odometer: 196328 km
 Engine Capacity: 1597 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17
 Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
 Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre tread's depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,018.10	6,108.21	7,909.89	56.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,690.00	1,170.00	2,520.00	68.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,708.10	7,278.21	10,429.89	58.90
Approved Total (Overridden) (S\$)		5,800.00		
(S\$)	17,708.10	5,800.00	11,908.10	67.25
+ GST 7.00/7.00% (S\$)	1,239.57	406.00	833.57	67.25
Nett Amount (S\$)	18,947.67	6,206.00	12,741.67	67.25
+ Car Rental (5.0 x S\$100.00/day + 7.00% GST) (S\$)		535.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		6,743.00		

INSPECTION

Date of Assignment: 23/04/2018

Date Inspected: 24/04/2018 Inspected At:

Torque 5 Pte Ltd (Kaki Bukit)
No. 8 Kaki Bukit Ave 4, #01-50
Singapore 415875

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Jan 2019)
Parts:	143	MERCEDES-BENZ C180K 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDK72L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Bent	1,900.00 F	*1,550.00 FL
2	1		*REAR BOOTLID LOGO	Necessary	98.00 F	*98.00 FL
3	1		*REAR BOOTLID EMBLEM -C180	Necessary	133.90 F	*133.90 FL
4	1		*REAR BOOTLID EMBLEM -CYCLE & CARRIAGE	Necessary	133.90 F	*133.90 FL
5	1		*REAR BOOTLID EMBLEM -KOMPRESSOR	Necessary	133.90 F	*133.90 FL
6	1		*REAR BOOTLID LOCK	Not Necessary	637.00 F	*- FL
7	1		*REAR BOOTLID WEATHER STRIP	Not Necessary	270.00 F	*- FL
8	1		*REAR BUMPER	Deformed	1,672.00 F	*1,448.64 FL
9	10		*REAR BUMPER CLIP	Necessary	50.00 F	*50.00 FL
10	1		*REAR BUMPER RETAINER (LH)	Necessary	76.00 F	*76.00 FL
11	1		*REAR BUMPER RETAINER (RH)	Necessary	76.00 F	*76.00 FL
12	1		*REAR BUMPER BRACKET (RH)	Not Necessary	45.00 F	*- FL
13	1		*REAR BUMPER REINFORCEMENT	Not Necessary	715.00 F	*- FL
14	1		*REAR BUMPER REINFORCEMENT BRACKET /GARNISH (NPA)	Not Necessary	0.00 F	*- FL
15	1		*REAR BUMPER INNER CENTRE GARNISH	Deformed	377.00 F	*377.00 FL
16	4		*REAR BUMPER REVERSE SENSOR	Shorted (2 PCS ONLY)	1,176.00 FS	*140.00 FS
17	1		*REAR BUMPER REVERSE SENSOR HARNESS	Not Necessary	196.30 F	*- FL
18	3		*REAR BUMPER CHROME PIECES	Necessary	1,428.00 F	*1,428.00 FL
19	1		*REAR BUMPER TOWING CAP	Missing	96.00 F	*96.00 FL
20	1		*REAR BUMPER AIR DUCT (LH)	Not Necessary	60.00 F	*- FL
21	1		*REAR BUMPER AIR DUCT (RH)	Not Necessary	60.00 F	*- FL
22	1		*TAIL LAMP (RH)	Cracked	684.00 F	*684.00 FL
23	2		*TAIL LAMP CLIP (RH)	Necessary	10.00 F	*10.00 FL
24	1		*TAIL LAMP PANEL (RH)	Not Necessary	187.20 F	*- FL
25	1		*REAR FENDER (RH)	Repair	1,600.00 F	*- FL
26	1		*REAR FENDER COWLING (RH)	Torn	220.00 F	*220.00 FL
27	10		*REAR FENDER COWLING CLIP(RH)	Necessary	50.00 F	*50.00 FL
28	1		*REAR END PANEL	Not Necessary	1,464.00 F	*- FL
29	1		*REAR END PANEL TOP GARNISH	Not Necessary	168.90 F	*- FL
30	10		*REAR END PANEL TOP GARNISH CLIP	Not Necessary	50.00 F	*- FL
31	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
32	1		*REAR END PANEL SEALANT	Not Necessary	80.00 FS	*- FS
33	1		*TAIL LAMP BRACKET (RH)	Necessary	120.00 F	*68.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **14,018.10** **6,771.34**
 - List Item Discount on L Items 0.00/10.00% (\$\$) 0.00 683.13

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Total Parts (S\$)					14,018.10	6,108.21

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO R&R ACCIDENT AFFECTED AREAS	New	1,300.00	400.00
2	TO PUTTY & RESPRAY ACCIDENT AFFECTED AREAS	New	1,250.00	600.00
3	TO RUST PROOF ACCIDENT AFFECTED AREAS	New	60.00	40.00
4	TO R&R REAR BOOT MECHANISM	New	80.00	60.00
5	TO R&R REAR LUGGAGE COMPARTMENT	New	200.00	0.00
6	TO R&R REAR BUMPER REVERSE SENSOR & CHECK FUNCTION	New	80.00	40.00
7	TO CHECK WIRING LAYOUT OF TAIL LAMP	New	80.00	30.00
8	TO CHECK ,DIAGNOSE & RESET ANY FAULT CODES	New	380.00	0.00
9	TO CHECK WHEEL ALIGNMENT	New	180.00	0.00
10	TO CHECK FOR WATER SEEPAGE	New	80.00	0.00
Gross Labour Cost (S\$)			3,690.00	1,170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >