

1592/01

INS. CASE OWNER:

CC 4/LPC180 07660, Uua3n2

LKK:  
IDAC:

Surveyor:

MARRUS

DOI: ASSIGNMENT 25/4/18

Date / Time: 21/4/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.: SL6 4123 Z  
Name of Insured: Ang Boon Lay  
Insured Tel No.: HP:  
Excess Sec II :SS D.O.A: 11/2/18  
Is driver the owner? ( YES / NO ) Nature of Accident :  
If NO. Driver Name / Age: Jazelle Rose Re Leon Mendoza  
Driver Tel No.: 86619105 (V/L: YES / NO)

Claim No.: 18/18/VP05/020400  
Policy No.: 213VP05016122  
Make / Model: 7-Egime  
Place of Accident: Traffic Junction of Bram/Case & Seayoon Rd  
GIA REPORT: YES / NO : TP GIA REPORT: YES / NO  
Insured Liability: % Final ? Yes / No

FBD 44620



INSRS: WSP: EROFIA  
Tel:  
Liability:  
RMKS:



INSRS: WSP:  
Tel:  
Liability:  
RMKS:



INSRS: WSP:  
Tel:  
Liability:  
RMKS:



INSRS: WSP:  
Tel:  
Liability:  
RMKS:

Date/Time	STAGE	DATE / PIC
SL6 4123 Z	Non-Reporting ltr (1st):	
FBD 44620 - M/T/M/2006/605754; N/A: 10/1/18	Non-Reporting ltr (2nd):	
SL6 4123 Z - x	Non-Reporting ltr (Final):	
* AM LOD attached.	Notification ltr (if non-pickup):	
- Please verify O/D's DL.	Call OI:	
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	<input type="checkbox"/>
	After call ltr to OI:	<input type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input type="checkbox"/>
	Towing Invoice:	<input type="checkbox"/>
	LTA / GIA:	<input type="checkbox"/>
	Medical Bill:	<input type="checkbox"/>
	DR:	<input type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
	LOD:	<input type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>

RECEIVED 11 JUL 2018  
RECEIVED 05 OCT 2018

<b>PRELIMINARY ADVICE</b>	Date/Time:	Sent By:	Confirm with:	Confirm by:
<b>FINALIZATION</b>	Date/Time:	Sent By:	Confirm with:	Confirm by:
Repair Cost:	SS	( days) Reduction:	%	Email <input type="checkbox"/> Call <input type="checkbox"/>
<b>FINAL SETTLEMENT</b>	Date/Time: 14/9/18	Confirm with: Ted Hwa Heng		Email <input type="checkbox"/> Call <input type="checkbox"/>
Final Liability:	% 100	(Agreed/ Assessed) BOLA S/N No.:	5	If NO or B 28. Ass. Lia:
Repair Cost:	SS 2000.00			
Loss of Rental (LOR):	SS	( days)		
Loss of Use (LOU):	SS 140.00	(S x 3 days)		
Loss of Income (LOI):	SS	(S x days)		
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/>	LOR + LOU <input type="checkbox"/> LOR + LO <input type="checkbox"/>	[Tick only one]		
GIA/LTA Search	SS			
Medical:	SS			1) Claim status: Normal/Reject/Private Settle
Disbursement:	SS	(e.g. Tow/Independent)		2) Report Format:
Legal Cost	SS			3) Survey fee:
<b>Total:</b>	SS 2140.00	<b>Global Sum SS:</b>		
<b>FINAL PAYMENT</b>	Date/Time:	Confirm with:		Email <input type="checkbox"/> Call <input type="checkbox"/>
Payee 1:	SS 2140.00	Name 1:	EROFIA MOTOR TRADING PTE LTD	
Payee 2: (Strike if N.A.)	SS	Name 2:		
Payee 3: (Strike if N.A.)	SS	Name 3:		





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD		Ref : CC4/LPC18007660/Uua3	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 26-04-2018	
		Code : LPC2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SLG 4123Z	Veh. Inspected	FBD 4462D
Policy No.	Z17VP05016122	Coverage (\$)	0.00
Claim No.	17/18/18/VP05/020400	Excess (\$)	0.00
Assign From		Assign Date	26/04/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	11/02/2018	Inspection Date	25/04/2018
Survey held at	EROFIA MOTOR TRADING PTE LTD 1 KAKI BUKIT AVENUE 6 #02-62 SINGAPORE 417883		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

**Catherine Chong (LKK Auto)**

---

**From:** ERIC WOO JUN KIAT <ericwoo@lonpac.com>  
**Sent:** Wednesday, 25 April, 2018 11:47 AM  
**To:** assignments@lkkauto.com  
**Cc:** erofia@singnet.com.sg; erofia2@gmail.com; MT\_Claim\_SG  
**Subject:** Our Ref: 17/18/18/VP05/020400 Accident involving SLG 4123Z & FBD 4462D at Boon Keng Rd junction on 11/2/18  
**Attachments:** 25042018113759.pdf

Dear Catherine / Nivitha,

Kindly refer to our attachment.

Please proceed to conduct a survey of the vehicle FBD 4462D on without Prejudice Basis.

We look forward to receiving your report soon.

Thank you.

Best Regards,  
Eric Woo  
Claims Executive | Lonpac Insurance Bhd  
300 Beach Road, #17-04/07 The Concourse, Singapore 199555  
Tel: (65) 6279 9253 | Fax: (65) 6296 3767

25042018 @ 11:51am  
Mr. Teo veh in  
maruls

## Mei Kwan (LKKAuto)

---

**From:** ONG LI LI <llong@lonpac.com>  
**Sent:** Thursday, 31 May, 2018 9:23 AM  
**To:** Mei Kwan (LKKAuto); ERIC WOO JUN KIAT  
**Cc:** MT\_Claim\_SG; Thin Thin (LKKAuto); Vivian Lau (LKKAuto); Admin A; GERALD POH WEE BIN  
**Subject:** RE: Our Ref: 17/18/18/VP05/020400 Accident involving SLG 4123Z & FBD 4462D at Boon Keng Rd junction on 11/2/18  
**Attachments:** SLG4123Z 110218.PDF  
**Follow Up Flag:** Follow up  
**Flag Status:** Completed  
**Categories:** HMK

Hi Mei Kwan

Please see attached for our Insured's GIA report that you have requested.

Regards,  
Ong Li Li  
Senior Claims Executive | Lonpac Insurance Bhd  
300 Beach Road #17-04/07 The Concourse Singapore 199555  
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

---

**From:** Mei Kwan (LKKAuto) [mailto:Meikwan@lkkauto.com]  
**Sent:** Thursday, 31 May, 2018 8:36 AM  
**To:** ERIC WOO JUN KIAT  
**Cc:** MT\_Claim\_SG; Thin Thin (LKKAuto); Vivian Lau (LKKAuto); Admin A; GERALD POH WEE BIN; ONG LI LI  
**Subject:** RE: Our Ref: 17/18/18/VP05/020400 Accident involving SLG 4123Z & FBD 4462D at Boon Keng Rd junction on 11/2/18

**LPC ref: 17/18/18/VP05/020400**  
**LKK REF: CC4/LPC18007660/Uua3**

Dear Sir / Madam,

We refer to the above matter.

Kindly let us have a copy of your insured's GIA report for our necessary action.

Thank you.

Best Regards,

**Mei Kwan** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366 0055 | email: [MeiKwan@lkkauto.com](mailto:MeiKwan@lkkauto.com) | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Mei Kwan (LKKAuto)  
**Sent:** Wednesday, 23 May, 2018 1:13 PM  
**To:** 'ERIC WOO JUN KIAT' <[ericwoo@lonpac.com](mailto:ericwoo@lonpac.com)>  
**Cc:** 'MT\_Claim\_SG' <[mt\\_claim@lonpac.com](mailto:mt_claim@lonpac.com)>; Thin Thin (LKKAuto) <[thinthin@lkkauto.com](mailto:thinthin@lkkauto.com)>; Vivian Lau (LKKAuto) <[vivianlau@lkkauto.com](mailto:vivianlau@lkkauto.com)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>

**Subject:** RE: Our Ref: 17/18/18/VP05/020400 Accident involving SLG 4123Z & FBD 4462D at Boon Keng Rd junction on 11/2/18

**LPC ref: 17/18/18/VP05/020400**  
**LKK REF: CC4/LPC18007660/Uua3**

Dear Sir / Madam,

We refer to the above matter.

Enclosed revert of vehicle: FBD 4462D

Date of survey: 25/04/2018

We have not authorized repairs.

Enclosed for your perusal is:

- Estimated cost of repair
- Preliminary Advice
- Photographs of TP vehicle in its damaged condition

Kindly let us have a copy of your insured's GIA report for our necessary action.

Please take note that the case handler in-charge is Thin Thin and she can be contacted at DID: 6841 2360.

***To check availability of the case handler, you may contact the undersigned.***

Thank you.

Best Regards,

**Mei Kwan** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366 0055 | email: [MeiKwan@lkkauto.com](mailto:MeiKwan@lkkauto.com) | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)

**Sent:** Wednesday, 25 April, 2018 11:54 AM

**To:** 'ERIC WOO JUN KIAT' <[ericwoo@lonpac.com](mailto:ericwoo@lonpac.com)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>

**Cc:** 'MT\_Claim\_SG' <[mt\\_claim@lonpac.com](mailto:mt_claim@lonpac.com)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>

**Subject:** RE: Our Ref: 17/18/18/VP05/020400 Accident involving SLG 4123Z & FBD 4462D at Boon Keng Rd junction on 11/2/18

Dear Eric,

Thank you for the assignment.

Best Regards,

**Catherine Chong** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** ERIC WOO JUN KIAT [<mailto:ericwoo@lonpac.com>]

**Sent:** Wednesday, 25 April, 2018 11:47 AM

**To:** [assignments@lkkauto.com](mailto:assignments@lkkauto.com)

**Cc:** [erofia@singnet.com.sg](mailto:erofia@singnet.com.sg); [erofia2@gmail.com](mailto:erofia2@gmail.com); MT\_Claim\_SG <[mt\\_claim@lonpac.com](mailto:mt_claim@lonpac.com)>

**Subject:** Our Ref: 17/18/18/VP05/020400 Accident involving SLG 4123Z & FBD 4462D at Boon Keng Rd junction on 11/2/18

Dear Catherine / Nivitha,

Kindly refer to our attachment.

Please proceed to conduct a survey of the vehicle FBD 4462D on without Prejudice Basis.

We look forward to receiving your report soon.

Thank you.

Best Regards,  
Eric Woo  
Claims Executive | Lonpac Insurance Bhd  
300 Beach Road, #17-04/07 The Concourse, Singapore 199555  
Tel: (65) 6279 9253 | Fax: (65) 6296 3767

**REPUBLIC OF SINGAPORE DRIVING LICENCE**



**ZHU TIANJIE**  
 18 Apr 1990  
 12 Jul 2017  
 TR 05-080000

002702543H

**YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)**

Class 2B Motorcycles <= 200 cc      **EFFECTIVE DATE**  
 07 Aug 2012

NP 428A

Licence No:G2043540U



**WORK PERMIT**  
 Employment of Foreign Manpower Act (Chapter 91A)  
 Republic of Singapore

Employer  
 PIZZA HUT SINGAPORE PTE LTD (FULL TIME STAFF)

Sector: **SERVICE**



Name  
**ZHU TIANJIE**  
 Occupation  
**DELIVERY MAN**

Work Permit No.  
**0 7489061-**

Date of Application  
**19-03-2012**

Date of Issue  
**14-03-2016**

Date of Expiry  
**20-03-2018**




L6583833



(3)

**VISIT PASS**  
 Immigration Regulations

Name  
**ZHU TIANJIE**



Date of Birth    Sex      Nationality  
**18-04-1990    M      CHINESE**

Pin      Date of Issue      Date of Expiry  
**G2043540U    14-03-2016    20-03-2018**

**MULTIPLE JOURNEY VISA ISSUED**

**YOU ARE TO SURRENDER THIS CARD WHEN IT IS CANCELLED OR HAS EXPIRED, OR WHEN A NEW CARD IS ISSUED TO YOU.**



## Enquire Transfer Fee

### Vehicle Details

Vehicle No.: FBD4462D  
Vehicle Type: P00 - Passenger Motorcycle/Autocycle/Moped  
Vehicle Attachment 1: No Attachment  
Vehicle Scheme: Normal  
Vehicle Make: YAMAHA  
Vehicle Model: FZ150I  
Chassis No.: PMYKG025090004869  
Propellant: Petrol  
Engine No.: G372EE004869  
Engine Capacity: 150 cc  
Maximum Power Output: -  
Maximum Laden Weight: 319 kg  
Unladen Weight: 114 kg  
Year Of Manufacture: 2009  
Original Registration Date: 11 Mar 2009  
Lifespan Expiry Date: -  
COE Category: D - Motorcycle  
Quota Premium: \$701.00  
COE Expiry Date: 10 Mar 2019  
Road Tax Expiry Date: 10 Mar 2019  
Inspection Due Date: 10 Mar 2019  
Intended Transfer Date: 26 Apr 2018  
CO2 Emission: -  
CO Emission: -  
HC Emission: -  
NOx Emission: -  
PM Emission: -

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

### Amount Payable

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
<b>Total Amount Payable:</b>			<b>25.00</b>

You may print this page for reference.

OK

Print

**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Foreign Identification Number
Owner ID:	3540U

**Vehicle Details**

Vehicle No.:	FBD4462D
Vehicle to be Exported:	No
Intended De-registration Date:	25 Apr 2018
Vehicle Make:	YAMAHA
Vehicle Model:	FZ150I
Primary Colour:	Red
Manufacturing Year:	2009
Engine No.:	G372EE004869
Chassis No.:	PMYKG025090004869
Maximum Power Output:	-
Open Market Value:	\$2,667.00
Original Registration Date:	11 Mar 2009
First Registration Date:	11 Mar 2009
Transfer Count:	2
Actual ARF Paid:	\$401.00

**Intended PARF Rebate Details**

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

**Intended COE Rebate Details**

COE Expiry Date:	10 Mar 2019
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$701.00
COE Rebate Amount:	\$60.00
<b>Total Rebate Amount:</b>	<b>\$60.00</b>

The information contained herein is correct as at 25 Apr 2018

OK

# EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

*Longpac*

Name : Chen Tin Leow

Accident Date : 11-Feb-18

Vehicle No : FBD 4462 D

Vehicle Model : Yamaha FZ150

## Estimated Repair Costs

Qty	Description <u>List Items</u>	Amount S(\$)
	<i>not authorized</i>	
1	Lampstay	\$ Best 95.00 ✓
1	Front fender	\$ cre 75.00 ✓
2	Fork inner tubes	\$ Best 370.00 ✓
2	Fork outer tubes	\$ Suller 390.00 ✓
1	Fork under bracket	\$ Best 232.00 ✓
1	Front rim shaft	\$ n 42.00 X
1	Front brake disc	\$ n 150.00 X
1	Headlamp	\$ s no 185.00 ✓
2	Front signals	\$ n 126.00 ✓
2	Front side cowlings	\$ n 270.00 X
1	Radiator	\$ n 345.00 X
2	Side mirrors	\$ n 160.00 ✓
1	Handle bar	\$ Best 85.00 ✓
2	Handle bar ends	\$ Best 56.00 ✓
1	Clutch lever	\$ cre 28.00 ✓
1	Brake lever	\$ cre 28.00 ✓
1	Meter assy	\$ s no 425.00 ✓
1	Fuel tank	\$ n 512.00 ✓
2	Front footrests	\$ o/s s no 70.00 pc
2	Front footrest brackets	\$ o/s Best 90.00 pc
1	Brake pedal	\$ n 48.00 ✓
1	Gear pedal	\$ n 48.00 X
1	Rear footrest -R/H	\$ n 35.00 X
1	Exhaust assy	\$ n 425.00 X
1	Exhaust protector -Chrome	\$ Best 68.00 ✓
1	Exhaust protector -Black	\$ n 48.00 X
2	Rear tailboards	\$ o/s n 310.00 pc
1	Rear fender	\$ n 70.00 X
		\$ 4,786.00
	Less 10%	\$ 478.60
		\$ 4,307.40

*not authorized*  
*take*  
*L/S*  
*side*  
*take photo after repair*  
*25/4/18*  
*ntscu 2/8*

*3118*  
*28062*

# EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

Name : Chen Tin Leow

Accident Date : 11-Feb-18

Vehicle No : FBD 4462 D

Vehicle Model : Yamaha FZ150

## Estimated Repair Costs

<u>Special Nett Items</u>		
1	Number plate (1 set)	\$ <i>Nett</i> 28.00 <i>10</i>
2	Fork oils	\$ <i>Nett</i> 30.00 <i>—</i>
2	Fork oil seals	\$ <i>Nett</i> 56.00 <i>—</i>
1	Steering cone (1 set)	\$ <i>Nett</i> 90.00 <i>—</i>
1	Rear box	\$ <i>MIS</i> 250.00 <i>150</i>
1	Rear box bracket	\$ <i>Nett</i> 100.00 <i>—</i>
1	Coolant	\$ <i>Nett</i> 15.00 <i>X</i>
1	ERP IU	\$ <i>Nett</i> 160.00 <i>X</i>
1	Sticker (1 set)	\$ <i>Nett</i> 85.00 <i>—</i>
		<b>\$ 814.00</b>

<u>S/No.</u>	<u>Labour</u>	
1	To provide towing service.	\$ 50.00 <i>35</i>
2	To check wiring and reset headlamp focusing.	\$ <i>Nett</i> 80.00 <i>X</i>
3	To provide labour.	\$ 380.00 <i>300</i>
4	To check, repair and straighten body frame.	\$ 350.00 <i>250</i>
		<b>\$ 860.00</b>

*3512.2*  
*3129.*

**Grand Total** **\$ 5,981.40**

Dollars: Five Thousand Nine Hundred Eighty-One And Forty Cents Only.



EROFIA MOTOR TRADING PTE LTD

EROFIA Auto Repairs (Pte) Ltd hereby notify the Repairer of the following:

- To resurvey vehicle after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

u 3/09 MV 220

# EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

Name : Chen Tin Leow

Accident Date : 11-Feb-18

Vehicle No : FBD 4462 D

Vehicle Model : Yamaha FZ150

## Estimated Repair Costs

Qty	Description List Items	Amount S(\$)
1	Lampstay	\$ Best 95.00 ✓
1	Front fender	\$ one 75.00 ✓
2	Fork inner tubes	\$ Best 370.00 ✓
2	Fork outer tubes	\$ Sullon 390.00 ✓
1	Fork under bracket	\$ Best 232.00 ✓
1	Front rim shaft	\$ n 42.00 x
1	Front brake disc	\$ Best 150.00 ✓
1	Headlamp	\$ Sro 185.00 ✓
2	Front signals	\$ Best 126.00 ✓
2	Front side cowlings	\$ n 270.00 x
1	Radiator	\$ n 345.00 x
2	Side mirrors	\$ Best 160.00 ✓
1	Handle bar	\$ Best 85.00 ✓
2	Handle bar ends	\$ Best 56.00 ✓
1	Clutch lever	\$ one 28.00 ✓
1	Brake lever	\$ one 28.00 ✓
1	Meter assy	\$ Sro 425.00 ✓
1	Fuel tank	\$ n 512.00 ✓
2	Front footrests	\$ O/S Best 70.00 ✓
2	Front footrest brackets	\$ O/S Best 90.00 ✓
1	Brake pedal	\$ Best 48.00 ✓
1	Gear pedal	\$ n 48.00 x
1	Rear footrest -R/H	\$ n 35.00 x
1	Exhaust assy	\$ n 425.00 x
1	Exhaust protector -Chrome	\$ Best 68.00 ✓
1	Exhaust protector -Black	\$ n 48.00 x
2	Rear tailboards	\$ O/S Best 310.00 ✓
1	Rear fender	\$ n 70.00 x
		\$ 4,786.00
	Front Rim 190 Best ✓	\$ 478.60
	Key Switch 90 one ✓	\$ 4,307.40

Not Authorized  
LHK  
L/S \$2000  
Sully  
When parts after repair  
25/4/18  
atscun

3548  
3032

# EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

Name : Chen Tin Leow

Accident Date : 11-Feb-18

Vehicle No: FBD 4462 D

Vehicle Model : Yamaha FZ150

## Estimated Repair Costs

### Special Nett Items

1	Number plate (1 set)	\$	net	28.00	10
2	Fork oils	\$	net	30.00	—
2	Fork oil seals	\$	net	56.00	—
1	Steering cone (1 set)	\$	net	90.00	—
1	Rear box	\$	mis	250.00	150
1	Rear box bracket	\$	net	100.00	—
1	Coolant	\$	net	15.00	x
1	ERP IU	\$	net	160.00	x
1	Sticker (1 set)	\$	net	85.00	—
		\$		<u>814.00</u>	

### S/No.

### Labour

1	To provide towing service.	\$		50.00	35
2	To check wiring and reset headlamp focusing.	\$	net	80.00	x
3	To provide labour.	\$		380.00	300
4	To check , repair and straighten body frame.	\$		350.00	250
		\$		<u>860.00</u>	

Grand Total

\$ 5,981.40

Dollars: Five Thousand Nine Hundred Eighty-One And Forty Cents Only.



EROFIA MOTOR TRADING PTE LTD



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC18007660/Uua3n2

300 BEACH ROAD  
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 09-10-2018



Code : LPC2

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLG 4123Z	Veh. Inspected	FBD 4462D
Policy No.	Z17VP05016122	Coverage (\$)	0.00
Claim No.	17/18/18/VP05/020400	Excess (\$)	0.00
Assign From	ERIC	Assign Date	25/04/2018

## 2. Vehicle Particulars & Condition

Make & Model	YAMAHA FZ150	c.c	150
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	PMYKG025090004869	Colour	RED
Odometer	46166	Steering	AFFECTED
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	80/90-17	PIRELLI	5 mm
L/H Front Tyre			mm
R/H Rear Tyre	100/80-17	PIRELLI	5 mm
L/H Rear Tyre			mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.
---

## 5. General Information

Accident Date	11/02/2018	Inspection Date	25/04/2018
Survey held at	EROFIA MOTOR TRADING PTE LTD 1 KAKI BUKIT AVENUE 6 #02-62 SINGAPORE 417883		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBD 4462D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	LAMPSTAY	BENT	95.00	95.00
1	FRONT FENDER	CRACKED	75.00	75.00
2	FORK INNER TUBES	BENT	370.00	370.00
2	FORK OUTER TUBES	BENT	390.00	390.00
1	FORK UNDER BRACKET	BENT	232.00	232.00
1	FRONT RIM SHAFT	TO REPAIR SEE LABOUR	42.00	-
1	FRONT BRAKE DISC	BENT	150.00	150.00
1	HEADLAMP	BROKEN	185.00	185.00
2	FRONT SIGNAL	N/S CUT / O/S BROKEN	126.00	126.00
2	FRONT SIDE COWLING	NOT NECESSARY	270.00	-
1	RADIATOR	NOT NECESSARY	345.00	-
2	SIDE MIRRORS	CUT	160.00	160.00
1	HANDLE BAR	BENT	85.00	85.00
2	HANDLE BAR ENDS	BENT	56.00	56.00
1	CLUTCH LEVER	CRACKED	28.00	28.00
1	BRAKE LEVER	CRACKED	28.00	28.00
1	METER ASSY	BROKEN	425.00	425.00
1	FUEL TANK	DENTED	512.00	512.00
2	FRONT FOOTRESTS	O/S TORN	70.00	35.00
2	FRONT FOOTRESTS BRACKETS	O/S BENT	90.00	45.00
1	BRAKE PEDAL	CUT	48.00	48.00
1	GEAR PEDAL	NOT NECESSARY	48.00	-
1	REAR FOOTREST -R/H	NOT NECESSARY	35.00	-
1	EXHAUST ASSY	TO REPAIR SEE LABOUR	425.00	-
1	EXHAUST PROTECTOR -CHROME	BENT	68.00	68.00
1	EXHAUST PROTECTOR -BLACK	NOT NECESSARY	48.00	-
2	REAR TAILBOARDS	O/S CUT	310.00	155.00
1	REAR FENDER	NOT NECESSARY	70.00	-
1	FRONT RIM	BENT	190.00	190.00

Report Ref No. CC4/LPC18007660/Uua3n2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	KEY SWITH	CRACKED	90.00	90.00
	LESS 10% DISCOUNT		-506.60	-354.80
			4,559.40	3,193.20
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET NUMBER PLATE (SN)	NECESSARY	28.00	10.00
2	FORK OILS (SN)	NECESSARY	30.00	30.00
2	FORK OILS SEALS (SN)	NECESSARY	56.00	56.00
1	SET STEERING CONE (SN)	NECESSARY	90.00	90.00
1	REAR BOX (SN)	MISSING	250.00	150.00
1	REAR BOX BRACKET (SN)	BENT	100.00	100.00
1	COOLANT (SN)	NOT NECESSARY	15.00	-
1	ERP IU (SN)	NOT NECESSARY	160.00	-
1	SET STICKER (SN)	NECESSARY	85.00	85.00
			814.00	521.00
	<b><u>LABOUR</u></b>			
	TO PROVIDE TOWING SERVICE.		50.00	35.00
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING.	NOT NECESSARY	80.00	-
	TO PROVIDE LABOUR.INCLUSIVE OF THE REPAIR OF FRONT RIM SHAFT AND EXHAUST ASSY .		380.00	300.00
	TO CHECK ,REPAIR AND STRAIGHTEN BODY FRAME.		350.00	250.00
			860.00	585.00
	<b>GRAND TOTAL</b>		<b>6,233.40</b>	<b>4,299.20</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>2,000.00</b>

Report Ref No. CC4/LPC18007660/Uua3n2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.