

ESTIMATE TO REPAIR

VEHICLE NO. : SJZ 5255 T
MAKE : MERCEDES BENZ
MODEL : C 180 CGI
YEAR : 2010
CHASSIS NO : WDD2040492A405978

SURVEYOR NAME :
DATE OF SURVEY : 25 APR 2018
TIME OF SURVEY :

DATE : 23-Apr-18
DATE OF ACCIDENT : 2-Apr-18
THIRD PARTY REF : GBH1958P / EQ INSURANCE

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Front Bumper	Nett		Build it	\$ 820.00
1 pc	N/S Front Bumper Retainer	Nett		2 items / 1 hr	\$ 19.00
1 pc	N/S Headlamp	Nett			\$ 670.00
1 pc	N/S Front Fender	Nett			\$ 430.00
					\$ 1,939.00
	Less 10%				\$ 193.90
					\$ 1,745.10
	To putty & spray painting.				\$ 600.00
	To check front wiring and focus headlights				\$ 30.00
	Labour Charges.				\$ 450.00
	Not Withair				
	11 Lyr 8?				
	Resurvey After Point				
	4 days				
TG-RA/-	TOTAL				\$ 2,825.10

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Lim Tan Motor Pte Ltd
Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721

Tel:65-64520893 Fax:65-64589127

Co.Reg No.199307277D

Website: www.LTM.sg

GST Reg No M2-0019086-0