



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 1008, Bukit Merah Lane 3,
#01-04/06/08/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise In Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre
Hilton Auto Trading
Dealing In New/Used Cars, Hire Purchase & Insurance.



TP INSURER: India International Insurance Pte Ltd (HQ)
UNKNOWN

Singapore

Claimant Insurer: NTUC Income Insurance Co-operative Ltd

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	23/04/2018
Vehicle Reg. No.:	GBG3215S	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	PERIYASAMY SACHIDHANANDHAM		
Make/Model:	NISSAN CABSTAR, 3.0 5M/T ABS 2DR 2WD EURO 5 (A)	Vehicle Reg. Date:	20/07/2017
Vehicle Colour:	WHITE	Chassis No:	JN1SC2F24Z0859769
Engine No:	ZD30023772N		
Odometer:	0 KM		
Paint Type:			
List Item Discount:	30.00 %	Nett Item Discount:	10.00 %
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Description of Accident/Loss	PLEASE REFER TO THE SKETCH PLAN		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

COST OF CLAIMS	Amount
Parts	3,100.61
Miscellaneous Items	10.00
Labour	1,110.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	4,220.61
+ GST 7.00% (S\$)	295.44
Nett Amount (S\$)	4,516.05

This claim is handled by: BILLY

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 25 Apr 2018)**Parts:** N/A NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5 (A) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for GBG3215S)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR FENDER (REAR) LH	10.00	0.00	*155.80 FN
2	1		*REAR MUDFLAP LH	0	0.00	*46.80 FS
3	1		*SIDE PANEL LH	10.00	0.00	*2,600.60 FN
4	1		*SIDE PANEL LOCK LATCH (REAR) LH	10.00	0.00	*33.30 FN
5	1		*REAR CORNER BRACKET LH	10.00	0.00	*163.40 FN
6	2		*REAR CORNER STOPPER LH	10.00	0.00	*17.80 FN
7	1		*SIDE PANEL STICKER	0	0.00	*380.00 FS
Sub Total (S\$)						3,397.70
- Nett Item Discount on N Items (S\$)						297.09
Total Parts (S\$)						3,100.61

F=Franchise part. S=SpcNett. N=NettItemDisc.

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	10.00
Sub Total (S\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO KNOCK AND STRAIGHTEN SIDE MEMBER LH. REMOVE AND REPLACE ACCIDENT DAMAGED PARTS. REALIGN ALL CONNECTION	New	450.00
2	SPRAY PAINT REAR FENDER LH, SIDE PANEL LH, SIDE MEMBER LH, REAR LATCH LH. CORNER BRACKET LH	New	600.00
3	RUST PROOF AFFECTED AREAS	New	60.00
Gross Labour Cost (S\$)			1,110.00

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >