

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

AXA INSURANCE SINGAPORE PTE LTD
 143 Cecil Street #01-01 GB Building
 069542

Attention : Motor Claim Department
 Contact : 338 7288 Fax No. : 880 4838

Estimate : ES000090

Date : 24/04/2018
 Vehicle Num. : SLM 5782H (LCR)
 Make/Model : HONDA VEZEL HYBRID
 Chassis/Eng# :
 Accident Date : 22/04/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1	REAR TAIL LAMP - LH ✓ CRK		700.00
2.	1	REAR SIDE BUMPER - LH R		250.00
3.	1	REAR BUMPER R		900.00
4.	1	REAR WHEEL ARCH MOULDING - LH ✓ CRK		250.00
List TotalS\$:				2,100.00
20.00% Discount S\$:				420.00
				1,680.00

SPECIAL NETT ITEMS :				
1.	1	REAR BUMPER CLIP		50.00 30
Special Nett Total S\$:				50.00
LABOUR :				
WIRINGS CHECK AND RECTIFY WHERE NECESSARY				180.00 30
TO DEACTIVE AND ACTIVATE HIGH VOLTAGE HYBRID BATTERY AS A REQUIREMENTS FOR SAFETY PRECAUTIONS.				280.00 X
TO CONDUCT A STANDARD OF OPEARTING PROCEDURE POST REPAIRS DIAGNOSTIC SCAN TEST A REQUIREMENT FOR HYBRID CARS UPON COMPLETION OF COLLISION REPAIRS.				280.00 X
LABOUR TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS, INCLUDING PANEL BEAT & REPLACE ABOVE PARTS				500.00 300

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

AXA INSURANCE SINGAPORE PTE LTD
 143 Cecil Street #01-01 GB Building
 069542

Attention : Motor Claim Department
 Contact : 338 7288 Fax No. : 880 4838

Estimate : ES000090

Date : 24/04/2018
 Vehicle Num. : SLM 5782H (LCR)
 Make/Model : HONDA VEZEL HYBRID
 Chassis/Eng# :
 Accident Date : 22/04/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		PUTTY AND SPRAY PAINT REAR & ALL AFFECTED AREAS.	400	500.00
		Labour Total S\$:		1,740.00

Sebastian
 26/4/18.
 - Part by part repair.
 - Photo Before Paint
 90036121
 Sebastianyeang@lkk-auto.com.

3 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

E. & O.E.

Total S\$: 3,470.00
 =====

for WORLD AUTO PTE LTD