Hsiao Tong (LKKAuto)

From:

Joel Goh <joel.goh@eqinsurance.com.sg>

Sent:

Tuesday, 12 March 2019 2:59 PM

To:

Hsiao Tong (LKKAuto)

Cc:

Admin A

Subject:

RE: <Seek Mandate> Your ref: DM18HO01084-JG Our ref:

CC4/EQI18007748/T1pa3s2 [ACCIDENT INVOLVING CB6541UP(EQ-OI) AND

SJC6513M(TP) ON 26/04/2018]

Dear Hsiao Tong

Please proceed to resolve this matter up to \$\$20,240.56.

Best Regards,

Joel Goh

Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110 did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190 www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify th

From: Hsiao Tong (LKKAuto) [mailto:chewht@lkkauto.com]

Sent: Saturday, February 2, 2019 2:52 PM

To: EQI PRS Cc: Admin A

Subject: <Seek Mandate> Your ref : TBA Our ref : CC4/EQI18007748/T1pa3s2 [ACCIDENT INVOLVING

CB6541UP(EQ-OI) AND SJC6513M(TP) ON 26/04/2018]

Your ref: TBA

Our ref: CC4/EQI18007748/T1pa3s2

Dear Sirs/Madam,

ACCIDENT INVOLVING CB6541UP(EQ-OI) AND SJC6513M(TP) ON 26/04/2018

We refer to the above matter.

This is a head-to-rear collision.

We did clarify with insured the nature of the accident and he's aware that NCD (if any) would be affected.

We seek your approval to offer Third Party repairer "KAH MOTOR CO SDN BHD" at \$20,240.56(all-in).

The summary is as follows: -

	Claimed Amount	Revised Amount			
1. Cost of Repair (w/GST)	\$ 24,211.85	\$ 19,440.56			
2. Loss of Use (16days x \$50.00)	\$ 800.00	\$ 800.00 (16days x \$50.00)			
Total	\$ 25,011.85	\$ 20,240.56			

^{**12}days recommendation for repair + 2Saturday + 2Sunday = 16days

Enclosed here with all the relevant documents for your perusal.

Kindly let us have your approval/instruction.

Best Regards,

Hsiao Tong, Chew | Case Handler LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

To: M/s EQ INSURANCE COMPANY LTD

Date: 11/04/2019

THIRD PARTY DIRECT SETTLEMENT

Vakiele Na	CB 6541U	(Insd Veh)	Your Ref. No.: DM18HO01084-JG
Vehicle No.	SJC 6513M	(TP Veh)	Our Ref. No.: CC4/EQI18007748/T1pa3s2
Date of Accident	26/4/2018		

Liability		100%	
Final Repair Cost	: \$	19,440.56	(W/GST)
Loss of Use	: \$	800.00	16 days
Rental (If any)	: \$		days
Others:	: \$		
	: \$		
		20,240.56	
Final Settlement Sum	: \$	20,240.56	
Remarks	:		

1)	KAH MOTOR CO. SDN. BHD.	: \$	20,240.56
		: \$	2 2 3 1 200 20 1 2 2 2 2

NUR SHAQILAH LKK Auto Consultants Pte Ltd

Hsiao Tong (LKKAuto)

From:

Hsiao Tong (LKKAuto)

Sent:

Saturday, 2 February 2019 2:52 PM

To:

'egiprs@eginsurance.com.sg'

Cc:

Admin A

Subject:

<Seek Mandate> Your ref: TBA Our ref: CC4/EQI18007748/T1pa3s2 [ACCIDENT

INVOLVING CB6541UP(EQ-OI) AND SJC6513M(TP) ON 26/04/2018]

Attachments:

LKK Survey Report & Photos.pdf; TP LOD_SJC6513M.pdf

Your ref: TBA

Our ref: CC4/EQI18007748/T1pa3s2

Dear Sirs/Madam,

ACCIDENT INVOLVING CB6541UP(EQ-OI) AND SJC6513M(TP) ON 26/04/2018

We refer to the above matter.

This is a head-to-rear collision.

We did clarify with insured the nature of the accident and he's aware that NCD (if any) would be affected.

We seek your approval to offer Third Party repairer "KAH MOTOR CO SDN BHD" at \$20,240.56(all-in).

The summary is as follows: -

	Claimed Amount	Revised Amount
Cost of Repair (w/GST)	\$ 24,211.85	\$ 19,440.56
2. Loss of Use (16days x \$50.00)	\$ 800.00	\$ 800.00 (16days x \$50.00)
Total	\$ 25,011.85	\$ 20,240.56

^{**12}days recommendation for repair + 2Saturday + 2Sunday = 16days

Enclosed here with all the relevant documents for your perusal.

Kindly let us have your approval/instruction.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: <u>chewht@lkkauto.com</u> | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Our Ref: CC4/EQI18007748/T1ua3

14 June 2018

Toh Yaik Hwee APT Blk 705 Hougang Ave 2 #08-265 Singapore 530705

Dear Sir/Madam,

ACCIDENT INVOLVING CB 6541U AND SJC 6513M ON 26/04/2018

We refer to the above accident where we are acting for EQ INSURANCE COMPANY LIMITED to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

THIN THIN HLAING

Case Handler DID: 6841 2360 FAX: 6741 4108

EMAIL: thinthin@lkkauto.com

c.c. EQ INSURANCE COMPANY LIMITED (Motor Claims Dept)

LETTER OF AUTHORITY

TO WHOM IT MAY CONCERN

ACCID	ENT IN	VOLVII	ig (owner	S VE	HCLE NO	52 1.0	206	513m	රින
(THIRD	PARTY'S	VEHICI	ENO.) CB	654	114	0	~ ^	4 18	
ALONG.	Seng	Kang	Square	10	Sens	Kary	East	Road	
	7	7				J			

I hereby authorize Kah Motor Co. Sdn Bhd (Kah Motor) and its agents or any person authorized by Kah Motor to do all or any of the following:

- To submit, resolve and make any claim(s) which I may have against the 3rd party insurers.
- To execute, sign discharge voucher/indemnity forms and all necessary documents in connection with and arising out of the above claim.
- Any payment should be made in favour of my name / Kah Motor Co. Sdn. Bhd.

	, //
	any
Owner S (Co stamp	& authorized signature if is Co registered vehicle)
Name:_	Ng Tze Hwee
NRIC No	= 58200591I
Vehicle No	: SJC 6513M
Date :_	17/5/18

1

Letter of Authority (insurer)

EQ Insurance Company Limited

5 Maxwell Road, #17-00 Tower Block, MND Complex, Singapore 069110 Tel: (65) 6223 9433 Fax: (65) 6223 4190 WITHOUT PREJUDICE to:

Any Personal Injury Claims

DISCHARGE VOUCHER

Claim No: DM18HO01084-JG

In consideration of the offer/payment of the sum of SINGAPORE DOLLARS: TWENTY THOUSAND TWO HUNDRED FORTY AND CENTS FIFTY SIX Only (\$\$20,240.56) by EQ Insurance Company Limited, I/we hereby accept such sum in full and final settlement of all claims (present or future), losses of use/injuries that I/we have or may have against EQ Insurance Co. Ltd and/or Toh Yaik Hwee/ Seow Yew Chye (the insurer, owner and driver of vehicle No. CB 6541U) in connection with or in any way arising from the accident along/at SLIP RD OF SENGKANG EAST ROAD on 26/04/2018 involving SJC 6513M (your client) and CB 6541U (Insured with EQ Insurance Co Ltd).

It is further agreed that this offer is not to be deemed as an admission of liability on the part of EQ Insurance Co. Ltd. and/or Toh Yaik Hwee/ Seow Yew Chye (the insurer, owner and driver of vehicle No. CB 6541U).

Dated this 13 (day) of MARCH (month) 2019 (year)

CLAIMANT		WITNESS	
Name	NG TZE HWEE	Name	: DESMOND TOH
Signature	<u> </u>	Signature	: Des
Address	: 223A COMPASSVALE WALK	Address	BODY REPAIR & PAINT CENTRE
	#10-625		SINGAPORE 729905 TEL: 6514 5266 FAX: 6365 1949
	SINGAPORE 541223		
NRIC No.	: <u>S8200591I</u>	NRIC No.	t



Kah Motor Co. Sdn. Bhd.

Service Tax Invoice

GST Reg No. M200050223

10/09/18 SVO18024127

09681

SJC6513M

SINV-BM18001066

Company Ref. No. S60FC1380G

(A Member of Oriental Holdings Berhad)

6A Mandai Estate, SINGAPORE 729903

Mandai Parts Centre

Phone No.: +65 6841 3838 Fax No.:

EQ INSURANCE COMPANY LTD MOTOR CLAIMS DEPT

5 MAXWELL ROAD

#17-00 TOWER BLK MND BUILDING

SINGAPORE, 069110

BML02I

BKRP02M

BOMISC1

BPOOR

Customer No. : WZE011

Invoice No. : Invoice Date :

Order No. Reference

Job Card No. Date/Time Received

26/04/18 / 11:13:50 AM Licence No. Model . JAZZ 1.5VTIR CVT 17YM

Car Chassis No. Car Engine No. : Mileage

JHMGK5850HX200597 L15B31190351 30073

Service Advisor NG SIN HAI 1596 : Served By : SHNG Page

180.00

560.00

560.00

560.00

560.00

320.00

100.00

5.040.00

2,700,00

450.00

380.00

560.00

560.00

450.00

12.60

39.20

39.20

39.20

39 20

22.40

7.00

352.80

189 00

31.50

26.60

39.20

39.20

31.50

192.60

599.20

599 20

599.20

599.20

342.40

107.00

5,392.80

2,889.00

481.50

406.60

599.20

599.20

481.50

7% GST Amount Incld No. Description U. PriceDisc % Qtv. UoM Amount Amount TP DIRECT SETTLEMENT (J/NO:

OWNER:NG TZE HWEE OWNER INSURER:LIBERTY ACC DATE:26/04/2018 SURVEYED BY: TAUFIKH DATE:26/04/2018 REF NO:

TP INSURER:EQ INSURANCE COMPANY LTD

INSPECT RR LIGHTING MECHANISMS.

TP VEH:CB6541U

BOSUN 0701 SUNDRIES 1 Hours 30.00 30.00 2 10 32.10 BA02R 0701 REMOVE & RENEW REVERSE SENSORS-4 1 Hours 180.00 180.00 12.60 192 60 PCS (N) BOJSE 0701 SEALANT FOR REAR END PANEL 1 100.00 Hours 100.00 7.00 107.00 BOJSE 0701 SEALANT FOR LHR FENDER Hours 80.00 80.00 5.60 85.60 BOJSE 0701 SEALANT FOR TAILGATE 80.00 1 Hours 00.08 5.60 85.60 BOJSE 0701 SEALANT FOR REAR FLOOR PANEL 1 Hours 80.00 80.00 5.60 85.60

1

1

1

1

1

1

1

Hours

180.00

560.00

560.00

560.00

560.00

320.00

100.00

5,040.00

2,700.00

450.00

380.00

560.00

560.00

450.00

PERFORM WATER TEST.(N) BMF00D 0701 RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)

BMI02D 0701 REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK LININGS GARNISHES & ETC.(N) BKTG02R 0701 REMOVE & TRANSFER ITEMS TO NEW

0701

TAILGATE. ADJUST & ALIGN TAILGATE.(N) BG02D 0701 REMOVE & INSTALL RR. WINDSCREEN.(N) BG51D REMOVE & INSTALL RR. L QTR GLASS.(N) 0701 BODAMKIT 0701 WINDSCREEN DAM KIT.

CUT OFF & RENEW RR PANEL

REMOVE UPHOLSTERY AND VACUUM

APPLY BODY UNDERSIDE COATING (N).

SHATTERED GLASS

RR FLOOR PAN & RENEW DAMAGE PARTS. SPRAY PAINTING ON REPAIRED OR BP06R 1718 REPLACED AREAS. (6P) REAR PORTION **BKOTOOR** 1718 REMOVE & RENEW RR FLOOR INSULATOR.

1466

(N) BKBU01R REMOVE, RE-FIX AND ALIGN REAR VIEW 1718 CAMERA BOMISC1 1718 REMOVE AND RENEW DVR CAMERA

1718

1718

GST Amount is calculated from individual line(s)

Printed by SHNG on 11 Sep 2018 at 4:42:00 PM This is a computer generated invoice. No signature is required. Please review your bill and advise us of any errors or omissions. Kah Motor reserves the right to deliver a subsequent bill for any charge omitted.

Please give us your feedback by scanning the QR Code using mobile device.





Service Tax Invoice

GST Reg No. M200050223

Company Ref. No. S60FC1380G

NG SIN HAI 1596

Kah Motor Co. Sdn. Bhd.

(A Member of Oriental Holdings Berhad) 6A Mandal Estate, SINGAPORE 729903

Mandai Parts Centre

Phone No.: +65 6841 3838 Fax No.:

EQ INSURANCE COMPANY LTD MOTOR CLAIMS DEPT

5 MAXWELL ROAD

#17-00 TOWER BLK MND BUILDING

SINGAPORE, 069110

Customer No. :

WZE011

Invoice No.	:	SINV-BM18001066
Invoice Date	:	10/09/18
Order No.	:	SVO18024127
Reference	:	
Job Card No.	:	09681
Date/Time Received	:	26/04/18 / 11:13:50 AM
Licence No.	:	SJC6513M
Model	:	JAZZ 1.5VTIR CVT 17YM
Car Chassis No.	:	JHMGK5850HX200597
Car Engine No.	:	L15B31190351
Mileage		30073

SHNG Served By

Service Advisor

Page

No.		Description		. UoM	U. PriceDisc %		Amount	7% GST Amount incld Amount GST	
1101		2000119201							
NMRS-4P-TM3040L	1718	4PCS ACT RR.SENSOR	1	Each	320.00		320.00	22.40	342.40
BO-NUM-COMP-L		NUMBER PLATE WITH CASING-L(N)	1	Each	45.00		45.00	3.15	48.15
33500-T5A-J02		TAILLIGHT ASSYR.	1	Each	217.40	25	163.05	11.41	174.46
33550-T5A-J02		TAILLIGHT ASSYL	1	Each	217.40	25	163.05	11.41	174.46
68100-TAS-Z50ZZ		TAILGATE COMP	1	Each	716.30	25	537.22	37.61	574.83
74440-T5A-003		WEATHERSTRIPTAILGATE	1	Each	92.30	25	69.22	4.85	74.07
74800-T7A-J02		LOCK ASSYTAILGATE	1	Each	76.60	25	57.45	4.02	61.47
75722-T5L-T01		EMBLEMRR.	1	Each	10.50	25	7.87	0.55	8.42
04715-T5B-000ZZ		FACERR.BUMPER	1	Each	492.60	25	369.45	25.86	395.31
71593-T5A-000		SPACERR.RR.BUMPER	1	Each	11.50	25	8.62	0.60	9.22
71598-T5A-000		SPACERL.RR.BUMPER	1	Each	11.50	25	8.62	0.60	9.22
91505-TM8-003		CLIPBUMPER	5	Each	2.00	25	7.50	0.53	8.03
66100-TAR-T10ZZ		PANEL COMPRR.	1	Each	314.00	25	235.50	16.49	251.99
84640-T5A-003ZA		LINING ASSYRR.PANEL	1	Each	60.80	25	45.60	3.19	48.79
84521-T5A-901ZA		LID ASSYSPARE TIRE	1	Each	186.00	25	139.50	9.77	149.27
73127-TY0-000		RUBBER CWINDSHIELD DAMPER	1	Each	11.20	25	8.40	0.59	8.99
73214-T5A-013		RUBBERWINDSHIELD DAMPER	2	Each	6.30	25	9.45	0.66	10.11
73226-SZW-000		DAMPERSTD 5X5	1	Each	8.30	25	6.22	0.44	6.66
BO-WS-SEALANT		WINDSCREEN SEALANT (N)	2	Each	60.00		120.00	8.40	128.40
38387-TZ5-A01		ANTENNA ASSYL.F.	1	Each	58.10	25	43.57	3.05	46.62
74940-TZ5-A01		BUZZER ASSYSMART	1	Each	59.30	25	44.47	3.11	47.58
04646-TAS-320ZZ		PANEL SET,L.RR.OUTSIDE	1	Each	559.30	25	419.47	29.36	448.83
73211-T5A-J01		GLASS SETRR.WINDSHIELD	1	Each	625.60	25	469.20	32.84	502.04
BO-R-COOL-RWS		SUPPLY & INSTALL SOLAR FILM ON REAR WINDSCREEN.	1	Labor	300.00		300.00	21.00	321.00
73525-SYY-000		RUBBERRR QTR W/SHIELD	2	Each	9.50	25	14.25	1.00	15.25
91501-T5A-901		CLIP A ,QUARTER WINDSHIELD	1	Each	3.40	25	2.55	0.18	2.73
91502-T5A-901		CLIP B ,QUARTER WINDSHIELD	1	Each	3.60	25	2.70	0.19	2.89
91503-TD4-003		CLIP C,QUARTER WINDSHIELD	1	Each	2.40	25	1.80	0.13	1.93
BO-WS-SEALANT		WINDSCREEN SEALANT (N)	1	Each	60.00		60.00	4.20	64.20
NMDVR-DR750S-2CH		DVR BLACKVUE 2 CHANNEL ADDITIONAL PART	1	Each	568.00		568.00	39.76	607.76
84550-T5S-M10		BOX ASSYCARGO FLOOR	1	Each	103.90	25	77.92	5.45	83.37
84440-T5A-J02ZA		LINING ASSYTAILGATE LOWER	1	Each	52.10	25	39.07	2.73	41.80
74890-T5B-911		GARNISH ASSYRR.LICENSE	1	Each	194.70	25	146.02	10.22	156.24
63720-T5A-900ZZ		GUTTER COMP, L.RR. PILLAR LOWER	1	Each	86.90	25	65.17	4.56	69.73
90650-TX6-A01		CLIPRR.COMBINATION LIGHT	1	Each	1.90	25	1.42	0.10	1.52

Printed by SHNG on 11 Sep 2018 at 4:42:00 PM

This is a computer generated invoice. No signature is required, Please review your bill and advise us of any errors or omissions.

Kah Motor reserves the right to deliver a subsequent bill for any charge omitted. GST Amount is calculated from individual line(s)

Please give us your feedback by scanning the QR Code using mobile device.





Service Tax Invoice

GST Reg No. M200050223

Company Ref. No. S60FC1380G

Kah Motor Co. Sdn. Bhd.

(A Member of Oriental Holdings Berhad) 6A Mandai Estate, SINGAPORE 729903

Mandai Parts Centre

Phone No.: +65 6841 3838 Fax No.:

EQ INSURANCE COMPANY LTD MOTOR CLAIMS DEPT

5 MAXWELL ROAD

#17-00 TOWER BLK MND BUILDING

SINGAPORE, 069110

Customer No. :

WZE011

Invoice No. Invoice Date SINV-BM18001066 10/09/18

Order No. Reference

Job Card No.

09681 26/04/18 / 11:13:50 AM

JAZZ 1.5VTIR CVT 17YM

Date/Time Received Licence No.

:

SJC6513M

Model Car Chassis No. Car Engine No.

JHMGK5850HX200597 L15B31190351

SVO18024127

Mileage Service Advisor Served By

30073 NG SIN HAI 1596

3

: SHNG Page

7% GST Amount incld Description Qty. UoM U. PriceDisc % Amount Amount GST 76720-T5A-003 ARMRR.WIPER Fach 41.70 25 31.27 33.46 2.19 76730-T5A-003 BLADERR.WINDSHIELD WIPER 350M Each 1 40.20 25 30.15 2.11 32.26

> Sum Labor 13,530.00 947.10 14,477.10 Sum Item 4,338.75 303.71 4,642.46 Sum External Services 300.00 21.00 321.00 Total SGD 18,168.75 1,271.81 19,440.56

Total Payable (SGD)

19,440.56