

ASS. REC. BY:

REF: CS/CTU8007759 / Ar 6

Special Instructions:

Surveyor

Aurum

ASSIGNMENT (Office)

From (Person):

June Tay

of

CTL

Date/Time

26042018 3:10pm

Estimated Cost:

Bill to:

OD / TI / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLL 8204X

Insured:

G88 6446T

at Workshop m/s

Autolution

Tel:

9645 0079

of

19 Ubi Rd 4

Policy No:

DMCVSN9071021708

Claim No:

SNM18D02044C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

20042018

CA / REV / REP. / REV 24 HRS wpi

30042018 Claim

H.O.D. Endorsement:

Date/Time:

26042018 3:37pm

Person Contacted:

Hamzah

Vehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate

SLL 8204X - X

G88 6446T - CCB/CTU8001503 / AngSe

DUA 20042018

REF: CIL

MUMUK

ASSIGNMENT

From: Date: 30042018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLL 8204X

at Workshop n/s

of 19 Ubi Rd 4

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh: Hamzah

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SLL8204X. Yr Regn: 2017 March

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan Qashqai cc 1997

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 13793 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: SJNFBAJ1111926794.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / STD A/Rim or

Tyre Size: F: 225/45R19.

R: 225/45R19.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal: 06 mm R/Bal: 06 mm

L/Bal: 06 mm L/Bal: 06 mm

D.O.A. D.O.I. 30/04/18

Survey held at Tan Chong Club

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Chong

Final Sig \$ 2767.68 (Red. 978.08, 36%)

RECEIVED 10 OCT 2018

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: 4

f)

☐ : Final Report

Resurvey No. of Trip: -

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)

Survey Fee

Transportation

S + R = \$

Photos

Others

Report Format: TP

Lump Sum / 101: \$ 2767.68

☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Apr 2018		26 Apr 2018 15:10 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	OASES TRADING PTE LTD, Co. Reg. No.: 200516996D								
Main Claimant:	NILESH GHANSHYAM TRIVEDI, ID: S7184236C								
Vehicle Reg. No.:	SLL8204X	Date of Loss:	20/04/2018 09:00 - :59						
Claim Type:	TP / SNM18D02044C02	Policy/Cover Note No.:	DMCVSN9027021708 (Comprehensive)						
Vehicle Reg. No. (Insured):	GBB6448T	Policy No. (Claimant):	PNPV2018-00002533						
		Excess:	\$50.00						
Repairer:	Autolution Industrial Pte Ltd (Ubi) 19 Ubi Road 4, 408623 Ubi - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]								
Claimant's Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 08/05/2018]								
Driver/Custodian (Insured):	FOO AH KAU (68 / Male), NRIC: S2500881B, Tel: +6593660881								
Adj Asg. Remarks:	EST \$3745.18, ASSIGN MARCUS CHUA AS SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4236C
Vehicle Details	
Vehicle No.:	SLL8204X
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Oct 2018
Vehicle Make:	NISSAN
Vehicle Model:	QASHQAI 2.0 CVT ABS D/AIRBAG 2WD 5DR S/R
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	MR20453739W
Chassis No.:	SJNFBAJ11U1926794
Maximum Power Output:	106.0 kW (142 bhp)
Open Market Value:	\$19,507.00
Original Registration Date:	10 Mar 2017
First Registration Date:	10 Mar 2017
Transfer Count:	0
Actual ARF Paid:	\$19,507.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Mar 2027
PARF Rebate Amount:	\$14,630.00
Intended COE Rebate Details	
COE Expiry Date:	09 Mar 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,621.00
COE Rebate Amount:	\$42,502.00
Total Rebate Amount:	\$57,132.00

The information contained herein is correct as at 15 Oct 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/04/2018 14:55
Date Of Accident	20/04/2018 09:00
Exact Location Of Accident	KPE ENTRANCE AT UBI
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLL8204X
Insured/Policyholder	
Name Of Registered Owner	NILESH GHANSHYAM TRIVEDI
NRIC No	S7184236C
Email Address	NNHP2012@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97257248
Alternative Phone No	OTHERS-66695906

Vehicle Particulars

Manufacturer	NISSAN
Model	QASHQAI-2.0 PREMIUM (J10) (A)
Exact Purpose for which vehicle was being used at time of accident	

Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2018-00002533
Cover Note Number	

Driver

Name of Driver	NILESH GHANSHYAM TRIVEDI
NRIC No	S7184236C
Date Of Birth	14/04/1971
Occupation	INDOOR
Date Of Driving Pass	10/01/2004
Driving Experience	14 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97257248
Fax Number	
Contact Number	OTHERS-66695906
Email Address	NNHP2012@GMAIL.COM

Details Of Properties

Vehicle Category: COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number: S83175538

Contact Number: 97199075


Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 20TH APRIL 2018, MORNING, I, NILESH GHANSHYAM TRIVEDI (NRIC-571842360) WAS DRIVING TO WORK ALONE IN MY CAR (SL 8204X) ON MY USUAL ROUTE.

AROUND 9:00AM ON 20TH APRIL 2018, SUDDENLY MY CAR WAS HIT BY VEHICLE FROM BEHIND (VEHICLE NO: G8B 644RT) DAMAGING REAR PART OF MY CAR SL 8204X. VEHICLE BEHIND MY CAR WAS DRIVEN BY MR FOO AH KAU (NRIC-52500881B) AND DRIVING LICENCE NO. 52500881B.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

N. Ghanshyam
20/04/2018

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/PIN No.:

TH

Third Party Insurer Enquiry

Our Ref No: GR-18-062517

Date of Request: 25/04/2018

Your Ref No: Online Purchase

Tan Chong Motor Sales Pte Ltd
911, Bukit Timah Road
Singapore 589622

Dear Sir/Madam,

Enquiry Date: 25/04/2018
Enquiry By: Eric Koh Yong Lang
TP Vehicle No.: GBB6448T
Accident Date: 20/04/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
GBB6448T	China Taiping Insurance (Singapore) Pte. Ltd.	25/08/2017-24/08/2018	6389 6111

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

AUTOLUTION INDUSTRIAL PTE. LTD.

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : IHS/IC/HV0242/18

DATE : 20-APR-2018

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD #4
SINGAPORE 408623
TEL: 6490 9666 FAX: 6846 7483

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3 ANDON ROAD

#16-00 SPRINGLEAF TOWER

S(079909)

TEL : 63896111

FAX : 62247175

OWNER'S NAME : MR TRIVEDI NILESH GANESHYAM

ADDRESS : 53 TAMPINES AVE I

#11-04

S(529772)

TELEPHONE NO : 97257248

TYPE OF CLAIM : THIRD PARTY CLAIM

POLICY NO : *

VEHICLE NO : SLL8204X

MODEL CODE : F0RARBZJ11EWAFJ3-

MODEL/YEAR : NISSAN QASHQAI 2.0 MY2014

ENGINE NO : MR204537394

CHASSIS NO : SJNFBAJ11U1926794

MILEAGE : 13436 KM

DATE IN : 20/04/2018

LIABILITY : 0.00

EXCESS CLAUSE : 0.00

ESTIMATE BY : HANZAH

ACCIDENT DATE : 20/04/2018

- 96450079

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLLB200K

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	LABOUR CHARGES TO REPAIR REAR H/BACK DOOR, REAR PANEL AND RENEW REAR BUMPER.	900.00	850.00
2	ZZ/002	CHARGES TO SPRAY PAINTING SAME.	850.00	750.00
3	ZZ/003	REMOVE AND INSTALL REVERSE SENSOR TO RENEW.	110.00	✓
TOTAL LABOUR CHARGES			1860.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SL1820XX

		DAMAGED PARTS & PRICES				
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	REMARKS
1	SUNDRIES <i>Net</i>	NPN			50.00	20
2	SENSOR-REVERSE <i>Payd</i>	SENSOR			250.00	✓
3	EMBLEM-REAR DASHOAT <i>Free</i>	90892-4EAOA	87.00	✓		
4	EMBLEM-REAR NISSAN	90890-4EAOA	59.70	✓		
5	REAR BUMPER TOW HOOK COVER <i>Deformed</i>	85071-4EAOA	16.80	✓		
6	REAR BUMPER STAY LH <i>?</i>	H5211-4EAMA	126.00	X	} NN	
7	REAR BUMPER STAY RH <i>?</i>	H5210-4EAMA	126.00	X		
8	REAR BUMPER REINFORCEMENT <i>?</i>	H5030-4EAMA	619.20	X		
9	ENERGY ABSORBER REAR BUMPER <i>?</i>	85090-4EAOB	126.40	X		
10	REAR BUMPER SIDE BRKT LH <i>Net</i>	85221-4EAOA	35.90	✓		
11	RETAINER REAR BUMPER <i>Net</i>	79184-4EAOA	23.60	✓		
12	CLIP REAR BUMPER @ 17.40 EACH <i>Net</i>	85284-3000A	44.40	✓		
13	REAR BUMPER FASCIA <i>Deformed</i>	85002-4EX0H	717.00	✓		
SUB TOTAL			1982.20	0.00	300.00	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			396.44	0.00	0.00	
GRAND TOTAL			1585.76	0.00	300.00	
OVERALL TOTAL			1885.76			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLL8204K

TOTAL LABOUR CHARGES	1860.00
TOTAL SPARE PARTS CHARGES	1885.76
GRAND TOTAL	3745.76 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	Adrian King	04 Days.
SURVEYED DATE	:	30/04/18.	
AUTHORIZED DATE	:		
EXCESS CLAUSE	:	0.00	
LIABILITY	:	0.00	
REMARKS	:		

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

OK

Adrian

AUTOLUTION INDUSTRIAL PTE. LTD.

FINALIZED : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/H/0242/18

DATE : 20-APR-2018

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 6846 7483

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3 ANSON ROAD

#16-00 SPRINGFIELD TOWER

S(079909)

TEL : 63896111

FAX : 62247175

OWNER'S NAME : MR TRIVEDI NILESH GUNSHYAM

ADDRESS : 53 TAMPINES AVE 1

#11-04

S(529772)

TELEPHONE NO : 97257248

TYPE OF CLAIM : THIRD PARTY CLAIM

POLICY NO : *

VEHICLE NO : SLL8204X

MODEL CODE : FDRARBZJ11EWAFJJ

MODEL/YEAR : NISSAN QASHQAI 2.0 MY2014

ENGINE NO : MR20453739W

CHASSIS NO : SJHFBZJ11U1926794

MILEAGE : 13436 KM

DATE IN : 23/04/2018

LIABILITY : 0.00

EXCESS CLAUSE : 0.00

ESTIMATE BY : HANZAH

ACCIDENT DATE : 23/04/2018

4 days

96450079

AUTOLUTION INDUSTRIAL PTE. LTD.

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLLB204X

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	22/001	LABOUR CHARGES TO REPAIR REAR H/BACK DOOR, REAR PANEL AND RENEW REAR BUMPER.	900.00	850.00
2	22/002	CHARGES TO SPRAY PAINTING SAME.	850.00	750.00
3	22/003	REMOVE AND INSTALL REVERSE SENSOR TO RENEW.	110.00	110.00
TOTAL LABOUR CHARGES			1860.00	1710.00

AMTOLITION INDUSTRIAL PTE. LTD.

MATERIAL LIST FOR ACCIDENT VEHICLE REGD NO SLL8204X

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
1	SUNDRIES	NPN			20.00 OK
2	SENSOR-REVERSE	SENSOR			250.00 OK
3	EMBLEM REAR CASHIDA	90892-4EADA	87.00		OK
4	EMBLEM-REAR NISSAN	90890-4EADA	59.70		OK
5	REAR BUMPER TOW HOOK COVER	85071-4EADA	16.80		OK
6	REAR BUMPER STAY LH	15211-4EAMA	126.00		X
7	REAR BUMPER STAY RH	15210-4EAMA	126.00		X
8	REAR BUMPER REINFORCEMENT	15030-4EAMA	619.20		X
9	ENERGY ABSORBER REAR BUMPER	85090-4EAOB	126.40		X
10	REAR BUMPER SIDE BRKT LH	85221-4EADA	35.90		OK
11	RETAINER REAR BUMPER	79184-4EADA	23.80		OK
12	CLIP REAR BUMPER @ \$7.40 EACH	85284-JD00A	44.40		OK
13	REAR BUMPER FASCIA	85022-4EADH	717.00		OK
SUB TOTAL			984.80	0.00	270.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			196.92	0.00	0.00
GRAND TOTAL			787.88	0.00	270.00
OVERALL TOTAL			1057.88		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

AUTOLUTION INDUSTRIAL PTE. LTD.

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGD NO SLL8204X

NETT ITEM	984.60
LESS 20.00%	196.92
NETT AMOUNT	787.68

LIST ITEM	0.00
LESS 30.00%	0.00
LIST AMOUNT	0.00

SPECIAL NETT ITEM	270.00
LESS .00%	0.00
SPECIAL NETT AMOUNT	270.00

TOTAL LABOUR CHARGES	1719.00
TOTAL SPARE PARTS CHARGES	1057.68

TOTAL CHARGES	2767.68
ADD 7 % GST	193.74

GRAND TOTAL	2961.42
-------------	---------

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Apr 2018		26 Apr 2018 15:10 Edit Adj Rpt	\$2,767.68 Edit Estimates	\$2,767.68 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	OASES TRADING PTE LTD , Co. Reg. No.: 200516996D								
Main Claimant:	NILESH GHANSHYAM TRIVEDI , ID: S7184236C								
Vehicle Reg. No.:	SLL8204X	Date of Loss:	20/04/2018 09:00 - :59 [13 Months and 10 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D02044C02	Policy/Cover Note No.:	DMCVSN9027021708 (Comprehensive)						
Vehicle Reg. No. (Insured):	G886448T	Policy No. (Claimant):	PNPV2018-00002533						
		Excess:	\$40.00						
Repairer:	Autolution Industrial Pte Ltd (Ubi) 19 Ubi Road 4, 408623 Ubi - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]								
Claimant's Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 08/05/2018]								
Driver/Custodian (Insured):	FOO AH KAU (68 / Male), NRIC: S2500881B, Tel: +6593660881								
Adj Asg. Remarks:	EST \$3745.18, ASSIGN MARCUS CHUA AS SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLL8204X (SNM18D02044C02)**
[GBB6448T]

TP

NILESH GHANSHYAM TRIVEDI

Apr 20 2018 9:00AM

[OASES TRADING PTE LTD]

Autolution Industrial Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser		
Video			1 per page	☒	
No	Finalized On	Autolution Industrial Pte Ltd (Ubi)		Thumbnail	Print
1	20/04/18 18:09	Video - Accident [Linked Accident Report Documents]		Load MP4	☐
2	20/04/18 18:09	Video - Accident [Linked Accident Report Documents]		Load MP4	☐
Assessment Reports			1 per page	☒	
No	Finalized On	Autolution Industrial Pte Ltd (Ubi)		Thumbnail	Print
1	20/04/18 18:15	Accident Statement		Load HTM	☐
Photos/Images			3 per page	☒	
No	Finalized On	Autolution Industrial Pte Ltd (Ubi)		Thumbnail	Print
1	20/04/18 17:44	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
2	20/04/18 17:44	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
3	20/04/18 17:44	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
4	20/04/18 17:44	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
5	20/04/18 17:44	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
6	20/04/18 17:44	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
7	20/04/18 17:44	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
8	20/04/18 17:44	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
9	20/04/18 17:46	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
10	20/04/18 17:46	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
11	20/04/18 17:46	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
12	20/04/18 17:46	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
13	20/04/18 17:46	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
14	20/04/18 17:46	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
15	20/04/18 17:46	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
16	20/04/18 17:46	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
17	20/04/18 17:47	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
18	20/04/18 17:47	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
19	20/04/18 17:47	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	15/10/18 11:26	General View		Load PDF	☐

Video			1 per page	☒
No	Finalized On	Autolution Industrial Pte Ltd (Ubi)	Thumbnail	Print
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	26/04/18 15:09	REPAIR EST	Load PDF	
2	26/04/18 15:10	OI GIA REPORT	Load PDF	
No	Finalized On	Autolution Industrial Pte Ltd (Ubi)	Thumbnail	Print
1	20/04/18 18:08	Sketch Plan [Linked Accident Report Documents]	Load TIF	
2	20/04/18 18:08	Sketch Plan #2 [Linked Accident Report Documents]	Load TIF	

Linked Accident Report Documents

Video			1 per page	☒
No	Finalized On	Autolution Industrial Pte Ltd (Ubi)	Thumbnail	Print
1	20/04/18 18:09	Video - Accident	Load MP4	
2	20/04/18 18:09	Video - Accident	Load MP4	
Assessment Reports			1 per page	☒
No	Finalized On	Autolution Industrial Pte Ltd (Ubi)	Thumbnail	Print
1	20/04/18 18:15	Accident Statement	Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Autolution Industrial Pte Ltd (Ubi)	Thumbnail	Print
1	20/04/18 17:44	Accident Photo	Load JPG	☒
2	20/04/18 17:44	Accident Photo	Load JPG	☒
3	20/04/18 17:44	Accident Photo	Load JPG	☒
4	20/04/18 17:44	Accident Photo	Load JPG	☒
5	20/04/18 17:44	Accident Photo	Load JPG	☒
6	20/04/18 17:44	Accident Photo	Load JPG	☒
7	20/04/18 17:44	Accident Photo	Load JPG	☒
8	20/04/18 17:44	Accident Photo	Load JPG	☒
9	20/04/18 17:46	Accident Photo	Load JPG	☒
10	20/04/18 17:46	Accident Photo	Load JPG	☒
11	20/04/18 17:46	Accident Photo	Load JPG	☒
12	20/04/18 17:46	Accident Photo	Load JPG	☒
13	20/04/18 17:46	Accident Photo	Load JPG	☒
14	20/04/18 17:46	Accident Photo	Load JPG	☒
15	20/04/18 17:46	Accident Photo	Load JPG	☒
16	20/04/18 17:46	Accident Photo	Load JPG	☒
17	20/04/18 17:47	Accident Photo	Load JPG	☒
18	20/04/18 17:47	Accident Photo	Load JPG	☒
19	20/04/18 17:47	Accident Photo	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Autolution Industrial Pte Ltd (Ubi)	Thumbnail	Print
1	20/04/18 18:08	Sketch Plan	Load TIF	
2	20/04/18 18:08	Sketch Plan #2	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118007759/ARBQ2

Date: 26/10/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN9027021708

Claimant Vehicle
No: SLL8204XInsured Vehicle
No: GBB6448T

Date of Loss: 20/04/2018

Nature of Claim: TP

Claim
No: SNM18D02044C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLL8204X

Make & Model: NISSAN QASHQAI, 2.0 PREMIUM (J10) (A)

Engine No: MR20453739W

Reg. Date: 10/03/2017 (Man. Year: 2017)

Chassis No: SJNFBAJ11U1926794

Colour: White

Odometer: 13793 km

Engine Capacity: 1997 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R19

Rear Tyre Size: 225/45 R19

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,885.76	1,057.68	828.08	43.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,860.00	1,710.00	150.00	8.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,745.76	2,767.68	978.08	26.11
+ GST 7.00/7.00% (S\$)	262.20	193.74	68.46	26.11
Nett Amount (S\$)	4,007.96	2,961.42	1,046.54	26.11

INSPECTION

Date of Assignment: 26/04/2018

Date Inspected: 30/04/2018 Inspected At:

Autolution Industrial Pte Ltd (Ubi)

19 Ubi Road 4

Singapore 408623

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Oct 2018)
Parts:	M1-SUV	NISSAN QASHQAI 2.0 PREMIUM (J10) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLL8204X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*EMBLEM REAR QASHQAI	Necessary	87.00 FN	*87.00 FN
2	1		*EMBLEM -REAR NISSAN	Necessary	59.70 FN	*59.70 FN
3	1		*REAR BUMPER TOW HOOK COVER	Deformed	16.80 FN	*16.80 FN
4	1		*REAR BUMPER STAY LH	Not Necessary	126.00 FN	*- FN
5	1		*REAR BUMPER STAY RH	Not Necessary	126.00 FN	*- FN
6	1		*REAR BUMPER REINFORCEMENT	Not Necessary	619.20 FN	*- FN
7	1		*ENERGY ABSORBER REAR BUMPER	Not Necessary	126.40 FN	*- FN
8	1		*REAR BUMPER SIDE BRKT LH	Necessary	35.90 FN	*35.90 FN
9	1		*RETAINER REAR BUMPER	Necessary	23.80 FN	*23.80 FN
10	6		*CLIP REAR BUMPER	Necessary	44.40 FN	*44.40 FN
11	1		*REAR BUMPER FASCIA	Deformed	717.00 FN	*717.00 FN
12	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
13	1		*SENSOR -REVERSE	Damaged	250.00 FS	*250.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	2,282.20	1,254.60
- Nett Item Discount on N Items 20.00/20.00% (\$\$)	396.44	196.92
Total Parts (\$\$)	1,885.76	1,057.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REPAIR REAR H/BACK DOOR ,REAR PANEL AND RENEW REAR BUMPER	New	900.00	850.00
2	CHARGES TO SPRAY PAINTING SAME	New	850.00	750.00
3	REMOVE AND INSTALL REVERSE SENSOR TO RENEW	New	110.00	110.00
Gross Labour Cost (\$\$)			1,860.00	1,710.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >