

VIVIAN



**TRANSIT
ENGINEERING**

ACCIDENT TIME REPORTED	1800hrs
ACCIDENT DATE	19-Apr-18
BUS CAPTAIN NAME	TAN LEE MING
EMPLOYEE NUMBER	

BUS REGISTRATION NUMBER	SB53406U
BUS TYPE (SD/DD)	DD
BUS ROUTE NUMBER	
BUS ADVERTS (Y/N)	N

SECTION 1: PARTS & CONSUMABLE ITEMS (MATERIAL COST)				
	Part No.	Part or Item Description	Quantity	Total Cost
			7% GST	\$0.00
			FINAL TOTAL COST	\$0.00

SECTION 2: ASSESSMENT / REPAIR / SPRAY PAINT (LABOUR COST)			TOTAL COST
	LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR SPRAY PAINT)		
	TO REPLACE/REPAIR THE DAMAGED PARTS (INCLUDING SPRAY PAINTING)		300 \$500.00
		7% GST	\$35.00
		FINAL TOTAL COST	\$535.00

ESTIMATED ACCIDENT REPAIR COST



SECTION 5: REPAIRS TO BUS ADVERTISEMENT VINYL/PANELS (ADVERTISEMENT COST)

TOTAL ADVERTISEMENT REPAIR COST	-
---------------------------------	---

SECTION 6: RECOVERY OF ACCIDENT BUS (TOWING COST)

TOTAL TOWING COST	-
-------------------	---

SECTION 7: NUMBER OF DAYS UNDER ACCIDENT REPAIR (LOSS OF USE COST)

		Date In For Repairs	27/4/2018
		Date Out From Repairs	28/4/2018
BUS TYPE (SD / DD)	DD	Number of Days Under Repair	1
LOSS OF USE COST			\$400.00

SUMMARY	
SECTION NO.	COST
1	\$0.00
2	\$535.00
3	-
4	-
5	\$400.00
ESTIMATED ACCIDENT REPAIR COST (1+2+3+4+5)	\$935.00

PAGE 2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
Hp 90010068

1 day

27/04/18 @ 1600hrs

Resurvey after repair