

HONDA

HAH MOTOR CO. SDN. BHD.

A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

30/4/18
a

10.15 Survey

Customer : CHINA TAIPING INSURANCE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
Registration No : SDV1116E
Chassis No : JHMRU1810GX201969
Model : HRV DX-SIN CVT YM 2016
Owner's Name : IVY KUAH RONG XUAN
Ins Policy No. :
Date of Accident : 26/4/2018

Document No. : SQT18001741
Date : 27. Apr 2018
Customer No. : WZC008
Svc Advisor : LIEW THYE WEI
Engine No : L15B4531972
Date | Time : 27. Apr 2018 10:23:13 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: IVY KUAH RONG XUAN OWNER INSURER: SD17V05680 / VPC2 / R00 ACC DATE: 26/4/18 SURVEYED BY: DATE: REF NO: TP INSURER: CHINA TAIPING TP VEH: SKZ1166G						
73215-T7A-003	RUBBER CR.WINDHSIELD DAM	1	19.30	25	14.47	1.01	15.48
73226-SZW-000	DAMPERSTD 5X5	1	8.30	25	6.22	0.44	6.66
76711-T6A-003	CAPPIVOT	1	4.70	25	3.52	0.25	3.77
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER	1	19.30	25	14.47	1.01	15.48
91501-S70-003	FASTENER BW/SHIELD	4	3.20	25	9.60	0.67	10.27
91502-S70-003	FASTENER B	2	4.90	25	7.35	0.51	7.86
91536-SS0-J01	FASTENER AW/SHIELD	2	3.50	25	5.25	0.37	5.62
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
68100-T7A-J20ZZ	TAIL GATE COMP	1	838.90	25	629.17	44.04	673.21
04715-T7A-900ZZ	FACE,RR.BUMPER	1	463.70	25	347.77	24.34	372.11
04717-T7A-000ZZ	FACER.RR.BUMPER CORNER	1	92.30	25	69.22	4.85	74.07
04718-T7A-000ZZ	FACEL.RR.BUMPER CORNER	1	92.30	25	69.22	4.85	74.07
71593-T7A-000	SPACERR.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
71598-T7A-000	SPACERL.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
75722-T7W-A01	EMBLEMRR.	1	12.90	25	9.67	0.68	10.35
75725-T8N-T00	EMBLEM,RR. I-VTEC	1	14.10	25	10.57	0.74	11.31
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00		320.00	22.40	342.40
					Sum Item	1593.74	111.56
BOSUN	SUNDRIES	1	30.00		30.00	2.10	32.10