

INS. CASE OWNER:

CC 6 / AIG1800

LKK:

IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merit:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :S\$

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost: S\$ (days) Reduction: % Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.: 24

If O or B 28, Ass. Lia:

Repair Cost: S\$ 6439.26

Loss of Rental (LOR):

S\$

(days)

Loss of Use (LOU):

S\$

420.00 (560 x 7 days)

Loss of Income (LOI):

S\$

(\$ x days)

LOR only ☐LOU only ☐LOR + LOU ☐LOR + LOI ☐

(Tick only one)

GIA/LTA Search

S\$

2.00

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$

6861.26

Global Sum S\$: 6850.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

S\$

6850.00

Name 1:

OPTIMA WERKZ PTE LTD

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

COPY SENT 16/12/18

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$220

REF: **ML6****2849 / 6/02****ASSIGNMENT**From: _____ Date: **04/05/2018**

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: **SLB 7183B**
at Workshop n/s: **Optima Works**
of: **9A Sorongoun North Ave 3**

Insured: _____

Policy No: _____


Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.**10:30am**

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? Yes or No

GIA / PR Seen: _____ Consistent? Yes or No

Est. Repairs: **6** days Res: Yes or No

Lump Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **SLB 7183B** Yr Regn: **04 / 16**Type: ☒ M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Honda Jade** CC: **1496**Colour: **M. Brown** A/C: _____ Insured / Std / NI / NASp. Reading: **1738P** T/Radio: Insured / Std / NI / NA

Engl No: _____

C/No: **FR4 1010236**Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size F: **215/50R17**

R: _____

BS / DON / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal: **9** mm R/Bal: **9** mmL/Bal: **9** mm L/Bal: **9** mmD.O.A: **25/4/18** D.O.L: **4/5/18**

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rec

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

7/5 File party to Coroner**WV can't survey at north area.****PIP # 608 C Road # 3268-08/357**

Date/Time: File Pass to?

☐

Prel. Report

11

☐

Final Report

Date/Time: File Return to?

12

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transportation

1 - 2 - 3 - 4

1 - 2 - 3 - 4

1 - 2 - 3 - 4

Report Format:

Lump Sum / L.B.I: (\$)

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Insp (\$)☐ Weekend (\$)

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/AIG18007849/Uua3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 29-04-2018		
		Code : AIG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SCM 7272G	Veh. Inspected	SLB 7283B	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	29/04/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	25/04/2018	Inspection Date	04/05/2018	
Survey held at	OPTIMA WERKZ PTE LTD 6, KUNG CHONG ROAD SINGAPORE 159143			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Ku

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 03 May 2018

Third Party Insurer: AIG

Vehicle No: SLB7283B

Third Party Veh No: SCM7272G

Model: HONDA JADE HYBRID 1.5X A

Date of Accident: 25 APRIL 2018

Chassis: FR4-1010236

ESTIMATE

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$	
1	REAR FENDER LH		By \$1,231.10	✓
1	REAR FENDER GLASS LH		Sm \$470.30	X
1	REAR FENDER GLASS MOULDING LH		m \$145.70	✓
1	REAR FENDER INNER SHIELD LH		GAT \$215.80	X
8	REAR FENDER INNER SHIELD CLIP LH	\$3.90	neu \$31.20	X
1	REAR BUMPER		re \$907.50	X
10	REAR BUMPER CLIP	\$3.90	re \$39.00	X
1	REAR BUMPER SIDE RETAINER LH		re \$27.30	X
1	REAR DOOR LH		By \$1,299.70	✓
1	REAR DOOR BLACK FRAME STICKER 'OUTER' LH		re \$34.70	✓
1	REAR DOOR BLACK FRAME STICKER 'INNER' LH		re \$34.70	✓
1	REAR DOOR INNER TRIM BOARD LH		re \$678.50	X
1	ROCKER SIDE SKIRTING LH		mb \$623.70	✓
10	ROCKER SIDE SKIRTING CLIP LH	\$3.90	re \$39.00	✓
1	REAR 17" SPORT RIM 'ORIGINAL' LH		re \$1,391.90	✓
SUB TOTAL			\$7,170.10	5047.50
Less 20%			\$1,434.02	1029.50
PARTS TOTAL			\$5,736.08	4038.00

QTY	SPECIAL NETT	UNIT S\$	AMOUNT S\$
1	REAR FENDER GLASS SEALANT WITH PRIMER LH		re \$80.00
S/N TOTAL			\$80.00

Not Notified
Resurvey By paint
6 days
86018.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 03 May 2018

Third Party Insurer:

AIG

Vehicle No: SLB7283B

Third Party Veh No:

SCM7272G

Model: HONDA JADE HYBRID 1.5X A

Date of Accident:

25 APRIL 2018

Chassis: FR4-1010236

ESTIMATE

LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION	\$1,400.00	800
TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION	\$1,200.00	800
TO TUFF KOTE / ANTI-RUST	\$80.00	601
TO DISMANTLE & REINSTALL REAR LH DOOR INNER COMPONENT MECHANISM TO FACILITATE REPAIR WITH CHECK FOR FUNCTION	\$180.00	601
TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	\$150.00	1001
TO CHECK WIRING WITH WATER LEAKAGE TEST	\$80.00	201
TO SEND VEHICLE FOR 3D COMPUTERISED CHECK & ADJUSTED WHEEL ALIGNMENT	\$60.00	✓
TO DISMANTLE & CHECK REAR LH UNDER CARRIAGE COMPONENT	na \$180.00	X
TO DISMANTLE & REPLACED REAR BUMPER PARKING SENSOR	na \$60.00	X
TO REMOVE AND REFIT REAR LH FENDER QUARTER GLASS	\$80.00	501
LABOUR TOTAL		\$3,470.00 2250.00
WINSON	TOTAL	\$9,286.08

P - \$4038.00

SH - \$70.00

V - \$2250.00

P/P - \$6358.00 & 6 days

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 03 May 2018

Third Party Insurer: AIG

Vehicle No: SLB7283B

Third Party Veh No: SCM7272G

Model: HONDA JADE HYBRID 1.5X A

Date of Accident: 25 APRIL 2018

Chassis: FR4-1010236

ESTIMATE

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
1	REAR FENDER LH		By \$1,231.10 ✓
1	REAR FENDER GLASS LH		Sm \$470.30 X
1	REAR FENDER GLASS MOULDING LH		me \$145.70 ✓
1	REAR FENDER INNER SHIELD LH		Sm \$215.80 X
8	REAR FENDER INNER SHIELD CLIP LH	\$3.90	va \$31.20 X
1	REAR BUMPER		12 \$907.50 X
10	REAR BUMPER CLIP	\$3.90	va \$39.00 X
1	REAR BUMPER SIDE RETAINER LH		Sm \$27.30 X
1	REAR DOOR LH		By \$1,299.70 ✓
1	REAR DOOR BLACK FRAME STICKER 'OUTER' LH		me \$34.70 —
1	REAR DOOR BLACK FRAME STICKER 'INNER' LH		me \$34.70 —
1	REAR DOOR INNER TRIM BOARD LH		Sm \$678.50 X
1	ROCKER SIDE SKIRTING LH		\$623.70 ?
10	ROCKER SIDE SKIRTING CLIP LH	\$3.90	\$39.00 ?
1	REAR 17" SPORT RIM 'ORIGINAL' LH		Net \$1,391.90 ✓
SUB TOTAL			\$7,170.10
Less 20%			-\$1,434.02
PARTS TOTAL			\$5,736.08

QTY	SPECIAL NETT	UNIT S\$	AMOUNT S\$
1	REAR FENDER GLASS SEALANT WITH PRIMER LH		me \$80.00 301a
S/N TOTAL			\$80.00

Not Notified
Me may B & paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

6 days

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 03 May 2018

Third Party Insurer:

AIG

Vehicle No: SLB7283B

Third Party Veh No:

SCM7272G

Model: HONDA JADE HYBRID 1.5X A

Date of Accident:

25 APRIL 2018

Chassis: FR4-1010236

ESTIMATE

LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION	\$1,400.00	800
TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION	\$1,200.00	800
TO TUFF KOTE / ANTI-RUST	\$80.00	60
TO DISMANTLE & REINSTALL REAR LH DOOR INNER COMPONENT MECHANISM TO FACILITATE REPAIR WITH CHECK FOR FUNCTION	\$180.00	60
TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	\$150.00	100
TO CHECK WIRING WITH WATER LEAKAGE TEST	\$80.00	20
TO SEND VEHICLE FOR 3D COMPUTERISED CHECK & ADJUSTED WHEEL ALIGNMENT	\$60.00	✓
TO DISMANTLE & CHECK REAR LH UNDER CARRIAGE COMPONENT	nn \$180.00	X
TO DISMANTLE & REPLACED REAR BUMPER PARKING SENSOR	nn \$60.00	X
TO REMOVE AND REFIT REAR LH FENDER QUARTER GLASS	\$80.00	50

LABOUR TOTAL \$3,470.00

WINSON

TOTAL

\$9,286.08

Our Ref : SLB7283B / TP#655
Your Ref : SCM7272G

WITHOUT PREJUDICE

Date : 13 August 2018

AIG ASIA PACIFIC INSURANCE PTE. LTD.
AIG BUILDING
78 Shenton Way #07-16
Singapore 079120

Attention: Motor Claims Department

**ACCIDENT INVOLVING SLB7283B & SCM7272G ON 25/04/2018
AT DOVER PARKVILLE CONDO CARPARK**

We refer to the above captioned.

We are claiming the below followings :

- Cost of Repair (incl. of GST)	S\$6,439.26
- Loss of Use	S\$560.00 (\$80 x 07 days)
- LTA/GIA Search Fee	S\$2.00

Grand Total	<u>S\$7,001.26</u>
--------------------	---------------------------

If you have any enquiries, please contact our representative, Ms. Sharon Ten at 64849919 or email sharon@ow.sg / lily.loi@ow.sg

All payment is to be issued direct to **Optima Werkz Pte Ltd.**

Your prompt attention is most grateful and look forward to your speedy settlement.

Yours faithfully

OPTIMA WERKZ PTE LTD

Encl.

This is a computer generated printout and no signature is required.

SATISFACTION CUM DISCHARGE VOUCHER

I/~~We~~ hereby declare and confirm that I/~~We~~ have received from my/~~our~~ repairer Optima Werkz Pte Ltd for my/~~our~~ motor vehicle registration no SLB 7783B which is repaired to my/~~our~~ entire satisfaction and is now in good running order.

My/~~our~~ vehicle sent in for above repair from 31/05/2018 (date) to 06/06/18 (date).



Owner Signature & Co. Stamp (if applicable)

Name Of Owner : Chua Peck Hwa Pauline

NRIC No : S7235664H

Address : Blk 146 Bishan St 11

08-53 Singapore S70146

Date : 06/06/2018

AUTHORISATION TO ACT

I/We Chua Peck Hwa, Pauline ("the third party claimant") of B12 146
Bishan St 11 # 08-05(S) 570146 (address), owner of SLB7283B (vehicle
no.) hereby authorize Optima Werkz Pte Ltd ("the workshop")
to act for me with respect to my claim for repair costs and/or rental and/or loss of use
("claim") for my vehicle no. SLB7283B that was damaged pursuant to the accident which
occurred on 25/04/18 (date) along Dover Parkville Condo Carpark
(location) involving vehicle no/s SCM7222G ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they
deem fit and the workshop is further authorized to receive payment further to settlement of
my claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a
without prejudice and without admission of liability basis insofar as the driver/owner/insurers
of the other vehicle/s is concerned.

Dated this 31st (day) of May (month) 20 18 (year)



Signed by "the third party claimant"
(with chop if applicable)



Signed by "the workshop"
(with chop)

Thin Thin (LKKAuto)

From: Thin Thin (LKKAuto)
Sent: Wednesday, 23 May 2018 1:13 PM
To: 'engkhooon9@yahoo.com.sg'
Subject: ACCIDENT INVOLVING SCM 7272G & SLB 7283B ON 25/04/2018



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/AIG18007849/Uua3

23 MAY 2018

LIM ENG KHOON

Dear Sir/Madam,

ACCIDENT INVOLVING SCM 7272G & SLB 7283B ON 25/04/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

THIN THIN HLAING
Case Handler
DID: 6841 2360
FAX: 6741 4108
Email: thinthin@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, **OPTIMA WERKZ PTE LTD** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **SS 6,850.00** (Global Sum) for vehicle no. **SLB 7283B** that was damaged pursuant to the accident which occurred on **25/04/2018** (date) along **DOVER PARKVILLE CONDO CARPARK** (location) involving vehicle no/s **SCM 7272G**.

This is pursuant to the inspection conducted on **04/05/2018** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **CHUA PECK HWA PAULINE** ("the third party claimant") of vehicle no. **SLB 7283B** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SLB 7283B** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 05 (day) of December (month) 2018 (year)



KSC

Signed by appointed surveyor



Signed by "the workshop" (with chop)

Without Prejudice

"The contents of this document apply to property damages claim only. All personal injuries and damages arising therefore are not included from the ambit and application of this document."

Optima Werkz Pte Ltd

9A Serangoon North Avenue 5, Singapore 554500
Tel (+65) 6484 9919 Fax: (+65) 6481 1101
Co Reg & GST No: 201212455W

TAX INVOICE

To: AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

Tel 64191000
Fax: 68357416

INV NO. : 121805175
INVOICE DATE : 10/08/2018
REF : TP#655
VEH NO. : SLB7283B
CAR MODEL : JADE HYBRID 1.5X
CURRENT MILEAGE:
ADVISOR : WINSON
TERMS : COD

DESCRIPTION	QTY	UOM	U.PRICE SGD	AMOUNT SGD
REAR FENDER LH	1	PC	984.88	984.88
REAR FENDER GLASS MOULDING LH	1	PC	116.56	116.56
REAR FENDER INNER SHIELD LH	1	PC	172.64	172.64
REAR FENDER INNER SHIELD CLIP LH	1	PC	24.96	24.96
REAR DOOR LH	1	PC	1,039.76	1,039.76
REAR DOOR BLACK FRAME STICKER 'OUTER' LH	1	PC	27.76	27.76
REAR DOOR BLACK FRAME STICKER 'INNER' LH	1	PC		27.76
ROCKER SIDE SKIRTING LH	1	PC	498.96	498.96
ROCKER SIDE SKIRTING CLIP LH	1	PC	31.20	31.20
REAR 17" SPORT RIM 'ORIGINAL' LH	1	PC	1,113.52	1,113.52
REAR FENDER GLASS SEALANT WITH PRIMER LH	1	PC	30.00	30.00
TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION	1	JOB	800.00	800.00
TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION	1	JOB		800.00
TO TUFF KOTE / ANTI-RUST	1	JOB	60.00	60.00
TO DISMANTLE & REINSTALL REAR LH DOOR INNER COMPONENT MECHANISM TO FACILITATE REPAIR WITH CHECK FOR FUNCTION	1	JOB		60.00
TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	1	JOB	100.00	100.00
TO CHECK WIRING WITH WATER LEAKAGE TEST	1	JOB	20.00	20.00
TO SEND VEHICLE FOR 3D COMPUTERISED CHECK & ADJUSTED WHEEL ALIGNMENT	1	JOB	60.00	60.00
TO REMOVE AND REFIT REAR LH FENDER QUARTER GLASS	1	JOB	50.00	50.00

Optima Werkz Pte Ltd

9A Serangoon North Avenue 5, Singapore 554500
Tel (+65) 6484 9919 Fax: (+65) 6481 1101
Co Reg & GST No: 201212455W

TAX INVOICE

To: AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

Tel 64191000
Fax: 68357416

INV NO. : 121805175
INVOICE DATE : 10/08/2018
REF : TP#655
VEH NO. : SLB7283B
CAR MODEL : JADE HYBRID 1.5X
CURRENT MILEAGE:
ADVISOR : WINSON
TERMS : COD

DESCRIPTION	QTY	UOM	U.PRICE SGD	AMOUNT SGD
-------------	-----	-----	----------------	---------------

Remarks: DOA: 25/04/18 @ 1020HRS
CLAIMANT: CHUA PECK HWA PAULINE
NRIC NO: S7235464H
TP VEHICLE: SCM7272G

Singapore Dollars: Six Thousand Four Hundred Thirty-Nine And Cent Twenty-Six Only

Name: _____

NRIC No.: _____

Signature: _____

SUB TOTAL	SGD	6,018.00
GST 7.00%	SGD	421.26
GRAND TOTAL	SGD	6,439.26

I/We confirm that I/We incurred the repair costs herein and will observe my/our agreement with the repairs.
I/We declare the repairs for above vehicle have been completed to my/our satisfaction.

- 1) New parts purchased and installed by Optima Werkz Pte Ltd, will be entitled to warranty period of one (1) year or mileage up to 30,000km, whichever comes first, from the date of invoice, with the exception to wear & tear items.
- 2) Recon Parts purchased and installed by Optima Werkz Pte Ltd, will be entitled to warranty period of six (6) months or mileage up to 10,000km, whichever comes first, from the date of invoice, with the exception to wear & tear items.
- 3) Goods sold are not refundable/returnable.

Original Invoice is only valid when the payment is acknowledge receipt by Optima Werkz Pte Ltd. Interest of 2% per month will be charged on any outstanding amount.

for Optima Werkz Pte Ltd

AUTHORISED SIGNATURE(S)



RECORDS MANAGEMENT CENTRE

GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-062784

Date of Request: 25/04/2018

Your Ref No:

Online Purchase

Optima Werkz Pte Ltd
6 Kung Chong Road
Singapore 159143

Dear Sir/Madam,

Enquiry Date 25/04/2018
Enquiry By Sharon Ten Chai Ling
TP Vehicle No. SCM7272G
Accident Date 25/04/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque



RECORDS MANAGEMENT CENTRE

GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-062784

Date of Request: 25/04/2018

Your Ref No:

Online Purchase

Optima Werkz Pte Ltd
6 Kung Chong Road
Singapore 159143

Dear Sir/Madam,

Enquiry Date 25/04/2018
Enquiry By Sharon Ten Chai Ling
TP Vehicle No. SCM7272G
Accident Date 25/04/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SCM7272G	AIG Asia Pacific Insurance Pte. Ltd.	13/03/2018-12/03/2019	65-6419-3000
SCM7272G	AIG Asia Pacific Insurance Pte. Ltd.	16/03/2018-15/03/2019	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Apr 2018 Edit Reg		04 May 2018 00:00 Edit Adj Rpt	S\$6,018.00 Edit Estimates	S\$6,018.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	LIM ENG KHOON , ID: S0130676F								
Main Claimant:	CHUA PECK HWA PAULINE , ID: S7235464H								
Vehicle Reg. No.:	SLB7283B	Date of Loss:	25/04/2018 10:00 - :59 [24 Months and 5 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 0140890579SG	Policy/Cover Note No.:	1800026124 (Comprehensive)						
Vehicle Reg. No. (Insured):	SCM7272G	Policy No. (Claimant):	2100507188-01						
		Excess:							
Repairer:	Optima Werkz Pte Ltd (HQ) 6 Kung Chong Road, 159143 Leng Kee - Tel: 64721313								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 09/05/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (30/04/2018): Request To Upload TP GIA Report AIG_SG (30/04/2018): No OI GIA Report (SCM7272G VS SLB7283B) 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLB7283B (0140890579SG)
[SCM7272G]**

TP

CHUA PECK HWA PAULINE

Apr 25 2018 10:00AM

[LIM ENG KHOON]

Optima Werkz Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page		<div></div>	<input checked="" type="checkbox"/>		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print			
1	(Draft)	Third Party Express Settlement – Payment Breakdown													1	Edit				
Assessment Reports															1 per page		<div></div>	<input checked="" type="checkbox"/>		
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)														Thumbnail	Print			
1	07/05/18 16:22	Accident Statement From: SC – Reg. No: SCM7272G, Claimant: LIM ENG KHOON													1	Load HTM				
Photos/Images															3 per page		<div></div>	<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print			
1	08/12/18 09:03	General View													1	Load JPG	<input checked="" type="checkbox"/>			
2	08/12/18 09:03	Odometer Reading													1	Load JPG	<input checked="" type="checkbox"/>			
3	08/12/18 09:03	General View													1	Load JPG	<input checked="" type="checkbox"/>			
4	08/12/18 09:03	General View													1	Load JPG	<input checked="" type="checkbox"/>			
5	08/12/18 09:03	General View													1	Load JPG	<input checked="" type="checkbox"/>			
6	08/12/18 09:03	General View													1	Load JPG	<input checked="" type="checkbox"/>			
7	08/12/18 09:03	General View													1	Load JPG	<input checked="" type="checkbox"/>			
8	08/12/18 09:03	General View													1	Load JPG	<input checked="" type="checkbox"/>			
9	08/12/18 09:03	General View													1	Load JPG	<input checked="" type="checkbox"/>			
10	08/12/18 09:03	General View													1	Load JPG	<input checked="" type="checkbox"/>			
11	08/12/18 09:03	General View													1	Load JPG	<input checked="" type="checkbox"/>			
12	08/12/18 09:03	General View													1	Load JPG	<input checked="" type="checkbox"/>			
13	08/12/18 09:03	General View													1	Load JPG	<input checked="" type="checkbox"/>			
14	08/12/18 09:03	General View													1	Load JPG	<input checked="" type="checkbox"/>			
15	08/12/18 09:06	Reinspection Photo													1	Load JPG	<input checked="" type="checkbox"/>			
16	08/12/18 09:06	Reinspection Photo													1	Load JPG	<input checked="" type="checkbox"/>			
17	08/12/18 09:06	Reinspection Photo													1	Load JPG	<input checked="" type="checkbox"/>			
18	08/12/18 09:06	Reinspection Photo													1	Load JPG	<input checked="" type="checkbox"/>			
19	08/12/18 09:06	Reinspection Photo													1	Load JPG	<input checked="" type="checkbox"/>			
20	08/12/18 09:06	Reinspection Photo													1	Load JPG	<input checked="" type="checkbox"/>			
21	08/12/18 09:06	Reinspection Photo													1	Load JPG	<input checked="" type="checkbox"/>			
Documentation															1 per page		<div></div>	<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print			
1	02/05/18 09:23	TP GIA REPORT													1	Load PDF				
2	14/05/18 23:39	TP ESTIMATE - MARKED													1	Load PDF				
3	19/12/18 10:12	WORKSHOP INVOICE													1	Load PDF				
4	19/12/18 10:12	AUTHORISATION TO ACT FORM													1	Load PDF				
5	19/12/18 10:12	Release Voucher													1	Load PDF				
6	19/12/18 10:12	GIA SEARCH													1	Load PDF				
7	19/12/18 10:12	LETTER TO OI													1	Load PDF				

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SCM7272G (Insd veh)	Model:	HONDA JADE HYBRID 1.5
	SLB7283B (TP veh)		(A)
Date of Accident:	25/04/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> [X]	Yes	<input type="checkbox"/> []	No	
Repair Estimate	:	\$			9,936.11	
Final Repair Cost	:	\$			6,850.00	
Loss of Use	:	\$				7.00 days at \$60.00 per day
Rental (if any)	:	\$				days
LTA / GIA Search Fee	:	\$				
Others:	:	\$				
	:	\$				
Final Settlement Sum (Global Sum)	:	\$			6,850.00	

Is Third Party Workshop GIA Registered? ☐ [] **YES** ☒ [X] **NO** (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____100____(%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____%(%) Assessed Liability (*): ____%(%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Optima Werkz Pte Ltd	:	\$ 6,850.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

19 Dec
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18007849/KPA3Q2

Date: 19/12/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No: 1800026124

Claimant Vehicle No: SLB7283B

Insured Vehicle No: SCM7272G

Date of Loss: 25/04/2018

Nature of Claim: TP

Claim No: 0140890579SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLB7283B

Make & Model: HONDA JADE HYBRID, 1.5 (A)

Engine No: LEB3930246

Reg. Date: 20/04/2016 (Man. Year: 2015)

Chassis No: FR41010236

Colour: Metallic Brown

Odometer: 17389 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/50 R17

Rear Tyre Size: 215/50 R17

Front Left Side: Dunlop 9 mm

Rear Left Side: Dunlop 9 mm

Front Right Side: Dunlop 9 mm

Rear Right Side: Dunlop 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,816.08	4,068.00	1,748.08	30.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,470.00	1,950.00	1,520.00	43.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,286.08	6,018.00	3,268.08	35.19
+ GST 7.00/7.00% (S\$)	650.03	421.26	228.77	35.19
Nett Amount (S\$)	9,936.11	6,439.26	3,496.85	35.19
+ Loss of Use (7.0 x S\$60.00/day) (S\$)		420.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		6,861.26		
Global Sum Settlement (S\$)		6,850.00		

INSPECTION

Date of Assignment: 04/05/2018

Date Inspected: 04/05/2018 Inspected At:

9A SERANGOON NORTH AVE 5
SINGAPORE 554500

Repairer: Optima Werkz Pte Ltd (HQ)

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER	Bent	1,231.10 FL	*1,231.10 FL
2	1		*REAR FENDER GLASS LH	Serviceable	470.30 FL	*- FL
3	1		*REAR FENDER GLASS MOULDING LH	Necessary	145.70 FL	*145.70 FL
4	1		*REAR FENDER INNER SHIELD LH	Cracked	215.80 FL	*215.80 FL
5	8		*REAR FENDER INNER SHIELD CLIP LH	Necessary	31.20 FL	*31.20 FL
6	1		*REAR BUMPER	Repair	907.50 FL	*- FL
7	10		*REAR BUMPER CLIP	Not Necessary	39.00 FL	*- FL
8	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	27.30 FL	*- FL
9	1		*REAR DOOR LH	Bent	1,299.70 FL	*1,299.70 FL
10	1		*REAR DOOR BLACK FRAME STICKER OUTER LH	Necessary	34.70 FL	*34.70 FL
11	1		*REAR DOOR BLACK FRAME STICKER INNER LH	Necessary	34.70 FL	*34.70 FL
12	1		*REAR DOOR INNER TRIM BOARD LH	Serviceable	678.50 FL	*- FL
13	1		*ROCKER SIDE SKIRTING LH	Mtg Cracked	623.70 FL	*623.70 FL
14	10		*ROCKER SIDE SKIRTING CLIP LH	Necessary	39.00 FL	*39.00 FL
15	1		*REAR 17 SPORT RIM ORIGINAL LH	Dented	1,391.90 FL	*1,391.90 FL
16	1		*REAR FENDER GLASS SEALANT WITH PRIMER LH	Necessary	80.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	7,250.10	5,077.50
- List Item Discount on L Items 20.00/20.00% (S\$)	1,434.02	1,009.50
Total Parts (S\$)	5,816.08	4,068.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION	New	1,400.00	800.00
2	TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION	New	1,200.00	800.00
3	TO TUFF KOTE/ANTI RUST	New	80.00	60.00
4	TO DISMANTLE & REINSTALL REAR LH DOOR INNER COMPONENT MECHANISM TO FACILITATE REPAIR WITH CHECK FOR FUNCTION	New	180.00	60.00
5	TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	New	150.00	100.00
6	TO CHECK WIRING WITH WATER LEAKAGE TEST	New	80.00	20.00
7	TO SEND VEHICLE FOR 3D COMPUTERISED CHECK & ADJUSTED WHEEL ALIGNMENT	New	60.00	60.00
8	TO DISMANTLE & CHECK REAR LH UNDER CARRIAGE COMPONENT	New	180.00	0.00
9	TO DISMANTLE & REPLACED REAR BUMPER PARKING SENSOR	New	60.00	0.00
10	TO REMOVE AND REFIT REAR LH FENDER QUARTER GLASS	New	80.00	50.00
Gross Labour Cost (S\$)			3,470.00	1,950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >