

ASS. REC. BY:

REF: CS/E6718007870/Ubn2

Special Instruction:

Surveyor: Marcus

ASSIGNMENT (Office)

From (Person): Yee Pei Li

of E671

Date/Time: 02052018 11:20am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLM 7708L

Insured: XD3877L

at Workshop m/s Fastech Auto

Tel: 6746 5405

of Blk 1 Kaki Bukit Ave 6 #01-46

Policy No:

Claim No: XD3877L/3E/p1

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 28042018

CA / REV / REP. / REV 24 HRS Wp

H.O.D. Endorsement:

Date/Time:

Person Contacted: Nancy

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLM 7708L - X
	XD 3877L - X
3/5/18	Informed Pei Li pending workshop est by email
9/5/18	Email preli revised to Pei Li

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLM 7768L

at Workshop m/s Rf.

of XD 3877C

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 64k.

ADAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: 10 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLM 7768L Yr Regn: 4 / 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA/

Make: Honda c.c. 1496

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 55311 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RU11017504

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215 / 60 R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / HOHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 28/4/18 D.O.I. 30/4/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rf.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction LTA 50910 6 yrs 11 mcs. PBO

net 13290

Note new parts replaced.

8/5/18 cont. rmb Repair sum \$11500 with Alen. (Red 19,924.61, 6370)

RECEIVED 09 MAY 2018

Date/Time, File Pass to?

: Preli. Report

Days Of Repair: 6

1)

: Final Report

Resurvey No. of Trip: 2

Date/Time, File Return to?

Survey Fee:

2) 9/5- typist

Add Fee: : Site Insp (\$ _____)

Transportation: _____ \$ + RS, SI

Report Format: TP

: Interview (\$ _____)

Photos

Lump Sum / I.B.I: (\$ RS 11,500k)

: Tech. Invs (\$ _____)

Others

: Weekend (\$ _____)

TOTAL

350

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 9 May 2018 9:42 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'
Cc: SUR
Subject: RE: XD3877L / TP : SLM7768L/KK / DOA : 28/04/2018
Attachments: SLM 7768L PRELI REVISED.pdf

Dear Pei Li,

Enclosed preliminary revised of vehicle SLM 7768L
Date of survey: 30/4/2018
Number of days:6 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)
Sent: Thursday, 3 May 2018 9:06 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: RE: XD3877L / TP : SLM7768L/KK / DOA : 28/04/2018

Dear Pei Li,

Please be informed that we have inspected the vehicle SLM 7768L on 30/4/2018.

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 2 May 2018 11:23 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>
Cc: SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>
Subject: RE: XD3877L / TP : SLM7768L/KK / DOA : 28/04/2018

Dear Pei Li,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]
Sent: Wednesday, 2 May, 2018 11:20 AM
To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>
Subject: OI : XD3877L / TP : SLM7768L/KK / DOA : 28/04/2018

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **FASTECH AUTO PTE LTD.**

ADDRESS : 1 KAKI BUKIT AVENUE 6
#01-46/48/50 AUTOBAY
SINGAPORE 417883

PERSON TO CONTACT : NANCY LAM @ 6746 5405

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are our insured's and TP's SAS (**note: reports not to be released to any Third Party**). No estimates was provided.

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: XD3877L/SE/pl
Our Ref: CS/EG118007870/Uvb

Date: 9/5/2018

The Motor Claims Department
M/s: ERGO INSURANCE PTE LTD

Without Prejudice

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. SLM 7768L


We thank you for your instruction on 2/5/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 30/4/2018 at the premises of M/s FASTECH AUTO PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$31,424.61
Revised Estimate Amount	: S\$11,500.00 (REPAIR SUM)
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the front portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 3 May 2018 9:06 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'
Cc: SUR
Subject: RE: XD3877L / TP : SLM7768L/KK / DOA : 28/04/2018

Dear Pei Li,

Please be informed that we have inspected the vehicle SLM 7768L on 30/4/2018.

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 2 May 2018 11:23 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>
Cc: SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>
Subject: RE: XD3877L / TP : SLM7768L/KK / DOA : 28/04/2018

Dear Pei Li,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]
Sent: Wednesday, 2 May, 2018 11:20 AM
To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>
Subject: OI : XD3877L / TP : SLM7768L/KK / DOA : 28/04/2018

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **FASTECH AUTO PTE LTD.**

ADDRESS : 1 KAKI BUKIT AVENUE 6
#01-46/48/50 AUTOBAY
SINGAPORE 417883

PERSON TO CONTACT : NANCY LAM @ 6746 5405

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are our insured's and TP's SAS (**note: reports not to be released to any Third Party**). No estimates was provided.

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

Catherine Chong (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Wednesday, 2 May, 2018 11:20 AM
To: 'admin-d@lkkauto.com'
Subject: OI : XD3877L / TP : SLM7768L/KK / DOA : 28/04/2018
Attachments: XD3877L - SAS.pdf; SLM7768L - SAS.pdf; SLM7768L - PRS FORM.pdf

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **FASTECH AUTO PTE LTD.**

ADDRESS : 1 KAKI BUKIT AVENUE 6
#01-46/48/50 AUTOBAY
SINGAPORE 417883

PERSON TO CONTACT : NANCY LAM @ 6746 5405

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are our insured's and TP's SAS (**note: reports not to be released to any Third Party**). No estimates was provided.

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

Date: 02.05.2018
 Our Reference: XD 3877L/SE/pl
 Your Reference: SLM 7768L
 To: FASTECH AUTO PTE LTD

Sent via Fax
 or
 Email nancy.lam@fastechauto.com.sg

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SLM 7768L
 Insured's Vehicle: XD 3877L
 Date Of Accident: 28.04.2018

We acknowledge receipt of your request for PRS on: 30.04.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

* LKK

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

- Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
- Your request for inspection does not have your client's GIA report, kindly forward a copy.
- We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
- Our Insured's driver has not reported the accident to us todate.
- Others: OFFICER-IN-CHARGE - STEVE LIM

Prepared by:	<u>Pei Li</u>	6829 9194	<u>claims@ergo.com.sg</u>
Signature:			<u>FAX : 6829 9247</u>


Assessor use only:
 Assignment Date: _____
 Assignment Time: _____

Workshop use only:
Assessor attended workshop on:
 Date: _____
 Time: _____
 Inspector: _____

Remarks:

Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .



Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	0180X
Vehicle Details	
Vehicle No.:	SLM7768L
Vehicle to be Exported:	No
Intended De-registration Date:	30 Apr 2018
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X AUTO
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	L15B3517516
Chassis No.:	RU11017504
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$18,556.00
Original Registration Date:	17 Apr 2015
First Registration Date:	17 Apr 2015
Transfer Count:	1
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Apr 2025
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	16 Apr 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$67,749.00
COE Rebate Amount:	\$47,160.00
Total Rebate Amount:	\$50,910.00

The information contained herein is correct as at 30 Apr 2018

OK

FREE VALUATION

Let us tell you how much your car can sell for!

No obligations and it's FREE!

How much is my car worth?



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Black Lexus LS460 on offer. Price Neg! Pls Call now.



1 Owner! Fully Serviced By
Lexus. Lowest Depre. High trade
in. in House loan.
Speedo Motoring StarAd

* Free VICOM evaluation
* Free grooming and 6 months maintenance
* In-house workshop ensures quality service
* Member of SYTA and hire purchase association
* 100% deposit refund for unapproved loan

YONG LEE SENG MOTOR PTE LTD

Post an Ad Advertiser Login Ways of Selling

Browse by Category

« Back (1 2 3) Next »

Sort by Date Posted 20 results/page

47 vehicles

honda vezel

Advanced Search Submit

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
honda vezel		Any	Any	2015	Any	Any	Any	Available
	Honda VezeL 1.5A X	\$68,800	\$8,860 /yr	21-Aug-2015	1,496 cc	48,500 km	SUV	Available
Excellent Condition, Accident Free, Low Mileage, Bank Loan In-house Loan Available, Trade In Welcome. 3 Months Warranty From Our In-house Workshop.								
Posted: 29-Apr-2018 Tags: 2015 Honda VezeL, Honda VezeL, Honda, VezeL, Used Honda								
	Honda VezeL 1.5A X	\$74,800	\$9,480 /yr	21-Sep-2015	1,496 cc	38,000 km	SUV	Available
1 Owner. High ARF At \$9,359. Genuine Mileage, Comes With Service Record. Very Well Maintained. Flexible Loan Package Down Payment. Please Call Direct Salesperson To Confirm On Availability Of Car Befo...								
AL Autocar Pte Ltd								
Posted: 29-Apr-2018 Tags: 2015 Honda VezeL, Honda VezeL, Honda, VezeL, Used Honda								
	Honda VezeL 1.5A X	\$75,800	\$9,630 /yr	02-Oct-2015	1,496 cc	31,000 km	SUV	Available
Pearl White Unit! Well Maintained By Previous Owner, Accident Free. Most Popular Compact SUV, Low Mileage, One Owner, Buy With A Peace Of Mind. Trade In Welcome, Flexible Loan, Come View And Test Driv...								
AL Autocar Pte Ltd								
Posted: 29-Apr-2018 Tags: 2015 Honda VezeL, Honda VezeL, Honda, VezeL, Used Honda								
	Honda VezeL 1.5A X	\$67,800	\$9,260 /yr	18-May-2015	1,496 cc	-	SUV	Available
Graded A by STP								
Only 1 Owner! Just Like Brand New! Extended Warranty Available! Behold One Of The Top Selling SUV That Gives You Excellent Fuel Economy And Its Responsive Too. Buy It From Us With A Peace Of Mind, A C...								
Dickson Automobile								
Posted: 29-Apr-2018 Tags: 2015 Honda VezeL, Honda VezeL, Honda, VezeL, Used Honda								
Car Buying	Car Selling	Car Ownership						
Car Aftermarket	On The Move	Lifestyle						
	Honda VezeL 1.5A X	\$69,800	\$9,030 /yr	06-Aug-2015	1,496 cc	52,000 km	SUV	Available
Purchase With A Piece Mind, 1 Owner. Excellent Condition. 100% No Repairs Needed. View To Believe. Huge & Spacious, Fuel Savings. Low Maintenance, Comfort And Driver Appeal With Superb Handling. Price...								
Lay Auto Pte Ltd								
Posted: 28-Apr-2018 Tags: 2015 Honda VezeL, Honda VezeL, Honda, VezeL, Used Honda								
	Honda VezeL 1.5A X	\$74,833	\$9,420 /yr	08-Oct-2015	1,496 cc	29,000 km	SUV	Available
1 Owner! Mileage Done 29000km Only!Original Paintwork And Accident Free! Exterior And Interior Of Vehicle Is Well Maintained, Under Carriage And Auto Gear Is In Good State. Price Negotiable! Kindly Ca...								
Posted: 28-Apr-2018 Tags: 2015 Honda VezeL, Honda VezeL, Honda, VezeL, Used Honda								
Compare	Honda VezeL 1.5A X	\$75,800	\$9,730 /yr	04-Sep-2015	1,496 cc	28,000 km	SUV	Available

Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
 MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
 ROAD TRANSPORT ACT, 1987 (MALAYSIA)
 MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number: 5090059041-01 **Cover :** drivo CLASSIC

- | | |
|--|---|
| 1. Index mark and Registration Number of Vehicle | : SLM7768L |
| Chassis Number | : RU11017504 |
| 2. Name of Policyholder | : RAINBOW LEASING |
| 3. Effective Date of Insurance | : 17 Apr 2018 |
| 4. Expiry Date of Insurance | : 16 Apr 2019 |
| 5. Persons or Classes of Persons entitled to drive# | |
| (a) The Policyholder. | |
| (b) Any other person who is driving on the Policyholder's order or with his/her permission. | |
| | Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. |
| 6. Limitations as to Use# | |
| (a) Use for social domestic and pleasure purposes and in connection with the Policyholder's or Hirer's business. | |

This Policy does not cover

- (a) Use for racing, pace-making, reliability trial or speed-testing.
- (b) Use for the carriage of goods (other than samples) in connection with any trade or business.
- (c) Use for the carriage of passengers for reward purposes.
- (d) Use for any purpose in connection with the Motor Trade.

Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: S\$2,000
EXCESS (SECTION 2)	: S\$1,500
WINDSCREEN EXCESS	: S\$100
ADDITIONAL EXCESS	: N/A
UNNAMED DRIVER EXCESS	: PLEASE REFER OVERLEAF
REPAIR AT OWNER'S PREFERRED WORKSHOP	: NO
INSURE WITH COE	: YES
NCD PROTECTION	: NO
TRANSPORT ALLOWANCE	: NO
EXCESS WAIVER	: NO
PRIMARY DRIVER	: N/A
NAMED DRIVER (1)	: N/A
NAMED DRIVER (2)	: N/A
HIRE PURCHASE COMPANY	: SPEEDO CAPITAL PTE. LTD.
SUM INSURED	: MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : DQ INSURE (00000572952)
 Date of Issue : 13 Apr 2018 11:58 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED



Countersigned By:

 Authorised Officer



 Chief Executive

FASTECH AUTO PTE LTD
 1 Kaki Bukit Ave 6
 #01-46/48/50 Autobay
 SINGAPORE 417883

not allocated
 date
 30/4/18
 Rep. Sum \$ 11500
 Bay.

VEHCILE NO: SLM 7768L

QTY	PARTICULAR	AMOUNT
1 PCS	BONNET <i>892.30</i>	20/suc \$1,280.00 ✓
2 PCS	BONNET HINGES @\$85.00 <i>78 x 2 = 156.00</i>	3ent \$170.00 ✓
1 PCS	BONNET INSULATOR <i>185.30</i>	Re \$211.30 ✓
1 SET	BONNET INSULATOR CLIPS	rec \$50.00 ✓
2 PCS	BONNET SIDE RUBBERS @\$35.00	rec \$70.00 ✓
1 PCS	BONNET LOCK	721 \$135.50 ✓
1 PCS	BONNET LOCK CABLE	17 \$68.00 x
1 PCS	BONNET LOCK BRACKET	CRB \$115.00 ✓
1 PCS	FRONT BUMPER <i>801.70</i>	20 \$950.00 ✓
1 PCS	FRONT BUMPER REINFORCEMENT <i>321.00</i>	but \$480.00 ✓
2 PCS	FRONT BUMPER SIDE RETAINERS @\$65.00	but \$130.00 ✓
2 PCS	FRONT BUMPER BRACKETS @\$115.00	NS \$230.00 x
1 PCS	FRONT BUMPER CENTRE GRILLE <i>166.00</i>	CRB \$285.00 ✓
1 PCS	FRONT BUMPER LOWER SPOILER	822 \$525.00 x
1 PCS	FRONT BUMPER UNDER COVER	17 \$480.00 x
1 PCS	FRONT BUMPER TOW COVER	17 \$45.00 x
2 PCS	FRONT BUMPER FOG LAMP COVERS @\$180.00	17 \$360.00 x
2 PCS	FRONT BUMPER FOG LAMPS @\$445.00	17 \$890.00 x
1 SET	FRONT BUMPER CLIPS <i>50</i>	122 \$60.00 ✓
1 PCS	FRONT GRILLE <i>389.50</i>	CRB \$525.00 ✓
1 PCS	FRONT GRILLE GARNISH <i>385.00</i>	CRB \$548.00 ✓
1 PCS	FRONT GRILLE LOGO	rec \$38.80 ✓
2 PCS	HEADLAMPS @\$2010.00 <i>1759.10 x 2 = 3518.20</i>	CRB \$4,020.00 ✓
2 PCS	HEADLAMP LOWER BRACKETS @\$85.00	CRB \$170.00 ✓
1 PCS	FRONT SUPPORT PANEL <i>576.20</i>	but \$745.11 ✓
1 PCS	FRONT SUPPORT PANEL TOP GARNISH <i>212.30</i>	1721 \$322.30 ✓
1 SET	FRONT SUPPORT PANEL TOP GARNISH CLIPS	rec \$50.00 ✓
2 PCS	FRONT FENDERS @\$688.00	17 \$1,376.00 x
2 PCS	FRONT FENDER OUTER PROTECTORS @\$295.00 <i>225.30 x 2 =</i>	To. 17 \$590.00 ✓ <i>450.60</i>
1 PCS	FRONT HORN UNIT	17 \$110.00 x
1 PCS	AIR CON CONDENSER <i>845.10</i>	3ent/pn1 \$1,568.00 ✓
1 PCS	AIR CON CONDENSER SIDE GARNISH O/S	1721 \$148.00 ✓
1 PCS	RADIATOR <i>1615.20</i>	3ent \$1,817.50 ✓

(20%)

1 PCS	RADIATOR FAN COWLING	165.30	CNA	\$288.30	✓
1 PCS	RADIATOR FAN MOTOR		11	\$488.20	X
1 PCS	AIR DUCT		11	\$185.00	✓
1 PCS	AIR CLEANER BOX		11	\$745.30	X
1 PCS	BATTERY POSITIVE COVER		waged	\$48.00	✓
1 PCS	FRONT INTAKE MANIFOLD	1315.30	CNA	\$1,916.00	✓
1 PCS	TROTTLE BODY		11	\$1,450.00	X
1 PCS	AIR CON DISCHARGE HOSE		11	\$322.00	X
1 PCS	AIR CON SUCTION HOSE		11	\$318.00	X
1 PCS	WIPER WASHER TANK		11	\$160.00	X
1 PCS	WIPER TANK NECK		de	\$42.30	✓
1 PCS	AIR CON FAN COWLING	168.50	CNA	\$245.00	✓
1 PCS	AIR CON FAN MOTOR		11	\$388.00	X
1 PCS	AIR CON COMPRESSOR		11	\$1,825.00	X
				\$26,984.61	

20%

1 PCS	S.NETT		Surf	\$50.00	40
1 BOT	FRONT LICENSE PLATE W/HOLDER		Surf	\$50.00	30
	RADIATOR COOLANT				

LABOUR CHARGES:				
TOWING CHARGE			\$120.00	50
TO CHECK WIRING			\$80.00	30
TO DISMENTLE & REPLACING INTAKE MANIFOLD			\$80.00	30
TO SPRAY RUST PROOFING			\$150.00	60
TO MOUNT VEHICLE ON CAR O-LINER			11	\$380.00 X
TO DISMENTLE & REFIX FRONT UNDERCARRIAGE			11	\$380.00 X
TO REFILL AIR CON GAS			\$150.00	100
LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN			\$1,500.00	800
& REPLACING PARTS			\$1,500.00	1000
TO PUTTY & SPRAY PAINTING				

TOTAL \$31,424.61
240

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

13396-1
10716-88
12816-88



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ERGO INSURANCE PTE LTD		Ref : CS/EGI18007870/Uvbn2	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 14-05-2018	
		Code : EGI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	XD 3877L	Veh. Inspected	SLM 7768L
Policy No.		Coverage (\$)	0.00
Claim No.	XD3877L/SE/pl	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	02/05/2018
2. Vehicle Particulars & Condition			
Make & Model	HONDA VEZEL (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	RU11017504	Colour	WHITE
Odometer	55311	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60 R16	MICHELIN	7 mm
L/H Front Tyre	215/60 R16	MICHELIN	7 mm
R/H Rear Tyre	215/60 R16	MICHELIN	7 mm
L/H Rear Tyre	215/60 R16	MICHELIN	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	28/04/2018	Inspection Date	30/04/2018
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLM 7768L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BONNET	DENTED / BUCKLED	1,280.00	892.30
2	BONNET HINGES @\$85.00	BENT	170.00	156.00
1	BONNET INSULATOR	DEFORMED	211.30	185.30
1	SET BONNET INSULATOR CLIPS	NECESSARY	50.00	50.00
2	BONNET SIDE RUBBERS @\$35.00	NECESSARY	70.00	70.00
1	BONNET LOCK	TWISTED	135.50	135.50
1	BONNET LOCK CABLE	NOT NECESSARY	68.00	-
1	BONNET LOCK BRACKET	CRACKED	115.00	115.00
1	FRONT BUMPER	DENTED	950.00	801.70
1	FRONT BUMPER REINFORCEMENT	BENT	480.00	321.00
2	FRONT BUMPER SIDE RETAINERS @\$65.00	BENT	130.00	130.00
2	FRONT BUMPER BRACKETS @\$115.00	NO SUCH PARTS	230.00	-
1	FRONT BUMPER CENTRE GRILLE	CRACKED	285.00	166.00
1	FRONT BUMPER LOWER SPOILER	SERVICEABLE	525.00	-
1	FRONT BUMPER UNDER COVER	NOT NECESSARY	480.00	-
1	FRONT BUMPER TOW COVER	NOT NECESSARY	45.00	-
2	FRONT BUMPER FOG LAMP COVERS @\$180.00	NOT NECESSARY	360.00	-
2	FRONT BUMPER FOG LAMPS @\$445.00	NOT NECESSARY	890.00	-
1	SET FRONT BUMPER CLIPS	NECESSARY	60.00	50.00
1	FRONT GRILLE	CRACKED	525.00	389.50
1	FRONT GRILLE GARNISH	CRACKED	548.00	385.00
1	FRONT GRILLE LOGO	NECESSARY	38.80	38.80
2	HEADLAMPS @\$2010.00	CRACKED	4,020.00	3,518.20
2	HEADLAMP LOWER BRACKETS @\$85.00	CRACKED	170.00	170.00
1	FRONT SUPPORT PANEL	BENT	745.11	576.20
1	FRONT SUPPORT PANEL TOP GARNISH	TORN	322.30	212.30
1	SET FRONT SUPPORT PANEL TOP GARNISH CLIPS	NECESSARY	50.00	50.00
2	FRONT FENDERS @\$688.00	TO REPAIR SEE LABOUR	1,376.00	-
2	FRONT FENDER OUTER PROTECTORS @\$295.00	TORN	590.00	450.60

Report Ref No. CS/EGI18007870/Uvbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT HORN UNIT	NOT NECESSARY	110.00	-
1	AIR CON CONDENSER	BENT / PUNCTURE	1,568.00	845.10
1	AIR CON CONDENSER SIDE GARNISH O/S	TORN	148.00	148.00
1	RADIATOR	BENT	1,817.50	1,615.20
1	RADIATOR FAN COWLING	CRACKED	288.30	165.30
1	RADIATOR FAN MOTOR	NOT NECESSARY	488.20	-
1	AIR DUCT	TWISTED	185.00	185.00
1	SIR CLEANER BOX	NOT NECESSARY	745.30	-
1	BATTERY POSITIVE COVER	WARPED	48.00	48.00
1	FRONT INTAKE MANIFOLD	CRACKED	1,916.00	1,315.30
1	TROTTLER BODY	NOT NECESSARY	1,450.00	-
1	AIR CON DISCHARGE HOSE	NOT NECESSARY	322.00	-
1	AIR CON SUCTION HOSE	NOT NECESSARY	318.00	-
1	WIPER WASHER TANK	NOT NECESSARY	160.00	-
1	WIPER TANK NECK	DEFORMED	42.30	42.30
1	AIR CON FAN COWLING	CRACKED	245.00	168.50
1	AIR CON FAN MOTOR	NOT NECESSARY	388.00	-
1	AIR CON COMPRESSOR	NOT NECESSARY	1,825.00	-
	LESS 20% DISCOUNT		-	-2,679.22
			26,984.61	10,716.88
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT LICENSE PLATE W/HOLDER (SN)	BENT	50.00	40.00
1	BOT RADIATOR COOLANT (SN)	NECESSARY	50.00	30.00
			100.00	70.00
	<u>LABOUR</u>			
	TOWING CHARGE.		120.00	50.00
	TO CHECK WIRING.		80.00	30.00
	TO DISMANTLE & REPLACING INTAKE MANIFOLD.		80.00	30.00
	TO SPRAY RUST PROOFING.		150.00	60.00
	TO MOUNT VEHICLE ON CAR O-LINER.	NOT NECESSARY	380.00	-
	TO DISMANTLE & REFIX FRONT UNDERCARRIAGE.	NOT NECESSARY	380.00	-
	TO REFILL AIR CON GAS.		150.00	100.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF FRONT FENDERS. TO PUTTY & SPRAY PAINTING.		1,500.00	800.00
			1,500.00	1,000.00
			4,340.00	2,070.00
GRAND TOTAL			31,424.61	12,856.88
RECOMMENDED COST OF REPAIR SUM				11,500.00

Report Ref No. CS/EGI18007870/Uvbn2

NOTE: NEW PARTS REPLACEMENT

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.