

BODYFIX

NO 10 ANG MO KIO INDUSTRIAL PARK 2A #04-06

AMK AUTOPOINT SINGAPORE 568047

Tel No. : 62571289 Fax No. : 64837432

E-Mail : bodyfix@singnet.com.sg

Tax Reg. No. : 53010635C Buss. Reg. No. : 53010635C

AIG ASIA PACIFIC INSURANCE PTE LTD

Estimate : ES180502

Attention : Motor Claim Department

Date : 02/05/2018

Vehicle Num. : SJY 6509 K

Make/Model : VOLKSWAGEN JETTA-2010

Chassis/Eng# : WVVZZZ1KZAM133202

Accident Date : 27/04/2018

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1 PC	FRONT BUMPER / cut		865.00 /
2.	10 PCS	FRONT BUMPER CLIPS / AC	3.00	30.00 /
3.	1 PC	FRONT BUMPER SIDE RETAINER - RH / RL		30.00 /
4.	1 PC	FRONT BUMPER PROTECTOR RH / SCR		73.00 /
5.	1 PC	FRONT BUMPER LOWER GRILLE X		253.00 X
6.	1 PC	FRONT BUMPER LOWER LIP X / NN		309.00 X
7.	1 PC	FRONT BUMPER CHROME MOULDING - RH / AC		67.00 /
8.	1 PC	FOG LAMP (FRONT -RH) X		168.00 X
9.	1 PC	FOG LAMP COVER RH X / NN		114.00 X
10.	1 PC	FRONT FENDER (RH) / RUC		465.00 /
11.	1 PC	FRONT FENDER INNER SHIELD (RH) / RL		123.00 /
12.	1 PC	HEAD LAMP (RH) / SCR		545.00 /
13.	1 PC	FRONT SHOCK ABSORBER - RH X		273.00 X
14.	1 PC	FRONT LOWER ARM (RH) X / NN		295.00 X
15.	1 PC	FRONT KNUCKLE ARM -RH X		500.00 X
16.	1 PC	FRONT KNUCKLE BEARING RH X		487.00 X
17.	RH - FRT	TYRE RIM X		922.00 X
18.		BONNET REPAIR		
List Total S\$:				5,519.00
SPECIAL NETT ITEMS :				
1.	1 PC	FRONT TYRE (RH) X / NN		300.00
Special Nett Total S\$:				300.00
LABOUR :				
RUST-PROOFING ON THE ACCIDENT AFFECTED PORTIONS				60 80.00

CONTINUE / ...

2838.2
2.9%: 2250

BODYFIX

NO 10 ANG MO KIO INDUSTRIAL PARK 2A #04-06

AMK AUTOPOINT SINGAPORE 568047

Tel No. : 62571289 Fax No. : 64837432

E-Mail : bodyfix@singnet.com.sg

Tax Reg. No. : 53010635C Buss. Reg. No. : 53010635C

AIG ASIA PACIFIC INSURANCE PTE LTD

Estimate : ES180502

Attention : Motor Claim Department

Date : 02/05/2018

Vehicle Num. : SJY 6509 K

Make/Model : VOLKSWAGEN JETTA-2010

Chassis/Eng# : WVVZZZ1KZAM133202

Accident Date : 27/04/2018

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		LABOUR TO REPLACE ABOVE PARTS, PANEL BEAT, REPAIR & RE-ALIGN DAMAGE PARTS	400	1,200.00
		PUTTY & SPRAY PAINT BONNET, FRONT BUMPER & LOWER LIP, RH FRONT FENDER & OTHER AFFECTED AREAS	400	1,100.00
		Labour Total S\$:		2,380.00

4 Days

Unsur repair

After repair photos

Gao Qiang - 82880282

02/5/18.

SingDollars : Eight Thousand One Hundred Ninety-Nine Only

E. & O.E.

Total S\$: 8,199.00

=====

for BODYFIX

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: