

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

INDIA

Name : Ho Ah Chye

Accident Date : 17-Apr-18

Vehicle No : FZ 3134 U

Vehicle Model : Honda Wave

Estimated Repair Costs

Qty	Description	Amount S(\$)
	<u>List Items</u>	
2	Fork inner tubes	\$ 180.00 180.00 ✓
2	Fork outer tubes	\$ 190.00 190.00 ✓
1	Fork under bracket	\$ 170.00 170.00 ✓
1	Front rim	\$ 150.00 150.00 ✓
1	Front rim spooky (1 set)	\$ 60.00 60.00 X
1	Front rim shaft	\$ 42.00 42.00 X
1	Front rim bearing	\$ 38.00 38.00 X
1	Front brake disc	\$ 145.00 145.00 X
1	Headlamp	\$ 80.00 80.00 ✓
2	Side mirrors	\$ 96.00 96.00 ✓
2	Front signals	\$ 100.00 100.00 ✓
1	Handle bar	\$ 78.00 78.00 ✓
2	Handle bar ends	\$ 44.00 44.00 ✓
1	Hand grip (1 set)	\$ 50.00 50.00 ✓
1	Brake lever	\$ 32.00 32.00 ✓
1	Air fitter box	\$ 80.00 80.00 ✓
1	Front footrest bracket	\$ 48.00 48.00 ✓
2	Front footrest rubbers	\$ 44.00 44.00 ✓
1	Gear pedal	\$ 40.00 40.00 ✓
1	Brake pedal	\$ 42.00 42.00 ✓
2	Rear footrests	\$ 76.00 76.00 X
2	Rear footrest brackets	\$ 130.00 130.00 X
1	Exhaust assy	\$ 380.00 380.00 ✓
1	Exhaust protector	\$ 45.00 45.00 ✓
2	Rear tailboards	\$ 190.00 190.00 ✓
1	Rear fender	\$ 68.00 68.00 ✓
1	Fairing assy (1 set)	\$ 420.00 420.00 ✓
		\$ 3,018.00
		\$ 301.80
		\$ 2,716.20

Less 10%

Not Authorized
Labe

L/S # 1500/r
Take photo After repair.
30/4/18
H day.

1699
1528.1

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

Name : Ho Ah Chye

Accident Date : 17-Apr-18

Vehicle No : FZ 3134 U

Vehicle Model : Honda Wave

Estimated Repair Costs

Special Nett Items

1	Number plate (1 set)	\$	31	28.00	20
2	Fork oils	\$	ru	30.00	✓
2	Fork oil seals	\$	ru	56.00	✓
1	Steering cone bearing (1 set)	\$	ru	85.00	✓
1	ERP IU	\$	147	170.00	165
		\$		369.00	

S/No. Labour

1	To provide towing service.	\$		50.00	35
2	To check wiring and reset headlamp focusing.	\$	11	80.00	X
3	To provide labour.	\$		380.00	300
4	To check , repair and straighten body frame.	\$		400.00	250
		\$		910.00	

Grand Total

\$ 3,995.20

Dollars: Three Thousand Nine Hundred Ninety-Five And Twenty Cents Only.

2470.1
1976


EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: