

15/6/2017

INS. CASE OWNER:

CC 4 /LPC1800

7898, A w63n2

LKK:

IDAC:

Surveyor:

Adrian

DOI:

ASSIGNMENT

7014/18

Date / Time:

7014/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

GBB 6782C

Name of Insured:

VILANO ENGINEERING PIV

Insured Tel No.:

HP:

Excess Sec II :\$S

D.O.A:

28/4/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

PALKIRISAMY SRIKUMAR

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

18/18/18/1600/0 20571

Policy No.:

2/18/1600/101594

Make / Model:

Kia

Place of Accident:

WOODWARDS AVE 12

OI GIA REPORT: YES / NO

YES

TP GIA REPORT: YES / NO

YES

Insured Liability:

%

Final ? Yes / No

Sgn 18982



INSRS:

WSP:

Tel:

Liability:

RMKS:

prime motor



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

7/5/18
vikan

12/5/19

File pass to typist typ report

1/7/19

File pass to LSP to work

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$S

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

22/6/19

Confirm with:

Sulayi cheng

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

1

If NO or B 28, Ass. Lia:

Repair Cost:

\$S

11500.00

Loss of Rental (LOR):

\$S

(

days)

Loss of Use (LOU):

\$S

960.00

(\$

60

x

16 days)

Loss of Income (LOI):

\$S

-

(\$

x

days)

LOR only

☐

LOU only

☒

LOR + LOU

☐

LOR + LOI

☐

[Tick only one]

GIA/LTA Search

\$S

7.45

Medical:

\$S

-

Disbursement:

\$S

-

(e.g. Tow/ Independent)

Legal Cost

\$S

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$400

450.00

Total:

\$S

12467.45

Global Sum \$S:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$S

12467.45

Name 1:

Prime Motor Works

Payee 2: (Strike if N.A.)

\$S

-

Name 2:

-

Payee 3: (Strike if N.A.)

\$S

-

Name 3:

-

wh 1/7/19

REF:

ASS. REC. BY: Adrian Ling

ASSIGNMENT

21/11/09.

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 14 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SJU 1898R Yr Regn: 2009, NovType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan Sylphy C.C. 1498Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 67797 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JN1BAAG11Z010428Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/60R15R: 195/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Habilead

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 30/04/18Survey held at PrimeDes. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP Lon Pae</u>
<u>16/5/19</u>	<u>Confirm ds \$11500.00 with 14 working days</u>
	<u>INV : 24 K</u>
	<u>PV : 12.5K</u>
	<u>Nett : 11.5K</u>
	<u>(Ed = \$19577.10 63%)</u>

Date/Time, File Pass to?

☐ : Preli. Report1) _____
Date/Time, File Return to?☐ : Final Report

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

S + RS _____ SI

Photos

Others

Report Format : _____

Lump Sum / I.B.I. (\$) _____

TOTAL

Report + 100%



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CC4/LPC18007898/Awb3	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 30-04-2018	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBB 6782C	Veh. Inspected	SJU 1898R	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	30/04/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	28/04/2018	Inspection Date	30/04/2018	
Survey held at	PRIME MOTOR WORKS BLK 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Post an Advertisement

Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

July 2009 BMW 630i Cabriolet (New 10-Yr Coe)



\$9000 Deprecation To Own This
German 4 Seater Sport
Cabriolet! Cheapest In Town!
Tely Auto Credit [Show Ad](#)

Browse by Category

Sort by Date Posted

20 results/page

20 vehicles

Sylphy

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Sylphy		Any	Any	2010	Any	Any	Any	Available
	Nissan	Sylphy 1.5A	\$22,800	\$8,080 /yr	12-Jan-2010	1,498 cc	109,000 km	Sedan	Available
New Arrival, Very Well Maintained, Original Condition, Clean Interiors, Elegant Maroon Paints With Cream Leather Interiors, High Loan Available, Trade In Are Welcome, Call Now!									
Posted: 22-Apr-2018 Tags: 2010 Nissan Sylphy, Nissan Sylphy, Nissan, Sylphy, Used Nissan									
	Nissan	Sylphy 2.0A	\$25,800	\$8,660 /yr	14-Jan-2010	1,997 cc	72,500 km	Sedan	Available
Tip Top Condition Sylphy Is Up For Sale. With Brand New Amaron Car Battery And With New 4 Tyres. Well Maintained. Authentic Low Mileage Of 67572km Shown. Call Me Now If You're Interested.									
Posted: 15-Mar-2018 Tags: 2010 Nissan Sylphy, Nissan Sylphy, Nissan, Sylphy, Used Nissan									
	Nissan	Sylphy 1.5A	\$26,800	\$10,090 /yr	09-Feb-2010	1,498 cc	-	Sedan	Available
Just 1 Owner! Well Maintained, Excellent Condition! Extended Warranty Available! An Extremely Spacious Yet Responsive Sedan, That You Will Definitely Enjoy Your Ride Comfortably In. Buy It From Us Wit...									
Dickson Automobile									
Posted: 16-Mar-2018 Tags: 2010 Nissan Sylphy, Nissan Sylphy, Nissan, Sylphy, Used Nissan									
	Nissan	Sylphy 1.5A	\$24,800	\$8,590 /yr	25-Feb-2010	1,498 cc	-	Sedan	Available
1 Owner Only, Immaculate Condition, Reliable And Good Fuel Consumption, Spacious Cockpit Like A Executive Sedan, All In All, A Proven All Round Best Japanese Sedan.									
Ka-Hup Vehicles Trading									
Posted: 25-Apr-2018 Tags: 2010 Nissan Sylphy, Nissan Sylphy, Nissan, Sylphy, Used Nissan									

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

	Nissan	Sylphy 1.5A	\$23,988	\$8,240 /yr	26-Feb-2010	1,498 cc	-	Sedan	Available
No Admin Fee! 1 Careful Owner, Tip Top Condition, 100% Accident Free, Park Under Shelter. As Good As New! View To Believe! Low Down Payment, Cheap Insurance Premium Of Your Choice! High Loan Approval ...									
Posted: 29-Apr-2018 Tags: 2010 Nissan Sylphy, Nissan Sylphy, Nissan, Sylphy, Used Nissan									
	Nissan	Sylphy 1.5A	\$24,800	\$8,260 /yr	24-Mar-2010	1,498 cc	146,604 km	Sedan	Available
10% Down Payment. \$949/Month. Good Condition. Flexible Loan Package. Instant Approval. Ex Bankrupt Welcome. High Trade In.									
Posted: 05-Apr-2018 Tags: 2010 Nissan Sylphy, Nissan Sylphy, Nissan, Sylphy, Used Nissan									
	Nissan	Sylphy 1.5A	\$25,833	\$8,770 /yr	26-Mar-2010	1,498 cc	129,780 km	Sedan	Available
Agent Maintained Unit! Mileage Done 16k Per Year Only, Original Paintwork And Accident Free! Exterior And Interior Of Vehicle Well Maintained By Ex Careful Owner. View To Believe With No Obligations. Un...									
Posted: 30-Apr-2018 Tags: 2010 Nissan Sylphy, Nissan Sylphy, Nissan, Sylphy, Used Nissan									
	Nissan	Sylphy 1.5A	\$26,000	\$8,770 /yr	13-Apr-2010	1,498 cc	103,000 km	Sedan	Available
Well Taken Care By 1 Single Owner In Good Working Condition. Loan 80% Available, Monthly \$898 x 24 Months.									

Compare



High Loan Available At Low Interest Rate, Trade In Welcom...

Posted: 28-Apr-2018 Tags: 2009 Nissan Sylphy, Nissan Sylphy, Nissan, Sylphy, Used Nissan



Nissan Sylphy 1.5A

\$19,300

\$7,840 /yr

31-Jul-2009

1,498 cc

95,700 km

Sedan

Available

Lady Owner, Low Mileage, Accident Free. Good To Renew COE. Interested Please Call For Viewing.

DIRECT OWNER

Posted: 22-Apr-2018 Tags: 2009 Nissan Sylphy, Nissan Sylphy, Nissan, Sylphy, Used Nissan



Nissan Sylphy 1.5A

\$20,600

\$8,920 /yr

31-Jul-2009

1,498 cc

-

Sedan

Available

Graded B by **STRA**

Just 2 Owners! Very Low Mileage! Extended Warranty Available! High Trade In! Well Maintained Spacious Sedan In Superb Condition, View It And Believe! Buy It From Us With A Peace Of Mind, A Company Acc...

Dickson Automobile

Posted: 19-Mar-2018 Tags: 2009 Nissan Sylphy, Nissan Sylphy, Nissan, Sylphy, Used Nissan



Caught On Camera

A picture says a thousand words and a video clip could get you 100% on your insurance claims. Every car needs a camera for those unexpected moments when things happen. A list of the best dash cams available with reviews.

Find out more!



Nissan Sylphy 1.5A

\$18,800

\$7,010 /yr

28-Aug-2009

1,498 cc

-

Sedan

Available

Excellent Interior And Exterior Condition. Well Maintained Car. Reliable And Easy Maintenance. Spacious Mid-Size Sedan. View To Believe. Bank And In House Loan Available. \$0 Down Payment Available. Ca...

Posted: 26-Apr-2018 Tags: 2009 Nissan Sylphy, Nissan Sylphy, Nissan, Sylphy, Used Nissan



Nissan Sylphy 1.5A

\$22,800

\$9,280 /yr

30-Sep-2009

1,498 cc

102,000 km

Sedan

Available

1 Owner! Super Well Maintained By Owner, 100% Accident Free, No Repair Needed. View To Believe, STA/Vicom Evaluation Welcome, Flexible Loan Available, Call Now For A Viewing!

Posted: 09-Apr-2018 Tags: 2009 Nissan Sylphy, Nissan Sylphy, Nissan, Sylphy, Used Nissan



Nissan Sylphy 1.5A

\$24,800

\$10,100 /yr

25-Nov-2009

1,498 cc

100,316 km

Sedan

Available

Beautiful Well Kept Interior With Wood Trimmings, One Of The Most Popular Affordable Sedan With Luxury Looks, 100% Accident Free! Verified By STA! Immaculate Condition, Reluctant Sale By Owner But Nee...

Prem Roy Motoring

Posted: 10-Mar-2018 Tags: 2009 Nissan Sylphy, Nissan Sylphy, Nissan, Sylphy, Used Nissan

CO-SIGNMENT

Save this search criteria, to get email alerts whenever a match is found.

Make: Model: Price: Depreciation: Reg Date: Eng Cap: Mileage: Veh Type: Status:

For old advertisements, view [Expired ads](#)

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used Sylphy, Sylphy Singapore, used Sylphy Singapore, used Sylphy, used vehicles Singapore or even buy used Sylphy Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2018 sgCarMart. All rights reserved.

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Business
Owner ID: 0290D

Vehicle Details

Vehicle No.: SJU1898R
Vehicle to be Exported: No
Intended De-registration Date: 28 Apr 2018
Vehicle Make: NISSAN
Vehicle Model: SYLPHY 1.5L 4AT ABS D/AB 2WD 4DR
Primary Colour: Silver
Manufacturing Year: 2009
Engine No.: HR15265012B
Chassis No.: JN1BAAG11Z0110428
Maximum Power Output: 80.0 kW (107 bhp)
Open Market Value: \$17,877.00
Original Registration Date: 21 Nov 2009
First Registration Date: 21 Nov 2009
Transfer Count: 2
Actual ARF Paid: \$17,877.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 20 Nov 2019
PARF Rebate Amount: \$9,832.00

Intended COE Rebate Details

COE Expiry Date: 20 Nov 2019
COE Category: A - Car (1600cc & below)
COE Period(Years): 10
QP Paid: \$16,747.00
COE Rebate Amount: \$2,618.00
Total Rebate Amount: \$12,450.00

The information contained herein is correct as at 28 Apr 2018

OK

Adrian Lkt. Longpac

PRIME MOTOR WORKS

BLOCK 1, KAKI BUKIT AVENUE 6, #01-43, SINGAPORE 417883

NEEDS CAR

TEL: 6747 9241 FAX: 6741 7276 HP: 9067 8767

30/04/2018**Blk 1 Kaki Bukit Ave 6**

EMAIL: primemotorworks@hotmail.sg

01-43

RGB No: 53177286A

Singapore 417883

TP Longpac

nett: 111K

Vivian

Accident date: 28/04/2018**Estimated repair cost for vehicle no: SJU1898R NISSAN SYLPHY 1.5 '09****CHASSIS NUMER: JN1BAAG11Z0110428**

S/n	Qty	Nett Items	U/price	Amount	
1	2	Front Head Lamp <i>cracked</i>	\$558.00	\$1,116.00	✓
2	2	Front Head Lamp Lower Bracket <i>HP new</i>	\$38.10	\$76.20	X
3	1	Front Bumper <i>deformed</i>		\$566.20	✓
4	2	Front Bumper Side Retainer <i>new</i>	\$35.20	\$70.40	✓
5	10	Front Bumper Clips <i>new</i>	\$6.50	\$65.00	30 ✓
6	1	Front Bumper Inner Sponge <i>cracked</i>		\$207.10	✓
7	1	Front Bumper Reinforcement <i>Best</i>		\$563.70	✓
8	2	Front Bumper Reinforcement Bracket <i>HP new</i>	\$155.40	\$310.80	X
9	1	Front Bumper Fog Lamp <i>cracked</i>		\$327.30	✓
10	1	Front Bumper Fog Lamp Cover <i>cracked</i>		\$130.10	✓
11	1	Front Bumper Number Plate <i>HP new</i>		\$50.00	X
12	2	Front Bumper Side Moulding <i>new</i>	\$48.80	\$97.60	✓
13	1	Front L/H Fender <i>Buckled</i>		\$573.50	✓
14	1	Front L/H Fender Cowling <i>3 HP new</i>		\$77.40	X
15	10	Front L/H Fender Cowling Clips <i>3 HP new</i>	\$6.50	\$65.00	X
16	1	Front Grille <i>cracked</i>		\$364.50	✓
17	1	Front Grille Emblem Logo <i>new</i>		\$66.40	✓
18	6	Front Grille Clips <i>new</i>	\$6.50	\$39.00	20 ✓
19	1	Front Support Panel <i>2 HP</i>		\$308.50	X
20	1	Front Support Panel Top Cover <i>HP</i>		\$381.50	X
21	8	Front Support Panel Top Cover Clips <i>HP</i>	\$6.50	\$52.00	X
22	1	Front Bonnet <i>2 HP</i>		\$1,023.80	X
23	1	Front Bonnet Chrome Moulding <i>HP</i>		\$127.50	X
24	1	Front Bonnet Lock <i>HP</i>		\$62.10	X
25	1	Front Bonnet Insulator <i>new</i>		\$147.00	X
26	8	Front Bonnet Insulator Clips <i>new</i>	\$6.50	\$52.00	X
27	1	Rear Boot Lid <i>distorted</i>		\$796.70	✓
28	2	Rear Boot Lid Hinges <i>Best</i>	\$41.00	\$82.00	✓
29	1	Rear Boot Lid Emblem Logo <i>3 new</i>		\$66.40	✓
30	1	Rear Boot Lid Sylphy Logo <i>3 new</i>		\$88.10	✓
31	1	Rear Boot Lid Center Top Chrome Moulding <i>cracked</i>		\$270.60	✓
32	4	Rear Boot Lid Center Top Chrome Moulding Clips <i>new</i>	\$6.50	\$26.00	✓

33	1	Rear Boot Lid Center Lower Chrome Moulding	cracked	\$152.70	✓
34	4	Rear Boot Lid Center Lower Chrome Moulding Clips	new	\$6.50	\$26.00 ✓
35	1	Rear Boot Lid Number Plate	3MP		\$50.00 ✗
36	2	Rear Boot Lid Number Plate Lamp	free	\$66.50	\$133.00 ✗
37	2	Rear Boot Lid Side Reflector	cracked	\$220.10	\$440.20 ✓
38	1	Rear Boot Lid Inner Lock	Damaged		\$102.50 ✓
39	1	Rear Boot Lid Inner Rubber	lt		\$106.30 ✓
40	1	Rear Boot Lid Inner Trim Board	3MP		\$497.00 ✗
41	8	Rear Boot Lid Inner Trim Board Clips	new	\$6.50	\$52.00 ✗
42	2	Rear Tail Lamp	cracked	\$241.80	\$483.60 ✓
43	2	Rear Tail Lamp Panel	lt Distorted	\$165.10	\$330.20 -165.10
44	4	Rear Tail Lamp Clips	new	\$8.50	\$34.00 ✓
45	2	Rear Tail Lamp Lower Bracket	Damaged	\$35.20	\$70.40 ✓
46	1	Rear Bumper	Distorted		\$660.80 ✓
47	2	Rear Bumper Side Retainer	new	\$51.20	\$102.40 ✓
48	10	Rear Bumper Clips	new	\$6.50	\$65.00 30
49	1	Rear Bumper Center Moulding	new		\$162.80 ✓
50	2	Rear Bumper Mud Shield	3MP	\$51.10	\$102.20 ✗
51	8	Rear Bumper Mud Shield Clips	new	\$6.50	\$52.00 ✗
52	2	Rear Bumper Bracket	Dented	\$91.70	\$183.40 ✓
53	1	Rear Bumper Inner Sponge	deformed		\$38.60 ✓
54	2	Rear Bumper Side Reflector	lt cracked	\$66.60	\$133.20 -66.60
55	1	Rear End Panel	Distorted		\$438.70 ✓
56	1	Rear End Panel Top Garnish	deformed		\$242.80 ✓
57	1	Rear End Panel Lock Sensor	Damaged		\$69.10 ✓
58	2	Rear Fender	lt Buckle, RH Repair	\$996.40	\$1,992.80 -996.40
59	2	Rear Fender Inner Trim Board	3MP	\$231.70	\$463.40 ✗
60	16	Rear Fender Inner Trim Board Clips	new	\$6.50	\$104.00 ✗
61	2	Rear Fender Air-Duct	HP new	\$69.10	\$138.20 ✗
62	1	Rear Spare Tyre Panel	Repair		\$774.10 ✗
63	1	Rear Spare Tyre Panel Top Cover	deformed		\$495.00 ✓
64	1	Rear Windscreen	new		\$1,364.00 ✗
65	1	Rear Windscreen Moulding	new		\$157.30 ✓
66	1	Rear Exhaust Aluminium Cover	HP new		\$144.70 ✗
67	2	Rear Exhaust Mounting	HP new	\$47.10	\$94.20 ✗

10687.30
9618.51

Subtotal : \$18,707.00

S/n	Qty	S/Nett Items	U/price	Amount
1	1	Rear Bumper Reverse Sensor	Damaged	\$350.00 -200
2	1	Rear Spare Tyre Panel & End Panel Sealant	HP new	\$450.00 ✗
3	1	Front Air-Con Condenser	HP new	\$453.80 ✗

4	1	Front Radiator	HPM	\$517.90	X
5	1	Rear Boot Lid Camera	Damaged	\$680.00	880
6	1	Rear Exhaust	Repair	\$504.00	X
7	1	Rear Center Exhaust	HPM	\$374.40	X
Subtotal :				\$3,330.10	

580

Labour charges

To remove & refit cushion	\$280.00	80
To remove & refit reverse sensor	\$120.00	50
To remove & refit rear & center exhaust	\$380.00	80
To remove & refit rear camera	\$180.00	50
To remove & refit rear petrol tank	\$280.00	80
To remove & refit rear windscreen	\$120.00	✓
Gum	\$50.00	✓
To remove & refit front air-con condenser, radiator, fan motor & top up gas	\$380.00	X
To check wiring	\$100.00	60
Tuff kote	\$150.00	100
Panel beating	\$4,000.00	2000
Spray painting	\$3,000.00	1800

Subtotal : \$9,040.00

Total:- \$31,077.10

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 14668.57
2/5: 11.5K (Nett Value)
14 Days
11.5K

Catherine Chong (LKK Auto)

From: ERIC WOO JUN KIAT <ericwoo@lonpac.com>
Sent: Monday, 30 April, 2018 11:49 AM
To: assignments@lkkauto.com
Cc: MT_Claim_SG
Subject: Our Ref: 18/18/18/VC00/020571 Accident involving GBB6782C & SJU1898R on 28/4/18
Attachments: 30042018114444.pdf

Dear Catherine / Nivitha,

Kindly refer to our attachment.

Please proceed to conduct a survey of the vehicle SJU 1898R on without Prejudice Basis.

We look forward to receiving your report soon.

Thank you.

Best Regards,
Eric Woo
Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6279 9253 | Fax: (65) 6296 3767

30/4/2018 @ 11:51am
Subj: veh in
Adrian

Shu Pei (LKKAUTO)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Thursday, 3 May 2018 12:09 PM
To: Shu Pei (LKKAUTO)
Cc: MT_Claim_SG
Subject: RE: Our Ref: 18/18/18/VC00/020571 Accident involving GBB6782C & SJU1898R on 28/4/18 **LKK REF:CC4/LPC18007898/Awb3
Attachments: 03052018120245.pdf

Dear Shu Pei,

Attached insured's GIA report for your attention.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]
Sent: Wednesday, 2 May, 2018 6:31 PM
To: ERIC WOO JUN KIAT; GERALD POH WEE BIN
Cc: MT_Claim_SG; Admin A; Vivian Lau (LKKAUTO)
Subject: RE: Our Ref: 18/18/18/VC00/020571 Accident involving GBB6782C & SJU1898R on 28/4/18 **LKK REF:CC4/LPC18007898/Awb3

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SJU 1898R at M/s Prime Motor Works.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Please be informed that estimated cost of repair and preliminary advice is not ready yet.

Our case handler in-charge is Vivian and she can be contacted at DID: 6841 8625.

Thank you

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Monday, 30 April 2018 11:52 AM
To: 'ERIC WOO JUN KIAT' <ericwoo@lonpac.com>; assignments <assignments@lkkauto.com>
Cc: 'MT_Claim_SG' <mt_claim@lonpac.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: Our Ref: 18/18/18/VC00/020571 Accident involving GBB6782C & SJU1898R on 28/4/18

Dear Eric,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ERIC WOO JUN KIAT [<mailto:ericwoo@lonpac.com>]
Sent: Monday, 30 April, 2018 11:49 AM
To: assignments@lkkauto.com
Cc: MT_Claim_SG <mt_claim@lonpac.com>
Subject: Our Ref: 18/18/18/VC00/020571 Accident involving GBB6782C & SJU1898R on 28/4/18

Dear Catherine / Nivitha,

Kindly refer to our attachment.

Please proceed to conduct a survey of the vehicle SJU 1898R on without Prejudice Basis.

We look forward to receiving your report soon.

Thank you.

Best Regards,

Eric Woo

Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6279 9253 | Fax: (65) 6296 3767

Jia Le (LKK Auto)

From: Admin nht <admin@nhtmotor.com>
Sent: Friday, 28 June 2019 12:54 PM
To: Jia Le (LKK Auto)
Cc: Huey Yon (LKKAuto); Reports (LKKAuto); Chloe; Olivia Lau (LKKAuto); Admin A; Shu Pei (LKKAuto)
Subject: Re: FW: SJU1898R CLAIMING GBB6782C DOA 28.04.18 [PRIME]
Attachments: SJU1898R DV.pdf

Without Prejudice

Hi Carlor

Enclosed signed discharge voucher with company stamp for your reference.

We had hand over the original copy of discharge voucher to Adrian for bring back to you,thanks.


Best Regards,

Sukyi Chong

Prime Motor Works

1 Kaki Bukit Ave 6 Blk C #01-43 Autobay @ Kaki Bukit S(417883)

Tel : 6747 9241 Fax : 6741 7276



On Thu, Jun 27, 2019 at 2:51 PM Admin nht <admin@nhtmotor.com> wrote:
Without Prejudice

Hi Carlor

Contents noted with thanks.


Best Regards,

Sukyi Chong

Prime Motor Works

1 Kaki Bukit Ave 6 Blk C #01-43 Autobay @ Kaki Bukit S(417883)

Tel : 6747 9241 Fax : 6741 7276



On Thu, Jun 27, 2019 at 2:15 PM Jia Le (LKK Auto) <JiaLe@lkkauto.com> wrote:

Without Prejudice

Dear Sukyi,

Please sign the DV and return the original to us.

Thanks.

Best Regards,

Carlor Chan | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749 5792 | email: Jiale@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin nht [mailto:admin@nhtmotor.com]

Sent: Thursday, 27 June 2019 1:57 PM

To: Vivian Lau (LKKAuto)

Cc: Huey Yon (LKKAuto); Reports (LKKAuto); Jia Le (LKK Auto); Chloe; Olivia Lau (LKKAuto); Admin A; Shu Pei (LKKAuto)

Subject: Re: FW: SJU1898R CLAIMING GBB6782C DOA 28.04.18 [PRIME]

Without Prejudice

Hi Jia Le

Please advice your offer and revert for close case,thanks.


Best Regards,

Sukyi Chong

Prime Motor Works

1 Kaki Bukit Ave 6 Blk C #01-43 Autobay @ Kaki Bukit S(417883)

Tel : 6747 9241 Fax : 6741 7276



On Thu, Jun 13, 2019 at 9:46 AM Admin nht <admin@nhtmotor.com> wrote:

Without Prejudice - **gentle reminder**

Hi Vivian

Contents noted with thanks.

Hi Jia Le

Hope to receive your offer soon for close case,thanks.

Best Regards,

Sukyi Chong

Prime Motor Works

1 Kaki Bukit Ave 6 Blk C #01-43 Autobay @ Kaki Bukit S(417883)

Tel : 6747 9241 Fax : 6741 7276



On Thu, Jun 13, 2019 at 9:39 AM Vivian Lau (LKKAUTO) <vivianlau@lkkauto.com> wrote:

'WITHOUT PREJUDICE'

SAVE AS TO COSTS

Dear Sukyi,

Thank you for the email.

Please be informed that the case has being reassign to Ms Jia Le.

We are preparing our report to seek your mandate approval

Dear Jia Le

Kindly assist .

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Thank you

Best Regards,

Vivian Lau | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-8625 | email: Vivianlau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin nht [mailto:admin@nhtmotor.com]
Sent: Thursday, 13 June, 2019 9:33 AM
To: Vivian Lau (LKKAUTO) <vivianlau@lkkauto.com>
Cc: Chloe <chloe@nhtmotor.com>; Olivia Lau (LKKAUTO) <olivialau@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Shu Pei (LKKAUTO) <shupeil@lkkauto.com>
Subject: Re: FW: SJU1898R CLAIMING GBB6782C DOA 28.04.18 [PRIME]

Without Prejudice - **gentle reminder**

Hi Vivian

Please advice your offer and revert for close case, thanks.

Best Regards,

Sukyi Chong

Prime Motor Works

1 Kaki Bukit Ave 6 Blk C #01-43 Autobay @ Kaki Bukit S(417883)

Tel : 6747 9241 Fax : 6741 7276

On Thu, May 30, 2019 at 9:09 AM Admin nht <admin@nhtmotor.com> wrote:

Without Prejudice

Hi Vivian

Contents noted with thanks.

Hope to heard from you soon,thanks.

Best Regards,

Sukyi Chong

Prime Motor Works

1 Kaki Bukit Ave 6 Blk C #01-43 Autobay @ Kaki Bukit S(417883)

Tel : 6747 9241 Fax : 6741 7276

On Wed, May 29, 2019 at 6:45 PM Vivian Lau (LKKAuto) <vivianlau@lkkauto.com> wrote:

'WITHOUT PREJUDICE'

SAVE AS TO COSTS

Dear Sukyi,

We refer to the email below.

We are in the mist of preparing our report to seek your mandate approval

We will get back to you for an update/offer in due course.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Thank you

Best Regards,

Vivian Lau | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-8625 | email: Vivianlau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shu Pei (LKKAuto)

Sent: Wednesday, 29 May, 2019 6:18 PM

To: Admin nht <admin@nhtmotor.com>

Cc: Chloe <chloe@nhtmotor.com>; Olivia Lau (LKKAuto) <olivialau@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Vivian Lau (LKKAuto) <vivianlau@lkkauto.com>

Subject: RE: FW: SJU1898R CLAIMING GBB6782C DOA 28.04.18 [PRIME]

Dear Sir / Madam,

Thank you for your email.

Our respective case handler will look into the matter and revert to you in due course.

Please note that: -

LKK ref	Officer in charge
CC4/LPC18007898/Awb3	Vivian

To check availability of the case handler, you may contact the undersigned

Best Regards,

Shu Pei| Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin nht <admin@nhtmotor.com>

Sent: Wednesday, 29 May 2019 1:10 PM

To: Admin A <admin-a@lkkauto.com>

Cc: Chloe <chloe@nhtmotor.com>; Olivia Lau (LKKAuto) <olivialau@lkkauto.com>

Subject: Re: FW: SJU1898R CLAIMING GBB6782C DOA 28.04.18 [PRIME]

Without Prejudice

Hi Admin

Please advice your offer and revert for close case.

Please advice officer in-charge with claim reference number,thanks.

Best Regards,

Sukyi Chong

Prime Motor Works

1 Kaki Bukit Ave 6 Blk C #01-43 Autobay @ Kaki Bukit S(417883)

Tel : 6747 9241 Fax : 6741 7276

On Wed, May 29, 2019 at 10:42 AM Chloe <chloe@nhtmotor.com> wrote:

****Please note that NEW HOCK TECK MOTOR PTE LTD is now GST-registered***

Regards,

Chloe

New Hock Teck Motor Pte. Ltd.

GST Reg No.: 201718370k

Tel: 67479241 Fax: 67417276

1 Kaki Bukit Ave 6 Blk C #01-43

Singapore 417883

----- Forwarded message -----

From: **Shu Pei (LKKAuto)** <shupeil@lkkauto.com>

Date: Tue, May 21, 2019 at 6:58 PM

Subject: FW: SJU1898R CLAIMING GBB6782C DOA 28.04.18 [PRIME]

To: Chloe <chloe@nhtmotor.com>

Cc: Admin A <admin-a@lkkauto.com>, Vivian Lau (LKKAuto) <vivianlau@lkkauto.com>

Dear Sir / Madam,

Thank you for your email.

Our respective case handler will look into the matter and revert to you in due course.

Please note that: -

LKK ref	Officer in charge
CC4/LPC18007898/Awb3	Vivian

To check availability of the case handler, you may contact the undersigned

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupe@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Chloe <chloe@nhtmotor.com>

Sent: Tuesday, 21 May 2019 4:08 PM

To: Admin A <admin-a@lkkauto.com>

Subject: SJU1898R CLAIMING GBB6782C DOA 28.04.18 [PRIME]

Without Prejudice

Dear Motor Claims Department,

Enclosed LOD and supporting documents for your reference.

Originals have been posted out.

Please kindly advise officer in charge and hope to receive offer soon.

Thank you.

Regards,

Chloe

PRIME MOTOR WORKS

Tel: 67479241 Fax: 67417276

1 Kaki Bukit Ave 6 Blk C #01-43

Singapore 417883



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CC4/LPC18007898/Awb3n2	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 04-07-2019	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBB 6782C	Veh. Inspected	SJU 1898R	
Policy No.	Z/18/VC00/101594	Coverage (\$)	0.00	
Claim No.	18/18/18/VC00/020571	Excess (\$)	0.00	
Assign From	GERALD	Assign Date	30/04/2018	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN SYLPHY	c.c	1498	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	JN1BAAG11Z110428	Colour	SILVER	
Odometer	67797	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/60 R15	HABILEAD	6 mm	
L/H Front Tyre	195/60 R15	HABILEAD	6 mm	
R/H Rear Tyre	195/60 R15	HABILEAD	6 mm	
L/H Rear Tyre	195/60 R15	HABILEAD	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/04/2018	Inspection Date	30/04/2018	
Survey held at	PRIME MOTOR WORKS BLK 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		14 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJU 1898R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
2	FRONT HEAD LAMP @\$558.00 (N)	CRACKED	1,116.00	1,116.00
2	FRONT HEAD LAMP LOWER BRACKET @\$38.10 (N)	NOT NECESSARY	76.20	-
1	FRONT BUMPER (N)	DEFORMED	566.20	566.20
2	FRONT BUMPER SIDE RETAINER @\$35.20 (N)	NECESSARY	70.40	70.40
10	FRONT BUMPER CLIPS @\$6.50 (N)	NECESSARY	65.00	30.00
1	FRONT BUMPER INNER SPONGE (N)	CRACKED	207.10	207.10
1	FRONT BUMPER REINFORCEMENT (N)	BENT	563.70	563.70
2	FRONT BUMPER REINFORCEMENT BRACKET @\$155.40 (N)	NOT NECESSARY	310.80	-
1	FRONT BUMPER FOG LAMP (N)	CRACKED	327.30	327.30
1	FRONT BUMPER FOG LAMP COVER (N)	CRACKED	130.10	130.10
1	FRONT BUMPER NUMBER PLATE (N)	NOT NECESSARY	50.00	-
2	FRONT BUMPER SIDE MOULDING @\$48.80 (N)	NECESSARY	97.60	97.60
1	FRONT L/H FENDER (N)	BUCKLED	573.50	573.50
1	FRONT L/H FENDER COWLING (N)	NOT NECESSARY	77.40	-
10	FRONT L/H FENDER COWLING CLIPS @\$6.50 (N)	NOT NECESSARY	65.00	-
1	FRONT GRILLE (N)	CRACKED	364.50	364.50
1	FRONT GRILLE EMBLEM LOGO (N)	NECESSARY	66.40	66.40
6	FRONT GRILLE CLIPS @\$6.50 (N)	NECESSARY	39.00	20.00
1	FRONT SUPPORT PANEL (N)	NOT NECESSARY	308.50	-
1	FRONT SUPPORT PANEL TOP COVER (N)	NOT NECESSARY	381.50	-
8	FRONT SUPPORT PANEL TOP COVER CLIPS @\$6.50 (N)	NOT NECESSARY	52.00	-
1	FRONT BONNET (N)	NOT NECESSARY	1,023.80	-
1	FRONT BONNET CHROME MOULDING (N)	NOT NECESSARY	127.50	-
1	FRONT BONNET LOCK (N)	NOT NECESSARY	62.10	-
1	FRONT BONNET INSULATOR (N)	NOT NECESSARY	147.00	-
8	FRONT BONNET INSULATOR CLIPS @\$6.50 (N)	NOT NECESSARY	52.00	-
1	REAR BOOT LID (N)	DISTORTED	796.70	796.70
2	REAR BOOT LID HINGES @\$41.00 (N)	BENT	82.00	82.00
1	REAR BOOT LID EMBLEM LOGO (N)	NECESSARY	66.40	66.40
1	REAR BOOT LID SYLPHY LOGO (N)	NECESSARY	88.10	88.10

Report Ref No. CC4/LPC18007898/Awb3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BOOT LID CENTER TOP CHROME MOULDING (N)	CRACKED	270.60	270.60
4	REAR BOOT LID CENTER TOP CHROME MOULDING CLIPS @\$6.50 (N)	NECESSARY	26.00	26.00
1	REAR BOOT LID CENTER LOWER CHROME MOULDING (N)	CRACKED	152.70	152.70
4	REAR BOOT LID CENTER LOWER CHROME MOULDING CLIPS @\$6.50 (N)	NECESSARY	26.00	26.00
1	REAR BOOT LID NUMBER PLATE (N)	NOT NECESSARY	50.00	-
2	REAR BOOT LID NUMBER PLATE LAMP @\$66.50 (N)	NOT NECESSARY	133.00	-
2	REAR BOOT LID SIDE REFLECTOR @\$220.10 (N)	CRACKED	440.20	440.20
1	REAR BOOT LID INNER LOCK (N)	DAMAGED	102.50	102.50
1	REAR BOOT LID INNER RUBBER (N)	CUT	106.30	106.30
1	REAR BOOT LID INNER TRIM BOARD (N)	NOT NECESSARY	497.00	-
8	REAR BOOT LID INNER TRIM BOARD CLIPS @\$6.50 (N)	NOT NECESSARY	52.00	-
2	REAR TAIL LAMP @\$241.80 (N)	CRACKED	483.60	483.60
2	REAR TAIL LAMP PANEL @\$165.10 (N)	N/S DISTORTED	330.20	165.10
4	REAR TAIL LAMP CLIPS @\$8.50 (N)	NECESSARY	34.00	34.00
2	REAR TAIL LAMP LOWER BRACKET @\$35.20 (N)	DAMAGED	70.40	70.40
1	REAR BUMPER (N)	DISTORTED	660.80	660.80
2	REAR BUMPER SIDE RETAINER @\$51.20 (N)	NECESSARY	102.40	102.40
10	REAR BUMPER CLIPS @\$6.50 (N)	NECESSARY	65.00	30.00
1	REAR BUMPER CENTER MOULDING (N)	NECESSARY	162.80	162.80
2	REAR BUMPER MUD SHIELD @\$51.10 (N)	NOT NECESSARY	102.20	-
8	REAR BUMPER MUD SHIELD CLIPS @\$6.50 (N)	NOT NECESSARY	52.00	-
2	REAR BUMPER BRACKET @\$91.70 (N)	DENTED	183.40	183.40
1	REAR BUMPER INNER SPONGE (N)	DEFORMED	38.60	38.60
2	REAR BUMPER SIDE REFLECTOR @\$66.60 (N)	N/S CRACKED	133.20	66.60
1	REAR END PANEL (N)	DISTORTED	438.70	438.70
1	REAR END PANEL TOP GARNISH (N)	DEFORMED	242.80	242.80
1	REAR END PANEL LOCK SENSOR (N)	DAMAGED	69.10	69.10
2	REAR FENDER @\$996.40 (N)	N/S BUCKLED / O/S TO REPAIR SEE LABOUR	1,992.80	996.40
2	REAR FENDER INNER TRIM BOARD @\$231.70 (N)	NOT NECESSARY	463.40	-
16	REAR FENDER INNER TRIM BOARD CLIPS @\$6.50 (N)	NOT NECESSARY	104.00	-

Report Ref No. CC4/LPC18007898/Awb3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR FENDER AIR-DUCT @\$69.10 (N)	NOT NECESSARY	138.20	-
1	REAR SPARE TYRE PANEL (N)	TO REPAIR SEE LABOUR	774.10	-
1	REAR SPARE TYRE PANEL TOP COVER (N)	DEFORMED	495.00	495.00
1	REAR WINDSCREEN (N)	NOT NECESSARY	1,364.00	-
1	REAR WINDSCREEN MOULDING (N)	NECESSARY	157.30	157.30
1	REAR EXHAUST ALUMINIUM COVER (N)	NOT NECESSARY	144.70	-
2	REAR EXHAUST MOUNTING @\$47.10 (N)	NOT NECESSARY	94.20	-
	LESS 10% DISCOUNT		-	-1,068.73
			18,707.00	9,618.57
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	350.00	200.00
1	REAR SPARE TYRE PANEL & END PANEL SEALANT (SN)	NOT NECESSARY	450.00	-
1	FRONT AIR-CON CONDENSER (SN)	NOT NECESSARY	453.80	-
1	FRONT RADIATOR (SN)	NOT NECESSARY	517.90	-
1	REAR BOOT LID CANERA (SN)	DAMAGED	680.00	380.00
1	REAR EXHAUST (SN)	TO REPAIR SEE LABOUR	504.00	-
1	REAR CENTER EXHAUST (SN)	NOT NECESSARY	374.40	-
1	GUM (SN)	NECESSARY	50.00	50.00
			3,380.10	630.00
	<u>LABOUR</u>			
	TO REMOVE & REFIT CUSHION.		280.00	80.00
	TO REMOVE & REFIT REVERSE SENSOR (SN)		120.00	50.00
	TO REMOVE & REFIT REAR & CENTER EXHAUST.		380.00	80.00
	TO REMOVE & REFIT REAR CAMERA.		180.00	50.00
	TO REMOVE & REFIT REAR PETROL TANK.		280.00	80.00
	TO REMOVE & REFIT REAR WINDSCREEN.		120.00	120.00
	TO REMOVE & REFIT FRONT AIR-CON CONDENSER,RADIATOR,FAN MOTOR & TOP UP GAS.	NOT NECESSARY	380.00	-
	TO CHECK WIRING.		100.00	60.00
	TUFF KOTE.		150.00	100.00

Report Ref No. CC4/LPC18007898/Awb3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF O/S REAR FENDER,REAR SPARE TYRE PANEL AND REAR EXHAUST. SPRAY PAINTING.		4,000.00	2,000.00
			3,000.00	1,800.00
			8,990.00	4,420.00
GRAND TOTAL			31,077.10	14,668.57
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				11,500.00

Report Ref No. CC4/LPC18007898/Awb3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.