



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT

SOMPO INSURANCE SINGAPORE PL	Ref: CS3/SMO18007927/R1z4be2
50 RAFFLES PLACE #05-01/06	Date: 20-06-2018
SINGAPORE LAND TOWER SINGAPORE 048623	
	Code: SMO

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	PZ 489Y	Veh. Inspected	PC 1765P
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1801808/NSW	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	27/04/2018

2. Vehicle Particulars & Condition


Make & Model	KING LONG XMQ6900K	c.c	6693
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	LABR1DSB1BB203664	Colour	MULTI COLOUR
Odometer	237448 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	11 R22.5	WEST LAKE	8 mm
L/H Front Tyre	11 R22.5	WEST LAKE	8 mm
R/H Rear Tyre	11 R22.5 (D)	WEST LAKE	8/8 mm
L/H Rear Tyre	11 R22.5 (D)	WEST LAKE	8/8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.



5. General Information

Accident Date	26/03/2018	Inspect Date / Time	02/05/2018 (10:53 AM)
Survey held at	STS TRANSPORT MANAGEMENT PTE LTD 15 PIONEER SECTOR 2 SINGAPORE 628376		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
 B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
 C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
 D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,000-\$3,000

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	-----------------------

Report Ref No. CS3/SMO18007927/R1z4be2

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.