* .	ASS. REC. BY: SUIVALOY SMART CLOIM From (Person):	Ywnne	_	AS	SIGN	MENT	191/K <i>563</i> (Office) 1		ate/Time:	30042018
	ATHRONIA HARLES AND	(VOIII))	-		Bi	ll to:			
191	To Inspect Vehicle at Workshop m/s of Policy No: Sum Insured:	: No:	Ah Blk 10	AMK Ym	Water 12814		Claim No: _ Excess: _	Insured: Tel: OI - OI SUMOU	DAF	1214 05042018
	Make of Veh: (Client's Record) CA REV Date/Time:	REP. / RE	9.14ay	n Perso	on Contr		Zla	1 40 m and 1	H.O.D. F	ndorsement
		SKK 712 @ 17: @ 09:	5H -	×	revise	ed t	to Yuan	e Via	Son a Authoriz	art dain. ation via en

RECEIVED 1 7 JAN 2019

Cate/Time, File Pass to? : Preli.	Report	Days Of Repair:	_		
19/01/19 Final 1	Report	Resurvey No. of Trip:	1	Survey Fee.	300
Date/Time, File Return to?				Transportation.	
2)	Add Fee	: Site Insp (\$)S+RSSI	
	7	: Interview (\$) Photos	
Report Format :	S\$3	Tech. Invs (\$) Cithers	
Lump Sum / I.B.I: (\$ 6.854)	1- P/P	Weekend (\$)	
,				FOTAL	

Menu



Service Request Details

Claim

S8M00D7F

Reference

None 🥒

Loss Date

April 5, 2018

Request Date

April 30, 2018

Due Date

May 8, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated workshop survey

Actions Next Step Agree to perform service Decline Work Accept Work

Vehicle Information

Incident Vehicle Registration #

SKK7725H

Make

BMW

Menu

Service Address

10 Ang Mo Kio Ind. Park 2A, , , 568047

Primary Contact/Insured

LOY SIEW ENG NO. 33 LEITH PARK, 547948, Singapore 96868286

Claim Handler

ANG Yvonne 6568804461 yvonne.ang@axa.com.sg

Additional Instructions EXCESS \$400 + \$500 TOTAL \$900

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message

Shirley Hiew (LKK Auto)

From:

Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Sent:

Friday, 4 May 2018 9:27 AM

To:

zila@ahlimmotor.com.sg

Cc:

muihong@ahlimmotor.com.sg; 'SUR'

Subject:

SKK 7725H-DOA: 05/04/2018 (AXA OD)

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle SKK 7725H (Excess \$ 900/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>Sur@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



51 UBI AVE 1, #02-25 PAVA UIII INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Immediate Advice

To: AXA Insurance Pte Ltd

Date: 17/01/2019

Survey Details:

Date of loss	5-Apr-18
Date of appointment	30-Apr-18
Date of survey	2-May-18
Location of survey	10 Ang Mo Kio Ind. Park 2A,
GARAGON CONTRACTOR SANCTON SAN	#01-09 S568047

Vehicle Details:

Claim Type:	Own Damage	
Vehicle number	SKK 7725H	
Make and Model	B.M.W. 520I AT D/AB 2WD 4DR LED NA	
Date of registration	30-Aug-13	
Excess	\$900	
Market Value	\$100,000	
Parf Rebate	\$80,186	
Nett Loss	\$19,814	

Repair details:

Initial Estimate	20,376.00

Proposed/Revised repair cost:

Total Lump Sum(if applicable)	\$6,854.00
Labour	\$2,390.00
Check items (estimate)	\$0.00
Parts	\$4,464.00

DAYS

51 UBLAYE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

AMAGES CONSISTENT, REPAIR COST ECONOMICAL. WE	3
IAVE AUTHORIZED REPAIR.	

Mandate:

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	



51 UBI AVE 1, 202-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL; (065) 62563561 FAX; (065) 62564315

Immediate Advice

To: AXA Insurance Pte Ltd Date: 03/05/2018

Survey Details:

Date of loss	5-Apr-18	
Date of appointment	30-Apr-18	
Date of survey	2-May-18	
Location of survey	10 Ang Mo Kio Ind. Park 2A, #01-09 S568047	

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SKK 7725H
Make and Model	BMW 520I AT D/AB 2WD 4DR LED NAV
Date of registration	30-Aug-13
Excess	\$900
Market Value	\$100,000
Parf Rebate	\$80,186
Nett Loss	\$19,814

Repair details:

Initial Estimate	19924
Illitial Estimate	13324

Proposed/Revised repair cost:

Parts	\$4,202
Check items (estimate)	\$2,397
Labour	\$2,390
Total	\$8,989
Lump Sum(if applicable)	\$

Number of days for repair	8 days	
---------------------------	--------	--



51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

Pending some parts prices.	

Mandate:

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Fax Number Contact Number

EMail Address

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

Any false reporting may be referred to the Police for investigation.

- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

	ACCIDENT STATEMENT
Date Of Report	05/04/2018 15:48
Date Of Accident	05/04/2018 10:15
Exact Location Of Accident	BLK 410 ANG MO KO AVE 10 OSCP
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SKK7725H
Insured/Policyholder	
Name Of Registered Owner	LOY SIEW ENG
NRIC No	S0503234B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91682969
Alternative Phone No	OTHERS-96868286
Vehicle Particulars	
Manufacturer	BMW
Model	520I-2.0 AT D/AB 2WD 4DR LED NAV (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA001686
Cover Note Number	01/09/2017 - 31/08/2018
Driver	
Name of Driver	GOH DOH TAN
NRIC No	S0255926I
Date Of Birth	19/07/1940
Occupation	INDOOR
Date Of Driving Pass	18/08/1967
Driving Experience	50 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96868286

DOHTAN@GMAIL.COM

OTHERS-91682926

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time:

Driver's Signature

Mme

(If driver is not the policyholder)

Date & Time:

Reporting Ce

Name: NRIC/FIN No.:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 3234B

Vehicle Details

Vehicle No.: SKK7725H

Vehicle to be Exported: No

Intended De-registration Date: 21 Apr 2018

Vehicle Make: B.M.W.

Vehicle Model: 520I AT D/AB 2WD 4DR LED NAV

Primary Colour: White

Manufacturing Year: 2013

Engine No.: A8120572N20B20B

Chassis No.: WBA5A320X0D333765

Maximum Power Output: 135.0 kW (181 bhp)

Open Market Value: \$46,840.00 Original Registration Date: 30 Aug 2013 First Registration Date: 30 Aug 2013

Transfer Count: 0

Actual ARF Paid: \$52,576.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 29 Aug 2023 PARF Rebate Amount: \$39,432.00

Intended COE Rebate Details

COE Expiry Date: 29 Aug 2023

COE Category: E - Open Category

COE Period(Years): 10

OP Paid: \$79,223.00 COE Rebate Amount: \$41,021.00 Total Rebate Amount: \$80,453.00

The information contained herein is correct as at 21 Apr 2018

OK

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID: Vehicle Details	3234B
Vehicle No.:	SKK7725H
Vehicle to be Exported:	No
Intended De-registration Date:	03 May 2018
Vehicle Make:	B.M.W.
Vehicle Model:	520I AT D/AB 2WD 4DR LED NAV
Primary Colour:	White
Manufacturing Year:	2013
Engine No.:	A8120572N20B20B
Chassis No.:	WBA5A320X0D333765
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$46,840.00
Original Registration Date:	30 Aug 2013
First Registration Date:	30 Aug 2013
Transfer Count:	0
Actual ARF Paid: Intended PARF Rebate Details	\$52,576.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Aug 2023
PARF Rebate Amount: Intended COE Rebate Details	\$39,432.00
COE Expiry Date:	29 Aug 2023
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$79,223.00
COE Rebate Amount:	\$40,754.00
Total Rebate Amount:	\$80,186.00

The information contained herein is correct as at 03 May 2018

Sketch Plan Pg. 3



lpax novideo clearedy. noinjum.



96868286/91682926 (WHZ)





Sketch Plan Pg. 5

	To Whom It May Concern,
	Accident involving my vehicle no. Skk 7725H on 05 04 2018 (date) with SJ G 8512G (other vehicle no) along BIK HO Arg Mo kio Ave 10 0506
	1, Loy Siew Eng Nric No. S0503234B
	Owner of vehicle no. Sex 7725H am aware of the accident of my vehicle on 05 04 2018 (Date) while car was driven by GON Don Tan
Χ	Nric No. S02559261. Thereby, authorise him / her to make the report. Name
	Date:
	······································
	To fill in if there is a OD claim
	I am aware of the circumstances and agreeable to claim my own insurance for the above accident
X	Name
	Date:



No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COP

M/S: AXA INSURANCE PTE LTD

8 SHENTON WAY

#27-01 AXA TOWER

SINGAPORE 068811

TEL: 63387288

ATTN: Motor Claim Department

Your Ref No:

Claim Type:

Own Damage

Accident Date:

Description

39 SIDE SKIRT CLIPS

150162514315

FAX: 63382522

Estimate No: MC0912989

Quantity

Date:

06 Apr 2018

Policy No:

GA001686

N/s book Veh Reg No:

SKK7725H Make/Model: BMW 520I AT D/AB

S8M00D7F

05/04/2018

U/Price

	Description	19x162564315	U/Price	Quantity		Cost	Amount
						<u>SS</u>	<u>S\$</u>
	SPARE PARTS		1	L IPC	3		١
1	FRONT BUMPER			♣ 1 PC		900.00	
2	FRONT BUMPER SIDE RETAINER	LH		1 PC	Sm	8.00	
3	FRONT BUMPER CLIPS			15 PC	na	22.50 🗶	
4	FRONT FENDER LH			1 PC	R	450.00	
5	FRONT FENDER COWLING (FRO)	NT SECTION)		1 PC	3cm	90.00 7	X
6	FRONT FENDER COWLING CLIPS	S		8 PC	n	12.00 2	X
7	FRONT FENDER COWLING (REAL	R SECTION)		1 PC	cm	90.00	1
8	FRONT FENDER COWLING CLIPS	;		8 PC	M	12.00 -	
9	FRONT FENDER CHROME MOUL	DING		1 PC	na	85.00 -	
10	FRONT DOOR LH			1 PC	3	,150.00	
11	FRONT DOOR HINGE TOP & LOW	/ER		2 PC	n	80.00 X	
12	FRONT DOOR CHECKER			1 PC	n	85.00 X	
13	FRONT DOOR RUBBER (AT DOOR	₹)		1 PC	na	125.00 -	_
14	FRONT DOOR RUBBER TOP - CH	ECK PRICE		1 PC		0.0000 Z	χ
15	FRONT DOOR RUBBER LOWER			1 PC	~	35.00 2	1
16	FRONT DOOR RUBBER (AT BOD'	Y)		1 PC	Sm	150.00 X	^
17	FRONT DOOR POWER WINDOW	MOTOR		1 PC	A.	220.00 7	X.
18	FRONT DOOR POWER WINDOW	REGULATOR		1 PC	h	260.00 7	Y
19	FRONT DOOR INNER LOCK			1 PC	n	215.00 🗶	^
20	FRONT DOOR OUTER HANDLE W	/ITH CHROME MOULDING		1 PC	Pm	580.00 X	
21	SIDE MIRROR ARM LH			1 PC	Se-	680.00	Y
22	SIDE MIRROR SIGNAL LAMP LH	- CHECK PRICE		1 PC	1 ~	0.0000 🗶	
23	SIDE MIRROR LOWER COVER LE			1 PC	ne	0.0000 ~	- 60
24	REAR DOOR LH	NIM.	(O)	1 PC	RI	,150.00	_
25	REAR DOOR HINGE TOP	1	101	1 PC	X	40.00 ×	
26	REAR DOOR HINGE LOWER	1/#/	[2]	1 PC	n	40.00 X	
27	REAR DOOR CHECKER	NVd1	67	1 PC	54	85.00 X	
28	REAR DOOR RUBBER (AT DOOR)			1 PC	ne	125.00 -	
29	REAR DOOR RUBBER TOP - CHE	CK PRICE		1 PC	Son	0.0000 ?	χ
30	REAR DOOR RUBBER LOWER			1 PC	1cm	55.00 ?	X
31	REAR DOOR RUBBER (AT BODY)	ř.		1 PC	Ja	145.00 X	330
32	REAR DOOR POWER WINDOW M	OTOR		1 PC		220.00 7	Y
33	REAR DOOR POWER WINDOW R	EGULATOR		1 PC	4	220.00 7	7
34	REAR DOOR INNER TRIMBOARD			1 PC	5m 1.	X 00.086,	
35	REAR DOOR INNER LOCK		-89	1 PC	n	170.00 🗶	
36	SIDE SKIRT LH - CHECK PRICE		mg.	M IPC	L.	0.0000	350
37	SIDE SKIRT BRACKET FRONT - C	HECK PRICE		1 PC	DEA	0.0000 🗶	12
38	SIDE SKIRT BRACKET REAR - CH	IECK PRICE		1 PC	3	0.0000 ∠	



No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S: AXA INSURANCE PTE LTD

8 SHENTON WAY

#27-01 AXA TOWER

SINGAPORE 068811

TEL:

63387288

ATTN: Motor Claim Department

FAX: 63382522

S8M00D7F

64 TO SPRY ANTI-RUST COATING ON AFFECTED AREAS.

Your Ref No: Claim Type:

Own Damage

Accident Date: 05/04/2018 Estimate No: MC0912989

Date:

06 Apr 2018

Policy No:

GA001686

Veh Reg No: Make/Model:

SKK7725H BMW 520I AT D/AB

NZ 150.00 X

1 PC

2WD

Estimate Repair Cost to Vehicle No :SKK7725H

	Description	U/Price	Quantity		Cost	Amount
					<u>SS</u>	SS
10	REAR FENDER LH		1 PC	10	1,150.00 X	
11	REAR FENDER COWLING LH		1 PC	Sin	110.00 🗶	
12	REAR FENDER COWLING CLIPS		8 PC	22	12.00 X	
3	REAR BUMPER		1 PC	R	1,050.00 🗶	
14	REAR BUMPER SIDE RETAINERS LH		1 PC	20	120.00 🗶	
5	REAR BUMPER CLIPS		15 PC	nn		
16	FRONT WHEEL BEARING LH		1 PC	nn		
17	REAR WHEEL BEARING LH		1 PC	no	~145.00 2	
					^	12,134.00

Rea 1 2000.00 Special Nett SPORT RIM LHR, LHF FL 0.0000 7 49 TYRE LHF LHR - CHECK PRICE 2 PC vn 20.00 X INNER SEAL (REAR W/S) 1 PC ~~ 40.00 × 51 WINDSCREEN SEALANT (REAR W/S) 1 PC 20.00 🗶 52 INNER SEAL (RR QUARTER GLASS LH) 1 PC 53 WINDSCREEN SEALANT (RR QUARTER GLASS LH) 40.00 X 1 PC 2,120.00

301 LABOUR 54 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS 1 PC 40.00 AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING. 601 55 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT. 1 PC 80.00 56 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN. 150.00 X 1 PC TO DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM 1 PC 160.00 SUCH AS POWER WINDOW MOTOR AND REGULATOR TO NEW DOOR/FACILITATE REPAIR. 601. ◆58 TO REMOVE AND REINSTALL/REPLACE QUARTER GLASS. 1 PC 80.00 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER 1 PC 250.00 TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS. 60 TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE - FRONT 1 PC 180.00 X NN 180.00 7 X 61 TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE - REAR 1 PC TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER 1 PC 120.00 SENSORS. LABOUR TO RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC NN 280.00 FAULT



No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg GST:M9-0009639-E RCB NO:06470300B



06 Apr 2018

GA001686

SKK7725H

M/S: AXA INSURANCE PTE LTD

8 SHENTON WAY

#27-01 AXA TOWER

SINGAPORE 068811

TEL: 63387288

ATTN: Motor Claim Department

FAX: 63382522

Veh Reg No:

Policy No:

Date:

Make/Model: BMW 520I AT D/AB

Estimate No: MC0912989

2WD

Your Ref No:

S8M00D7F

Claim Type:

Own Damage

Accident Date:

05/04/2018

Estimate Repair Cost to Vehicle No :SKK7725H

	Description	U/Price	Quantity	Cost	Amo	unt
65	TO DISMANTLE ALL DAMAGED PARTS TO CUT & WELD REAR LH.TO KNOCK & REPAIR FRONT DOOR PILLAR LH,ROCKER PALH,CTR PILLAR LH INNER PANELS AND AFFECTED AREAS. TO	NEL	1 PC	<u>\$\$</u> 2,000.00	8001	<u>S\$</u>
66	LISTED PARTS BACK SAME. TO SPRAY FRONT BUMPER, FRONT FENDER LH, FRONT DOOR I MIRROR LH, FROTN DOOR PILLAR LH, SIDE SKIRT LH, ROCKER LH, REAR DOOR LH, RR FENDER LH, REAR BUMPER.	.H,SIDE	1 PC	2,000.00	1200	

5,670.00

20,376.00

Amount Before Excess

S\$ 19,924.00

Add GST @ 7%

1,394.68

Total Amount payable

S\$ 21.318.68

TOTAL: SINGAPORE DOLLAR TWENTY ONE THOUSAND THREE HUNDRED EIGHTEEN AND CENTS SIXTY EIGHT ONLY

Please arrange this vehicle to be surveyed soonest possible.

Thank You

For AH LIM MOTOR COMPANY

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify

the Repairer of the following:

• To resurvey before after spray painting

- To display designed part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg GST:M9-0009639-E RCB NO:06470300B

M/S:

AXA INSURANCE PTE LTD

8 SHENTON WAY

#27-01 AXA TOWER

SINGAPORE 068811

TEL:

63387288

FAX: 63382522

ATTN: Motor Claim Department

Estimate No: MC0912989

Date:

18 May 2018

Policy No:

GA001686

Veh Reg No:

SKK7725H

Make/Model: BMW 520I AT D/AB

2WD

Your Ref No:

S8M00D7F

Claim Type: Accident Date: Own Damage

05/04/2018

Estimate Repair Cost to Vehicle No :SKK7725H

Description

U/Price

Quantity

Cost

Amount

SS

S\$

Supplementary Parts to Repair

SPARE PARTS

1 DOOR VIEW MIRROR SURROUND

IPC CM 54.00 L

54.00

DoTakaby Siman 18/418

Amount Before Excess

S\$ 54.00

S\$ 3.78

Total Amount payable

S\$ 57.78

The above vehicle was surveyed by KENNETH KONG -LKK on 02/05/2018

For AH LIM MOTOR COMPANANY
AH LIM MOTOR COMPANANY
AH LIM MOTOR COMPANANY

GST Amount

No. 10 Ang Mo Kio Industrial Park 2A No. 10 Ang Mo Kio Industrial Park 2A #01-09 AMK Autopoint Stratepore 568047 #01-09 AMK Autopoint Stratepore 568047 AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



SATISFACTION VOUCHER / WORKSHOP'S WARRANTY

To: AXA Insurance Pte					
vehicle of registration	n number	hereby a	confirm that V	we have tak	en delivery of my/our Workshop, Messrs epairs arising from the
accident involving my/o my/our entire satisfaction I/we have no further cla	ur vehicle that on. Save for m	occurred on y/our rights unde	er the Warran	ty set out be	have been effected to
I/We hereby authorise r excess) which amount confirm that such paym Ltd to indemnify me/ us	s to S\$ <u>6.3</u> ent shall wholl	y discharge any	and all liability	to the said on the part	Workshop and I/we of AXA Insurance Pte
Dated: 14/05/20	13				
Signature of the Policy	nolder or duly a	authorized repres	sentative and	company sta	mp where applicable.

WORKSHOP'S WARRANTY

Subject to provisions (a) to (d) below, the repairs effected to the abovementioned vehicle are warranted good by the Workshop for twelve (12) months from the date of this Satisfaction Voucher and during this period, rectification of repairs effected by the Workshop which prove to be faulty shall be undertaken by the Workshop free of charge.

This Warranty shall be inapplicable to:

- faults arising out of abnormal usage of the vehicle;
- faults due to attempts to correct any defect in the repairs effected by the Workshop or the mishandling of rectification work to the vehicle by persons other than the Workshop;
- (c) manufacturing defects in any parts replaced that could not reasonably have been detected by the Workshop at the time the repairs were effected;
- (d) faults or defects arising out of normal wear and tear, misuse, neglect, accident, flood, acts of God, or use in violation of the specifications relevant to the vehicle.

No. 10 Ang Mo Kio Industrial Park 2A MCT-09 AMK Autgobint Singapore 568047 Tel: 6483 1244 Fax: 6483 6170

Signature and startip of the Workshop



No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimme@singnescom.ASTT FINALISATION
GST:M9-0009639-E RCB NO:06470300B

Claim No:

Policy No:

Veh Reg No:

Ref No:

Date:

DRAFT FINALISAY Model

MC0912989

MF0911343

19 Sep 2018

GA001686

SKK7725H

2WD

BMW 520I AT D/AB

M/S:

AXA INSURANCE PTE LTD

8 SHENTON WAY #27-01 AXA TOWER

SINGAPORE 068811

TEL:

63387288

ATTN: Motor Claim Department

Your Ref No:

S8M00D7F

Claim Type:

Own Damage

Accident Date:

05/04/2018

FAX: 63382522

Repair Cost to Vehicle No (For Finalization):SKK7725H Amount Cost Quantity U/Price Description S\$ S\$ SPARE PARTS 450.00 1 PC FRONT FENDER LH 90.00 1 PC FRONT FENDER COWLING (REAR SECTION) 2 12.00 8 PC FRONT FENDER COWLING CLIPS 3 85.00 1 PC FRONT FENDER CHROME MOULDING 4 1,150.00 1 PC FRONT DOOR LH 5 125.00 1 PC FRONT DOOR RUBBER (AT DOOR) 6 60.00 1 PC SIDE MIRROR LOWER COVER LH 1.150.00 1 PC REAR DOOR LH 8 1 PC 125.00 REAR DOOR RUBBER (AT DOOR) 9 1 PC 330.00 SIDE SKIRT LH 10 8.00 1 PC SIDE SKIRT BRACKET FRONT 11 15.00 10 PC SIDE SKIRT CLIPS 54.00 1 PC DOOR VIEW MIRROR SURROUND 3,654.00 Special Nett 810.00 1 PC 14 SPORT RIM LHR 810.00 AH LIM MOTOR COMPANY stur läikaa Mil LABOUR 15 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS 30.00 1 PC AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING. 60.00 1 PC 16 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT. 160.00 17 TO DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM 1 PC SUCH AS POWER WINDOW MOTOR AND REGULATOR TO NEW DOOR/FACILITATE REPAIR. 60.00 1 PC 18 TO REMOVE AND REINSTALL/REPLACE QUARTER GLASS 80.00 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER 1 PC TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS. 20 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD REAR FENDER 800.00 1 PC LH.TO KNOCK & REPAIR FRONT DOOR PILLAR LH, ROCKER PANEL LH,CTR PILLAR LH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME. 1,200.00 21 TO SPRAY FRONT BUMPER, FRONT FENDER LH, FRONT DOOR LH, SIDE 1 PC MIRROR LH, FROTN DOOR PILLAR LH, SIDE SKIRT LH, ROCKER PANEL LH,REAR DOOR LH,RR FENDER LH,REAR BUMPER.



No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg GST:M9-0009639-E RCB NO:06470300B

DRAFT FINALISATION

M/S:

AXA INSURANCE PTE LTD

8 SHENTON WAY

#27-01 AXA TOWER

SINGAPORE 068811

TEL:

63387288

FAX: 63382522

ATTN: Motor Claim Department

Your Ref No:

Claim Type:

S8M00D7F Own Damage

Accident Date:

05/04/2018

DRAFT FINALISATION

Claim No:

Policy No:

Veh Reg No:

Make/Model:

Ref No:

Date:

Repair Cost to Vehicle No (For Finalization): SKK7725H

Description

U/Price

Quantity

Cost

S\$

Amount S\$

2,390.00

Amount Before Excess

\$\$ 6,854.00

Less Excess

MC0912989

MF0911343

19 Sep 2018

GA001686

SKK7725H

2WD

BMW 520I AT D/AB

S\$ 900.00 S\$ 5,954.00

Amount Before GST Add GST @ 7%

416.78

Total Amount payable

S\$ 6,370.78

TOTAL: SINGAPORE DOLLAR SIX THOUSAND THREE HUNDRED SEVENTY AND CENTS SEVENTY EIGHT ONLY The above vehicle was surveyed by KENNETH KONG -LKK on 02/05/2018

FOR AHAHM MOTOR SPOR ANY

No. 10 Ang Mo Kio Industrial Park 2A #01-09-AMK Autopoint Singapore 568047 Tel: 6489-1244 Fax: 6483 6170

AUTHORISED SIGNATURE



No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimme@singnet.com.sg GST:M9-0009639-E RCB NO:06470300B

AXA INSURANCE PTE LTD M/S:

8 SHENTON WAY

#27-01 AXA TOWER SINGAPORE 068811

63387288 TEL:

ATTN: Motor Claim Department

Own Damage Claim Type:

Accident Date: 05/04/2018 Claim No:

MC0912989

Final No:

AL0928958

Date:

08 Oct 2018

Policy No:

GA001686

Veh Reg No:

SKK7725H Make/Model: BMW 520I AT D/AB

2WD

Your Ref No:

S8M00D7F

LH, REAR DOOR LH, RR FENDER LH, REAR BUMPER.

Tax Invoice-Final Repair Cost to Vehicle No :SKK7725H

FAX: 63382522

	Description U/Price	Quantity	Cost SS	Amount S\$
	SPARE PARTS		114	24
1	FRONT FENDER LH	1 PC	450.00	
2	FRONT FENDER COWLING (REAR SECTION)	1 PC	90.00	
3	FRONT FENDER COWLING CLIPS	8PC	12.00	
4	FRONT FENDER CHROME MOULDING	1 PC	85.00	
5	FRONT DOOR LH	1 PC	1,150.00	
6	FRONT DOOR RUBBER (AT DOOR)	1 PC	125.00	
7	SIDE MIRROR LOWER COVER LH	1 PC	60.00	
8	REAR DOOR LH	1 PC	1,150.00	
9	REAR DOOR RUBBER (AT DOOR)	1 PC	125.00	
10	SIDE SKIRT LH	1 PC	330.00	
11	SIDE SKIRT BRACKET FRONT	1 PC	8.00	
12	SIDE SKIRT CLIPS	10 PC	15.00	
13	DOOR VIEW MIRROR SURROUND	1 PC	54.00	
-520				3,654.00
	Special Nett			
14		1 PC	810.00	
15100	SPORT RIM LHR 110 10 Sug Mo Kin Industrial Park 2A 110 10 Sug Mo Kin Industrial Park 2A Autopoint Sir papore 5680 110 1244 For 1453 6170	47	:	810.00
	LABOUR			
15	TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	30.00	
16	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	1 PC	60.00	
	TO DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM SUCH AS POWER WINDOW MOTOR AND REGULATOR TO NEW DOOR/FACILITATE REPAIR.	1 PC	160.00	
18	TO REMOVE AND REINSTALL/REPLACE QUARTER GLASS	1 PC	60.00	
	TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER	1 PC	80.00	
- e 15	TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.			
20	TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD REAR FENDER LH. TO KNOCK & REPAIR FRONT DOOR PILLAR LH, ROCKER PANEL LH, CTR PILLAR LH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	I PC	800.00	
21	TO SPRAY FRONT BUMPER, FRONT FENDER LH, FRONT DOOR LH, SIDE MIRROR LH, FROTN DOOR PILLAR LH, SIDE SKIRT LH, ROCKER PANEL	1 PC	1,200.00	



No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg GST:M9-0009639-E RCB NO:06470300B

M/S:

AXA INSURANCE PTE LTD

8 SHENTON WAY

#27-01 AXA TOWER

SINGAPORE 068811

TEL:

63387288

FAX: 63382522

ATTN: Motor Claim Department

Your Ref No: Claim Type:

S8M00D7F Own Damage

Accident Date:

Description

05/04/2018

Tax Invoice-Final Repair Cost to Vehicle No :SKK7725H

U/Price

Claim No:

Final No:

Policy No:

Veh Reg No:

Make/Model:

Date:

Quantity

Cost

Amount SS

SS

2,390.00

Amount Before Excess

S\$ 6,854.00

Less Excess

MC0912989

AL0928958

08 Oct 2018

GA001686

SKK7725H

2WD

BMW 520I AT D/AB

SS 900.00

Amount Before GST

SS 5,954.00

Add GST @ 7%

416.78

Total Amount payable

SS 6,370.78

TOTAL: SINGAPORE DOLLAR SIX THOUSAND THREE HUNDRED SEVENTY AND CENTS SEVENTY EIGHT ONLY The above vehicle was surveyed by KENNETH KONG -LKK on 02/05/2018

For AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Industrial Park 2A #01-09 AMIC Autopoint 51 papare 558047 Tek 6463 1244 - 52 3483 8170

E. & O. E.

AUZHORISED SIGNATURE