



MS/G (inHouse) 0D

PDI TUAS

3/5/2018 @ 10am.

Tan Shu Shi 97495749
Exp \$500

Phone No.
Fax No.
E-Mail

PDI TUAS

CHONG RUI FANG
(ZHANG RUIFANG)
415C FERNVALE LINK
#08-62
Singapore 702415
Singapore

Consent, Not Authorize VAT Registration No. M20098505-2
3/5/18 @ 1425 Tax No. 199101494Z

Service Quote

Customer No. CV029611
Quote No. SER/QUO/1800736
QuoteDate 28/04/18
Salesperson Lawrence Tan Say Ch
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Make Volkswagen **Model Description** JETTA TSI (DSG) SPORTLINE
License No. SKT1178Y **VIN** WVAWZZZ46ZF004840
Engine Code M4 **Labor Type** M4

Mileage 99,117
Initial Registration 26/05/15
Engine No. CAX F10752

Service Advisor Tang Shu Shi
Sales Advisor Lawrence Tan Say Chuan
Model Code 1633G5

No.	Description	Qty.	UoM	Unit Price	Amount
P B&P CELETTE	VEHICLE ON BENCH- CELETTE (	1	Gram		1,500.00
P B&P MACP LABOUR	LABOUR	8	UNIT		3,800.00
P B&P MACP LABOUR	TRANSFER DOOR MECHANISM	2	UNIT		950.00
P B&P MACP PAINT	SPRAY PAINT	5	UNIT		3,000.00
P B&P DIAG	PROGRAMMING & CALIBRATION	1	Time Un		480.00
P B&P MECH	COMPULSORY TO DO AFTER AC				
P B&P MECH	CHECK WIRE HARNESS, ECU, S	1	Time Un		280.00
P B&P MECH	Nett				
P B&P MECH	R&R D/BOARD TO R&R DOOR HI	3	Time Un		1,425.00
P B&P MECH	Nett				
P B&P MECH	R&R RIM & BALANCE	1	Time Un		50.00
P B&P WHEEL ALIGNMENT	B&P WHEEL ALIGNMENT NETT	1	Time Un		300.00
	Sum Labor				11,785.00
P 311601361	RUBBER VALVE	1	Pieces		1.73
	Use Predecessor 281601361				
P 3C8857537 GRU	LHS MIRROR COVER	1	Pieces		181.95
P 5C6805911N	LHS FENDER LINER	1	Pieces		132.62
P 5C6807183A	FRT BUMPER SIDE BRACKET LH	1	Pieces		32.26
P 5C6807184A	FRT BUMPER SIDE BRACKET RH	1	Pieces		31.11
P 5C6821105A	FENDER LH	1	Pieces		691.67
	Use Predecessor 5C6821105				
P 5C6821111A	FENDER ELEMENT	1	Pieces		30.71
	Use Predecessor 5C6821111				
P 5C6821135	LHS FENDER BRACKET	1	Pieces		45.27
Sum carried forward					12,932.30

Payments to: - BBN: - Acc.-No.:

PDI TUAS

PDI TUAS

CHONG RUI FANG
(ZHANG RUIFANG)
415C FERNVALE LINK
#08-62
Singapore, 793415
Singapore

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV029611
Quote No. SER/QUO/1800736
QuoteDate 28/04/18
Salesperson Lawrence Tan Say Ch
Page 2

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	JETTA TSI (DSG) SPORTLINE	99,117	Tang Shu Shi
License No.	VIN	Initial Registration	Sales Advisor
SKT1778Y	WVWZZZ16ZFM001840	26/05/15	Lawrence Tan Say Chuan
Engine Code	Labor Type	Engine No.	Model Code
	M4	CAX F10752	1633G5

Continued			12,932.30
P 5C6831055G	LHS FRONT DOOR Predecessor 5C6831055E	1 Pieces	bt / 1,292.81
P 5C6833055E	LH REAR DOOR Use 5C6833055C or 5C6833111A	1 Pieces	bt / 2,090.75
P 5C6837249A	CHECK ROD Use Predecessor 5C6837249	1 Pieces	? 112.43
P 5C6837431 5AP	CHANNEL SEAL	1 Pieces	? 367.83
P 5C6837461K	REGULATOR SISL Recall 101-2015	1 Pieces	? 510.33
P 5C6837477B 5AP	LHS DOOR TOP MLDG Predecessor 5C6837477 5AP	1 Pieces	? 105.42
P 5C6837651	LF FRONT DOOR SEAL	1 Pieces	neu / 60.09
P 5C6839699D	DOOR SEAL Predecessor 5C6839699C	1 Pieces	neu / 164.09
P 5C6845201B	LHS FRT DOOR GLASS	1 Pieces	cut / 300.54
P 5C6857521C	LHS MIRROR GLASS	1 Pieces	cut / 194.64
P 5C8857507J	LHS MIRROR HOUSING	1 Pieces	cut / 295.65
P 5G0010029J	STICKER (AIRBAG)	1 Pieces	? 17.72
P 5K0073147C 88Z	ALLOY WHEELS 17" SILEX With Tyre 225/45 R17 Pirelli	1 Pieces	cut / 1,102.38
P 5K2837015E	DOOR LOCK	1 Pieces	? 486.35
P 5N0837885H	SUPPORT DOOR HANDLE Use Predecessor 5N0837885G	1 Pieces	cut / 96.02
P 7D0000279A	STICKER (CHASSIS NO)	1 Pieces	? 235.23
P 7L6868243	DOOR BOARD CLIP	14 Pieces	neu / 31.08
P 8K0831401H	HINGE UPPER	1 Pieces	? 89.25
Sum carried forward			20,484.88

Payments to: - BBN: - Acc.-No.:

PDI TUAS

PDI TUAS

CHONG RUI FANG
(ZHANG RUIFANG)
415C FERNVALE LINK
#08-62
Singapore, 793415
Singapore

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV029611
Quote No. SER/QUO/1800736
QuoteDate 28/04/18
Salesperson Lawrence Tan Say Ch
Page 3

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	JETTA TSI (DSG) SPORTLINE	99,117	Tang Shu Shi
License No.	VIN	Initial Registration	Sales Advisor
SKT1778Y	WVWZZZ16ZFM001840	26/05/15	Lawrence Tan Say Chuan
Engine Code	Labor Type	Engine No.	Model Code
	M4	CAX F10752	1633G5

		Continued	20,484.88
P 8K0831401H	HINGE LOWER	1 Pieces	? 89.25
P D 378500A2	DOOR INSULATOR	1 Pieces	all 53.34
P D 378500A2	DOOR INSULATOR	1 Pieces	all 53.34
P N 10516801	NUT	6 Pieces	all 7.47
P N 90346302	RIVET	10 Pieces	all 17.85
	Sum Item		8,921.13

Sum Labor	11,785.00
Sum Item	8,921.13

Total SGD	20,706.13
7% GST	20,706.13 1,449.48
Total SGD Incl. GST	22,155.61

Explanations

P = Proportionately Charged

Payment Terms No Credit

Payments to: - BBN: - Acc.-No.: