



SINGAPORE CIVIL DEFENCE FORCE

FIRE REPORT

1. GENERAL INFORMATION			
INCIDENT NO. : /20180427/0901		LOCATION OF FIRE: Along Ayer Rajah Expressway towards Tuas Near Lamp Post No. 425 Singapore	
FIRE REPORTED ON : 27 April 2018			
TIME OF CALL : 20:48:56 hrs			
STATION COVERAGE : Clementi Fire Station			
2. INCIDENT INFORMATION			
FIRE INVOLVED: The dashboard of a Honda car (SJU7407K).			
METHOD OF EXTINGUISHMENT: By SCDF crew using a hose reel jet and a 38mm hose line jet from fire appliance.			
PROBABLE CAUSE OF FIRE: Accidental (Electrical origin at the dashboard)			
DAMAGE SUSTAINED: As a result of the fire, the car was damaged.			
3. FATALITY/INJURY INFORMATION			
NAME	PIN/FIN	ADDRESS	DEAD/INJURIES SUSTAINED
NIL	NIL	NIL	NIL
REPORT CERTIFIED TRUE AND CORRECT BY: CINDY HAN for COMMISSIONER SINGAPORE CIVIL DEFENCE FORCE			

This is a computer generated Fire Report. No signature is required.