



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 21.09.2018

Survey Details:

Date of loss	25.04.2018
Date of appointment	03.05.2018
Date of survey	03.05.2018
Location of survey	Chunni Motor Work Pte Ltd

Vehicle Details:

Claim Type:	Third party
Vehicle number	SHC 631T
Make and Model	Hyundai I40 (1685cc)
Date of registration	30.04.2014
Excess	NIL
Market Value/ Book Value	(est)
Parf/COE Rebate	(est)
Nett Loss	(est)

Repair details:

Initial Estimate	\$ 30,190.34
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 12,980.34
Check items (estimate)	NIL
Labour	\$ 2,530.00
Supplementary	NIL
Total	\$ 15,510.34
Lump Sum(if applicable)	\$ 12,400.00

Number of days for repair	<u>10</u>
---------------------------	-----------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Date: 21.09.2018

Remarks:

--

Mandate:

Liability(TP)	100%	
Proposed repair cost (w/GST)	\$ 13,268.00	
Loss of use	NIL	
Loss of rental	\$ 1,560.00	(12days x \$130.00)
Loss of income	\$ 600.00	(12days x \$50.00)
LTA/GIA search fees	\$ 7.49	
Others	NIL	
Proposed Total	\$ 15,435.49	

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2839G
Vehicle Details	
Vehicle No.:	SHA8783X
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Sep 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E 220 CDI BLUEEFFICIENCY
Primary Colour:	White
Manufacturing Year:	2012
Engine No.:	65192431233202
Chassis No.:	WDD2120022A676082
Maximum Power Output:	125.0 kW (167 bhp)
Open Market Value:	\$40,934.00
Original Registration Date:	31 Aug 2012
First Registration Date:	31 Aug 2012
Transfer Count:	0
Actual ARF Paid:	\$40,934.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Aug 2020
PARF Rebate Amount:	\$26,607.00
Intended COE Rebate Details	
COE Expiry Date:	30 Aug 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$48,892.00
COE Rebate Amount:	\$11,861.00
Total Rebate Amount:	\$38,468.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 21 Sep 2018

OK



Re:RE: Re:<SEEK MANDATE> - S8M00FBM [ACCIDENT INVOLVING GBE 2626G(OI) & SHC 631T(TP) ON 25/04/2018]

Type

🔍 Question

Message

PLS PROCEED TO OFFER AS FOLLOWS: \$13,960.00 ALL IN COR: \$11,970.00 (W/GST) LOR: \$1,430.00 (11DAYS) LOI \$550.00 LTA: \$7.49 TOTAL: \$13,957.49 ~ \$13,960.00 ALL IN

Reply



Re:<SEEK MANDATE> - S8M00FBM [ACCIDENT INVOLVING GBE 2626G(OI) & SHC 631T(TP) ON 25/04/2018]

Type

🗉 Question

Message

WE DO NOT AGREE WITH YOU THAT TPV MAY HAVE HIT THE KERB. AS PER THE VIDEO FOOTAGE, THIS IS A HEAD TO REAR COLLISION AND AFTER THE IMPACT, TPV DID NOT COME INTO CONTACT WITH THE KERB. BASED ON SURVEY PHOTOS, THERE IS NO PHOTOS SHOWING DAMAGES/ PARTS OF ANY FRONTAL DAMAGES. PLS REVIEW ON YOUR IA AND RE-SEEK MANDATE WITHOUT ANY FRONTAL DAMAGES.

Reply

Hsiao Tong (LKKAUTO)

From: Hsiao Tong (LKKAUTO)
Sent: Monday, 15 October 2018 3:03 PM
To: 'Chunni Motor'
Cc: Bryan Ang (LKKAUTO)
Subject: Your Ref: SHC 631T *Our Ref: CC4/ASM18008098/Dpb3 [ACCIDENT INVOLVING GBE 2626G(AXA) & SHC 631T ON 25/04/2018]

Your Ref: **SHC 631T** Without Prejudice
Our Ref: CC4/ASM18008098/Dpb3

Dear Sirs/Madam,

ACCIDENT INVOLVING GBE 2626G(AXA) & SHC 631T ON 25/04/2018

We refer to the above matter.

For cost of repair, we have our principal instruction to offer L/Sum \$11,000.00(before GST) with 10 repair days.

Kindly confirm.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

~~11770~~
11770-W
1862.08
7.45

13639.57
G/S \$13639.57

Hsiao Tong (LKKAUTO)

From: Chunni motor Work <chunnimw@yahoo.com.sg>
Sent: Tuesday, 16 October 2018 11:46 AM
To: Hsiao Tong (LKKAUTO)
Subject: Re: Your Ref: SHC 631T *Our Ref: CC4/ASM18008098/Dpb3 [ACCIDENT INVOLVING GBE 2626G(AXA) & SHC 631T ON 25/04/2018]
Attachments: LOD.pdf

Your Ref : CC4/ASM18008098/Dpb3
Our Ref : SHC 631 T (250418)

WITHOUT PREJUDICE

Dear Hsiao Tong

Your email of even date refers.

Please see the attached LOD as requested.

Strictly on a without prejudice basis and without any admission of liability, we confirm settlement for our client's property damage claim (Cost of repair and the loss of rental & income during the period of repair) only as per your principals, M/s AXA Insurance Pte Ltd's offer.

Please note that the settlement reached is strictly for the aforesaid property damage claim only and is without prejudice to the hirer of SHC 631 T, Liew Su Yeow's injury claim and other losses against your insured.

Kindly forward us your Discharge Voucher for our client's execution as soon as possible.

Thank you and have a nice day !

Best Regards
William
Claims Department

Chunni Motor Work Pte Ltd
10 Ang Mo Kio Industrial Park 2A
#03-19 AMK AutoPoint
Singapore 568047

Tel : 6483-6016 (Claims)

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.
It may contain confidential and/or legally privileged information.
If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful.
Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.
Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.



Save the trees - Do you really need to print this e-mail?

On Monday, 15 October 2018, 3:12:06 PM SGT, Chunni Motor <chunnimotor@gmail.com> wrote:

----- Forwarded message -----

From: **Hsiao Tong (LKKAuto)** <chewht@lkkauto.com>

Date: Mon, Oct 15, 2018 at 3:02 PM

Subject: Your Ref: SHC 631T *Our Ref: CC4/ASM18008098/Dpb3 [ACCIDENT INVOLVING GBE 2626G(AXA) & SHC 631T ON 25/04/2018]

To: Chunni Motor <chunnimotor@gmail.com>

Cc: Bryan Ang (LKKAuto) <bryanang@lkkauto.com>

Your Ref: **SHC 631T**

Without Prejudice

Our Ref: CC4/ASM18008098/Dpb3

Dear Sirs/Madam,

ACCIDENT INVOLVING GBE 2626G(AXA) & SHC 631T ON 25/04/2018

We refer to the above matter.

For cost of repair, we have our principal instruction to offer L/Sum \$11,000.00(before GST) with 10 repair days.

Kindly confirm.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Wednesday, 17 October 2018 4:05 PM
To: 'Chunni motor Work'
Subject: RE: Your Ref: SHC 631T *Our Ref: CC4/ASM18008098/Dpb3 [ACCIDENT INVOLVING GBE 2626G(AXA) & SHC 631T ON 25/04/2018]

Without Prejudice

Hi,

We refer to the above matter.

We propose settlement at a global sum of **\$13,630.00**(Cost of repair and the loss of rental & income).

Please confirm acceptance.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Chunni motor Work <chunnimw@yahoo.com.sg>
Sent: Tuesday, 16 October 2018 11:46 AM
To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Subject: Re: Your Ref: SHC 631T *Our Ref: CC4/ASM18008098/Dpb3 [ACCIDENT INVOLVING GBE 2626G(AXA) & SHC 631T ON 25/04/2018]

Your Ref : CC4/ASM18008098/Dpb3
Our Ref : SHC 631 T (250418)

WITHOUT PREJUDICE

Dear Hsiao Tong

Your email of even date refers.

Please see the attached LOD as requested.

Strictly on a without prejudice basis and without any admission of liability, we confirm settlement for our client's property damage claim (Cost of repair and the loss of rental & income during the period of repair) only as per your principals, M/s AXA Insurance Pte Ltd's offer.

Please note that the settlement reached is strictly for the aforesaid property damage claim only and is without prejudice to the hirer of SHC 631 T, Liew Su Yeow's injury claim and other losses against your insured.

Kindly forward us your Discharge Voucher for our client's execution as soon as possible.

Thank you and have a nice day !

Hsiao Tong (LKKAUTO)

From: Chunni motor Work <chunnimw@yahoo.com.sg>
Sent: Wednesday, 17 October 2018 5:21 PM
To: Hsiao Tong (LKKAUTO)
Subject: Re: Your Ref: SHC 631T *Our Ref: CC4/ASM18008098/Dpb3 [ACCIDENT INVOLVING GBE 2626G(AXA) & SHC 631T ON 25/04/2018]

Your Ref : CC4/ASM18008098/Dpb3
Our Ref : SHC 631 T (250418)

WITHOUT PREJUDICE

Hi Hsiao Tong

Your email of 17-10-2018 refers.

Strictly on a without prejudice basis and without any admission of liability, we confirm settlement for our client's property damage claim (Cost of repair and the loss of rental and income during the period of repair) at a global sum of \$13,630.00.

Please note that the settlement reached is strictly for the aforesaid property damage claim only and is without prejudice to the hirer of SHC 631 T, Liew Su Yeow's injury claim and other losses against your principals, M/s AXA Insurance Pte Ltd and /or their insured.

Kindly forward us your Discharge Voucher for our client's execution as soon as possible.

Thank you and have a nice day !

Best Regards
William
Claims Department

Chunni Motor Work Pte Ltd
10 Ang Mo Kio Industrial Park 2A
#03-19 AMK AutoPoint
Singapore 568047

Tel : 6483-6016 (Claims)

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed. It may contain confidential and/or legally privileged information. If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses. Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.



Save the trees - Do you really need to print this e-mail?

On Wednesday, 17 October 2018, 4:05:02 PM SGT, Hsiao Tong (LKKAuto) <chewht@lkkauto.com> wrote:

Without Prejudice

Hi,

We refer to the above matter.

We propose settlement at a global sum of **\$13,630.00**(Cost of repair and the loss of rental & income).

Please confirm acceptance.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Chunni motor Work <chunnimw@yahoo.com.sg>

Sent: Tuesday, 16 October 2018 11:46 AM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Subject: Re: Your Ref: SHC 631T *Our Ref: CC4/ASM18008098/Dpb3 [ACCIDENT INVOLVING GBE 2626G(AXA) & SHC 631T ON 25/04/2018]

Your Ref : CC4/ASM18008098/Dpb3

Our Ref : SHC 631 T (250418)

WITHOUT PREJUDICE

Dear Hsiao Tong

Your email of even date refers.

Please see the attached LOD as requested.

Strictly on a without prejudice basis and without any admission of liability, we confirm settlement for our client's property damage claim (Cost of repair and the loss of rental & income during the period of repair) only as per your principals, M/s AXA Insurance Pte Ltd's offer.

Please note that the settlement reached is strictly for the aforesaid property damage claim only and is without prejudice to the hirer of SHC 631 T, Liew Su Yeow's injury claim and other losses against your insured.

Kindly forward us your Discharge Voucher for our client's execution as soon as possible.

Thank you and have a nice day !

Best Regards

William

Claims Department

Chunni Motor Work Pte Ltd

10 Ang Mo Kio Industrial Park 2A

#03-19 AMK AutoPoint

Singapore 568047

Tel : 6483-6016 (Claims)

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.
It may contain confidential and/or legally privileged information.
If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.
Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission

or any modification.



Save the trees - Do you really need to print this e-mail?

On Monday, 15 October 2018, 3:12:06 PM SGT, Chunni Motor <chunnimotor@gmail.com> wrote:

----- Forwarded message -----

From: **Hsiao Tong (LKKAUTO)** <chewht@lkkauto.com>

Date: Mon, Oct 15, 2018 at 3:02 PM

Subject: Your Ref: SHC 631T *Our Ref: CC4/ASM18008098/Dpb3 [ACCIDENT INVOLVING GBE 2626G(AXA) & SHC 631T ON 25/04/2018]

To: Chunni Motor <chunnimotor@gmail.com>

Cc: Bryan Ang (LKKAUTO) <bryanang@lkkauto.com>

Your Ref: **SHC 631T**

Without Prejudice

Our Ref: CC4/ASM18008098/Dpb3

Dear Sirs/Madam,

ACCIDENT INVOLVING GBE 2626G(AXA) & SHC 631T ON 25/04/2018

We refer to the above matter.

For cost of repair, we have our principal instruction to offer L/Sum \$11,000.00(before GST) with 10 repair days.

Kindly confirm.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	GBE 2626G (Insd veh)	Model:	HYUNDAI
	SHC 631T (TP veh)		I40
Date of Accident:	25/04/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	:	\$	32,303.66
Final Repair Cost	:	\$	11,770.00
Loss of Token Sum	:	\$	550.00
			11 days at \$50.00 per day
Rental (if any)	:	\$	1,312.08
			11 days
LTA / GIA Search Fee	:	\$	7.45

Others:	:	\$	
---------	---	----	--

	:	\$	
Final Settlement Sum (GLOBAL SUM)	:	\$	13,630.00

Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)	
A) For Non GIA Registered Workshop:	Agreed Liability ____100____(%)
B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: ____
BOLA Liability: ____ (%)	Assessed Liability (*): ____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	
Remarks _____ _____	

Payment Instruction: Payee's Breakdown			
1)	CHUNNI MOTOR WORK PTE LTD	:	\$ 13,630.00

NUR SHAQILAH BTE ABDOL
WAHAB

08/11/2018
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM18008098/Dpb3s2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: KIAN CHUAN			Date : 08-11-2018	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBE 2626G	Veh. Inspected	SHC 631T	
Policy No.	GA237728/1	Coverage (\$)	0.00	
Claim No.	S8M00FBM	Excess (\$)	0.00	
Assign From	KIAN CHUAN	Assign Date	03/05/2018	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I40	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	KMHLB41UMEU052424	Colour	YELLOW	
Odometer	473710	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60R16	WEST LAKE	5 mm	
L/H Front Tyre	205/60R16	WEST LAKE	5 mm	
R/H Rear Tyre	205/60R16	WEST LAKE	5 mm	
L/H Rear Tyre	205/60R16	WEST LAKE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/04/2018	Inspection Date	03/05/2018	
Survey held at	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 631T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	RADIATOR GRILLE (CONSISTENT)	SERVICEABLE	294.35	-
1	RADIATOR GRILLE H EMBLEM (CONSISTENT)	SERVICEABLE	113.65	-
1	FRONT BUMPER COVER (CONSISTENT)	DISTORTED	562.30	562.30
1	FRONT BUMPER SPONGE (CONSISTENT)	NOT NECESSARY	142.20	-
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	NOT NECESSARY	526.10	-
1	FRONT BUMPER CENTRE GRILLE (CONSISTENT)	NOT NECESSARY	178.60	-
2	FRONT BUMPER CENTRE GRILLE TOP GARNISH @ \$80.00 (CONSISTENT)	NOT NECESSARY	160.00	-
2	FRONT BUMPER BRACKET TOP (LH/RH) @ \$22.40 (CONSISTENT)	SERVICEABLE	44.80	-
2	FRONT BUMPER BRACKET (LH/RH) @ \$24.60 (CONSISTENT)	SERVICEABLE	49.20	-
2	FRONT BUMPER RETAINER MOUNTING @ \$9.20 (CONSISTENT)	SERVICEABLE	18.40	-
1	HEADLAMP SUPPORT TOP COVER (CONSISTENT)	SERVICEABLE	398.00	-
1	HEADLAMP SUPPORT PANEL ASSY (CONSISTENT)	NOT NECESSARY	1,067.50	-
2	HEADLAMP (LH/RH) @ \$1388.00 (CONSISTENT)	NOT NECESSARY	2,776.00	-
1	RADIATOR (CONSISTENT)	NOT NECESSARY	850.20	-
1	RADIATOR FAN BLADE, COWLING, MOTOR ASSY (CONSISTENT)	NOT NECESSARY	792.95	-
2	RADIATOR BRACKET (RH/LH) @ \$6.50 (CONSISTENT)	SERVICEABLE	13.00	-
2	RADIATOR GUARD @ \$35.00 (CONSISTENT)	SERVICEABLE	70.00	-
2	HORN UNIT (LH/RH) @ \$86.75 (CONSISTENT)	NOT NECESSARY	173.50	-
1	HORN WIRE (CONSISTENT)	NOT NECESSARY	156.50	-
1	AIRCON CONDENSER (CONSISTENT)	NOT NECESSARY	1,137.35	-
1	INTER COOLER (CONSISTENT)	NOT NECESSARY	921.90	-
2	INTER COOLER MOUNTING (CONSISTENT)	NOT NECESSARY	25.90	-
1	BOOT LID (CONSISTENT)	BROKEN	1,681.40	1,681.40
1	BOOT LID RUBBER (CONSISTENT)	DEFORMED	115.80	115.80
2	BOOT LID HINGE (LH/RH) @ \$178.10 (CONSISTENT)	TO REPAIR SEE LABOUR	356.20	-
1	BOOT LID LOCK UPPER (CONSISTENT)	BENT	137.90	137.90
1	BOOT LID LOCK LOWER (CONSISTENT)	BENT	31.70	31.70

Report Ref No. CC4/ASM18008098/Dpb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOOT LID 'H' EMBLEM (CONSISTENT)	NECESSARY	27.20	27.20
1	BOOT LID CRDI PLATE (CONSISTENT)	NECESSARY	41.00	41.00
2	BOOT LID LAMP (LH/RH) @ \$556.80 (CONSISTENT)	CRACKED	1,113.60	1,113.60
2	LICENCE LAMP (LH/RH) @ \$33.95 (CONSISTENT)	SERVICEABLE	67.90	-
1	BOOT LID TRIMBOARD (CONSISTENT)	TORN	172.70	172.70
10	BOOT LID TRIMBOARD CLIPS (CONSISTENT)	NECESSARY	11.00	11.00
1	BOOTLID MOULDING (CONSISTENT)	BENT	85.00	85.00
1	BOOTLID I40 EMBLEM (CONSISTENT)	NECESSARY	41.00	41.00
1	BOOTLID LOWER GARNISH (CONSISTENT)	CRACKED	398.00	398.00
1	REAR BUMPER (CONSISTENT)	CRACKED	603.60	603.60
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	BROKEN	504.35	504.35
2	REAR BUMPER REINFORCEMENT BRACKET (LH/RH) @ \$180.00 (CONSISTENT)	NOT NECESSARY	360.00	-
10	REAR BUMPER CLIP (CONSISTENT)	NECESSARY	22.00	22.00
2	REAR BUMPER BRACKET @ \$49.00 (CONSISTENT)	SERVICEABLE	98.00	-
1	REAR BUMPER SPONGE (CONSISTENT)	TORN	143.40	143.40
1	REAR BUMPER UNDER COVER (CONSISTENT)	DENTED	225.00	225.00
2	REAR BUMPER REFLECTOR LAMP (LH/RH) @ \$32.00 (CONSISTENT)	NOT NECESSARY	64.00	-
2	TAIL LAMP (LH/RH) @ \$565.60 (CONSISTENT)	CRACKED	1,131.20	1,131.20
2	TAIL LAMP QUARTER PANEL (LH/RH) @ \$97.90 (CONSISTENT)	O/S DENTED / N/S NOT NECESSARY	195.80	97.90
1	REAR PANEL (CONSISTENT)	BUCKLED	592.30	592.30
1	REAR PANEL GARNISH (CONSISTENT)	DEFORMED	57.70	57.70
1	REAR PANEL LOWER PANEL (CONSISTENT)	DENTED	495.50	495.50
1	SPARE TYRE HOLDER (CONSISTENT)	SERVICEABLE	28.80	-
1	SPARE TYRE PANEL (CONSISTENT)	BUCKLED	900.50	900.50
1	SPARE TYRE PANEL CUSHION (CONSISTENT)	SERVICEABLE	209.05	-
1	REAR TOWING HOOK (CONSISTENT)	SERVICEABLE	94.60	-
1	MEMBER ASSY - REAR FLOOR CENTRE (CONSISTENT)	NOT NECESSARY	170.75	-
1	PANEL ASSY - REAR FLOOR SIDE (RH) (CONSISTENT)	TO REPAIR SEE LABOUR	92.40	-
2	EXHAUST PIPE INSULATOR @ \$58.55 (CONSISTENT)	NOT NECESSARY	117.10	-
2	EXHAUST SILENCER @ \$954.00 (CONSISTENT)	BENT	1,908.00	1,908.00

Report Ref No. CC4/ASM18008098/Dpb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	EXHAUST PIPE HANGER @ \$58.55 (CONSISTENT)	SERVICEABLE	117.10	-
1	EXHAUST PIPE CENTRE (CONSISTENT)	NOT NECESSARY	1,150.30	-
1	REAR FENDER WITH HOUSING (RH) (CONSISTENT)	BUCKLED	4,736.80	4,736.80
1	REAR FENDER INNER LINING (RH) (CONSISTENT)	SERVICEABLE	164.40	-
1	REAR FENDER AIR-DUCT (CONSISTENT)	NOT NECESSARY	51.60	-
1	REAR FENDER TRIM BOARD (RH) (CONSISTENT)	BENT	188.75	188.75
1	REAR WINDSCREEN MOULDING (CONSISTENT)	NECESSARY	60.00	60.00
	LESS 20% DISCOUNT		-5,847.16	-3,217.12
			23,388.64	12,868.48
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE (SN) (CONSISTENT)	NOT NECESSARY	25.00	-
1	FRONT N PLATE TRIM COVER (SN) (CONSISTENT)	SERVICEABLE	30.00	-
1	BOOT LID COMFORT LOGO & TEL NO. STICKER (SN) (CONSISTENT)	NECESSARY	30.00	30.00
1	BOOT LID ADVERTISEMENT LOGO (SN) (CONSISTENT)	NECESSARY	100.00	100.00
1	REAR NO. PLATE (SN) (CONSISTENT)	SERVICEABLE	25.00	-
1	REAR BUMPER REVERSE SENSOR (SN) (CONSISTENT)	DAMAGED	135.70	135.70
1	REAR BUMPER ADVERTISEMENT LOGO (SN) (CONSISTENT)	NECESSARY	50.00	50.00
2	REAR FENDER ADVERTISEMENT LOGO (LH/RH) @ \$100.00 (SN) (CONSISTENT)	NECESSARY	200.00	200.00
1	REAR WINDSCREEN SEALANT (SN) (CONSISTENT)	NECESSARY	46.00	46.00
			641.70	561.70
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF BOOT LID HINGE (LH/RH) AND PANEL ASSY - REAR FLOOR SIDE (RH).		3,200.00	1,400.00
	SPRAY PAINTING CHARGE.		1,650.00	1,200.00
	WIRING CHARGE.		100.00	60.00
	TOWING CHARGE.	NOT NECESSARY	60.00	-
	REMOVE / REFIX AIRCON & REFILL GAS.	NOT NECESSARY	150.00	-
	TUFF KOTE.		100.00	40.00
	REMOVE / REFIX CUSHION & UPHOLSTERY REAR.		150.00	80.00
	REMOVE / REFIX REAR WINDSCREEN GLASS.		120.00	80.00

Report Ref No. CC4/ASM18008098/Dpb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE / REFIX REVERSE SENSOR.	NOT NECESSARY	120.00	40.00
	REMOVE / REFIX FUEL TANK.		150.00	-
	REMOVE / REFIX EXHAUST PIPE.		360.00	60.00
			6,160.00	2,960.00
GRAND TOTAL			30,190.34	16,390.18
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				11,000.00

Report Ref No. CC4/ASM18008098/Dpb3s2

ANG BRYAN TANI

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.